

DING AUTO PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

09/07/2018 9:36

JOB-NO: 85008431

OWNER'S PARTICULARS

NAME: LION CITY RENTALS PTE. LTD

CONTACT: 0

Page 1 of 4

ADDRESS: 50 UBI AVENUE 3

0

#01-12

NIL

SINGAPORE 408866

VEHICLE DETAILS

LICENSE NO: SLH5205J

TRANS: AUTO

CHASSIS: MR053REH104559106

MAKE / MODEL: TOYOTA / Altis Corolla 1.6 (A)

ENGINE: 1ZRY335956

OWNER'S INSURER: AIG ASIA PACIFIC INSURANCE PTE. LTD.

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO REMOVE & REPLACED DAMAGED BODY PARTS,REPAIR & REALIGN BODY WORK & CONSISTENT TO THE ACCIDENT AREAS	1.00	2,400.00	0.00	2,400.00		Y	1400
2 RUSH PROOFING	1.00	250.00	0.00	250.00		Y	150
3 TO ADJUST HEAD LAMP & CHECK WIRING	1.00	120.00	0.00	120.00		Y	30
4 REMOVE & REPLACE FRONT ENGINE	1.00	400.00	0.00	400.00		Y	200
5 REMOVE & REFIT FRONT WINDCREEN	1.00	130.00	0.00	130.00		Y	120
6 REMOVE & REFIT FRONT DASH BOARD	1.00	200.00	0.00	200.00		Y	150
7 REMOVE & REFIT FRONT SEAT RHS	1.00	150.00	0.00	150.00		Y	60
8 REMOVE & REFIT FRONT CARPET RHS	1.00	120.00	0.00	120.00		Y	60
9 R & R ROOF LINING	1.00	260.00	0.00	260.00		Y	X
10 MOUNT WORK BENCH	1.00	350.00	0.00	350.00		Y	200
11 TO REMOVE & REPLACED RH F DOOR & RHR DOOR,TRANSFER BOTH DOOR MECHANISM TO THE NEW DOOR	1.00	200.00	0.00	200.00		Y	120
12 R & R REAR SPORT RIM & FRONT SPORT RIM & TRANSFER BOTH TYRE TO THE NEW RIM	1.00	150.00	0.00	150.00		Y	80
13 WHEEL ALIGNMENT	1.00	150.00	0.00	150.00		Y	60
14 REMOVE & REFIT UNDER CARRIAGE	1.00	300.00	0.00	300.00		Y	180
15 ALIGNMENT FRONT SUPPORT PANEL,WHEEL HOUSE PANEL	1.00	120.00	0.00	120.00		Y	80
16 REFILL AIR CON GAS	1.00	100.00	0.00	100.00		Y	80
17 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT BUMPER.	1.00	250.00	0.00	250.00		Y	200
18 TO SPRAY PAINT ON THE AFFECTED AREAS,BONNET	1.00	250.00	0.00	250.00		Y	X
19 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT SUPPORT PANEL	1.00	250.00	0.00	250.00		Y	150
20 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT REINFORCEMENT	1.00	250.00	0.00	250.00		Y	X
21 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT FENDER RHS	1.00	250.00	0.00	250.00		Y	200
22 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT DOOR RHS	1.00	250.00	0.00	250.00		Y	200
23 TO SPRAY PAINT ON THE AFFECTED AREAS,REAR DOOR RHS	1.00	250.00	0.00	250.00		Y	200
24 TO SPRAY PAINT ON THE AFFECTED AREAS,REAR FENDER RHS	1.00	250.00	0.00	250.00		Y	200

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
25 TO SPRAY PAINT ON THE AFFECTED AREAS,ROCKER PANEL	1.00	250.00	0.00	250.00		Y	100
26 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT A PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
27 TO SPRAY PAINT ON THE AFFECTED AREAS,FRONT B PILLAR RHS	1.00	250.00	0.00	250.00		Y	100
28 R & R CONDENSOR & RADIATOR	1.00	120.00	0.00	120.00		Y	60 X
29 R & R LHS,RHS DOOR COMPONENTS	1.00	150.00	0.00	150.00		Y	X
30 R & R B PILLAR GARNISH	1.00	120.00	0.00	120.00		Y	60
31 R & R SEAT BELT RHS	1.00	120.00	0.00	120.00		Y	60
32 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,REAR BUMPER	1.00	250.00	0.00	250.00		Y	200
33 TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS,ROOF LINING	1.00	250.00	0.00	250.00		Y	X
34 ALIGNMENT FRONT CHASSIS	1.00	200.00	0.00	200.00		Y	X
TOTAL:		9,360.00	0.00	9,360.00			

MATERIALS

1 FRONT BUMPER	1.00	511.22	127.81	383.41	X L	Y	300
2 FRONT BUMPER FOG LAMP COVER RHS	1.00	121.75	30.44	91.31	SCU	Y	50
3 FRONT BUMPER LOWER GRILLE	1.00	138.71	34.68	104.03	X L	Y	
4 FRONT BUMPER SIDE RETAINER RHS	1.00	58.17	14.54	43.63	X L	Y	
5 FRONT BUMPER SIDE RETAINER LHS	1.00	58.17	14.54	43.63	X L	Y	
6 FRONT BUMPER BRACKET RHS	1.00	135.70	33.93	101.77	X L	Y	
7 FRONT BUMPER BRACKET LHS	1.00	135.70	33.93	101.77	X L	Y	
8 FRONT REINFORCEMENT	1.00	386.60	96.65	289.95	X L	Y	
9 FRONT REINFORCEMENT ARM LHS	1.00	135.70	33.93	101.77	X L	Y	
10 FRONT REINFORCEMENT ARM RHS	1.00	135.70	33.93	101.77	X L	Y	
11 FRONT BUMPER SPONGE	1.00	102.38	25.60	76.78	X L	Y	
12 FRONT BUMPER LOWER CENTRE COVER	1.00	211.67	52.92	158.75	X L	Y	
13 BONNET	1.00	1,140.40	285.10	855.30	X L	Y	
14 BONNET INSULATOR	1.00	301.36	75.34	226.02	X L	Y	
15 BONNET HINGE LHS	1.00	76.60	19.15	57.45	X L	Y	
16 BONNET HINGE RHS	1.00	76.60	19.15	57.45	X L	Y	
17 BONNET HINGE BOLT	1.00	38.25	9.56	28.69	X L	Y	
18 HEAD LAMP RHS	1.00	794.10	198.53	595.57	X L	Y	
19 HEAD LAMP PANEL RHS	1.00	564.00	141.00	423.00	X L	Y	
20 FRONT SUPPORT PANEL	1.00	1,074.60	268.65	805.95	X L	Y	
21 FRONT BRACE PANEL	1.00	115.70	28.93	86.77	X L	Y	
22 FRONT RADIATOR GRILLE	1.00	565.00	141.25	423.75	X L	Y	
23 FRONT RADIATOR GRILLE "TOYOTA" EMBLEM	1.00	48.00	12.00	36.00	X L	Y	
24 FRONT RADIATOR GRILLE TOP GARNISH	1.00	125.00	31.25	93.75	X L	Y	
25 FRONT FENDER RHS	1.00	859.00	214.75	644.25	X L	Y	
26 FRONT FENDER "VVTI" EMBLEM RHS	1.00	46.00	11.50	34.50	X L	Y	
27 FRONT FENDER INNER SHIELD RHS	1.00	182.00	45.50	136.50	X L	Y	
28 FRONT FENDER WHEEL HOUSE PANEL RHS	1.00	557.00	139.25	417.75	X L	Y	
29 FRONT FENDER QUARTER GARNISH RHS	1.00	65.00	16.25	48.75	X L	Y	
30 FRONT WASHER TANK MOTOR	1.00	196.00	49.00	147.00	X L	Y	
31 FRONT WASHER TANK	1.00	167.00	41.75	125.25	X L	Y	
32 FRONT DRIVER SHAFT RHS	1.00	1,441.60	360.40	1,081.20	X L	Y	
33 FRONT LOWER ARM RHS	1.00	265.07	66.27	198.80	X L	Y	
34 FRONT LOWER ARM BALL JOINT RHS	1.00	270.00	67.50	202.50	X L	Y	
35 FRONT KNUCLE ARM RHS	1.00	521.50	130.38	391.12	X L	Y	
36 FRONT KNUCLE ARM BEARING RHS	1.00	132.67	33.17	99.50	X L	Y	
37 FRONT KNUCLE ARM BOLT WITH NUT RHS	1.00	15.00	3.75	11.25	X L	Y	
38 FRONT SHOCK ABSORBER RHS	1.00	316.97	79.24	237.73	X L	Y	
39 FRONT SHOCK ABSORBER TOP MOULDING RHS	1.00	161.89	40.47	121.42	X L	Y	
40 FRONT SHOCK ABSORBER NUT SET	1.00	12.60	3.15	9.45	X L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
41 FRONT SHOCK ABSORBER DUST COVER RHS	1.00	48.95	12.24	36.71	?	L Y	
42 FRONT SHOCK ABSORBER BUSH RHS	1.00	27.85	6.96	20.89	?	L Y	
43 FRONT SHOCK ABSORBER SPRING RHS	1.00	122.60	30.65	91.95	?	L Y	
44 FRONT SHOCK ABSORBER SPRING SEAT UPPER RHS	1.00	56.75	14.19	42.56	?	L Y	
45 FRONT SHOCK ABSORBER SPRING SEAT LOWER RHS	1.00	69.85	17.46	52.39	?	L Y	
46 FRONT STABILIZER LINK RHS	1.00	190.70	47.68	143.02	?	L Y	
47 FRONT STABILIZER LINK NUT RHS	1.00	7.85	1.96	5.89	?	L Y	
48 FRONT STABILIZER BAR RHS	1.00	369.75	92.44	277.31	?	L Y	
49 FRONT STABILIZER BAR BRACKET RHS	1.00	29.75	7.44	22.31	?	L Y	
50 FRONT STABILIZER BAR BUSH RHS	1.00	37.85	9.46	28.39	?	L Y	
51 FRONT STEERING RAIL AND PINION ASSY	1.00	1,720.70	430.18	1,290.52	?	L Y	
52 FRONT WHEEL BEARING RHS	1.00	147.80	36.95	110.85	?	L Y	
53 FRONT WHEEL HUB RHS	1.00	268.40	67.10	201.30	?	L Y	
54 FRONT WHEEL HUB NUT	1.00	27.60	6.90	20.70	?	L Y	
55 FRONT BRAKE DISC RHS	1.00	221.70	55.43	166.27	?	L Y	
56 FRONT DOOR RHS	1.00	1,138.00	284.50	853.50	new	L Y	
57 FRONT DOOR WINDOW FRAME STICKER RHS	1.00	68.00	17.00	51.00	new	L Y	
58 FRONT DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	repair	L Y	
59 FRONT DOOR RUBBER BEADING RHS	1.00	183.60	45.90	137.70	new	L Y	
60 FRONT DOOR BODY RUBBER RHS	1.00	313.67	78.42	235.25	new	L Y	
61 FRONT DOOR GLASS RHS	1.00	442.50	110.63	331.87	X	L Y	
62 REAR FENDER RHS	1.00	1,085.00	271.25	813.75	repair	L Y	
63 REAR FENDER INNER SHIELD RHS	1.00	67.75	16.94	50.81	X	L Y	
64 FRONT DOOR CHECKER RHS	1.00	151.20	37.80	113.40	X	L Y	
65 FRONT DOOR HINGE UPPER RHS	1.00	78.34	19.59	58.75	?	L Y	
66 FRONT DOOR HINGE BOTTOM RHS	1.00	78.34	19.59	58.75	?	L Y	
67 FRONT DOOR TRIM BOARD RHS	1.00	1,333.60	333.40	1,000.20	?	L Y	
68 FRONT DOOR LOCK CATCH RHS	1.00	45.67	11.42	34.25	X	L Y	
69 FRONT DOOR WINDOW REGULATOR RHS	1.00	177.60	44.40	133.20	?	L Y	
70 FRONT DOOR WINDOW REGULATOR MOTOR RHS	1.00	566.72	141.68	425.04	?	L Y	
71 FRONT B PILLAR RHS	1.00	375.60	93.90	281.70	repair	L Y	
72 FRONT A PILLAR RHS	1.00	478.90	119.73	359.17	repair	L Y	
73 REAR DOOR RHS	1.00	1,198.50	299.63	898.87	PA	L Y	
74 REAR DOOR WINDOW FRAME STICKER RHS	1.00	67.84	16.96	50.88	new	L Y	
75 REAR DOOR OUTER HANDLE RHS	1.00	201.30	50.33	150.97	X	L Y	
76 REAR DOOR BODY RUBBER RHS	1.00	160.55	40.14	120.41	new	L Y	
77 REAR DOOR GLASS RHS	1.00	412.40	103.10	309.30	X	L Y	
78 REAR DOOR QUARTER GLASS RHS	1.00	86.40	21.60	64.80	?	L Y	
79 REAR DOOR QUARTER GLASS RHS RUBBER	1.00	80.24	20.06	60.18	?	L Y	
80 REAR DOOR CHECKER RHS	1.00	165.00	41.25	123.75	X	L Y	
81 REAR DOOR HINGE UPPER RHS	1.00	79.00	19.75	59.25	X	L Y	
82 REAR DOOR HINGE BOTTOM RHS	1.00	79.00	19.75	59.25	?	L Y	
83 REAR DOOR TRIM BOARD RHS	1.00	1,333.60	333.40	1,000.20	?	L Y	
84 REAR DOOR WINDOW REGULATOR RHS	1.00	170.00	42.50	127.50	X	L Y	
85 REAR DOOR WINDOW REGULATOR MOTOR RHS	1.00	564.00	141.00	423.00	X	L Y	
86 ROCKER PANEL RHS	1.00	628.00	157.00	471.00	PA	L Y	
87 SIDE MIRROR RHS	1.00	1,129.00	282.25	846.75	PA	L Y	
88 SIDE MIRROR COVER RHS	1.00	81.50	20.38	61.12	repair	L Y	
89 FRONT RADIATOR	1.00	1,510.50	377.63	1,132.87	X	L Y	
90 CONDENSOR	1.00	1,289.24	322.31	966.93	X	L Y	
91 FRONT ABS SENSOR RHS	1.00	420.00	105.00	315.00	X	L Y	
92 FRONT DISC ROTOR RHS	1.00	298.00	74.50	223.50	X	L Y	
93 FRONT DISC ROTOR DUST COVER RH	1.00	100.41	25.10	75.31	X	L Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
94 BRAKE CALIPER RHS	1.00	700.76	175.19	525.57	X L	Y	
95 FRONT BRAKE HOSE RHS	1.00	120.00	30.00	90.00	X L	Y	
96 CROSSMEMBER ASSY	1.00	1,812.60	453.15	1,359.45	X L	Y	
97 FRONT DOOR RUN CHANNEL	1.00	143.00	35.75	107.25	X L	Y	
98 REAR BUMPER	1.00	487.00	121.75	365.25	repair	Y	
99 REAR SHOCK ABSORBER RHS	1.00	317.00	79.25	237.75	X L	Y	
10 FRONT BUMPER CLIP	1.00	35.00	0.00	35.00	X S	Y	
10 FRONT NUMBER PLATE & CASING	1.00	80.00	0.00	80.00	X S	Y	
10 BONNET INSULATOR CLIP	1.00	35.00	0.00	35.00	X S	Y	
10 HEAD LAMP CLIP	1.00	35.00	0.00	35.00	new	Y	
10 FRONT RADIATOR GRILLE TOP GARNISH CLIPS	1.00	35.00	0.00	35.00	X S	Y	
10 FRONT FENDER INNER SHIELD CLIP RHS	1.00	35.00	0.00	35.00	new S	Y	
10 REAR FENDER INNER SHIELD RHS CLIP	1.00	35.00	0.00	35.00	X repaired	Y	
10 FRONT DOOR TRIM BOARD RHS CLIP	1.00	35.00	0.00	35.00	new S	Y	
10 REAR DOOR TRIM BOARD CLIP RHS	1.00	35.00	0.00	35.00	new S	Y	
10 FRONT SPORT RIM RHS	1.00	600.00	0.00	600.00	4300 S	Y	
11 FRONT TYRE RHS	1.00	450.00	0.00	450.00	70% punctured	Y	
11 REAR SPORT RIM RHS	1.00	600.00	0.00	600.00	300 S	Y	
11 REAR TYRE RHS	1.00	450.00	0.00	450.00	X S	Y	
11 WINDSCREEN SEALANT	1.00	80.00	0.00	80.00	X S	Y	
11 REAR BUMPER CLIP	1.00	35.00	0.00	35.00	X S	Y	
TOTAL:		38,604.11	9,007.39	29,596.72			
TOTAL PARTS & LABOUR :		47,964.11	9,007.39	38,956.72			

EXCESS/LOADING: \$\$ 0.00

No. Of Day:

15 days

RE-SURVEY BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 09 / 07 / 18 @ 1600

SURVEYED BY:

RASM

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

NOTE: TO CHECK PART PRICES