



SK Automobile Pte Ltd  
 (Co Reg. No. 201500047H)  
 1 Soon Lee Street #04-44/45  
 Pioneer Centre  
 Singapore 627605  
 Tel: 626204438 Fax : 6484 1111

TO	: LONPAC	DATE	: 9-Jul-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SFT46S
ADDRESS	:	MODEL	: HYUNDAI ELANTRA
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT	:	MICHAEL 9018 3598 / KUMAR 9897 3736	

**QUOTATION SUMMARY**

**CLAIM DETAIL : PARTS**

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	BOOT LID	1	\$ 1,720.00	\$ 1,720.00	PA ✓
2	BOOT LID INNER TRIM	1	\$ 548.00	\$ 548.00	X
3	BOOT LID INNER LOCK	1	\$ 487.00	\$ 487.00	at ✓
4	BOOT LID LOWER LOCK	1	\$ 42.70	\$ 42.70	X
5	BOOT LID EMBLEM "ELANTRA"	1	\$ 68.60	\$ 68.60	re ✓
6	BOOT LID EMBLEM "S"	1	\$ 65.50	\$ 65.50	re ✓
7	BOOT LID HINGE	2	\$ 132.00	\$ 264.00	X
8	BOOT LID LOGO	1	\$ 37.40	\$ 37.40	re ✓
9	BOOT LID WEATHERSTRIP	1	\$ 254.00	\$ 254.00	at ✓
10	BOOT LID DETECTOR INNER (SENSOR) <i>(new photo)</i>	1	\$ 351.50	\$ 351.50	CRA ✓
11	BOOT LID DETECTOR OUTER (SENSOR)	1	\$ 310.00	\$ 310.00	X
12	TAILLAMP <i>photo (new taillamp)</i>	<i>11/2</i>	<i>CRA</i> \$ 876.00	\$ 1,752.00	RE-X
13	REAR BUMPER	1	\$ 678.00	\$ 678.00	DE ✓
14	REAR BUMPER LOWER	1	\$ 489.00	\$ 489.00	SEA ✓
15	REAR BUMPER RETAINER	1	\$ 87.00	\$ 87.00	CRA ✓
16	REAR BUMPER BRACKET	2	\$ 25.00	\$ 50.00	re ✓
17	REAR BUMPER REFLECTOR	2	\$ 120.00	\$ 240.00	X
18	REAR BUMPER REINFORCEMENT	1	\$ 455.00	\$ 455.00	at ✓
19	REAR BUMPER SIDE COVER LH	1	\$ 187.00	\$ 187.00	X

20	REAR BUMPER SIDE COVER RH	1	\$ 121.00	\$ 121.00	X
21	REAR FENDER INNER COWLING	2	\$ 187.00	\$ 374.00	X
22	AIR VENT	2	\$ 110.00	\$ 220.00	X
23	REAR END PANEL	1	\$ 680.00	\$ 680.00	PA ✓
24	REAR END PANEL TOP GARNISH	1	\$ 289.00	\$ 289.00	DE ✓
25	REAR DETECTOR WIREHARNES	1	\$ 690.00	\$ 690.00	X
26	REAR FLOOR PANEL TOP BOARD	1	\$ 445.00	\$ 445.00	X

TOTAL PRICE \$ 10,905.70  
 LESS 20% \$ 2,181.14  
**SUB TOTAL PRICE \$ 8,724.56**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIP SET	1	\$ 65.00	\$ <del>30</del> 65.00	me ✓
2	BOOT LID INSULATOR CLIP SET	1	\$ 65.00	\$ <del>30</del> 65.00	me ✓
3	TAILLAMP CLIP SET	1	\$ 32.00	\$ <del>me</del> 32.00	me ✓
4	REAR FENDER INNER COWLING CLIP SET	1	\$ 100.00	\$ 100.00	X
5	REAR FENDER SIDE INNER TRIM CLIP SET	1	\$ 100.00	\$ 100.00	X
6	REAR END PANEL TOP GARNISH CLIP SET	1	\$ 25.00	\$ 25.00	me ✓
7	REAR END PANEL SEALANT	1	\$ 120.00	\$ <del>120.00</del>	40
8	REVERSE SENSOR SET	1	\$ 250.00	\$ <del>250.00</del>	200mm

**TOTAL \$ 757.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

1	PANEL BEATING, REMOVAL AND REPLACING PARTS.	\$ <del>1,500.00</del>	700	
2	TO SPRAY PAINT AFFECTED AREA .	\$ <del>1,500.00</del>	600	
3	TO APPLY TUFF COAT.	\$ <del>250.00</del>	60	
4	PERFORM REAR WIRING CHECK.	\$ <del>60.00</del>	30	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.	\$ <del>80.00</del>	60	
6	REMOVE AND REFIX REVERSE CAMERA.	\$ <del>80.00</del>	60	
7	TRANFER BOOT LID MECHANISM.	\$ <del>80.00</del>	60	
8	CONDUCT WATER LEAKAGE TEST.	\$ <del>80.00</del>	30	

TOTAL \$ 3,630.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,481.56
TOTAL LABOUR COST : \$ 3,630.00
TOTAL REPAIR COST : \$ 13,111.56

APPROVED DETAILS

EXCESS
NO. OF WORKING DAYS : 6 days
RE-SURVEY : yes
PART BY PART OR (LUMP) :
DATE & TIME OF SURVEY : 11/07/18 @ 11:00
SURVEYED BY : PASUE
CONTACT NUMBER : 90010068
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: