

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4723E

DATE 6/7/2018 9:43

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 1,349.50	BT
	Boot Lid Rubber			\$ 110.90	deformed
	Boot Lid Lock Upper			\$ 132.10	?
	Boot Lid Lock Lower			\$ 30.30	?
	Boot Lid Sonata Plate			\$ 43.60	nee
	Boot Lid Hyundai Plate			\$ 24.20	nee
	Boot Lid 'H' Emblem			\$ 26.10	nee
	Boot Lid CRDI Plate			\$ 22.70	nee
	Boot Lid Lamp (LH/RH)	\$	230.20	\$ 460.40	crack
	Rear Bumper			\$ 578.40	BT
	Rear Bumper Reinforcement			\$ 483.30	?
	Rear Bumper Clip			\$ 22.00	nee
	Rear Bumper Sponge			\$ 137.40	?
	Rear Bumper Under Cover			\$ 185.80	?
	Rear Bumper Protector (LH/RH)	\$	38.00	\$ 76.00	X Svc
	Tail Lamp (LH/RH)	\$	344.00	\$ 688.00	crack
	Rear Panel			\$ 391.80	deformed
	Rear Panel Garnish			\$ 95.80	crack
	SUB TOTAL			\$ 4,858.30	
	LESS 20%			\$ 971.66	
	DISCOUNTED TOTAL			\$ 3,886.64	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett nee
	Rear Bumper Reverse Sensor			\$ 135.70	Nett X Svc
	Rear Bumper Rubber Mat			\$ 50.00	Nett nee
				\$ 215.70	
	Labour Charge				
	Panel Beating			\$ 850.00	600
	Spray Painting Charge			\$ 750.00	600
	Wiring Charge			\$ 50.00	20
	Tuff Kote			\$ 50.00	00
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 1,820.00	
	ESTIMATE TOTAL			\$ 5,922.34	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.