

YAP JUN XIN
BLK 419 #04-225
BUKIT BATOK WEST AVENUE2
SINGAPORE 650419

File No : SH/2018086/07/006/TP
Date : 05-July-2018

Estimated cost of repair for vehicle no: SLZ4927X HYUNDAI ELANTRA
Accident involving vehicle no: SLZ4927X & GBE3787T on 26-June-2018

| Description | Quantity | List Price |
|--|----------|---------------------------------|
| Bumper | 1 | \$ <i>R</i> 320.00 <i>7</i> |
| Grille | 1 | \$ <i>R</i> 265.00 ✓ |
| RH head lamp | 1 | \$ <i>CM</i> 480.00 ✓ |
| | | \$ 1,065.00 |
| | Add 15% | \$ 159.75 |
| | | \$ 1,224.75 |
| To spray painting bonnet, bumper, accident and repair ares. | 1 | \$ 550.00 <i>250</i> |
| To spray paint special code for damaged portion. | 1 | \$ <i>(B11)</i> 200.00 <i>7</i> |
| Labour to removed front bumper, damaged parts, jack out RH inner panel, renew, and adjust bumper alignment. | 1 | \$ 350.00 <i>250</i> |
| To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp. | 1 | \$ 25.00 <i>20</i> |
| | | <u>\$ 2,349.75</u> |

T/Party: EQ INSURANCE COMPANY LTD

Not Notified
Resurvey By party
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: