



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS/III18012461/R1qbs2

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 14-08-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	URA	Veh. Inspected	SKU 9722A
Policy No.		Coverage (\$)	0.00
Claim No.	LPL2018D0000018	Excess (\$)	0.00
Assign From	BOBBY KOH	Assign Date	09/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ODYSSEY	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JHMRC1890FC202535	Colour	BLACK
Odometer	077513	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55R17	BRIDGESTONE	6 mm
L/H Front Tyre	215/55R17	BRIDGESTONE	6 mm
R/H Rear Tyre	215/55R17	BRIDGESTONE	6 mm
L/H Rear Tyre	215/55R17	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/07/2018	Inspection Date	10/07/2018
Survey held at	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------