

ASS. FHC BY

REF: CS/CT#18012462/ Kvd3/

Small Instructions

Sub Vendor

Meinen

ASSIGNMENT (Office)

Person

Hueng Shing Yi

of

CTI

Date/Time: 9/7/18 @ 3:55pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KP 338L

Insured:

SJM 1149L

at Workshop n/a:

MBM wheelpower

Tel:

9328 8668

of

160 Sin Ming Drive #06-02

Policy No:

DMPCSN 3007151801

Claim No:

SNM18D03351C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 05/07/2018

CA / REV / REP. / REV 24 HRS

'up)

H.O.D. Endorsement:

Date/Time: 4pm @ 9/7/2018

Person Contacted:

Darry

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKP 338L-X

SJM 1149L-NA MSG/2000438/K

DOA: 7/01/2012

14/8 1/1 Pm 8860d Car fire Dam (Red 19,778.50, 6990)

REF: CTL

Merimen

ASSIGNMENT

From: Date 11.07.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKP 338L

at Workshop/cus:

MBM Wheelpower

of

160 Sin Ming Drive #06-02

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Danny

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res: Yes or No

Lump Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No SKP 338L Yr Regn 01 14

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M. E250

cc 1991

Colour:

M. Grey

A/C Insured / Std / NI / NA

Sp Reading:

104186

T/Radio: Insured / Std / NI / NA

Eng/No:

WDD 2120362A8 31188

C/No:

Gen. Cond Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD/Rim or

Tyre Size:

F:

245/40R18

R:

265/35R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

7

mm

R/Bal:

6

mm

L/Bal:

7

mm

L/Bal:

6

mm

D.O.A:

5/7/18

D.O.I:

11/7/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

01/ body

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

12/7 File pass to Customer

RECEIVED 15 AUG 2018

Date/Time, File Pass to:



Prel. Report

If



Final Report

Date/Time, File Return to:

15/8- typist

Report Format:

merimen

Lump Sum / I.B.F. (\$)

8600/-

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Vehicle (\$)

Survey Fee:

Transportation

1. 2 - P.S. 12

1. 1000

1. 1000

1. 1000

Total:

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		09 Jul 2018 15:55 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ONG YOKE MIN, ID: S6815520G		
Main Claimant:	JONATHAN NG PENG KEONG, ID: S7511641A		
Vehicle Reg. No.:	SKP338L	Date of Loss:	05/07/2018 16:00 - :59
Claim Type:	TP / SNM18D03351C02	Policy/Cover Note No.:	DMPCSN3007151801 (Comprehensive)
Vehicle Reg. No. (Insured):	SJM1149L	Policy No. (Claimant):	GA009531/1
		Excess:	S\$0.00
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/07/2018]		
Driver/Custodian (Insured):	ONG YOKE MIN (50 / Male), NRIC: S6815520G		
Adj Asg. Remarks:	EST \$30,124.25, ASSIGN KENNETH KONG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Danny Ong <danny.ong@mbmwheelpower.com.sg>
Sent: Friday, 6 July, 2018 4:20 PM
To: Claims Dept of CTI
Cc: stephanie.lin@mbmwheelpower.com.sg
Subject: Liability Status - Accident involving SKP338L & SJM1149L (CHINA TAIPING) on 05/07/2018
Attachments: SKP338L.pdf

Dear Sir / Madam,

Appreciate if you can advise us on the liability status first for the below loss

Before we arrange a pre-survey for the above mentioned vehicle.

Kindly refer to the attached GIA report and repair estimate.

Our Client's Vehicle Number:	SKP338L
CNT Vehicle Number:	SJM1149L
Date/Time of Loss:	05/07/2018 1600hrs

Kindly arrange your surveyor to survey the vehicle at **160 Sin Ming Drive #06-03 Sin Ming Autocity**
Singapore 575722

Please contact Danny 93288668 for the survey arrangement

Best regards,

Danny Ong | Claims Advisor



T 6262 8888 | F 6452 5333 | M 9328 8668

Email: danny.ong@mbmwheelpower.com.sg

MBM Wheelpower Pte Ltd

160 Sin Ming Drive • #06-02

Sin Ming AutoCity • Singapore 575722

www.mbmwheelpower.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

➔ Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SKP338L
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	With Sun Roof
Vehicle Scheme:	Normal
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 A
Chassis No.:	WDD2120362A831188
Propellant:	Petrol
Engine No.:	27492030045764
Engine Capacity:	1991 cc
Maximum Power Output:	155.0 kW (207 bhp)
Maximum Laden Weight:	2245 kg
Unladen Weight:	1680 kg
Year Of Manufacture:	2013
Original Registration Date:	09 Jan 2014
Lifespan Expiry Date:	-
COE Category:	B - Car (1601cc & above)
Quota Premium:	\$78,700.00
COE Expiry Date:	08 Jan 2024
Road Tax Expiry Date:	08 Jan 2019
PARF Eligibility Expiry Date:	08 Jan 2024
Inspection Due Date:	08 Jan 2019
Intended Transfer Date:	28 Jul 2018
CO2 Emission:	142.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$5,000.00
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/07/2018 12:08
Date Of Accident	05/07/2018 16:00
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP338L
Insured/Policyholder	
Name Of Registered Owner	JONATHAN NG PENG KEONG
NRIC No	S7511641A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96600168
Alternative Phone No	OFFICE-96600168

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA009531/1
Cover Note Number	

Driver

Name of Driver	JONATHAN NG PENG KEONG
NRIC No	S7511641A
Date Of Birth	26/04/1975
Occupation	INDOOR
Date Of Driving Pass	28/12/1995
Driving Experience	22 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96600168
Fax Number	
Contact Number	OFFICE-96600168
Email Address	NOEMAIL

Address -
 Postcode -
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

refer attached report.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJM1149L
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver WILLIAM ONG
 NRIC/Passport Number S6815520G
 Contact Number 96363879
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKS4425B
 Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	GUO MIN
NRIC/Passport Number	
Contact Number	97877290
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PRN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5th July 2018 1600 HRS, I was travelling along PIE Changi Airport toward KUALA. AT THAT ALONG TO A Payot exit I heard the RIGHT LAIRZ LOUD BRACE from my vehicle on the road. WITHIN A Second vehicle SJM 1149 L Budge into SKS 4425 B & Continue to HIT me which I was on the 2nd lane.

* VIDEO FOOTAGE CAPTURED *

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

REPORTING CENTRE PERSONNEL

MBM WHEELPOWER PTE LTD

Your Ref: SJM1149L

Our Ref: SKP338L

To: CHINA TAIPING

CC

Fax

*Not Authorized
11 Lm 88600h
Resurvey After Pain
Jdan*

Date: 6/7/2018
From: Danny
Fax: 64525333
Contact: 93286666
Make / Model: MERCEDES E250 A
Chassis No.: WDD2120362A831188
Engine No.: 27492030045764
Year of Make: 2013
Accident Date: 5 July 2018

ESTIMATE FOR VEHICLE NO. : SKP338L

DESCRIPTION	QTY	List Price	
FRONT RH DOOR <i>2210.00</i>	1	\$ 2,380.00	✓
FRONT RH DOOR WEATHERSTRIP	1	\$ 365.00	✓
FRONT RH DOOR HINGE UPP	1	\$ 195.00	X
FRONT RH DOOR HINGE LOWER	1	\$ 210.00	X
FRONT RH DOOR INNER TRIM	1	\$ 185.00	X
FRONT RH DOOR HANDLE	1	\$ 510.00	X
FRONT RH DOOR HANDLE COVER	1	\$ 145.00	X
FRONT RH DOOR WINDOW MOTOR	1	\$ 695.00	X
FRONT RH DOOR WINDOW COVER	1	\$ 120.00	X
FRONT RH DOOR LOCK	1	\$ 580.00	X
FRONT RH DOOR BEARING BRACKET	1	\$ 220.00	X
FRONT RH DOOR INNER CARRIER	1	\$ 790.00	X
REAR RH DOOR <i>2450-10</i>	1	\$ 2,550.00	✓
REAR RH DOOR WEATHERSTRIP	1	\$ 365.00	✓
REAR RH DOOR HINGE UPP	1	\$ 195.00	X
REAR RH DOOR HINGE LOWER	1	\$ 210.00	X
REAR RH DOOR INSULATOR	1	\$ 210.00	X
REAR RH DOOR HANDLE	1	\$ 510.00	✓
REAR RH DOOR HANDLE COVER	1	\$ 145.00	✓
REAR RH DOOR WINDOW MOTOR	1	\$ 745.00	✓
REAR RH DOOR WINDOW COVER	1	\$ 120.00	X
REAR RH DOOR LOCK	1	\$ 590.00	X
REAR RH DOOR INTERIOR TRIM	1	\$ 2,350.00	X
REAR RH DOOR ACTUATION	1	\$ 230.00	X
REAR RH TOP TRIM	1	\$ 600.00	X
REAR RH DOOR LINGING	1	\$ 290.00	X
REAR RH DOOR PANELING	1	\$ 185.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

mbm wheelpower

TANK FLAP	1	\$	<i>R</i> 175.00	<i>X</i>
RH SIDE SKIRT	1	\$	<i>Sm</i> 1,650.00	<i>X</i>
REAR RH FENDER <i>2166.39</i>	1	\$	<i>R</i> 2,750.00	<i>✓</i>
REAR RH FENDER INNER SHIELD	1	\$	<i>Sm</i> 280.00	<i>X</i>
REAR RH FENDER INNER SHIELD CLIPS @\$8 EACH	10	\$	<i>nn</i> 80.00	<i>X</i>
REAR BUMPER	1	\$	<i>R</i> 2,365.00	<i>X</i>
REAR BUMPER RH SIDE RETAINER	1	\$	<i>Sm</i> 75.00	<i>X</i>
DISTANCE SENSOR @\$250 EACH	1	\$	<i>Sm</i> 500.00	<i>X</i>
REAR RH TAIL LAMP	1	\$	<i>R</i> 950.00	<i>X</i>
Total: \$			24,515.00	
LESS 10% \$			(2,451.50)	
Parts Total: \$			22,063.50	

SPECIAL NETT

BODY SEALANT	1	\$	<i>nn</i> 80.00	<i>30sm</i>
REAR RH RIM		\$	<i>Sm</i> 1,750.00	<i>X</i>

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	1,600.00	<i>1000l</i>
TO REMOVE AND REPLACE FUEL TANK FIXTURE AND TO UPHOLSTERY TO FACILITATE REPAIRS	\$	100.00	<i>60l</i>
TO REMOVE AND REPLACE FRONT RH DOOR TO NEW DOOR	\$	150.00	<i>80l</i>
TO REMOVE AND REPLACE REAR RH DOOR TO NEW DOOR	\$	150.00	<i>80l</i>
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	80.00	<i>✓</i>
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	80.00	<i>30l</i>
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	2,100.00	<i>1100l</i>
<i>28,378.50</i> Total: \$	28,153.50		
7% GST: \$	1,970.75		
Grand Total: \$	30,124.25		

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		09 Jul 2018 15:55 Edit Adj Rpt	\$8,600.00 Edit Estimates	\$8,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ONG YOKE MIN , ID: S6815520G								
Main Claimant:	JONATHAN NG PENG KEONG , ID: S7511641A								
Vehicle Reg. No.:	SKP338L	Date of Loss:	05/07/2018 16:00 - :59 [53 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03351C02	Policy/Cover Note No.:	DMPCSN3007151801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJM1149L	Policy No. (Claimant):	GA009531/1						
		Excess:	S\$0.00						
Repairer:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6262 8888								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 18/07/2018]								
Driver/Custodian (Insured):	ONG YOKE MIN (50 / Female), NRIC: S6815520G								
Adj Asg. Remarks:	EST \$30,124.25, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKP338L (SNM18D03351C02)
[SJM1149L]
TP
JONATHAN NG PENG KEONG
Jul 5 2018 4:00PM
[ONG YOKE MIN]
MBM Wheelpower Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)							Thumbnail	Print	
1	06/07/18 12:20	Accident Statement								Load HTM	
Photos/Images									3 per page		☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)							Thumbnail	Print	
1	06/07/18 12:15	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
2	06/07/18 12:15	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
3	06/07/18 12:15	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
4	06/07/18 12:15	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
5	06/07/18 12:15	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
6	06/07/18 12:15	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
7	06/07/18 12:15	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	12/07/18 11:36	General View								Load PDF	
2	15/08/18 09:53	Reinspection Photo								Load PDF	
Documentation									1 per page		☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	09/07/18 15:52	REPAIR EST WITH TP GIA								Load PDF	
2	09/07/18 15:52	EMAIL FM MBM								Load PDF	
3	09/07/18 15:53	OI GIA								Load PDF	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)							Thumbnail	Print	
1	06/07/18 12:16	Sketch Plan [Linked Accident Report Documents]								Load TIF	
2	06/07/18 12:16	Sketch Plan #2 [Linked Accident Report Documents]								Load TIF	
3	06/07/18 12:16	Sketch Plan #3 [Linked Accident Report Documents]								Load TIF	
4	06/07/18 12:16	Sketch Plan #4 [Linked Accident Report Documents]								Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	23/08/18 14:08	SUPPLEMENTARY PART								Load PDF	

Linked Accident Report Documents

										View	View in Browser	
Assessment Reports										1 per page		☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)							Thumbnail	Print		
1	06/07/18 12:20	Accident Statement							 Load HTM			
Photos/Images										3 per page		☒

Assessment Reports			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	06/07/18 12:15	Accident Photo	 Load JPG	☒
2	06/07/18 12:15	Accident Photo	 Load JPG	☒
3	06/07/18 12:15	Accident Photo	 Load JPG	☒
4	06/07/18 12:15	Accident Photo	 Load JPG	☒
5	06/07/18 12:15	Accident Photo	 Load JPG	☒
6	06/07/18 12:15	Accident Photo	 Load JPG	☒
7	06/07/18 12:15	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	06/07/18 12:16	Sketch Plan	 Load TIF	
2	06/07/18 12:16	Sketch Plan #2	 Load TIF	
3	06/07/18 12:16	Sketch Plan #3	 Load TIF	
4	06/07/18 12:16	Sketch Plan #4	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012462/KVD3Q2

Date: 23/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3007151801

Claimant Vehicle
No: SKP338LInsured Vehicle
No: SJM1149L

Date of Loss: 05/07/2018

Nature of Claim: TP

Claim
No: SNM18D03351C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP338L

Make & Model: MERCEDES-BENZ 200E, 2.0 (A)

Engine No: 27492030045764

Reg. Date: 09/01/2014 (Man. Year: 2013)

Chassis No: WDD2120362A831188

Colour: Metallic Grey

Odometer: 104186 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 265/35 R18

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,118.50	8,315.84	15,802.66	65.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	2,430.00	1,830.00	42.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,378.50	10,745.84	17,632.66	62.13
Approved Total (Overridden) (S\$)		8,600.00		
(S\$)	28,378.50	8,600.00	19,778.50	69.70
+ GST 7.00/7.00% (S\$)	1,986.50	602.00	1,384.50	69.70
Nett Amount (S\$)	30,365.00	9,202.00	21,163.00	69.70

INSPECTION

Date of Assignment: 09/07/2018

Date Inspected: 11/07/2018 Inspected At:

 MBM Wheelpower Pte Ltd (HQ)
 160 Sin Ming Drive #06-02, Sin Ming
 AutoCity
 Singapore 575722

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2018)	
Parts: 143	MERCEDES-BENZ 200E 2.0 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKP338L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Bent	2,380.00 FL	*2,210.00 FL
2	1		*FRONT RH DOOR WEATHERSTRIP	Necessary	365.00 FL	*365.00 FL
3	1		*FRONT RH DOOR HINGE UPP	Repair	195.00 FL	*- FL
4	1		*FRONT RH DOOR HINGE LOWER	Repair	210.00 FL	*- FL
5	1		*FRONT RH DOOR INNER TRIM	Serviceable	185.00 FL	*- FL
6	1		*FRONT RH DOOR HANDLE	Serviceable	510.00 FL	*- FL
7	1		*FRONT RH DOOR HANDLE COVER	Serviceable	145.00 FL	*- FL
8	1		*FRONT RH DOOR WINDOW MOTOR	Serviceable	695.00 FL	*- FL
9	1		*FRONT RH DOOR WINDOW COVER	Serviceable	120.00 FL	*- FL
10	1		*FRONT RH DOOR LOCK	Repair	580.00 FL	*- FL
11	1		*FRONT RH DOOR BEARING BRACKET	Serviceable	220.00 FL	*- FL
12	1		*FRONT RH DOOR INNER CARRIER	Serviceable	790.00 FL	*- FL
13	1		*REAR RH DOOR	Bent	2,550.00 FL	*2,450.10 FL
14	1		*REAR RH DOOR WEATHERSTRIP	Necessary	365.00 FL	*365.00 FL
15	1		*REAR RH DOOR HINGE UPP	Repair	195.00 FL	*- FL
16	1		*REAR RH DOOR HINGE LOWER	Repair	210.00 FL	*- FL
17	1		*REAR RH DOOR INSULATOR	Serviceable	210.00 FL	*- FL
18	1		*REAR RH DOOR HANDLE	Dented	510.00 FL	*510.00 FL
19	1		*REAR RH DOOR HANDLE COVER	Mtg Distorted	145.00 FL	*145.00 FL
20	1		*REAR RH DOOR WINDOW MOTOR	Distorted / Jammed	745.00 FL	*745.00 FL
21	1		*REAR RH DOOR WINDOW COVER	Serviceable	120.00 FL	*- FL
22	1		*REAR RH DOOR LOCK	Repair	590.00 FL	*- FL
23	1		*REAR RH DOOR INTERIOR TRIM	Serviceable	2,350.00 FL	*- FL
24	1		*REAR RH DOOR ACTUATION	Serviceable	230.00 FL	*- FL
25	1		*REAR RH TOP TRIM	Serviceable	600.00 FL	*- FL
26	1		*REAR RH DOOR LINGING	Serviceable	290.00 FL	*- FL
27	1		*REAR RH DOOR PANELING	Serviceable	185.00 FL	*- FL
28	1		*TANK FLAP	Repair	175.00 FL	*- FL
29	1		*RH SIDE SKIRT	Serviceable	1,650.00 FL	*- FL
30	1		*REAR RH FENDER	Bent	2,750.00 FL	*2,166.39 FL
31	1		*REAR RH FENDER INNER SHIELD	Serviceable	280.00 FL	*- FL
32	10		*REAR RH FENDER INNER SHIELD CLIPS	Not Necessary	80.00 FL	*- FL
33	1		*REAR BUMPER	Repair	2,365.00 FL	*- FL
34	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	75.00 FL	*- FL
35	1		*DISTANCE SENSOR	Serviceable	500.00 FL	*- FL
36	1		*REAR RH TAIL LAMP	Serviceable	950.00 FL	*- FL
37	1		*BODY SEALANT	Necessary	80.00 FS	*30.00 FS
38	1		*REAR RH RIM	Serviceable	1,750.00 FS	*- FS
39	1		*RH SIDE MIRROR LOWER COVER	Dented / Cut	250.00 FL	*250.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part, S=SpcNett, L=ListItemDisc.						
				Sub Total (S\$)	26,595.00	9,236.49
			- List Item Discount on L Items 10.00/10.00% (S\$)		2,476.50	920.65
				Total Parts (S\$)	24,118.50	8,315.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK-OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,600.00	1,000.00
2	TO REMOVE AND REPLACE FUEL TANK FIXTURE AND TO UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	60.00
3	TO REMOVE AND REPLACE FRONT RH DOOR TO NEW DOOR	New	150.00	80.00
4	TO REMOVE AND REPLACE REAR RH DOOR TO NEW DOOR	New	150.00	80.00
5	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	80.00	80.00
6	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	80.00	30.00
7	TO SPRAY PAINT ON THE AFFECTED AREAS	New	2,100.00	1,100.00
Gross Labour Cost (S\$)			4,260.00	2,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >