

ASS. REC. BY:

REF: CS/CTI18012464/RIvd3/02

Special Instruction:

Survivor:
Mummen

ASSIGNMENT (Office)

From (Person): Jayn Lay of CTI Date/Time: 9/7/18 @ 3:31pm

Estimated Cost: Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKA 519K Insured: SLN 4203P

at Workshop m/s Cheng Auto Body Tel: 6631 0707

of 5 Soon Lee Street #01-62

Policy No: DMHCSN1733.111700 Claim No: SNM18D03359C02

Sum Insured: Excess:

Make of Veh: D.O.A. 05/07/2018

(Client's Record)

10/07/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:51pm @ 9/7/2018 Person Contacted: Mum

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKA 519K - CC4/AIG17009564/DK6392 DOA: 15/05/2018
	SLN 4203P - X.
17/7/18	LS \$5200 confirmed by email (Red) 4429.76, 4670

Surveyor

Ref

REF:

65682

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 519K

at Workshop m/s CHONH ANU

of 5, SUM LEE ST #01-62

Insured: CTI/np

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 20K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No


Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT



Veh No: SKA 519K Yr Regn: 2009 / MAR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA CAMRY 2.0A C.C. 1998

Colour: GOLD A/C: Insured / Std / NI / NA

Sp. Reading: 132750 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRO53BK4107043421

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 05/07/18 D.O.I. 11/07/18

Survey held at CHONH ANU

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 18 JUL 2018

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

2) A/T - typist

Report Format: merimen

Lump Sum / I.B.I.: (\$) 520012

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

) S + RS: SI

) Photos

) Others

TOTAL

220

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 17 July 2018 4:37 PM
To: 'CAB@CHENGAUTO.COM'
Cc: SUR
Subject: RE: SKA 519K-DOA:5/7/2018 (CHINA TAIPING TP)

Dear Sir,

Noted with thanks.

Kindly send relevant documents to CHINA TAIPING.

OIC Jowyn Tay, REF: SNM18D03359C02

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CAB@CHENGAUTO.COM [mailto:CAB@CHENGAUTO.COM]
Sent: Tuesday, 17 July 2018 11:14 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: SKA 519K-DOA:5/7/2018 (CHINA TAIPING TP)

Dear Veron,

Your Claim Ref. No. : SNM18D03359C02
CHENG AUTO Ref. No. : SKA519K / NAG SUMALLYA
Insured Name : NAG SUMALLYA
Policy Number : GA029967 / 1
Insurer/Policy Type : AXA INSURANCE /
Date of Loss : 05/07/2018
Our Vehicle No. : SKA519K
TP Vehicle No. : SLN4203P / CHINA TAIPING INSURANCE

COMPREHENSIVE

We refer to your offer.

We accept the offer S\$5,200.00 & 06 days.

Thank you.

Thanks & Best Regards,



CHENG AUTO BODYWORKS

HP: 8666 7775 | Office-Tel: 6631 0707 | Fax: 6316 2431

Reporting Centre

Address: 5 Soon Lee Street #01-60 Pioneer Point, Singapore 627607

Email: claims@chengauto.com

Workshop

Address: 5 Soon Lee Street #01-62 Pioneer Point, Singapore 627607

Email: cab@chengauto.com

Windscreen

Address: 5 Soon Lee Street #01-41 Pioneer Point, Singapore 627607

Email: windscreen@chengauto.com

Spraypainting

Address: 1 Soon Lee Street #06-41 Pioneer Centre, Singapore 627605

Email: cab@chengauto.com

On 16/7/2018 12:42 PM, Veron Chen (LKKAuto) wrote:

Dear Muru,

WITHOUT PREJUDICE

Offer Lump Sum \$5200 @ 6 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Foreign Identification Number
Owner ID:	6568Q

Vehicle Details

Vehicle No.:	SKA519K
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.0 AUTO ABS AIRBAG
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	1AZE131454
Chassis No.:	MR053BK4107043421
Maximum Power Output:	108.0 kW (144 bhp)
Open Market Value:	\$25,948.00
Original Registration Date:	25 Mar 2009
First Registration Date:	25 Mar 2009
Transfer Count:	2
Actual ARF Paid:	\$25,948.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2019
PARF Rebate Amount:	\$12,974.00

Intended COE Rebate Details

COE Expiry Date:	24 Mar 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$3,000.00
COE Rebate Amount:	\$48.00
Total Rebate Amount:	\$13,022.00

The information contained herein is correct as at 11 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/07/2018 11:51
Date Of Accident	05/07/2018 17:40
Exact Location Of Accident	KPE TOWARDS PIE (TUAS) / CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA519K
Insured/Policyholder	
Name Of Registered Owner	NAG SUMALLYA
NRIC No	G5016568Q
Email Address	SUMALLYANAG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91015264
Alternative Phone No	OFFICE-91015264

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.0 AUTO ABS AIRBAG
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA029967/1
Cover Note Number	

Driver

Name of Driver	ABHINANDA NAG
Work Permit No	G5122116N
Date Of Birth	18/11/1976
Occupation	INDOOR
Date Of Driving Pass	25/05/2016
Driving Experience	2 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-91015264
Fax Number	
Contact Number	
EMail Address	ABHINANDANAG@GMAIL.COM

Address	SINGAPORE
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED S & C REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN4203P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM WEN QIANG, DOUGLAS
NRIC/Passport Number	S9108302G
Contact Number	91138590
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBG316D
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

HOI YUNG LIN (XU YONGLIN)

NRIC/Passport Number

S8022102I

Contact Number

96824703

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"]; the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I am fully aware that my insurer may have a 14-day period for me to decide on filing an Own Damage Claim.

Accident Sketch Plan

SKETCH PLAN

Date of Accident: 05/07/18

KPE
TOWARDS
PIE (TUAS)
/ CTE



A : SKA519K
B : SLN4203P
C : GBG316D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05/07/2018 at 1740 hrs, I was travelling along KPE towards PIE (Tuas) / CTE as the traffic was heavy and the vehicle in front of me stopped. I stopped too. I then suddenly felt a huge impact hit my rear. As I came down to check, Vehicle B (SLN4203P) had collided onto the rear of my vehicle and there was another vehicle, Vehicle C (GBG316D) which had collided onto Vehicle B.

- ☐ Own Damage Claim
- ☒ Third Party Claim
- ☐ OD/TP Claim at another workshop :
- ☐ Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Abhinanda Nagar
Driver's Signature
(if driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
LIM WEN QIANG, DOUGLAS

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/07/2018
Vehicle Reg. No.:	SKA519K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ABHINANDA NAG	Driver (Insured):	LIM WEN QIANG, DOUGLAS
Make/Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Vehicle Reg. Date:	25/03/2009
Vehicle Colour:	BEIGE	Chassis No:	MR053BK4107043421
Engine No:	1AZE131454		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE SEE ATTACHED S & C REPORT		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	5,539.76
Miscellaneous Items	890.00
Labour	3,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,629.76
+ GST 7.00% (S\$)	674.08
Nett Amount (S\$)	10,303.84

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jul 2018)

Parts: 143 TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/SKA519K/09/07/2018 09:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT	25.00	0.00	Ref - *991.20 FL
2	1		*BOOT HINGE RH	25.00	0.00	Suc X *70.35 FL
3	1		*BOOT HINGE LH	25.00	0.00	Suc X *70.35 FL
4	1		*BOOT INSULATOR	25.00	0.00	Suc X *561.75 FL
5	1		*BOOT CHROME	25.00	0.00	CRA - *370.65 FL
6	1		*BOOT LOGO	25.00	0.00	Ref - *59.85 FL
7	1		*EMBLEM CAMRY	25.00	0.00	Ref - *59.85 FL
8	1		*EMBLEM 2.0	25.00	0.00	Ref - *59.85 FL
9	1		*BOOT REFLECTOR RH	25.00	0.00	Suc X *425.25 FL
10	1		*BOOT REFLECTOR LH	25.00	0.00	Suc X *425.25 FL
11	1		*BOOT LOCK	25.00	0.00	Ref - *401.10 FL
12	1		*TAILLAMP RH	25.00	0.00	CRA - *584.85 FL
13	1		*TAILLAMP LH	25.00	0.00	CRA - *584.85 FL
14	1		*BOOT RUBBER	25.00	0.00	Ref - *234.15 FL
15	1		*BOOT CATCH	25.00	0.00	Ref - *36.75 FL
16	1		*ENDPANEL TOP GANISH	25.00	0.00	DE - *352.80 FL
17	1		*ENDPANEL	25.00	0.00	Ref - *638.40 FL
18	1		*REAR BUMPER	25.00	0.00	DE - *573.30 FL
19	1		*BUMPER RETAINER RH	25.00	0.00	Ref - *91.35 FL
20	1		*BUMPER RETAINER LH	25.00	0.00	Ref - *91.35 FL
21	1		*BUMPER CLIPS SET	25.00	0.00	Ref - *50.00 FL
22	1		*BUMPER REFLECTOR RH	25.00	0.00	Suc X *59.85 FL
23	1		*BUMPER REFLECTOR LH	25.00	0.00	CRA - *59.85 FL
24	1		*BUMPER BRACKET RH	25.00	0.00	Ref - *66.15 FL
25	1		*BUMPER BRACKET LH	25.00	0.00	Ref - *66.15 FL
26	1		*REINFORCEMENT REAR	25.00	0.00	Ref - *401.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,386.35
- List Item Discount on L Items (S\$)	1,846.59
Total Parts (S\$)	5,539.76

Cheng Auto Bodyworks/SKA519K/09/07/2018 09:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	BOOT INNER TRIM CLIPS 1 SET	30 New 50.00
2	1	BOOT OUT GARNISH CLIPS 1 SET	30 New 50.00
3	1	REAR BUMPER CLIPS 1 SET	New 50.00
4	1	REAR ENDPANEL SEALANT	40 New 60.00
5	1	REAR FLOOR PANEL INSULATION	nn X 200.00
6	1	REAR LH FENDER INNER LOWER CLIPS 1 SET	nn X 50.00
7	1	REAR NO. PLATE W/ COVER	35 New 50.00
8	1	REAR PANEL TOP GARNISH CLIPS 1 SET	New 30.00
9	1	REAR REVERSE SENSOR	200 New 300.00
10	1	REAR RH FENDER INNER LOWER CLIPS 1 SET	nn X 50.00
Sub Total (S\$)			890.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	LABOUR	New	700 1,200.00
2	SPRAYPAINTING	New	800 1,200.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	300 100.00
4	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	New	80 150.00
5	REMOVE/ REFIT UPHOLSTERY LINING GARNISH	New	80 200.00
6	TO CHECK REVERSE SENSOR FUNCTION	New	50.00
7	ANTI-CORROSION	New	100 200.00
8	TO CHECK REVERSE CAMERA FUNCTION	New	X 100.00
Gross Labour Cost (S\$)			3,200.00

Cheng Auto Bodyworks/SKA519K/09/07/2018 09:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Rasul
Hp 90010068

6 days

HS

11/07/18 @ 1140

Resurvey after repair

Cheng Auto Bodyworks (Co.Reg.No:53315238X)

5 Soon Lee Street #01-62 Pioneer Point

Singapore 627607

Tel: 6631 0707 Fax: 6316 2431 Email: cab@chengauto.com

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
LIM WEN QIANG, DOUGLAS

Singapore

Claimant Insurer: AXA Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/07/2018
Vehicle Reg. No.:	SKA519K	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ABHINANDA NAG	Driver (Insured):	LIM WEN QIANG, DOUGLAS
Make/Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Vehicle Reg. Date:	25/03/2009
Vehicle Colour:	BEIGE		
Engine No:	1AZE131454	Chassis No:	MR053BK4107043421
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	PLEASE SEE ATTACHED S & C REPORT		
Present Location:	CHENG AUTO BODYWORKS (HQ)		

COST OF CLAIMS

	Amount
Parts	5,539.76
Miscellaneous Items	890.00
Labour	3,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,629.76
+ GST 7.00% (S\$)	674.08
Nett Amount (S\$)	10,303.84

This claim is handled by: LAI JIA WEN RACHEL

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jul 2018)

Parts: 143 TOYOTA CAMRY 2.0 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Auto Bodyworks/SKA519K/09/07/2018 09:56

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT	25.00	0.00	Ref - 991.20 FL
2	1		*BOOT-HINGE RH	25.00	0.00	X - 70.35 FL
3	1		*BOOT-HINGE LH	25.00	0.00	X - 70.35 FL
4	1		*BOOT-INSULATOR	25.00	0.00	X - 561.75 FL
5	1		*BOOT-CHROME	25.00	0.00	CRA - 370.65 FL
6	1		*BOOT-LOGO	25.00	0.00	Ref - 59.85 FL
7	1		*EMBLEM CAMRY	25.00	0.00	Ref - 59.85 FL
8	1		*EMBLEM 2.0	25.00	0.00	Ref - 59.85 FL
9	1		*BOOT-REFLECTOR RH	25.00	0.00	X - 425.25 FL
10	1		*BOOT-REFLECTOR LH	25.00	0.00	X - 425.25 FL
11	1		*BOOT-LOCK	25.00	0.00	Ref - 401.10 FL
12	1		*TAILLAMP RH	25.00	0.00	CRA - 584.85 FL
13	1		*TAILLAMP LH	25.00	0.00	CRA - 584.85 FL
14	1		*BOOT-RUBBER	25.00	0.00	Ref - 234.15 FL
15	1		*BOOT-CATCH	25.00	0.00	Bt - 36.75 FL
16	1		*ENDPANEL TOP GANISH	25.00	0.00	DE - 352.80 FL
17	1		*ENDPANEL	25.00	0.00	PA - 638.40 FL
18	1		*REAR BUMPER	25.00	0.00	DE - 573.30 FL
19	1		*BUMPER RETAINER RH	25.00	0.00	Ref - 91.35 FL
20	1		*BUMPER RETAINER LH	25.00	0.00	Ref - 91.35 FL
21	1		*BUMPER CLIPS SET	25.00	0.00	Ref - 50.00 FL
22	1		*BUMPER-REFLECTOR RH	25.00	0.00	X - 59.85 FL
23	1		*BUMPER-REFLECTOR LH	25.00	0.00	CRA - 59.85 FL
24	1		*BUMPER-BRACKET RH	25.00	0.00	Ref - 66.15 FL
25	1		*BUMPER-BRACKET LH	25.00	0.00	Ref - 66.15 FL
26	1		*REINFORCEMENT REAR	25.00	0.00	Bt - 401.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)

7,386.35

- List Item Discount on L Items (S\$)

1,846.59

Total Parts (S\$)

5,539.76

Cheng Auto Bodyworks/SKA519K/09/07/2018 09:56. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	BOOT INNER TRIM CLIPS 1 SET
2	1	BOOT OUT GARNISH CLIPS 1 SET
3	1	REAR BUMPER CLIPS 1 SET
4	1	REAR ENDPANEL SEALANT
5	1	REAR FLOOR PANEL INSULATION
6	1	REAR LH FENDER INNER LOWER CLIPS 1 SET
7	1	REAR NO. PLATE W/ COVER
8	1	REAR PANEL TOP GARNISH CLIPS 1 SET
9	1	REAR REVERSE SENSOR
10	1	REAR RH FENDER INNER LOWER CLIPS 1 SET

30 New 50.00
 30 New 50.00
 New 50.00
 40 60.00
 X 200.00
 X 50.00
 35 New 50.00
 30.00
 200 New 300.00
 X 50.00

Sub Total (\$\$)

890.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	LABOUR
2	SPRAYPAINTING
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING
4	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE
5	REMOVE/ REFIT UPHOLSTERY LINING GARNISH
6	TO CHECK REVERSE SENSOR FUNCTION
7	ANTI-CORROSION
8	TO CHECK REVERSE CAMERA FUNCTION

New 700 1,200.00
 New 800 1,200.00
 New 30 60 100.00
 New 80 150.00
 New 80 200.00
 New 50.00
 New 100 200.00
 New X 100.00

Gross Labour Cost (\$\$)

3,200.00

Cheng Auto Bodyworks/SKA519K/09/07/2018 09:56. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
 Hp 90010068
 6 days
 H/S
 11/07/18 @ 1140
 Resurvey after repair

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012464/R1VD3N2

Date: 18/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1733111700
Claimant Vehicle No :	SKA519K	Insured Vehicle No :	SLN4203P
Date of Loss:	05/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03359C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKA519K	Engine No:	1AZE131454
Make & Model:	TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Chassis No:	MR053BK4107043421
Reg. Date:	25/03/2009 (Man. Year: 2009)	Odometer:	132750 km
Colour:	Gold		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,539.76	4,330.16	1,209.60	21.83
Miscellaneous Items	890.00	415.00	475.00	53.37
Labour	3,200.00	1,840.00	1,360.00	42.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,629.76	6,585.16	3,044.60	31.62
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	9,629.76	5,200.00	4,429.76	46.00
+ GST 7.00/7.00% (S\$)	674.08	364.00	310.08	46.00
Nett Amount (S\$)	10,303.84	5,564.00	4,739.84	46.00

INSPECTION

Date of Assignment:	09/07/2018	Present Location:	Cheng Auto Bodyworks (HQ)
Date Inspected:	11/07/2018	Inspected At:	Cheng Auto Bodyworks (HQ)
			5 Soon Lee Street #01-62 Pioneer Point
			Singapore 627607
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 18 Jul 2018)

Parts: 143 **TOYOTA CAMRY 2.0 ABS AIRBAG (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKA519K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Bent	991.20 FL	*991.20 FL
2	1		*BOOT HINGE RH	Serviceable	70.35 FL	*- FL
3	1		*BOOT HINGE LH	Serviceable	70.35 FL	*- FL
4	1		*BOOT INSULATOR	Serviceable	561.75 FL	*- FL
5	1		*BOOT CHROME	Cracked	370.65 FL	*370.65 FL
6	1		*BOOT LOGO	Necessary	59.85 FL	*59.85 FL
7	1		*EMBLEM CAMRY	Necessary	59.85 FL	*59.85 FL
8	1		*EMBLEM 2.0	Necessary	59.85 FL	*59.85 FL
9	1		*BOOT REFLECTOR RH	Serviceable	425.25 FL	*- FL
10	1		*BOOT REFLECTOR LH	Serviceable	425.25 FL	*- FL
11	1		*BOOT LOCK	Bent	401.10 FL	*401.10 FL
12	1		*TAILLAMP RH	Cracked	584.85 FL	*584.85 FL
13	1		*TAILLAMP LH	Cracked	584.85 FL	*584.85 FL
14	1		*BOOT RUBBER	Necessary	234.15 FL	*234.15 FL
15	1		*BOOT CATCH	Bent	36.75 FL	*36.75 FL
16	1		*ENDPANEL TOP GANISH	Deformed	352.80 FL	*352.80 FL
17	1		*ENDPANEL	Bent	638.40 FL	*638.40 FL
18	1		*REAR BUMPER	Deformed	573.30 FL	*573.30 FL
19	1		*BUMPER RETAINER RH	Necessary	91.35 FL	*91.35 FL
20	1		*BUMPER RETAINER LH	Necessary	91.35 FL	*91.35 FL
21	1		*BUMPER CLIPS SET	Necessary	50.00 FL	*50.00 FL
22	1		*BUMPER REFLECTOR RH	Serviceable	59.85 FL	*- FL
23	1		*BUMPER REFLECTOR LH	Cracked	59.85 FL	*59.85 FL
24	1		*BUMPER BRACKET RH	Necessary	66.15 FL	*66.15 FL
25	1		*BUMPER BRACKET LH	Necessary	66.15 FL	*66.15 FL
26	1		*REINFORCEMENT REAR	Bent	401.10 FL	*401.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,386.35	5,773.55
- List Item Discount on L Items 25.00/25.00% (S\$)	1,846.59	1,443.39
Total Parts (S\$)	5,539.76	4,330.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BOOT INNER TRIM CLIPS 1 SET (Necessary)	50.00	30.00
2	1	BOOT OUT GARNISH CLIPS 1 SET (Necessary)	50.00	30.00
3	1	REAR BUMPER CLIPS 1 SET (Necessary)	50.00	50.00
4	1	REAR ENDPANEL SEALANT (Necessary)	60.00	40.00
5	1	REAR FLOOR PANEL INSULATION (Not Necessary)	200.00	0.00
6	1	REAR LH FENDER INNER LOWER CLIPS 1 SET (Not Necessary)	50.00	0.00
7	1	REAR NO. PLATE W/ COVER (Bent)	50.00	35.00
8	1	REAR PANEL TOP GARNISH CLIPS 1 SET (Necessary)	30.00	30.00
9	1	REAR REVERSE SENSOR (Not Working)	300.00	200.00
10	1	REAR RH FENDER INNER LOWER CLIPS 1 SET (Not Necessary)	50.00	0.00
Sub Total (S\$)			890.00	415.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	1,200.00	700.00
2	SPRAYPAINTING	New	1,200.00	800.00
3	DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC., REMOVE & REINSTALL DAMAGED PARTS, TEST & RECTIFY FOR PROPER FUNCTIONING	New	100.00	30.00
4	TRANSFER TAILGATE MECHANISM TO NEW TAILGATE	New	150.00	80.00
5	REMOVE/ REFIT UPHOLSTERY LINING GARNISH	New	200.00	80.00
6	TO CHECK REVERSE SENSOR FUNCTION	New	50.00	50.00
7	ANTI-CORROSION	New	200.00	100.00
8	TO CHECK REVERSE CAMERA FUNCTION	New	100.00	-
Gross Labour Cost (S\$)			3,200.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >