



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR **SLN1438Z****Finalization**

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **25012**
Reg No/Reg Date **25/04/2017**
Date In/Mileage **12/07/2018/ 12648**
Chassis No **WDD1760432J496964**
Engine No **27091031036868**
Make/Model **MB/MB A 200 (W176) "STYLE"**
Colour/Trim **021 162 south sea b/ 044 471 ARTICO/Fabr**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	23/07/2018/ 19:13		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST Customer Request M BPNSUN POLICY NO/ACC DATE : DMPCSN3020231800 // 05/06/2018 DRIVE IN/EXCESS : 09/07/2018 // \$500.00 DATE IN/DATE SURVEY: 10/07/2018 @ 1230 // RASUL LKK BY/AUTHORIZED ON : 12/07/2018 @ 1015 // VERON LKK				
S BPNSUB SUPPLY 1 PC NO PLATE				60.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLAGE WITH NEW BODY PANELS WITH REFINISH.				960.00
A BPIRES RESPRAY FRONT BUMPER				600.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT-NETT				120.00
X BPNEXC INSURANCE EXCESS				-500.00
X RADIATOR GRILLE MERCEDES STAR	1.00	130.65	00.00	130.65
X RADIATOR GRILLE MB STAR HOLDER	1.00	72.06	00.00	72.06
X RADIATOR GRILLE ORNAMENTAL TRIM	1.00	116.50	00.00	116.50
X RADIATOR GRILLE	1.00	564.59	00.00	564.59
X FRONT LICENSE PLATE MOLDING	1.00	58.68	00.00	58.68
X FRONT BUMPER	1.00	1146.15	00.00	1146.15
X FRONT IMPACT ABSORBER	1.00	120.19	00.00	120.19

Attn: **Rasul****03 Working Days**

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 3,828.82
7% GST on 3828.82 268.02

Authorized signatory and company stamp

Total Payable 4,096.84

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR **3LN1H38Z** **SUPPLEMENTARY**

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No **25012**
Reg No/Reg Date **25/04/2017**
Date In/Mileage **12/07/2018/ 12648**
Chassis No **WDD1760432J496964**
Engine No **27091031036868**
Make/Model **MB/MB A 200 (W176) "STYLE"**
Colour/Trim **021 162 south sea b/ 044 471 ARTICO/Fabr**

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	23/07/2018/ 19:13		395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Z REQUEST				
Customer Request				
M BPNSUN				
POLICY NO/ACC DATE : DMPCSN3020231800 // 05/06/2018				
DRIVE IN/EXCESS : 09/07/2018 // \$500.00				
DATE IN/DATE SURVEY: 10/07/2018 @ 1230 // RASUL LKK				
BY/AUTHORIZED ON : 12/07/2018 @ 1015 // VERON LKK				
X FRONT IMPACT ABSORBER	1.00	120.19	00.00	120.19

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: shenhooyik@cyclecarriage.com.sg

Confirmed & accepted by

Nett **120.19**
7% GST on **120.19** **8.41**

Authorized signatory and company stamp

Total Payable 128.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg