

ASS. REC. BY:

REF:

CS/CTI18012471/ Bsd3et

Special Instruction:

Surveyor:

T-G Lim

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

9/7/18 @ 4:47pm

Estimated Cost:

Bill to:

TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

WC 6725P

Insured:

at Workshop m/s

Fook Heng Motor

Tel:

62443203

of

No. 29 Sungai Kadut St-4

Policy No.:

DMCVSN1806861800

Claim No.:

SNM18D02992001/5

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

(Client's Record)

D.O.A.

13/06/2018

CA / 

REV

/ REP. / REV 24 HRS

16/07/2018 @ Morning

H.O.D. Endorsement:

Date/Time:

5:20pm @ 9/7/18

Person Contacted:

Annie

Vehicle 

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	WC 6725P-X
11/07/18 @ 16:38	revised IA to Elaine Cheong via merimer.
11/07/18 @ 16:42	mandate requested authorize repair to Chiro Taping via merimer.
23/07/18 @ 16:39 p.m.	mandate approved by Alfred Toh via merimer.
23/07/18 @ 17:15 p.m.	revert authorize repair to Annie (repairer) via email.

TC Lim

REF: CTL

ASSIGNMENT

From: \_\_\_\_\_ Date: 10072018

Estimated Cost: \_\_\_\_\_

OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV

To inspect Vehicle No: WC 6725P

at Workshop m/s: Fook Heng

of: No. 29 Sungei Kadut St 4

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \$1500.00

(Client's Record)

Make of Veh: ISUZU CYH52

(Policy Condition) Morning

Remark: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: 98K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 25 days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA /  FEV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: WC 6725 P Yr Regn: 21 Oct 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Cement Mixer Truck

Make: ISUZU C.C 15,681

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: No display - wires cut T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JALCYH52 SD7000372

Gen. Cond: Good / Fair /  Poor / Burnt

Steering: Inorder /  Jammed / Leaked / Burnt or

Brake: Inorder /  Jammed / Leaked / Burnt or

Modi:  S/Rim / STD A/Rim or

Tyre Size: F: 295-80R 22.5(S) x 2  
R: 295-80R 22.5(D) x 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	4 mm	L/Bal.	4 mm
D.O.A.	13/6/18	D.O.I.	10.7.18 1100 am

Survey held at: Workshop, Sungei Kadut 29, St 4

Des. of Damages:  Front /  Rear /  O/S /  N/S /  U/C /  Rooftop or

The  L/O /  Chassis frame /  Body Structure affected due to collision.

Date / Time	Action / Instruction
24/09/18	Confirmed 45 \$35,000/- @ 25 days with Mr. Lim Teow Guan. (\$22,884.45 Red - 40%)

RECEIVED 24 SEP 2018

Date/Time, File Pass to? 24/09/18

1)  : Preli. Report

Typist  : Final Report

Date/Time, File Return to?

Days Of Repair: 25

Resurvey No. of Trip: 2

- Add Fee:
- Site Insp (\$)
  - Interview (\$)
  - Tech. Invs (\$)
  - Weekend (\$)

Survey Fee:	220
Transportation:	
Photos:	
Others:	
TOTAL:	220

Report Format:

Lump Sum / I.B.I: (\$ 35,000/- 45)

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Monday, 9 July 2018 4:47 PM  
**To:** assignments@lkkauto.com  
**Subject:** FW: VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC6725P (1020) - SNM18D02992C01/5  
**Attachments:** IMG\_0003.pdf; IMG\_0004.pdf; IMG\_0005.pdf; MSAT18077170-WC6725P.pdf  
**Importance:** High

Dear All,

### OWN DAMAGE CLAIM

Policy Number: DMCVSN1806861800  
Policy excess: \$1,500.00

The email below with attachments has reference.

Please proceed to survey our insured's vehicle as soon as possible.

Please revert & advise the economical repair limit / market value / whether the drum is damaged and check consistency of damages.

Thank you.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

### **China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6225 5879  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



---

**From:** Andrew Lee

**Sent:** Friday, 29 June, 2018 3:13 PM

**To:** Susan Teo <susan.teo@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>

**Cc:** Alice Ng <alice.ng@sg.cntaiping.com>

**Subject:** VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC6725P (1020) - SNM18D02992C01/5

Dear All

For your necessary information & action.

**Andrew Lee**

Senior Manager

Personal Lines Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6148

Fax (65) 6225 3592

[www.sg.cntaiping.com](http://www.sg.cntaiping.com)



*Disclaimer :*

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Ryan Poh [<mailto:ryan.pohlk@ssgroup.sg>]

**Sent:** Friday, 29 June, 2018 12:09 PM

**To:** Andrew Lee

**Subject:** Fwd: VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC6725P (1020)

FYI

Sent from my iPad

Begin forwarded message:

**From:** "Yeong Siew Lien" <[slmoter@yahoo.com.sg](mailto:slmoter@yahoo.com.sg)>

**To:** "Ryan Poh" <[ryan.pohlk@ssgroup.sg](mailto:ryan.pohlk@ssgroup.sg)>, "[roychong71@gmail.com](mailto:roychong71@gmail.com)" <[roychong71@gmail.com](mailto:roychong71@gmail.com)>

**Subject:** VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC6725P (1020)

Dear Bryan,

This is the estimate report of WC6725P (1020) for your reference. Thank you.

Best Regards,  
Annie Yeong  
Fook Heng Motor Service

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18012471/Bsd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 09-07-2018



Code : CTI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	WC 6725P
Policy No.	DMCVSN1806861800	Coverage (\$)	0.00
Claim No.	SNM18D02992C01/5	Excess (\$)	1,500.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	09/07/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	13/06/2018	Inspection Date	
Survey held at	FOOK HENG MOTOR SERVICE 29 SUNGAI KADUT STREET 4 SINGAPORE 729054		

## 5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5909H
Vehicle Details	
Vehicle No.:	WC6725P
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	6WG1419522
Chassis No.:	JALCYH52SD7000372
Maximum Power Output:	-
Open Market Value:	\$118,863.00
Original Registration Date:	21 Oct 2013
First Registration Date:	21 Oct 2013
Transfer Count:	2
Actual ARF Paid:	\$5,944.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Oct 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$71,001.00
COE Rebate Amount:	\$37,447.00
<b>Total Rebate Amount:</b>	<b>\$37,447.00</b>

The information contained herein is correct as at 11 Jul 2018

OK

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 24 September 2018 3:26 PM  
**To:** 'Yeong Siew Lien'  
**Cc:** "SUR"  
**Subject:** RE: WC 6725P OD (CTI)

Dear Annie,

Please sent over to China Taiping Insurance (Singapore) Pte Ltd the Final invoice, all supporting documents with insured duly signed & stamped.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeong Siew Lien [mailto:slmoter@yahoo.com.sg]

Sent: Monday, 24 September 2018 2:57 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Subject: Re: WC 6725P OD (CTI)

Agreed. Thank you.

Sent from my iPhone

> On 24 Sep 2018, at 2:44 PM, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

>

> Dear Annie,

>

> Please confirm final fig (lump sum) \$35,000.00 @ 25 days of repairs before excess \$ 1,500/- & GST.

>

>

>

> Thank you.

> Best Regards,

> Shirley Hiew | Case Handler

> LKK Auto Consultants Pte Ltd

> Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51,

> Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

>

>

> -----Original Message-----

> From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

> Sent: Monday, 23 July 2018 5:15 PM

> To: 'Yeong Siew Lien' <slmoter@yahoo.com.sg>

> Cc: "SUR" <sur@lkkauto.com>



## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 23 July 2018 5:15 PM  
**To:** 'Yeong Siew Lien'  
**Cc:** "SUR"  
**Subject:** RE: WC 6725P OD (CTI)

Dear Annie,

As instructed by our client, please proceed at repair cost not exceeding \$35,000.00 (inclusive supplementary) to repair the insured vehicle WC 6725P (Excess \$ 1,500/-) on lump sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Monday, 23 July 2018 4:58 PM

To: 'Yeong Siew Lien' <slmoter@yahoo.com.sg>

Cc: "SUR" <sur@lkkauto.com>

Subject: RE: WC 6725P OD (CTI)

Dear Annie,

As instructed by our client, please proceed to repair the insured vehicle WC 6725P (Excess \$ 1,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 23 July 2018 4:58 PM  
**To:** 'Yeong Siew Lien'  
**Cc:** "SUR"  
**Subject:** RE: WC 6725P OD (CTI)

Dear Annie,

As instructed by our client, please proceed to repair the insured vehicle WC 6725P (Excess \$ 1,500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeong Siew Lien [mailto:slmoter@yahoo.com.sg]

Sent: Thursday, 19 July 2018 10:24 AM

To: slmoter@yahoo.com.sg; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: "SUR" <sur@lkkauto.com>

Subject: Re: WC 6725P OD (CTI)

Dear Shirley,

As Spoken, Please confirm acceptance to the final cost of repair@Lump sum \$35,000.00 (before \$1,500.00 of excess & no GST). Thanks you.

Best Regards,

Annie Yeong

Fook Heng Motor Service

-----  
On Thu, 19/7/18, Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Subject: WC 6725P OD (CTI)

To: slmoter@yahoo.com.sg

Cc: ""SUR"" <sur@lkkauto.com>

Date: Thursday, 19 July, 2018, 9:35 AM

Dear  
Annie,

As spoken, Kindly check the repair cost limit whether you are able to repair the vehicle not exceeding \$ 32,000.00

. Thank you. Best Regards, Shirley Hiew | Case Handler LKK Auto Consultants Pte Ltd Phone:

6256-3561 | email: Sur@lkkauto.com |

fax: 6256-4315 Blk 51, Paya Ubi

Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

## View Received Message

This mail is associated with :

**\*WC6725P (SNM18D02992C01)**

OD

Jun 13 2018 2:00PM

[ZHI WEI TRANSPORT PTE LTD]

Fook Heng Motor Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on **23/07/2018 16:39 PM.**

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$35000.00) - WC6725P - Claim Handler: Elaine Cheong

Approved:35000.00:Please assist to notify Fook Heng Motor Service to get Insured to return CTPI Satisfaction Voucher DULY SIGNED & STAMPED.

### DOCUMENTS SUMMARY

There are no documents.

### View Received Message

This mail is associated with :

**\*WC6725P (SNM18D02992C01)**

OD

Jun 13 2018 2:00PM

[ZHI WEI TRANSPORT PTE LTD]

Fook Heng Motor Service

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA\_TAIPING), sent on 18/07/2018 14:55 PM.

**To** LKK\_HQ

**Subject** Alert - Adj Mandate Approved (S\$32000.00) - WC6725P - Claim Handler: Elaine Cheong

Approved:32000.00.

#### DOCUMENTS SUMMARY

There are no documents.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Elaine Cheong

Date: 11 Jul 2018

**Preliminary Advice**

Vehicle No	: WC6725P	Accident Date	: 13/06/2018
Make	: ISUZU CYH52S	Policy No.	: DMCVSN1806861800
Assignment Date	: 11/07/2018	Excess	: S\$1,500.00
Date of Inspection	: 10/07/2018	Est. Duration of Repair	: 25 days
Inspection At	: Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922 Singapore 460100		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front, o/s and n/s portion and the u/c, chassis frame and body structure affected due to collision parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	57,884.45
Revised Amount	:S\$	47,532.95
Check Items (Estimated)	:S\$	6,680.00
Total	:S\$	54,212.95
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	37,447.00
Salvage Value	:S\$	
Margin for Repair	:S\$	60,553.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

(Draft)

MSAT#8077170 / Sing Ah Tea Motor & Panel Service Pte Ltd - Pioneer  
ENTRY DATE & TIME: 14/06/2018 14:18  
SUBMITTED BY: (To Be Confirmed)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 14/06/2018 14:18  
Date Of Accident 13/06/2018 14:50  
Exact Location Of Accident TPE TOWARDS SLE  
Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number WC6725P  
Insured/Policyholder  
Name Of Registered Owner ZHI WEI TRANSPORT PTE LTD  
Co Reg No 201525909H  
Email Address ROYCHONG71@GMAIL.COM  
Mobile Phone No (LOCAL) +65-82855585  
Alternative Phone No Office-NOPHONE

### Vehicle Particulars

Manufacturer ISUZU  
Model CYH52S-15.7 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO  
Policy Number DMCVSN1806861800

Cover Note Number

### Driver

Name of Driver AN CHANGFU  
Passport No/FIN G8317322Q  
Date Of Birth 07/02/1975  
Occupation OUTDOOR  
Date Of Driving Pass 20/10/2008  
Driving Experience 9 YEARS AND 7 MONTHS  
Gender MALE  
Mobile Number (LOCAL) +65-81354738  
Fax Number  
Contact Number  
EMail Address NOEMAIL  
Address N/A  
Postcode

Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance Company of Driver's Own Vehicle

**General Information of the Accident**

Type Of Accident COLLIDED INTO PROPERTY  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

AS PER POLICE REPORT NO: T/20180614/2025 REMARKS: VEHICLE WAS NOT PRESENT FOR PHOTO TAKING WHEN MAKING THE REPORT AS VEHICLE CANT BE TOW.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTIES**


Vehicle Registration Number XB8997B  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTIES**

Vehicle Registration Number  
 Vehicle Make/Model/Colour  
 Details Of Properties RAILING  
 Vehicle Category GOVERNMENT  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number



SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

As per police report No: 7/20180614/2025

Claim own policy  
 Claim third party  
 Claim OD / TP at other works hop Foot-Heng  
 For record purposes  
 Policy No. \_\_\_\_\_  
 Insurer China Vch.No. WC6925P

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

[Signature]  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

[Signature]  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



*[Handwritten Signature]*

*[Handwritten Signature]*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.



**SINGAPORE  
POLICE FORCE**



T/20180614/2025

1 of 3

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

Report No. T/20180614/2025

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 14/06/2018 11:07	Vide Report No.: F/20180613/0158	Station Diary No.: 47
--	-------------------------------------	--------------------------

<b>Name of Informant:</b> AN CHANGFU		<b>Address:</b> 238 PASIR RIS STREET 21 ONN WAH BUILDING SINGAPORE 510238	
<b>ID Type / ID No.:</b> FIN NO / G8317322Q		<b>Contact No.:</b> Home/Office: Mobile: 81354736	
<b>Nationality:</b> CHINESE		<b>Email:</b>	
<b>Sex:</b> Male	<b>Age:</b> 43	<b>Date of Birth:</b> 07/02/1975	<b>Type of Informant:</b> Driver
<b>Race:</b> Chinese		<b>Language:</b>	<b>Institution / School Name:</b>
<b>Occupation:</b> Lorry driver		<b>Driving Licence Information:</b> Class: 3,4 Date of Expiry:	

<b>Type of Accident:</b>	Non-Injury	<b>Drink Drive:</b>	No	<b>Date/Time of Accident:</b>	13/06/2018 14:50	<b>Type of Location:</b>	Expressway
<b>Location:</b> TAMPINES EXPRESSWAY TPE(SLE) 9km							
<b>Weather:</b> Clear		<b>Road Surface:</b> Dry		<b>Road Speed Limit:</b>			
<b>Traffic Flow:</b> Dual Carriage Way		<b>Traffic Control:</b> Traffic Light - Working		<b>Traffic Volume:</b> Moderate			
<b>Type of Collision:</b> Moving Vehicle Against - Parked Vehicle						<b>Anyone conveyed by ambulance:</b> No	

Vehicle No	Vehicle Type	Make	Year	Model	Colour	Collision	No. of Passengers
WC6725P	Cement Truck					Seriously Damaged	1
XB8997B	Lorry					Slightly Damaged	0

<b>Details of Pedestrian Involved:</b>	
<b>Any Pedestrian Involved:</b> No	<b>Use of Pedestrian Crossing:</b> NA
<b>No. of Pedestrians Injured:</b> NIL	



**SINGAPORE  
POLICE FORCE**



T/20180614/2025

2 of 3

Report No. T/20180614/2025

Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	AN CHANGFU	ID No.	G8317322Q
Related Vehicle	WC6725P (Cement Truck)	Contact No.	81354736
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: NIL
Date Treatment	13/06/2018	Date Discharge	NIL
No. of Days granted Medical Leave	04	Degree of Injury	Slight

**Brief Details.**

On 13/06/2018 at about 1450hrs, I was driving a cement truck along TPE(SLE), after Punggol Road. I was on the extreme left lane, as I was driving a heavy vehicle, along 40km/h. I saw a vehicle parked at the road shoulder ahead of mine, on the left. That vehicle, license number XB 8997B, was a vehicle commonly used by workers to cut the tress along the expressway. As I was approach the vehicle, I misjudged the amount of space between my truck and the above mentioned vehicle. I hit the right back of this vehicle, namely the scorpion area. At this juncture, I lost control of my vehicle. I only managed to steer it left, and this resulted in my truck hitting the guardrail at the side of the road shoulder. The whole front section of my cement truck is damaged. The scorpion area at the rear of the other vehicle was damaged. There was no passengers in the other vehicle. No one was injured. Later on that day, I went to visit the doctor, who gave me 4 days of medical leave for the minor scratches and bruises on my left elbow. I am lodging this report as directed by the Traffic Police officer present at the scene. I wish to state that this was due to my error in judgement.



**SINGAPORE  
POLICE FORCE**



T/20180614/2025

3 of 3

Report No. T/20180614/2025





Police Station Of Origin:  
Pasir Ris N.P.C  
1 Pasir Ris Drive 4 #01-01 SINGAPORE  
519457  
Tel No: 1800-5852999

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Insp MAVIN S/O JITENDRA 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 14/06/2018 11:07
Officer In Charge Of Case: TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430	Classification Of Case:
Authentication Stamp NP188	 <p>SINGAPORE POLICE FORCE</p> <p></p> <p>SIGNATURE</p>



ORIGINAL

MEDICAL CERTIFICATE

EMD2018224895

Name AN CHANGFU		NRIC No. G8317322Q
This is to certify that the above-named is unfit for duty for a period of <u>4</u> days from <u>13-Jun-2018</u> to <u>16-Jun-2018</u> inclusive		
Type of medical leave granted :		
<input type="checkbox"/> Hospitalization Leave	<input checked="" type="checkbox"/> Outpatient Sick Leave	Delivered on _____
Admitted on _____	<input type="checkbox"/> Maternity Leave	Operated on _____
Discharged on : _____	<input type="checkbox"/> Sterilization Leave	
This certificate is not valid for absence from court attendance.		
Diagnosis	Surgical Operation (if applicable)	
Fit for light duty from <u>N.A.</u> to <u>N.A.</u>		
Comments :		
The above-named patient attended my clinic at <u>N.A.</u> and left at <u>N.A.</u> No medical leave is necessary.		
Hospital/Clinic Emergency Medicine Singapore General Hospital	Ward No. Emergency Department Date 13-Jun-2018	Signature, Name (in BLOCK LETTERS) and Designation/MGR No.  NICHOLAS EU WEN SHUEN , 83899D



# 福興修理囉哩汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,  
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451

E-mail: slmoter@yahoo.com.sg  
Business Reg. No.: 52938821M

Date: 26th June, 2018

To: ZHI WEI TRANSPORT PTE LTD  
240 Pasir Ris St 21  
#02-45  
Singapore 510240

cc: Bryan

VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC6725P (FLEET NO: 1020)

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE	
1)	front cabin	1 pc	1)	\$ 18,500.00	DM ✓
2)	front bumper	1 pc	2)	\$ 1,280.00	DM ✓
3)	Headlamp LH	1 pc	3)	\$ 425.00	BR ✓
4)	headlamp bracket LH	1 pc	4)	\$ 320.00	BR ✓
5)	fog lamp LH	1 pc	5)	\$ 205.00	BR ✓
6)	signal lamp LH	1 pc	6)	\$ 48.00	MIS ✓
7)	turbo inter cooler	1 pc	7)	\$ 4,600.00	BR ✓
8)	turbo blower pipe LH	1 pc	8)	\$ 250.00	DIS ✓
9)	radiator	1 pc	9)	\$ <del>3,800.00</del>	BR ✓ 3500.
10)	radiator cowling	1 pc	10)	\$ 415.00	DM ✓
11)	fan blade	1 pc	11)	\$ 475.00	BR ✓
12)	front cabin support cross member	1 pc	12)	\$ 750.00	DIS ✓
13)	front cabin support cross member bracket LH	1 pc	13)	\$ 480.00	DIS ✓
14)	front cabin support cross member bracket RH	1 pc	14)	\$ 395.00	DIS ✓
15)	front spring bellow cab (02 pcs X \$280.00)	2 pcs	15)	\$ 560.00	BR ✓
16)	front cabin shock absorber (02 pcs X \$135.00)	2 pcs	16)	\$ 270.00	BR ✓
17)	cabin jet	1 pc	17)	\$ 1,180.00	BT ✓
18)	steering shaft	1 pc	18)	\$ 195.00	BT ✓
19)	cabin support member (n-shape) rear	1 pc	19)	\$ 1,265.00	BT ✓
20)	cabin support C channel	1 pc	20)	\$ 315.00	R
21)	spring below cab (02 pcs X \$195.00)	2 pcs	21)	\$ 390.00	DM ✓
22)	cabin shock absorber (02 pcs X \$135.00)	2 pcs	22)	\$ 270.00	BT ✓
23)	torque rod	1 pc	23)	\$ 120.00	BR ✓
24)	radiator water tank	1 pc	24)	\$ 285.00	<del>415</del> BR ✓
25)	water pipe	1 pc	25)	\$ 95.00	CUT ✓
26)	power steering oil tank	1 pc	26)	\$ 320.00	MIS ✓
27)	mudguard shelter LH	1 pc	27)	\$ 295.00	DIS ✓
28)	mudguard shelter bracket LH	1 pc	28)	\$ 65.00	DIS ✓
			Total (Parts)	\$ 37,568.00	

Cont'd in Page 2\*\*\*



# 福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,  
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451

E-mail: slmoter@yahoo.com.sg

Business Reg. No.: 52938821M

Cont'd sheet\*\*\*2

Vehicle No. WC6725P (FLEET NO: 1020)

Total (Parts) b/f \$ 37,568.00

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE	
29)	hydraulic cooler	1 pc	29)	\$ 1,280.00	BR ✓
30)	diesel tank	1 pc	30)	\$ 950.00	DIS ✓
31)	step panel LH	1 pc	31)	\$ 320.00	DIS ✓ 245.00
32)	spring complete LH	1 pc	32)	\$ 850.00	DM ✓
33)	spring complete RH	1 pc	33)	\$ 850.00	DM ✓
34)	U bolt (04 pcs X \$30.00)	1 pc	34)	\$ 120.00	DM ✓
35)	big wheel mounting shock absorber RH/LH	2 pcs	35)	\$ 370.00	DM ✓
36)	big wheel mounting shock absorber bracket RH/LH	2 pcs	36)	\$ 216.00	R X ✓
37)	air pipe RH	1 pc	37)	\$ 68.00	TN ✓
38)	engine cover protector	1 pc	38)	\$ 220.00	DIS ✓
39)	front engine mounting bush (\$195.00/each)	RH/LH 2 pcs	39)	\$ 390.00	DM ✓
40)	rear engine mounting bush (\$310.00/each)	RH/LH 2 pcs	40)	\$ 620.00	DM ✓
41)	front axle beam	1 pc	41)	\$ 4,800.00	BT ✓
42)	front axle track rod	1 pc	42)	\$ 395.00	BT ✓
				\$ 49,017.00	
				Less 15%	\$ 7,352.55
				Total (Parts)	\$ 41,664.45

NUMBER	NETT ITEMS	QUANTITY	NUMBER	UNIT PRICE	
43)	hydraulic oil (18 Liter X \$5.00)	18 Ltr	43)	\$ 90.00	NEC ✓
44)	center mudguard complete LH	1 pc	44)	\$ 250.00	200.00 ✓ NEC
45)	sideguard complete LH	1 pc	45)	\$ 180.00	150.00 ✓ NEC
46)	rear mudguard complete LH	1 pc	46)	\$ 480.00	300.00 ✓ DIS
47)	air-con heater	1 pc	47)	\$ 682.00	✓ NEC
48)	air-con blower	1 pc	48)	\$ 295.00	✓ NEC
49)	air-con condenser	1 pc	49)	\$ 550.00	✓ NEC
50)	air-con fan	1 pc	50)	\$ 385.00	✓ NEC
51)	air-con pipe (big size)	1 pc	51)	\$ 230.00	✓ NEC
52)	air-con pipe (small size)	1 pc	52)	\$ 118.00	✓ NEC
				Total (Nett Items)	\$ 3,260.00

Cont'd in Page 3\*\*\*\*



# 福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,  
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451

E-mail: slmoter@yahoo.com.sg  
Business Reg. No.: 52938821M

Cont'd sheet \*\*\*\*/3

Vehicle No. WC6725P (FLEET NO: 1020)

	Total (Parts) & (Nett Items) b/f	\$ 44,924.45
	<u>LABOUR CHARGES &amp; MISC</u>	
53)	To remove/refit cabin, engine & speed gear box to facilitate repairs	\$ <del>2,800.00</del> <sup>1,600.00</sup> - photo
54)	To remove and replace the above chassis, straighten, knock out, realign chassis to manufacturers specification.	\$ <del>2,600.00</del> <sup>2,000.00</sup> ✓
55)	To dismantle and installation to above damaged parts and job completed.	\$ <del>3,800.00</del> <sup>2,400.00</sup> ✓
56)	To remove/renew air-con compressor, air-con pipe & refill gas.	\$ <del>350.00</del> <sup>300.00</sup> ✓
57)	To spray paint on the accident affected area.	\$ <del>1,800.00</del> <sup>1,500.00</sup> ✓
58)	To change computerised wire.	\$ 1,130.00 Nec ✓
59)	Check computerised wire.	\$ <del>480.00</del> <sup>350.00</sup> nec ✓
	Total (Labour)	\$ 12,960.00

ALL TOTAL \$ 57,884.45

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before spray painting
- To inspect damaged parts during resurvey
- To check the subject to confirmation
- To inspect survey results with the insurance
- To sign the survey report
- To ensure that the subject to be resurveyed and to obtain the approval from insurance Company

acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

25 Days

TG Lim  
10/7/18

- Lump sum repair
- ? items photo
- photo after paint
- Not authorised

*[Signature]*  
24/7/18

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2018		11 Jul 2018 14:14 <a href="#">Edit Adj Rpt</a>	<b>S\$35,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$35,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	<b>ZHI WEI TRANSPORT PTE LTD</b> , Co. Reg. No.: 201525909H	
Vehicle Reg. No.:	<b>WC6725P</b>	Date of Loss: 13/06/2018 14:00 - :59 [55 Months and 23 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD / SNM18D02992C01</b>	Policy/Cover Note No.: DMCVSN1806861800 (Comprehensive)
		Excess: S\$1,500.00
Repairer:	<b>Fook Heng Motor Service (HQ)</b> 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203	
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]	
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 20/07/2018]	
Driver/Custodian:	AN CHANGFU (43 / Male), NRIC: G8317322Q, Tel: +6581354736	
Adj Asg. Remarks:	ASSIGNMENT GIVEN VIA EMAIL ON 09.07.18	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>CHINA_TAIPING (23/07/2018): Alert - Adj Mandate Approved (S\$35000.00) - WC6725P - Claim Handler: Elaine Cheo...</li> <li>CHINA_TAIPING (23/07/2018): Alert - Adj Mandate Approved (S\$35000.00) - WC6725P - Claim Handler: Elaine Cheo...</li> <li>CHINA_TAIPING (18/07/2018): Alert - Adj Mandate Approved (S\$32000.00) - WC6725P - Claim Handler: Elaine Cheo...</li> </ul>		


















































  



















































ALL ASSOCIATED TASKS										<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

## Claim Documents

\*WC6725P (SNM18D02992C01)  
OD  
Jun 13 2018 2:00PM  
[ZHI WEI TRANSPORT PTE LTD]  
Fook Heng Motor Service

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>		
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print						
1	14/06/18 16:32	<b>Accident Statement</b>		Load HTM							
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	11/07/18 16:38	<b>Adjuster Immediate Advice</b>		Load HTM							
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print						
1	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
2	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
3	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
4	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
5	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
6	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
7	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
8	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
9	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
10	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
11	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
12	14/06/18 15:00	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>						
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
2	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
3	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
4	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
5	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
6	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
7	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
8	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
9	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
10	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
11	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
12	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
13	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
14	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
15	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
16	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						
17	11/07/18 16:39	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>						

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
					<input checked="" type="checkbox"/>
18	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
19	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
20	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
21	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
22	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
23	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
24	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
25	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
26	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
27	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
28	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
29	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
30	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
31	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
32	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
33	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
34	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
35	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
36	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
37	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
38	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
39	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
40	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
41	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
42	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
43	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
44	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
45	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
46	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
47	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
48	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
49	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
50	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
51	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
52	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
53	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
54	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
55	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
56	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
57	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
58	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
59	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
60	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
61	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
62	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
63	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
64	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
65	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>
66	11/07/18 16:39	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
67	11/07/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
68	11/07/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
69	11/07/18 16:39	General View	 Load JPG	<input checked="" type="checkbox"/>
70	11/07/18 16:39	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
71	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
72	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
73	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
74	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
75	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
76	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
77	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
78	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
79	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
80	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
81	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
82	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
83	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
84	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
85	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
86	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
87	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
88	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
89	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
90	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
91	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
92	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
93	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
94	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
95	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
96	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
97	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
98	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
99	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
100	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
101	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
102	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
103	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
104	11/07/18 16:40	General View	 Load JPG	<input checked="" type="checkbox"/>
105	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
106	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
107	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
108	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
109	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
110	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
111	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
112	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
113	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
114	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
115	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
116	24/09/18 15:44	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
117	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
118	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
119	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
120	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
121	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
122	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
123	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
124	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
125	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
126	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
127	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
128	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
129	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
130	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
131	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
132	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
133	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
134	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
135	24/09/18 15:44	Dismantled Parts	Load JPG	<input checked="" type="checkbox"/>
136	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
137	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
138	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
139	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
140	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
141	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
142	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
143	24/09/18 15:45	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/07/18 16:35	SATISFACTION VOUCHER	Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	14/06/18 16:32	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	14/06/18 16:32	CI,IC,DL [Linked Accident Report Documents]	Load TIF	
3	14/06/18 16:32	POLICE REPORT [Linked Accident Report Documents]	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/18 09:13	ESTIMATE	Load PDF	

## Linked Accident Report Documents

View 

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	14/06/18 16:32	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
5	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	14/06/18 15:00	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	14/06/18 16:32	Sketch Plan	Load TIF	
2	14/06/18 16:32	CI,IC,DL	Load TIF	
3	14/06/18 16:32	POLICE REPORT	Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI18012471/BSD3E2

**Date:** 01/10/2018

#### REFERENCE

Insured/Claimant: ZHI WEI TRANSPORT PTE LTD Policy No: DMCVSN1806861800  
Date of Loss: 13/06/2018 Nature of Claim: OD Claim No: SNM18D02992C01

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WC6725P**  
 Make & Model: ISUZU CYH52S, 15.7 D (M) Engine No: 6WG1419522  
 Reg. Date: 21/10/2013 (Man. Year: 2013) Chassis No: JALCYH52SD7000372  
 Colour: Blue Odometer: 0 km  
 Engine Capacity: 15681 cc  
 Market Value/New Car Price: S\$98,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 (D) Rear Tyre Size: 295/80 R22.5 (D/D)  
 Front Left Side: Firenza 4/4 mm Rear Left Side: Firenza 4/4/4/4 mm  
 Front Right Side: Firenza 4/4 mm Rear Right Side: Firenza 4/4/4/4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	44,924.45	43,894.35	1,030.10	2.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,960.00	9,280.00	3,680.00	28.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>57,884.45</b>	<b>53,174.35</b>	<b>4,710.10</b>	<b>8.14</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>35,000.00</b>		
<b>- Excess (S\$)</b>	1,500.00	1,500.00	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>56,384.45</b>	<b>33,500.00</b>	<b>22,884.45</b>	<b>40.59</b>

#### INSPECTION

Date of Assignment: 11/07/2018  
 Date Inspected: 10/07/2018 Inspected At: Fook Heng Motor Service (HQ)  
 29 SUNGAI KADUT STREET 4  
 SINGAPORE 729054

Estimated Period of Repair: 25.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Hiew May Fung



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 01 Oct 2018)
<b>Parts:</b>	N/A ISUZU CYH52S 15.7 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for WC6725P)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CABIN	Damaged	18,500.00 FL	*18,500.00 FL
2	1		*FRONT BUMPER	Damaged	1,280.00 FL	*1,280.00 FL
3	1		*HEADLAMP LH	Broken	425.00 FL	*425.00 FL
4	1		*HEADLAMP BRACKET LH	Broken	320.00 FL	*320.00 FL
5	1		*FOG LAMP LH	Broken	205.00 FL	*205.00 FL
6	1		*SIGNAL LAMP LH	Missing	48.00 FL	*48.00 FL
7	1		*TURBO BLOWER PIPE LH	Distorted	250.00 FL	*250.00 FL
8	1		*RADIATOR	Broken	3,800.00 FL	*3,500.00 FL
9	1		*RADIATOR COWLING	Damaged	415.00 FL	*415.00 FL
10	1		*FAN BLADE	Broken	475.00 FL	*475.00 FL
11	1		*FRONT CABIN SUPPORT CROSS MEMBER	Distorted	750.00 FL	*750.00 FL
12	1		*FRONT CABIN SUPPORT CROSS MEMBER BRACKET LH	Distorted	480.00 FL	*480.00 FL
13	1		*FRONT CABIN SUPPORT CROSS MEMBER BRACKET RH	Distorted	395.00 FL	*395.00 FL
14	2		*FRONT SPRING BELLOW CAB	Broken	560.00 FL	*560.00 FL
15	2		*FRONT CABIN SHOCK ABSORBER	Broken	270.00 FL	*270.00 FL
16	1		*CABIN JET	Bent	1,180.00 FL	*1,180.00 FL
17	1		*STEERING SHAFT	Bent	195.00 FL	*195.00 FL
18	1		*CABIN SUPPORT MMEBER (N-SHAPE) REAR	Bent	1,265.00 FL	*1,265.00 FL
19	1		*CABIN SUPPORT C CHANNEL	Repair	315.00 FL	*- FL
20	2		*SPRING BELOW CAB	Damaged	390.00 FL	*390.00 FL
21	2		*CABIN SHOCK ABSORBER	Bent	270.00 FL	*270.00 FL
22	1		*TORQUE ROD	Broken	120.00 FL	*120.00 FL
23	1		*RADIATOR WATER TANK	Broken	285.00 FL	*285.00 FL
24	1		*WATER PIPE	Cut	95.00 FL	*95.00 FL
25	1		*POWER STEERING OIL TANK	Missing	320.00 FL	*320.00 FL
26	1		*MUDGUARD SHELTER LH	Distorted	295.00 FL	*295.00 FL
27	1		*MUDGUARD SHELTER BRACKET LH	Distorted	65.00 FL	*65.00 FL
28	1		*TURBO INTER COOLER	Broken	4,600.00 FL	*4,600.00 FL
29	1		*HYDRAULIC COOLER	Broken	1,280.00 FL	*1,280.00 FL
30	1		*DIESEL TANK	Distorted	950.00 FL	*950.00 FL
31	1		*STEP PANEL LH	Distorted	320.00 FL	*245.00 FL
32	1		*SPRING COMPLETE LH	Damaged	850.00 FL	*850.00 FL
33	1		*SPRING COMPLETE RH	Damaged	850.00 FL	*850.00 FL
34	4		*U BOLT	Damaged	120.00 FL	*120.00 FL
35	2		*BIG WHEEL MOUNTING SHOCK ABSORBER RH / LH	Damaged	370.00 FL	*370.00 FL
36	2		*BIG WHEEL MOUNTING SHOCK ABSORBER BRACKET LH / RH	Repair	216.00 FL	*- FL
37	1		*AIR PIPE RH	Torn	68.00 FL	*68.00 FL
38	1		*ENGINE COVER PROTECTOR	Distorted	220.00 FL	*220.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	2		*FRONT ENGINE MOUNTING BUSH RH / LH	Damaged	390.00 FL	*390.00 FL
40	1		*FRONT AXLE BEAM	Bent	4,800.00 FL	*4,800.00 FL
41	1		*FRONT AXLE TRACK ROD	Bent	395.00 FL	*395.00 FL
42	18		*LITER HYDRAULIC OIL	Necessary	90.00 FS	*90.00 FS
43	1		*CENTER MUDGUARD COMPLETE LH	Necessary	250.00 FS	*200.00 FS
44	1		*SIDE GUARD COMPLETE LH	Necessary	180.00 FS	*150.00 FS
45	1		*REAR MUDGUARD COMPLETE LH	Distorted	480.00 FS	*300.00 FS
46	1		*AIR-CON HEATER	Necessary	682.00 FS	*682.00 FS
47	1		*AIR-CON BLOWER	Necessary	295.00 FS	*295.00 FS
48	1		*AIR-CON CONDENSER	Necessary	550.00 FS	*550.00 FS
49	1		*AIR-CON FAN	Necessary	385.00 FS	*385.00 FS
50	1		*AIR-CON PIPE (BIG SIZE)	Necessary	230.00 FS	*230.00 FS
51	1		*AIR-CON PIPE (SMALL SIZE)	Necessary	118.00 FS	*118.00 FS
52	2		*REAR ENGINE MOUNTING BUSH RH / LH	Damaged	620.00 FL	*620.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>52,277.00</b>	<b>51,111.00</b>
- List Item Discount on L Items 15.00/15.00% (S\$)	7,352.55	7,216.65
<b>Total Parts (S\$)</b>	<b>44,924.45</b>	<b>43,894.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE / REFIT CABIN, ENGINE & SPEED GEAR BOX TO FACILITATE REPAIRS	New	2,800.00	1,600.00
2	TO REMOVE AND REPLACE THE ABOVE CHASSIS, STRAIGHTEN, KNOCK OUT, REALIGN CHASSIS TO MANUFACTURERS SPECIFICATIONS	New	2,600.00	2,000.00
3	TO DISMANTLE AND INSTALLATION TO ABOVE DAMAGED PARTS AND JOB COMPLETED	New	3,800.00	2,400.00
4	TO REMOVE / RENEW AIR-CON COMPRESSOR, AIR-CON PIPE & REFILL GAS	New	350.00	300.00
5	TO SPRAY PAINT ON THE ACCIDENT AFFECTED AREA	New	1,800.00	1,500.00
6	TO CHANGE COMPUTERISED WIRE	New	1,130.00	1,130.00
7	CHECK COMPUTERISED WIRE	New	480.00	350.00
<b>Gross Labour Cost (S\$)</b>			<b>12,960.00</b>	<b>9,280.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >