

Surveyor

Menmen

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

9/9/18 @ 3:05pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

GBE 4606B

Insured:

GBE 5827Z

at Workshop m/s:

Indeco Engineers

Tel:

6382 2736

of

No. 39 Defn Lane 12

Policy No:

BMCVSN 3003501801

Claim No:

SNM18D02934C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/06/2018

CA / REV / REP. / REV 24 HRS

1up

10/07/2018

H.O.D. Endorsement:

Date/Time:

4:05pm @ 9/9/18

Person Contacted:

Mr. Tan

Vehicle:

IN OUT

Date/Time

Action/Instruction (✓) Estimate

GBE 4606B-X

GBE 5827Z-X

REF: CTL

ASSIGNMENT

From: Date: 10072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GBE 4606B

at Workshop in/s: Inveco

of 3A Defu Lane 12

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 60

IDAC/Accident Rpt: Consistent? : Yes or No

GL / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBE 4606B Yr Regn: 1215

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SSANGYONG ACTYON 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: Bothy flip - T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KPADA1ETSP242239

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 225/75R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Honkoo/c

Front: 6 mm Rear: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 11/6/18 D.O.I. 10/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/7/18 21A 35752 7yrs. 6ml dep 8500
 confirmed fire/fg # 2854.00 with M&T.
 (Red # 967, 75%)

RECEIVED 24 JUL 2018

Date/Time, File Pass to?

11/7/18 12/18

Date/Time, File Return to?

21

Report Format: MER-7P

Lump Sum / I.B.I: (3) 2854

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation

1 S + RS 01

2 Photos

3 Others:

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		09 Jul 2018 15:05 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HUP YEW FOOD FACTORY, Co. Reg. No.: 27136000C		
Main Claimant:	SP POWERASSETS LIMITED, Co. Reg. No.: 200302108D		
Vehicle Reg. No.:	GBE4606B	Date of Loss:	11/06/2018 13:00 - :59
Claim Type:	TP / SNM18D02934C02	Policy/Cover Note No.:	DMCVSN3003501801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE5827Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12, 539315 Defu Lane - Tel: 6382 2738		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/07/2018]		
Adj Asg. Remarks:	EST \$3821, ASSIGN LKK AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2108D
Vehicle Details	
Vehicle No.:	GBE4606B
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	SSANGYONG
Vehicle Model:	ACTYON SPORTS D/CAB 2.0 5AT ABS D/AB 2WD
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	67196022652449
Chassis No.:	KPADA1ETSFP242239
Maximum Power Output:	-
Open Market Value:	\$23,367.00
Original Registration Date:	17 Dec 2015
First Registration Date:	17 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$24,714.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Dec 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$48,101.00
COE Rebate Amount:	\$35,752.00
Total Rebate Amount:	\$35,752.00

The information contained herein is correct as at 10 Jul 2018

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

SSANGYONG ACTYON

Price Range ▼

Depreciation ▼

Year Reg ▼

Vehicle Type ▼

Home » Used Cars » Ezy-1 Pte Ltd » Ssangyong Actyon Sports Double-Cab 2.0A

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Car Tyres



Ssangyong Actyon Sports Double-Cab 2.0A

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)



EZY-1 PT

NEW & USED COMMERCIAL

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)

Car Details

Price	\$51,800	
Depreciation	\$10,290 /yr View models with similar depreciation	?
Reg Date	23-Jul-2013 (5yrs 11days COE left)	
Manufactured	2012	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,998 cc	
Curb Weight	1,780 kg	?
Fuel type	Diesel	
Features	Auto Retractable Side Mirrors. 6 Gear Auto Transmission.	
Accessories	Basic FM Radio.	
Description	FREE 10 Servicing Worth Over \$1,000. 1 Owner! Fully Agent Maintained And Serviced! All Records Can Be Retrieved At Agent! New Paintwork! Can Be Registered Under Personal Name! Less Than \$1000 Monthly. Only 1 In The Market. Very Rare Powerful And Comfortable Workhorse. Door Step Viewing Can Be Arranged! You Dare To Test Drive, We Confirm To Sell!	
COE	\$65,036	?



Location Ma

[Compare](#)

Payed To: 62247175

Total Pages: 16

From: Tan/Indeco Tel 63822736

INDECO ENGINEERS PTE LTD

NO 39 DEFU LANE 12 SINGAPORE 539139

DID:63822736 FAX:63822817

VEHICLE NO: GBE4606B

DATE: 04/07/2018

MAKE/MODEL: SSANGYONG ACTYON SPORTS D/CAB 2.0 5AT ABS D/AB 2WD

CHASSIS NO: KPADA1ETSFP242239

TP CLAIM AGAINST GBE5827Z

REF: TP/GBE4606B

CHINA TAIPING INSURANCE

DATE OF ACCIDENT: 11/06/2018

(SINGAPORE) PTE LTD

NAME OF SPAPE PARTS	UNIT PRICE	QTY	LIST PRICE
FRONT BUMPER	\$ 450.00	1	\$ 450.00
FRONT BUMPER LOWER GRILLE	\$ 180.00	1	\$ 180.00
REAR BUMPER RH REFLECTOR	\$ 30.00	1	\$ 30.00
FRONT BUMPER REINFORCEMENT	\$ 280.00	1	\$ 280.00
REAR RH TAILLAMP	\$ 320.00	1	\$ 320.00
REAR TAILGATE	\$ 1,280.00	1	\$ 1,280.00
REAR BUMPER (REPAIR)	\$ 150.00	1	\$ 150.00
			\$ 2,690.00
LESS Rear bumper reflector o/s 10%			\$ 269.00
			\$ 2,421.00

PARTS / ITEMS (S/N)

FRONT BUMPER STICKER	\$ 300.00	1	\$ 300.00
REAR TAILGATE STICKER	\$ 250.00	1	\$ 250.00
REAR BUMPER STICKER	\$ 250.00	1	\$ 250.00

TOTAL PARTS COST

\$ 3,221.00

LABOUR CHARGES:

LABOUR TO CARRY OUT PANEL BEATING WORKS, REPLACEMENT, REPAIR, PUTTY AND SPRAY PAINTING WORKS.

\$ 600.00

PARTS AND LABOUR TOTAL COST

\$ 600.00

\$ 3,821.00

NO. OF REPAIR DAYS: 10

NOTE: SUPPLEMENTARY QUOTE WILL BE SUBMITTED IF ADDITIONAL FAULTS ARE FOUND DURING THE COURSE OF REPAIR.

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Allowed
The photo before painting.
10/7/18
2/2854/2
Total \$ 2854

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012472/UQD3N2

Date: 24/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3003501801
Claimant Vehicle No :	GBE4606B	Insured Vehicle No :	GBE5827Z
Date of Loss:	11/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D02934C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE4606B	Engine No:	67196022652449
Make & Model:	SSANGYONG ACTYON SPORTS, 2.0 D/CAB 2.0 AT AIRBAG 2WD (A)	Chassis No:	KPADA1ETSFP242239
Reg. Date:	17/12/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/75 R16	Rear Tyre Size:	225/75 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,221.00	2,254.00	967.00	30.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	600.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	3,821.00	2,854.00	967.00	25.31

INSPECTION

Date of Assignment:	09/07/2018		
Date Inspected:	10/07/2018	Inspected At:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12 Singapore 539315

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2018)
Parts:	M1-SUV	SSANGYONG ACTYON SPORTS 2.0 D/CAB 2.0 AT AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE4606B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	450.00 FL	*450.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Cracked	180.00 FL	*180.00 FL
3	1		*REAR BUMPER RH REFLECTOR	Broken	30.00 FL	*30.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	280.00 FL	*- FL
5	1		*REAR RH TAILLAMP	Cracked	320.00 FL	*320.00 FL
6	1		*REAR TAILGATE	Badly Dented	1,280.00 FL	*1,280.00 FL
7	1		*REAR BUMPER	Repair	150.00 FL	*- FL
8	1		*FRONT BUMPER STICKER	Not fitted	300.00 FS	*- FS
9	1		*REAR TAILGATE STICKER 70KM/H & 5 PAX	Necessary	250.00 FS	*20.00 FS
10	1		*REAR BUMPER STICKER	Necessary	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,490.00	2,480.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	269.00	226.00
Total Parts (\$\$)	3,221.00	2,254.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO CARRY OUT PANEL BEATING WORKS, REPLACEMENT, REPAIR, PUTTY AND SPRAY PAINTING WORKS	New	600.00	600.00
Gross Labour Cost (S\$)			600.00	600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >