

**COMFORTDELGRO ENGINEERING PTE LTD**  
**REPAIR ESTIMATE\***

VEHICLE NO : SHD 4978L

MAKE :

MODEL : HYUNDAI i40

AgAsia (LKS)  
 DATE 5/7/2018

TS

L/S

LKK - Naz

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Bracket Top (RH)			\$ 22.40
	Front Bumper Retainer Mounting			\$ 9.20
	Front Door Power Motor			\$ 530.50
	Front Wheel Hub Cap (RH)			\$ 150.70
	<b>SUB TOTAL</b>			<b>\$ 1,275.10</b>
	<b>LESS 20%</b>			<b>\$ 255.02</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,020.08</b>
	Front Fender Advertisement Logo (RH)			\$ 100.00
	Front Door Comfort Logo (RH)			\$ 75.00
	Front Door Advertisement Logo (RH)			\$ 100.00
				<b>\$ 275.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	FRT Wheel Alignment			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 1,320.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,615.08</b>

XR  
?  
?  
?  
/ scratch

Nett / acc  
Nett / acc  
Nett / acc

200  
600  
20  
111  
111

Naz LKK  
 6/7/18 1605  
 L/S  
 3 days  
 After repair photo

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.