

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SLU5086S

Type of Claim : TP

Vehicle No. : SLU5086S

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RHT003045

Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTD

Excess : 0

Date of Accident : 26/06/2018

Motor No. : 921955Q16W471528191

Policy No. : MSD/VPCP/18-000001

Time of Accident : 16:40

Suggested Days of Repair : 7

Case Owner : BLUECAR EAST ASIA PTE
LTD / BLUESG PTE LTD**Repair Estimates**

Parts (a) List Price Items \$ 3,168.00

Plus/Less 10% \$ 316.80

Total of Cost / List \$ 2,851.20

(b) Nett Price Items \$ -

Less 0% \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 45.00

Total Parts Cost (Appendix A) \$ 2,896.20

Labour (Appendix B) \$ 3,100.00

Total Repair Cost \$ 5,996.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Marcus Loh

Company : LKK

Survey conducted on : 10/7/18 at 10am.

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Date:

ESTIMATED REPAIR COST DETAILS

1

Vehicle No : SLU5086S

Case Owner : BLUECAR EAST ASIA
PTE LTD / BLUESG PTE
LTD

Make & Model : BLUECAR

Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003045

Engine No : 921955Q16W471528191

Date & Time : -

Supplier : -

Order By : -

Type of Claim : TP

S/No	Part Description	QTY	Unit Price	List Price	Nett Price	S/N	Remarks
1	REAR BUMPER ASSY <i>213</i>	1	\$ 2,156.00	\$ 2,156.00	\$ -	\$ -	✓
2	REAR BUMPER SCREW <i>214</i>	1	\$ 4.40	\$ 4.40	\$ -	\$ -	✓
3	REAR BUMPER REFLECTOR WITH LAMP RH <i>320</i>	1	\$ 171.60	\$ 171.60	\$ -	\$ -	✓
4	REAR BUMPER REFLECTOR WITH LAMP LH <i>320</i>	1	\$ 171.60	\$ 171.60	\$ -	\$ -	✓
5	REAR BUMPER REINFORCEMENT	1	\$ 242.00	\$ 242.00	\$ -	\$ -	17 X
6	REAR BUMPER REINFORCEMENT BRACKET RH	1	\$ 44.00	\$ 44.00	\$ -	\$ -	17 X
7	REAR BUMPER REINFORCEMENT BRACKET LH	1	\$ 44.00	\$ 44.00	\$ -	\$ -	17 X
8	REAR BUMPER SPONGE	1	\$ 92.40	\$ 92.40	\$ -	\$ -	17 X
9	REAR NUMBER PLATE W CASING <i>CM</i>	1	\$ -	\$ -	\$ -	\$ 45.00	40
10	NUMBER PLATE LAMP RH <i>CM</i>	1	\$ 121.00	\$ 121.00	\$ -	\$ -	4
11	NUMBER PLATE LAMP RH <i>CM</i>	1	\$ 121.00	\$ 121.00	\$ -	\$ -	4
12	0	1	\$ -	\$ -	\$ -	\$ -	-
13	0	1	\$ -	\$ -	\$ -	\$ -	-
14	0	1	\$ -	\$ -	\$ -	\$ -	-
15	0	1	\$ -	\$ -	\$ -	\$ -	-
16	0	1	\$ -	\$ -	\$ -	\$ -	-
17	0	1	\$ -	\$ -	\$ -	\$ -	-
18	0	1	\$ -	\$ -	\$ -	\$ -	-
19	0	1	\$ -	\$ -	\$ -	\$ -	-
20	0	1	\$ -	\$ -	\$ -	\$ -	-
21	0	1	\$ -	\$ -	\$ -	\$ -	-
22	0	1	\$ -	\$ -	\$ -	\$ -	-
23	0	1	\$ -	\$ -	\$ -	\$ -	-
24	0	1	\$ -	\$ -	\$ -	\$ -	-
25	0	1	\$ -	\$ -	\$ -	\$ -	-
26	0	1	\$ -	\$ -	\$ -	\$ -	-
27	0	1	\$ -	\$ -	\$ -	\$ -	-
28	0	1	\$ -	\$ -	\$ -	\$ -	-
29	0	1	\$ -	\$ -	\$ -	\$ -	-
30	0	1	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$3,168.00 \$ 3,168.00 \$ - \$45.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

BLUECAR EAST
ASIA PTE LTD /
BLUESG PTE

Year of Manufacture 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.