

ACCIDENT REPAIR ESTIMATES

Our Ref: TP / SLU5086S

Type of Claim : TP

Vehicle No. : SLU5086S

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RHT003045

Ins Company : AIG ASIA PACIFIC
INSURANCE PTE LTD

Excess : 0

Date of Accident : 26/06/2018

Motor No. : 921955Q16W471528191

Policy No. : MSD/VPCP/18-000001

Time of Accident : 16:40

Suggested Days of Repair : 7

Case Owner : BLUECAR EAST ASIA PTE
LTD / BLUESG PTE LTD**Repair Estimates**

Parts (a) List Price Items	\$ 3,168.00
Plus/Less 10%	\$ 316.80
Total of Cost / List	\$ 2,851.20
(b) Nett Price Items	\$ -
Less 0%	\$ -
Total of Nett Item	\$ -
(c) Special Nett Items	\$ 45.00
Total Parts Cost (Appendix A)	\$ 2,896.20
Labour (Appendix B)	\$ 3,100.00
Total Repair Cost	\$ 5,996.20

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

ESTIMATED REPAIR COST DETAILS

1

BLUECAR EAST ASIA
PTE LTD / BLUESG PTE
LTD

Vehicle No : SLU5086S

Case Owner : LTD

Make & Model : BLUECAR

Year Manufacture : 2017

Chassis No : VL4BCEB4RHT003045

Engine No : 921955Q16W471528191

Date & Time : -

Supplier : -

Order By : -

Type of Claim : TP

S/No	Part Description	QTY	Unit Price	List Price	Nett Price	S/N	Remarks
1	REAR BUMPER ASSY	1	\$ 2,156.00	\$ 2,156.00	\$ -	\$ -	-
2	REAR BUMPER SCREW	1	\$ 4.40	\$ 4.40	\$ -	\$ -	-
3	REAR BUMPER REFLECTOR WITH LAMP RH	1	\$ 171.60	\$ 171.60	\$ -	\$ -	-
4	REAR BUMPER REFLECTOR WITH LAMP LH	1	\$ 171.60	\$ 171.60	\$ -	\$ -	-
5	REAR BUMPER REINFORCEMENT	1	\$ 242.00	\$ 242.00	\$ -	\$ -	-
6	REAR BUMPER REINFORCEMENT BRACKET RH	1	\$ 44.00	\$ 44.00	\$ -	\$ -	-
7	REAR BUMPER REINFORCEMENT BRACKET LH	1	\$ 44.00	\$ 44.00	\$ -	\$ -	-
8	REAR BUMPER SPONGE	1	\$ 92.40	\$ 92.40	\$ -	\$ -	-
9	REAR NUMBER PLATE W CASING	1	\$ -	\$ -	\$ -	\$ 45.00	-
10	NUMBER PLATE LAMP RH	1	\$ 121.00	\$ 121.00	\$ -	\$ -	-
11	NUMBER PLATE LAMP RH	1	\$ 121.00	\$ 121.00	\$ -	\$ -	-
12	0	1	\$ -	\$ -	\$ -	\$ -	-
13	0	1	\$ -	\$ -	\$ -	\$ -	-
14	0	1	\$ -	\$ -	\$ -	\$ -	-
15	0	1	\$ -	\$ -	\$ -	\$ -	-
16	0	1	\$ -	\$ -	\$ -	\$ -	-
17	0	1	\$ -	\$ -	\$ -	\$ -	-
18	0	1	\$ -	\$ -	\$ -	\$ -	-
19	0	1	\$ -	\$ -	\$ -	\$ -	-
20	0	1	\$ -	\$ -	\$ -	\$ -	-
21	0	1	\$ -	\$ -	\$ -	\$ -	-
22	0	1	\$ -	\$ -	\$ -	\$ -	-
23	0	1	\$ -	\$ -	\$ -	\$ -	-
24	0	1	\$ -	\$ -	\$ -	\$ -	-
25	0	1	\$ -	\$ -	\$ -	\$ -	-
26	0	1	\$ -	\$ -	\$ -	\$ -	-
27	0	1	\$ -	\$ -	\$ -	\$ -	-
28	0	1	\$ -	\$ -	\$ -	\$ -	-
29	0	1	\$ -	\$ -	\$ -	\$ -	-
30	0	1	\$ -	\$ -	\$ -	\$ -	-

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL \$3,168.00 \$ 3,168.00 \$ - \$45.00

