

160 Sin Ming Drive, #05-11,
Sin Ming AutoCity
Singapore 575722
(Registration no :095744/00B)
Tel : 64533100, Fax 62669932

Date of Accident : 8/07/2018
Your Insured Vehicle
No : SLS 721K

<u>Estimate repair cost to NISSAN LATIO reg no : SJU 6415 T</u>	
<u>Nett Item</u>	
1pc rear bumper	S\$ 532.40
1pc rear bumper o/s retainer	36.00
1pc o/s/r panel air duct	55.30
1pc o/s taillamp	279.00
1pc o/s/r panel	1004.70
1pc o/s/r panel inner shield	115.00
	2022.40
	2022.40
Less 10%	202.24
	1820.16
<u>Labour & misc charges</u>	
Panel knocking	1000.00
Spray painting	750.00
Labour to remove and install rear windscreen	180.00
Sealant and clip	60.00
1pc windscreen moulding	100.00
Wire checking	40.00
Labour to remove and install petrol tank	150.00
Tuff kote	150.00
	4250.16

10%

CMA 532.40 —
D11 36.00 —
52 55.30 X
279.00 ?
B1 1004.70 —
CMA 115.00 —

Food
600
1200
200
200
600
300

HWA SENG SPRAY PAINTING COMPANY

~~I hereby authorize the Repairer of the following:~~

- ~~To resurvey before/after spray painting~~
- ~~To display damaged part(s) during resurvey~~
- ~~Parts prices are subject to confirmation~~
- ~~Third party survey is on a "Without Prejudice" basis~~
- ~~No illegal modification(s) is allowed~~
- ~~Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company~~

Acknowledged by Repairer
Signature:
Date:

Not Authorized
L1 Sur & ?
Resurvey After Paint
6000