

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

**INDIA INTERNATIONAL INSURANCE PTE LTD**  
 64 CECIL ST #04-05 IOB BUILDING  
 049711

Attention : Motor Claim Department  
 Contact : 6223 8122

**Estimate : ES000221**

Date : 09/07/2018  
 Vehicle Num. : SLL 5009M (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 17/06/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		<b>LIST ITEMS :</b>		
1.	1	FRONT DOOR - LH ✓DT		1,450.00
2.	1	FRONT FENDER LH ✓OT		950.00
3.	1	FRONT FENDER HYBRID EMBLEM LH ✓NEC		100.00
4.	1	FRONT WHEEL ARCH MOULDING LH ✓CUT		250.00
5.	1	FRONT BUMPER ✓CUT		900.00
6.	1	FRONT LOWER BUMPER X		300.00
7.	1	SIDE SKIRT LH X		450.00
8.	1	FRONT FENDER UNDER DUST COVER LH X		190.00
9.	1	FRONT BUMPER SIDE RETAINER L/H ?		120.00
		List Total S\$ :		4,710.00
		20.00% Discount S\$ :		942.00
				3,768.00
		<b>SPECIAL NETT ITEMS :</b>		
1.	1	FRONT WHEEL ARCH MOULDING CLIPS ✓NEC		<del>50.00</del> 30
2.	1	FRONT BUMPER CLIP ✓NEC		<del>50.00</del> 30
3.	1	SIDE SKIRT CLIPS X		50.00
4.	1	SPORT RIM R		1,600.00
5.	1	FRONT FENDER UNDER DUST COVER CLIPS ✓NEC		<del>50.00</del> 30
6.	1	FRONT TYRE LH X		188.00
		Special Nett Total S\$ :		1,988.00
		<b>LABOUR :</b>		
		TRANSFER DOOR MECHANISM		<del>180.00</del> 100
		TO REMOVE, REARRANGE FRT LH/RRRH DOOR ELECTRICAL WIRING		<del>280.00</del> 120

CONTINUE / ...

**WORLD AUTO PTE LTD**

47 Jalan Pemimpin #01-02/03  
 Halcyon 2, S'pore 577200  
 Tel No. : 6451 3933 Fax No. : 6455 7576  
 E-Mail : worldaut@singnet.com.sg  
 Website : www.worldauto.com.sg  
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD  
 64 CECIL ST #04-05 IOB BUILDING  
 049711

Attention : Motor Claim Department  
 Contact : 6223 8122

Estimate : ES000221

Date : 09/07/2018  
 Vehicle Num. : SLL 5009M (LCR)  
 Make/Model : HONDA VEZEL HYBRID  
 Chassis/Eng# :  
 Accident Date : 17/06/2018  
 Claim No. :  
 Reference :  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

.		LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		<del>1,200.00</del> 700
.		PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)		<del>1,500.00</del> 800
.		Labour Total S\$ :		3,160.00

Sathya Sai  
 10/7/2018

5 days

- Lump Sum Repair
- Question mark item photo
- Photo after paint

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

E. & O.E.	Signature:	Total S\$ :	8,916.00
	Date:		=====

for WORLD AUTO PTE LTD