

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/741/2018/GW
Date : 28-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Premium Leasing Pte Ltd
Address : 9 Leng Kee Rd
Singapore 159090
Telephone : HP +65 63662323
Type of Claim : Own Damage Claim
Policy No. : 100860745
Vehicle No : **SMA 1237 T**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : May-18
Engine No : CVK 058480
Chassis No : WAUZZZF54JA086555
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jun-18
Place of Accident : Along Scotts Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 1237 T

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N \$ 280.00 ✓
3	To remove front fittings, dismantle front bumper assy. Remove and renew rhs front fender, rhs front door and fittings. Inspect rhs A pillar . Repair all panel and renew bonnet and align. Renew damaged fittings, re-install all panel removed.	\$ 4,200.00 2250 ✓
4	To respray bonnet, rhs front fender, rhs front door, rhs mirror cover and rhs sill panel. ✓ 150. ✓ 1/2 ✓	\$ 3,300.00 2100 ✓
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓
6	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>8,732.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 1237 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT FENDER-RH <i>Dented</i>	\$ 920.00	✓
2	FRONT FENDER ATTACHMENT PARTS <i>me</i>	\$ 45.00	✓
3	FRONT FENDER CLOSING ELEMENT ?	\$ 65.00	?
4	FRONT FENDER BRACKET-LH/RH <i>best</i>	2 \$ 62.00	✓
5	FRONT FENDER UPPER BRACKET-LH <i>best</i>	\$ 50.00	✓
6	FRONT FENDER BRACE-RH ?	\$ 103.00	?
7	FRONT FENDER COVER <i>me</i>	\$ 16.00	✓
8	FRONT FENDER CLOSING ELEMENT-RH <i>me</i>	\$ 29.00	✓
9	FRONT FENDER TRIM-RH ?	\$ 138.00	?
10	FRONT DOOR TRIM-RH ?	\$ 138.00	?
11	BONNET <i>Dented</i>	\$ 2,499.00	✓
12	BONNET ATTACHMENT PARTS ?	\$ 105.00	?
13	BONNET LID HINGE <i>seen</i>	\$ 367.00	x
14	FRONT DOOR -RH <i>Dented</i>	TBC	✓
15	FRONT DOOR OUTER SEAL-RH <i>me</i>	\$ 192.00	✓
16	BONDING AGENT ?	\$ 43.00	?
17	CLEANING SOLUTION ?	\$ 64.00	?
18	FRONT DOOR CATCH-RH <i>me</i>	\$ 105.00	x
19	FRONT DOOR CATCH COVE-RH <i>me</i>	\$ 13.00	x
20	FRONT DOOR HINGE HALF UPPER PARTS-RH <i>me</i>	\$ 40.00	x
SUB-TOTAL SPARE PARTS CHARGES		\$ 4,994.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 1237 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT DOOR HINGE HALF LOWER PARTS-RH <i>MT</i>	\$ 40.00	X
22	EXTERIOR MIRROR MOUNTING-RH <i>new</i>	\$ 959.00	X
23	MIRROR CAP-RH <i>Repis</i>	\$ 217.00	X
24	FRONT TURN SIGNAL INDICATOR-RH <i>new</i>	\$ 93.00	X
25	SIDE MEMBER TRIM-RH <i>Deland</i>	\$ 723.00	✓
26	1 SET OF ATTACHMENT PARTS <i>new</i>	\$ 111.00	✓
27	1 SET OF ADHESIVE TAPES	\$ 182.00	✓
28	FRONT WHEEL HOUSING LINER-RH <i>Deland</i>	\$ 246.00	✓
29	WHEEL HOUSING ATTACHMENT PARTS ?	\$ 78.00	?
30	FRONT STONE CHIP GUARD-RH <i>new</i>	\$ 44.00	—
31	FRONT WHEEL SPOILER-RH ?	\$ 63.00	?
32	FRONT ALUMINIUM-RH <i>lit</i>	\$ 934.00	✓
33	RUBBER VALVE <i>new</i>	4 \$ 12.00	X
34	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 8,996.00	
TOTAL LABOUR CHARGES		\$ 8,732.00	
GRAND TOTAL		\$ 17,728.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 09/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Pups

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant