

ASSIGNED BY: Adrian King

REF: CC3 / A1618012512 / Adbnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 0999994958

Claims No. 806025118186

Sum Insured: _____ Excess: \$1,400.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 185K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 wks days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMA123TT. Yr Regn: 208 / Mung

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 SB c.c 1984.

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 1261 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPAU222FS4JA086555

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil (S/Rim) / STD A/Rim or

Tyre Size: F: 245/40R18.

R: 245/40R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 06 mm Rear R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 26/6/18 D.O.I. 09/07/18

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD AIG.
	SMA 123TT - CCU 1A1618011948/KPC3 DCA: 26/7/18
10/7/18	Revert via merimen
12/7/18	Anthony repair; inform repairer to proceed
21/9/18	Seek mandate for supp: for approve
23/10/18	Mandate approve
22/11/18	Mandate final amount RECEIVED 11 JAN 2019
17/12 3.47pm	Confirmed final fig \$13,122.08 and 8 days with Mr Boo. (Red. 5096.92, 27%)

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 8

1) : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:	200 10
Transportation:	
\$ + RS. \$1	
Photos	
Others	
TOTAL	210

- Add Fee:
- : Site Insp (\$)
 - : Interview (\$)
 - : Tech. Invs (\$)
 - : Weekend (\$)

Report Format: 00

Lump Sum / 100% (\$ 13,122.08)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 21 Nov 2018

Preliminary Advice

Vehicle No	: SMA1237T	Accident Date	: 26/06/2018
Make	: AUDI A5	Policy No.	: 0999994958
Assignment Date	: 10/07/2018	Excess	: S\$1,400.00
Date of Inspection	: 09/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,219.00
Revised Amount	:S\$	13,122.08
Check Items (Estimated)	:S\$	0.00
Total	:S\$	13,122.08
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	71,892.00
Salvage Value	:S\$	
Margin for Repair	:S\$	113,108.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 21 Sep 2018

Preliminary Advice

Vehicle No	: SMA1237T	Accident Date	: 26/06/2018
Make	: AUDI A5	Policy No.	: 0999994958
Assignment Date	: 10/07/2018	Excess	: S\$1,400.00
Date of Inspection	: 09/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,219.00	(Include supplementay 491.00)
Revised Amount	:S\$	12,126.00	(Include supplementay 491.00)
Check Items (Estimated)	:S\$	1,097.00	
Total	:S\$	13,223.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	71,892.00
Salvage Value	:S\$	
Margin for Repair	:S\$	113,108.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building 78 Shenton Way #07-16 Singapore 079120	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Date: 10 Jul 2018
<u>Preliminary Advice</u>	

Vehicle No	: SMA1237T	Accident Date	: 26/06/2018
Make	: AUDI A5	Policy No.	:
Assignment Date	: 10/07/2018	Excess	: S\$0.00
Date of Inspection	: 09/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,728.00	18,019
Revised Amount	:S\$	11,635.00	
Check Items (Estimated)	:S\$	1,097.00	
Total	:S\$	12,732.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	185,000.00
COE / PARF Rebate	:S\$	71,892.00
Salvage Value	:S\$	
Margin for Repair	:S\$	113,108.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Celine Fong (LKKAuto)

From: Celine Fong (LKKAuto)
Sent: Monday, 17 December 2018 3:47 PM
To: Boo seng yak; Adrian Ling (LKKAuto); SUR; Carrine Leong; jiyee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FIFNAL REVISION - S,A1237T - OD AIG - SURVEYED 9 JUL 18

Dear Mr Boo,

Confirm repair cost of \$13,122.08 before excess \$1,400.00 @ 8 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 21 November 2018 5:03 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FIFNAL REVISION - S,A1237T - OD AIG - SURVEYED 9 JUL 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$13,122.08 @ 8 days of repairs exclude 1 Sunday. Guo Qiang re-inspected vehicle on 19 Jul 18.

Your early closure is well appreciated.

Best regards - jb

Janice Lee (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, November 21, 2018 5:03 PM
To: Adrian Ling (LKKAuto); Janice Lee (LKKAuto); SUR; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FIFNAL REVISION - S,A1237T - OD AIG - SURVEYED 9 JUL 18
Attachments: PA07412018 - SMA 1237 T - Audi A5 SB 2.0 TFSI - FRONT +RHS+ Supp (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$13,122.08 @ 8 days of repairs exclude 1 Sunday. Guo Qiang re-inspected vehicle on 19 Jul 18.

Your early closure is well appreciated.

Best regards - jb

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Thursday, July 12, 2018 7:01 PM
To: claims@premiumauto.com.sg
Cc: SUR
Subject: SMA 1237T AIG OD DOA : 26/06/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SMA 1237T (excess \$1,400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Note: Please dismantle door and allow reinspection of damage to door pillar.

Please refer to below :

"Re-inspect and upload damage photos of RH A Pillar. If no damage labour of 4.5 days not justified. Re-inspection to be done for damage check and supplementary items / labour."

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SMA1237T (8060251181SG)**
OD
Jun 26 2018 6:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 27/11/2018 12:25 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$13122.08) - SMA1237T - Claim Handler: Mohd Zawaye, Norsazani

Approved:13122.08.

Print Received Message

This mail is associated with :

***SMA1237T (8060251181SG)**
OD
Jun 26 2018 6:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG)**, sent on 23/10/2018 15:23 PM.
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$12126.00) - SMA1237T - Claim Handler: Mohd Zawaye, Norsazani**

Approved:12126.00:Damage photos of RH A Pillar? If no damage labour of 4.5 days not justified. Upload finalise estimate.

Print Sent Message

This mail is associated with :

***SMA1237T (8060251181SG)**
OD
Jun 26 2018 6:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/10/2018 09:26 AM.
To Victor_KohCK; Norsazani.Zawaye@aig.com
Subject Re: Alert - Adj Mandate Maintained - SMA1237T - Claim Handler: Mohd Zawaye, Norsazani

Dear Victor,

According Adrian, 4.5 days of labour awarded is for the removal of front bumper, headlamp, replacement of front fender, side member trim, minor alignment to the A-Pillar.

Thanks.

Regards,
Jannice

<-- Original Message -->

From: AIG_SG
To: LKK_HQ
Sent On: 15/10/2018 02:08 PM
Subject: Alert - Adj Mandate Maintained - SMA1237T - Claim Handler: Mohd Zawaye, Norsazani

Maintained:Damage photos of RH A Pillar? If no damage labour of 4.5 days not justified. Upload finalise estimate.

Print Received Message

This mail is associated with :

***SMA1237T (8060251181SG)**
OD
Jun 26 2018 6:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 15/10/2018 14:08 PM.**
To **LKK_HQ**
Subject **Alert - Adj Mandate Maintained - SMA1237T - Claim Handler: Mohd Zawaye, Norsazani**

Maintained: Damage photos of RH A Pillar? If no damage labour of 4.5 days not justified. Upload finalise estimate.

4.5 Days of labour awarded for the removal of front bumper, handling, replacement of front fender, front door, side member trim, minor alignment to the A-Pillar.

Print Received Message

This mail is associated with :

***SMA1237T (8060251181SG)**
OD
Jun 26 2018 6:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/07/2018 14:51 PM.
To LKK_HQ
Subject SMA1237T / OD / 26/06/2018 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$1400.00

Thank you
Mohd Zawaye, Norsazani

Print Received Message

This mail is associated with :

***SMA1237T (8060251181SG)**
OD
Jun 26 2018 6:00PM
[PREMIUM LEASING PTE LTD]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/07/2018 16:36 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11635.00) - SMA1237T - Claim Handler: Mohd Zawaye, Norsazani

Approved:11635.00:Re-inspect and upload damage photos of RH A Pillar. If no damage labour of 4.5 days not justified. Re-inspection to be done for damage check and supplementary items / labour.

*Please dismantle door and allow reinspection
of damage to door Pillar*

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9676M
Vehicle Details	
Vehicle No.:	SMA1237T
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CVK058480
Chassis No.:	WAUZZZF54JA086555
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$37,959.00
Original Registration Date:	28 May 2018
First Registration Date:	28 May 2018
Transfer Count:	0
Actual ARF Paid:	\$45,143.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 May 2028
PARF Rebate Amount:	\$33,857.00
Intended COE Rebate Details	
COE Expiry Date:	27 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,501.00
COE Rebate Amount:	\$38,035.00
Total Rebate Amount:	\$71,892.00

The information contained herein is correct as at 10 Jul 2018

OK



HOTLINE TEL: (65) 8419-3000
FAX : (65) 6415-3723

COVER NOTE

Cover Note No. 100860745		Date 24 May 2018	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
SCHEDULE			
Policyholder	Premium Leasing Pte Ltd		
Age Condition	N/A	Registration No	TA SMA1237T
Policy Type	COMPREHENSIVE COMMERCIAL MOTOR	Make/Model	Audi A5 Sportback 2.0 TFSI
Effective Date	28 May 2018	CC/Tonnage	1,984.00
Expiry Date	27 May 2019	Engine No	CVK058480
Hire Purchase Company	HONG LEONG FINANCE LTD	Chassis No	WAUZZZF54JA086555
		Year of Registration	2018

This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.

Usage of vehicle only for the following purposes:

- Use only for social, domestic and pleasure purposes and for the Policyholder's business.
- Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes.

Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.

The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

CERTIFICATE OF INSURANCE

We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Issued at SINGAPORE

AIG ASIA PACIFIC INSURANCE PTE. LTD.

IMPORTANT NOTICE
THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD.

Authorised Representative

SSPYTP

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait of CHUA SIEW LAY FREDA

Licence Number: **S7503455E**

Name: **CHUA SIEW LAY FREDA (CAI XIULI FREDA)**

Birth Date: **31 Jan 1975**

Issue Date: **18 Apr 2005**

Barcode: 001336132J

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7503455E**



Portrait of CHUA SIEW LAY FREDA

Name: **CHUA SIEW LAY FREDA (CAI XIULI FREDA)**

蔡秀丽

Race: **CHINESE**

Date of birth: **31-01-1975**

Sex: **F**

Country of birth: **SINGAPORE**

S7503455E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars \leq 3000 kg with \leq 7 passengers, exclusive of the driver; and motor tractors / vehicles \leq 2500 kg

PASS DATE: **26 Aug 1997**

NP 428A

Licence No: **S7503455E**

3702989

Barcode

NRIC No: **S7503455E**

Portrait of CHUA SIEW LAY FREDA

Fingerprint

Date of issue: **18-04-2005**

APT BLK 470A UPPER SERANGOON CRESCENT #08-302
SINGAPORE 531470
NRIC No: **S7503455E**

Date: **28/02/2015**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/741/2018/GW
Date : 28-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Premium Leasing Pte Ltd
Address : 9 Leng Kee Rd
Singapore 159090
Telephone : HP +65 63662323
Type of Claim : Own Damage Claim
Policy No. : 100860745
Vehicle No : **SMA 1237 T**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : May-18
Engine No : CVK 058480
Chassis No : WAUZZZF54JA086555
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jun-18
Place of Accident : Along Scotts Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 1237 T

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓ 480
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N \$ 280.00 ✓ 280
3	To remove front fittings, dismantle front bumper assy. Remove and renew rhs front fender, rhs front door and fittings. Inspect rhs A pillar. Repair all panel and renew bonnet and align. Renew damaged fittings, re-install all panel removed.	\$ 4,200.00 2250 2250
4	To respray bonnet, rhs front fender, rhs front door, rhs mirror cover and rhs sill panel. ✓ 150 ✓ Y2 ✓	\$ 3,300.00 2100 2100
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓ 280
6	To carry out diagnostic check.	S/N \$ 192.00 ✓ 192
TOTAL LABOUR CHARGES		: \$ 8,732.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 1237 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT FENDER-RH <i>Distorted</i>	\$ 920.00	✓ 735.60
2	FRONT FENDER ATTACHMENT PARTS <i>Nil</i>	\$ 45.00	✓ X
3	FRONT FENDER CLOSING ELEMENT <i>Dist.</i>	\$ 65.00	? 51.60
4	FRONT FENDER BRACKET-LH/RH <i>Best</i>	2 \$ 62.00	✓ 48.32
5	FRONT FENDER UPPER BRACKET-LH <i>Best</i>	\$ 50.00	✓ 40.00
6	FRONT FENDER BRACE-RH <i>Dist.</i>	\$ 103.00	? 82.40
7	FRONT FENDER COVER <i>Not new</i>	\$ 16.00	✓ X
8	FRONT FENDER CLOSING ELEMENT-RH <i>new</i>	\$ 29.00	✓ 24.16
9	FRONT FENDER TRIM-RH <i>new</i>	\$ 138.00	? X
10	FRONT DOOR TRIM-RH <i>new</i>	\$ 138.00	? X
11	BONNET <i>Distorted</i>	\$ 2,499.00	✓ 1,999.20
12	BONNET ATTACHMENT PARTS <i>new</i>	\$ 105.00	? X
13	BONNET LID HINGE <i>new</i>	\$ 367.00	X X
14	FRONT DOOR -RH <i>Distorted</i>	TBC	✓ 2,153.60
15	FRONT DOOR OUTER SEAL-RH <i>new</i>	\$ 192.00	✓ 153.20
16	BONDING AGENT <i>new</i>	\$ 43.00	? }
17	CLEANING SOLUTION <i>new</i>	\$ 64.00	? } X
18	FRONT DOOR CATCH-RH <i>new</i>	\$ 105.00	X }
19	FRONT DOOR CATCH COVE-RH <i>new</i>	\$ 13.00	X }
20	FRONT DOOR HINGE HALF UPPER PARTS-RH <i>new</i>	\$ 40.00	X }
SUB-TOTAL SPARE PARTS CHARGES		\$ 4,994.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 1237 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT DOOR HINGE HALF LOWER PARTS-RH ^{MT}	\$ 40.00	+
22	EXTERIOR MIRROR MOUNTING-RH ^{MT}	\$ 959.00	+
23	MIRROR CAP-RH ^{Repair}	\$ 217.00	+
24	FRONT TURN SIGNAL INDICATOR-RH ^{MT}	\$ 93.00	+
25	SIDE MEMBER TRIM-RH ^{Deland}	\$ 723.00	✓ 578.40
26	1 SET OF ATTACHMENT PARTS ^{MT}	\$ 111.00	✓ 28.80
27	1 SET OF ADHESIVE TAPES	\$ 182.00	✓ 145.20
28	FRONT WHEEL HOUSING LINER-RH ^{Deland}	\$ 246.00	✓ 196.50
29	WHEEL SHOUSING ATTACHMENT PARTS ^{MT}	\$ 78.00	? X
30	FRONT STONE CHIP GUARD-RH ^{MT}	\$ 44.00	- 34.56
31	FRONT WHEEL SPOILER-RH ^{MT}	\$ 63.00	? X
32	FRONT ALUMINIUM-RH ^{cut}	\$ 934.00	✓ 747.20
33	RUBBER VALVE ^{MT}	4 \$ 12.00	+ X
34	SUNDRIES ^{MT}	\$ 300.00	? 74.50
TOTAL SPARE PARTS CHARGES		\$ 8,996.00	
TOTAL LABOUR CHARGES		\$ 8,732.00	
GRAND TOTAL		\$ 17,728.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

20274.84.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 09/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. PA/OD/741/2018/GW Date 18-Jul-18 Service Advisor Tony Foong Pages 1 Regn No SMA 1237 T Model No Audi A5 SB 2.0 TFSI
--	---

Quantity	Description	Unit Price	Amount
Parts			
1	WASH WATER RESERVIOR <i>selhd</i>	\$ 124.00	✓ 98.80
2	BUNGS <i>not nec</i>	\$ 7.00	✓
3	SEAL <i>nec</i>	\$ 54.00	✓ 42.64
4	FRONT FENDER TOP COVER - RH <i>not</i>	\$ 30.00	✓ 24.00
5	FRONT FENDER CHROME- RH <i>nec</i>	\$ 138.00	✓ 110.40
6	FRONT DOOR CHROME TRIM - RH	\$ 138.00	✓ 110.40
TOTAL		\$ 491.00	

For Premium Automobiles Pte Ltd

Adrian Ling
SLG
19/07/18



Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/741/2018/GW
Date : 28-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

You recommended 6 days
We took 8 days exclude 1 Sunday
jb 21 Nov 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Premium Leasing Pte Ltd
Address : 9 Leng Kee Rd
Singapore 159090
Telephone : HP +65 63662323
Type of Claim : Own Damage Claim
Policy No. : 100860745
Vehicle No : **SMA 1237 T**
Model Code : Audi A5 SB 2.0 TFSI
Model / Year : May-18
Engine No : CVK 058480
Chassis No : WAUZZZF54JA086555
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Jun-18
Place of Accident : Along Scotts Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 1237 T

S/n	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer rhs front door's multi-lock system and power window devices.	S/N \$ 280.00	\$ 280.00
3	To remove front fittings, dismantle front bumper assy. Remove and renew rhs front fender, rhs front door and fittings. Inspect rhs A pillar . Repair all panel and renew bonnet and align. Renew damaged fittings, re-install all panel removed. <i>Spoken with Adrian - agreed \$2250.00 9/7/18</i>	\$ 4,200.00	\$ 2,250.00
4	To respray bonnet, rhs front fender, rhs front door, rhs mirror cover and rhs sill panel.	\$ 3,300.00	\$ 2,100.00
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
6	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 8,732.00	\$ 5,582.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 1237 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT FENDER-RH	\$ 920.00	\$ 735.60
2	FRONT FENDER ATTACHMENT PARTS	\$ 45.00	
3	FRONT FENDER CLOSING ELEMENT	\$ 65.00	\$ 51.60
4	FRONT FENDER BRACKET-LH/RH	2 \$ 62.00	\$ 48.32
5	FRONT FENDER UPPER BRACKET-LH	\$ 50.00	\$ 40.00
6	FRONT FENDER BRACE-RH	\$ 103.00	\$ 82.40
7	FRONT FENDER COVER	\$ 16.00	
8	FRONT FENDER CLOSING ELEMENT-RH	\$ 29.00	\$ 24.16
9	FRONT FENDER TRIM-RH	\$ 138.00	
10	FRONT DOOR TRIM-RH	\$ 138.00	
11	BONNET	\$ 2,499.00	\$ 1,999.20
12	BONNET ATTACHMENT PARTS	\$ 105.00	
13	BONNET LID HINGE	\$ 367.00	
14	FRONT DOOR -RH	\$ 2,692.00	\$ 2,153.60
15	FRONT DOOR OUTER SEAL-RH	\$ 192.00	\$ 153.20
16	BONDING AGENT	\$ 43.00	
17	CLEANING SOLUTION	\$ 64.00	
18	FRONT DOOR CATCH-RH	\$ 105.00	
19	FRONT DOOR CATCH COVE-RH	\$ 13.00	
20	FRONT DOOR HINGE HALF UPPER PARTS-RH	\$ 40.00	
SUB-TOTAL SPARE PARTS CHARGES		\$ 7,686.00	\$ 5,288.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 1237 T.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 5,288.08
21	FRONT DOOR HINGE HALF LOWER PARTS-RH	\$ 40.00	
22	EXTERIOR MIRROR MOUNTING-RH	\$ 959.00	
23	MIRROR CAP-RH	\$ 217.00	
24	FRONT TURN SIGNAL INDICATOR-RH	\$ 93.00	
25	SIDE MEMBER TRIM-RH	\$ 723.00	\$ 578.40
26	1 SET OF ATTACHMENT PARTS	\$ 111.00	\$ 88.80
27	1 SET OF ADHESIVE TAPES	\$ 182.00	\$ 145.20
28	FRONT WHEEL HOUSING LINER-RH	\$ 246.00	\$ 196.80
29	WHEEL SHOUSING ATTACHMENT PARTS	\$ 78.00	
30	FRONT STONE CHIP GUARD-RH	\$ 44.00	\$ 34.56
31	FRONT WHEEL SPOILER-RH	\$ 63.00	
32	FRONT ALUMINIUM-RH	\$ 934.00	\$ 747.20
33	RUBBER VALVE	\$ 12.00	
34	SUPPLEMENTARY	\$ 491.00	\$ 386.24
35	SUNDRIES	\$ 300.00	\$ 74.80
	TOTAL SPARE PARTS CHARGES	\$ 12,179.00	\$ 7,540.08
	TOTAL LABOUR CHARGES	\$ 8,732.00	\$ 5,582.00
	GRAND TOTAL	\$ 20,911.00	\$ 13,122.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/741/2018/GW 18-Jul-18 Tony Foong 1 SMA 1237 T Audi A5 SB 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	WASH WATER RESERVIOR	\$ 124.00	\$ 98.80
2	BUNGS	\$ 7.00	
3	SEAL	\$ 54.00	\$ 42.64
4	FRONT FENDER TOP COVER - RH	\$ 30.00	\$ 24.00
5	FRONT FENDER CHROME- RH	\$ 138.00	\$ 110.40
6	FRONT DOOR CHROME TRIM - RH	\$ 138.00	\$ 110.40
	TOTAL	\$ 491.00	\$ 386.24

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMA 1237 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0741/2018/MAS

7 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SMA 1237 T Audi A5 SB 2.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SMA 1237 T**, claimant, **Premium Leasing Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85013307 – S\$12,542.63
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMA 1237 T

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jul 2018		10 Jul 2018 14:42 Edit Adj Rpt	S\$13,122.08 Edit Estimates	S\$13,122.08 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	PREMIUM LEASING PTE LTD, Co. Reg. No.: 201009676M, Tel: +6596546277		
Vehicle Reg. No.:	SMA1237T	Date of Loss:	26/06/2018 18:00 - :59 [29 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 8060251181SG	Policy/Cover Note No.:	D999994958 (Comprehensive)
		Excess:	S\$1,400.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani] Norsazani.Zawaye@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/07/2018]		
Driver/Custodian:	CHUA SIEW LAY FRED A (43 / Female), NRIC: S7503455E, Tel: +6596546277		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> ● AIG_SG (27/11/2018): Alert - Adj Mandate Approved (S\$13122.08) - SMA1237T - Claim Handler: Mohd Zaway... ● AIG_SG (23/10/2018): Alert - Adj Mandate Approved (S\$12126.00) - SMA1237T - Claim Handler: Mohd Zaway... ● AIG_SG (15/10/2018): Alert - Adj Mandate Maintained - SMA1237T - Claim Handler: Mohd Zawaye, Norsazan... ● AIG_SG (12/07/2018): Alert - Adj Mandate Approved (S\$11635.00) - SMA1237T - Claim Handler: Mohd Zaway... ● AIG_SG (12/07/2018): Alert - Adj Mandate Approved (S\$11635.00) - SMA1237T - Claim Handler: Mohd Zaway... ● AIG_SG (12/07/2018): SMA1237T / OD / 26/06/2018 / Coverage & Excess update 		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SMA1237T (8060251181SG)
 OD
 Jun 26 2018 6:00PM
 [PREMIUM LEASING PTE LTD]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View	Use Viewer
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	10/07/18 15:50	Adjuster Immediate Advice							Load HTM		
2	21/09/18 11:30	Adjuster Immediate Advice							Load HTM		
3	21/11/18 17:40	Adjuster Immediate Advice							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
2	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
3	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
4	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
5	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
6	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
7	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
8	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
9	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
10	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
11	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
12	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
13	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
14	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
15	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
16	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
17	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
18	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
19	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
20	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
21	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
22	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
23	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
24	10/07/18 15:34	General View							Load JPG	<input checked="" type="checkbox"/>	
25	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
26	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
27	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
28	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
29	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
30	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
31	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
32	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
33	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
34	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
35	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
36	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
37	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
38	21/09/18 12:21	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	

39	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
47	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
48	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
49	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
50	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
51	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
53	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	21/09/18 12:21	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/07/18 15:40	Singapore Accident Statement	1	Load PDF	
2	10/07/18 15:40	Cover Note	1	Load PDF	
3	10/07/18 15:40	Driver's Driving License	1	Load PDF	
4	10/07/18 15:40	MARK ESTIMATE	1	Load PDF	
5	19/07/18 17:54	SMA 1237T SUPPLEMENTARY ESTIMATE	1	Load PDF	
6	21/11/18 17:40	SMA 1237T FINALISED EST	1	Load PDF	
7	11/01/19 15:17	Supplementary	1	Load PDF	
8	11/01/19 15:17	WORKSHOP INVOICE	1	Load PDF	
9	11/01/19 15:17	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

				View	Use Viewer
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	09/07/18 11:16	Video - Accident	1	Load MP4	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	27/06/18 17:10	Accident Statement	1	Load HTM	
2	09/07/18 11:15	Addendum Sheet	1	Load JPG	<input checked="" type="checkbox"/>
3	09/07/18 11:16	Accident Statement Addm. #1	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	27/06/18 17:03	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>

12	27/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	27/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation					
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	27/06/18 17:09	Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	27/06/18 17:09	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid gray; height: 100px; width: 100%;"></div> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18012512/ACBN2
Date: 11/01/2019

REFERENCE

Insured/Claimant: PREMIUM LEASING PTE LTD Policy No: 0999994958
Date of Loss: 26/06/2018 Nature of Claim: OD Claim No: 8060251181SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA1237T	Engine No:	CVK058480
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF54JA086555
Reg. Date:	28/05/2018 (Man. Year: 2018)	Odometer:	1261 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes	
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Yes

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,542.84	7,540.08	4,002.76	34.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,732.00	5,582.00	3,150.00	36.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,274.84	13,122.08	7,152.76	35.28
- Excess (S\$)	1,400.00	1,400.00	0.00	0.00
(S\$)	18,874.84	11,722.08	7,152.76	37.90
+ GST 7.00/7.00% (S\$)	1,321.24	820.55	500.69	37.90
Nett Amount (S\$)	20,196.08	12,542.63	7,653.45	37.90

INSPECTION

Date of Assignment: 10/07/2018
Date Inspected: 09/07/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Distorted	920.00 FS	*735.60 FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	45.00 FS	*- FS
3	1		*FRONT FENDER CLOSING ELEMENT	Damaged	65.00 FS	*51.60 FS
4	2		*FRONT FENDER BRACKET-LH/RH	Bent	62.00 FS	*48.32 FS
5	1		*FRONT FENDER UPPER BRACKET-LH	Bent	50.00 FS	*40.00 FS
6	1		*FRONT FENDER BRACE-RH	Bent	103.00 FS	*82.40 FS
7	1		*FRONT FENDER COVER	Not Necessary	16.00 FS	*- FS
8	1		*FRONT FENDER CLOSING ELEMENT-RH	Necessary	29.00 FS	*24.16 FS
9	1		*FRONT FENDER TRIM-RH	Not Necessary	138.00 FS	*- FS
10	1		*FRONT DOOR TRIM-RH	Not Necessary	138.00 FS	*- FS
11	1		*BONNET	Dented	2,499.00 FS	*1,999.20 FS
12	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
13	1		*BONNET LID HINGE	Not Necessary	367.00 FS	*- FS
14	1		*FRONT DOOR-RH	Dented	2,153.60 FS	*2,153.60 FS
15	1		*FRONT DOOR OUTER SEAL-RH	Necessary	192.00 FS	*153.20 FS
16	1		*BONDING AGENT	Not Necessary	43.00 FS	*- FS
17	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
18	1		*FRONT DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
19	1		*FRONT DOOR CATCH COVE-RH	Not Necessary	13.00 FS	*- FS
20	1		*FRONT DOOR HINGE HALF UPPER PARTS-RH	Not Necessary	40.00 FS	*- FS
21	1		*FRONT DOOR HINGE HALF LOWER PARTS-RH	Not Necessary	40.00 FS	*- FS
22	1		*EXTERIOR MIRROR MOUNTING-RH	Not Necessary	959.00 FS	*- FS
23	1		*MIRROR CAP-RH	Repair	217.00 FS	*- FS
24	1		*FRONT TURN SIGNAL INDICATOR-RH	Not Necessary	93.00 FS	*- FS
25	1		*SIDE MEMBER TRIM-RH	Deformed	723.00 FS	*578.40 FS
26	1		*SET OF ATTACHMENT PARTS	Necessary	111.00 FS	*88.80 FS
27	1		*SET OF ADHESIVE TAPES	Necessary	182.00 FS	*145.20 FS
28	1		*FRONT WHEEL HOUSING LINER-RH	Deformed	246.00 FS	*196.80 FS
29	1		*WHEELS HOUSING ATTACHMENT PARTS	Not Necessary	78.00 FS	*- FS
30	1		*FRONT STONE CHIP GUARD-RH	Necessary	44.00 FS	*34.56 FS
31	1		*FRONT WHEEL SPOILER-RH	Not Necessary	63.00 FS	*- FS
32	1		*FRONT ALUMINIUM-RH	Cut	934.00 FS	*747.20 FS
33	4		*RUBBER VALVE	Not Necessary	12.00 FS	*- FS
34	1		*SUNDRIES	Necessary	300.00 FS	*74.80 FS
35	1		*WASH WATER RESERVOIR	Deformed	98.80 FS	*98.80 FS
36	1		*BUNGS	Not Necessary	7.00 FS	*- FS
37	1		*SEAL	Necessary	42.64 FS	*42.64 FS
38	1		*FRONT FENDER TOP COVER-RH	Damaged	24.00 FS	*24.00 FS
39	1		*FRONT FENDER CHROME-RH	Necessary	110.40 FS	*110.40 FS
40	1		*FRONT DOOR CHROME TRIM-RH	Necessary	110.40 FS	*110.40 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,542.84 7,540.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	280.00	280.00
3	TO REMOVE FRONT FITTINGS,DISMANTLE FRONT BUMPER ASSY.REMOVE AND RENEW RHS FRONT FENDER,RHS FRONT DOOR AND FITTINGS.INSPECT RHS A PILLAR.REPAIR ALL PANEL AND RENEW BONNET AND ALIGN.RENEW DAMAGED FITTINGS.RE-INSTALL ALL PANEL REMOVED	New	4,200.00	2,250.00
4	TO RESPRAY BONNET,RHS FRONT FENDER,RHS FRONT DOOR,RHS MIRROR COVER AND RHS SILL PANEL	New	3,300.00	2,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			8,732.00	5,582.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >