

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building

069542

Attention : Motor Claim Department

Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000220

Date : 07/07/2018

Vehicle Num. : SLH 149X (LCR)

Make/Model : HONDA SHUTTLE HYBRID

Chassis/Eng# :

Accident Date : 05/07/2018

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID ✓OT		1,350.00
2.	1	REAR BOOT HONDA LOGO EMBLEM ✓NEC		150.00
3.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) ✓NEC		100.00
4.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) ✓NEC		100.00
5.	1	REAR NUMBER PLATE LAMP GARNISH ✓CRK		460.00
6.	1	REAR NUMBER PLATE LAMP X		180.00
7.	2/LH,RH	REAR BOOT REFLECTOR LAMP X	580.00	1,160.00
8.	1	REAR BOOT INNER LOCK X		565.00
9.	1	REAR BOOT HAND GRIP COVER X		65.00
10.	1	REAR BOOT INNER TRIM BOARD ?		345.00
11.	1	REAR BOOT WEATHER STRIP ✓BT		180.00
12.	1	REAR WINDSCREEN GLASS MOULDING ✓NEC		250.00
13.	1	REAR BUMPER ✓DMA		1,150.00
14.	2/LH,RH	REAR BUMPER RETAINER X	120.00	240.00
15.	1	REAR BUMPER TOW COVER X		100.00
16.	2/LH,RH	REAR BUMPER INNER FOAM ?	100.00	200.00
17.	2/LH,RH	REAR BUMPER REFLECTOR GARNISH X	170.00	340.00
18.	2/LH,RH	REAR BUMPER REFLECTOR LENS X	180.00	360.00
19.	1	REAR END PANEL ✓OT		950.00
20.	1	REAR END PANEL TOP GARNISH ✓reform		260.00
21.	1	REAR BOOT TOOLKIT FOAM BOX ?		120.00
22.	1	REAR COMPARTMENT BOX X		420.00
23.	1	REAR FLOOR BOARD X		745.00
24.	2/LH,RH	REAR TAIL LAMP ?	580.00	1,160.00
25.	2/LOWER	REAR TAILLAMP PANEL ?	150.00	300.00
26.	2/UPPER	REAR TAILLAMP PANEL ?	250.00	500.00
List TotalS\$:				11,750.00
20.00% Discount S\$:				2,350.00
				9,400.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000220

Date : 07/07/2018
 Vehicle Num. : SLH 149X (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 05/07/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :				
1.	1	REAR NUMBER PLATE LAMP GARNISH CLIP ✓ NEC	50.00	30 <i>extra</i>
2.	1	REAR BOOT REFLECTOR LAMP CLIP X	50.00	
3.	1	REAR BOOT INNER TRIM BOARD CLIP ✓ NEC	50.00	30
4.	1	REAR BUMPER CLIP ✓ NEC	50.00	30
5.	1	REVERSE SENSOR ✓ DMG	280.00	250
6.	1	REAR END PANEL TOP GARNISH CLIPS ✓ NEC	50.00	30
7.	1	REAR TAILLAMP CLIPS ?	50.00	
8.	1	REAR WINDSCREEN SEALANT ✓ NEC	100.00	50
Special Nett Total S\$:			680.00	
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS			180.00	120
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES			180.00	100
WIRINGS CHECK AND RECTIFY WHERE NECESSARY			120.00	60
TO REMOVE, REINSTALL REAR TRIM, FLOOR CARPERT & SEAT TO FACILITATE REPAIRS.			120.00	60
TO APPLY RUSTPROOFING/ TUFFCOATING TREATMENT NECESSARY.			120.00	60
TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.			380.00	200
TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID			380.00	200

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department

Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000220

Date : 07/07/2018
 Vehicle Num. : SLH 149X (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 05/07/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

CARS UPON COMPLETION OF COLLISION REPAIRS.

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER) (pearl white)	1,500.00	750
---	----------	-----

TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN	2,000.00	1000
--	----------	------

Labour Total S\$:	4,980.00
--------------------	----------

Sathya Sai
 10/7/2018

7 days

- Part by Part repair
- Question mark item photo
- Photo before paint.

E. & O.E.

UKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to approval from Ins

Total S\$ 15,060.00

Acknowledged by Repairer

Signature:

Date:

for WORLD AUTO PTE LTD