



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Ms TAN GEOK KIAN Blk 470 Tampines St 44 #11-200 Singapore 520470	Cust No/Name /Ms Tan Geok Kian Reg No/Reg Date SGZ1193A / 04/10/2017 Date In/Mileage 09/07/2018/ 0 Chassis No KNAFZ411MJ5740971 Engine No G4FGH678892 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim B4U / MK
Contact No Mobile: 98342705	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	09/07/2018/ 18:31	DS	218 / MarsLer	60785
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNTB8088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS			60	80.00
S MIPNTB8088	DIAGNOSTIC/SCANNING			11X	250.00
S MIPNTB8088	TO REPLACE REAR BUMPER,BODY KIT,ETC			600	1800.00
S MIPNTB8088	STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS			me ✓	100.00
S MIPNT98088	TO APPLY SEALANT KIT ON REAR BODY KIT			840	1260.00
M SUK11010115-K3	K3 BODY KIT	1.00	1177.00	0.00	1177.00
M KS 86611 A7 B10	COVER-REAR BUMPER	1.00	688.00	0.00	688.00
M KS 86695 A7 B10	COVER-REAR BUMPER,CE	1.00	347.00	0.00	347.00
M KS 92405 A7 500	LH REFLECTOR REFLEX	1.00	99.00	0.00	99.00
M KS 86613 A7 001	LH SIDE BRACKET - RE	1.00	29.00	0.00	29.00
M KS 86614 A7 001	RH SIDE BRACKET - RE	1.00	29.00	0.00	29.00
M KS 06032 50 037A	FASTERNER- BUMPER	10.00	2.00	0.00	20.00
M KS 95720 A7 0009 P	ULTRASONIC SENSOR AS	1.00	177.00	0.00	177.00
2 NOTES	ACCIDENT ON 04/07/2018 ALONG LORONG 6 TOA PAYOH OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # FBL1602U TP INS : AXA <i>Not Affected</i> <i>2 day</i> <i>12/7/18</i> <i>the ph. before pay.</i> <i>P/P</i> <i>3420</i>				
Confirm & accepted by		Parts			2,566.00
		Labour			0.00
		Standard Menu			0.00
		Specialist Job			3,490.00
		Others(Lub,etc)			0.00
		Sundry			0.00
		Total(w/o GST)			6,056.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info														
AXA Insurance Pte Ltd 8 Shenton Way #27-01 AXA Tower, Singapore 068811 Attn: Motor Claims Contact No 63387288	<table> <tr> <td>Cust No/Name</td><td>/Ms Tan Geok Kian</td></tr> <tr> <td>Reg No/Reg Date</td><td>SGZ1193A / 04/10/2017</td></tr> <tr> <td>Date In/Mileage</td><td>02/07/2019/ 34537</td></tr> <tr> <td>Chassis No</td><td>KNAFZ411MJ5740971</td></tr> <tr> <td>Engine No</td><td>G4FGHH678892</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO K3 1.6 A SX SR</td></tr> <tr> <td>Colour/Trim</td><td>B4U / WK</td></tr> </table>	Cust No/Name	/Ms Tan Geok Kian	Reg No/Reg Date	SGZ1193A / 04/10/2017	Date In/Mileage	02/07/2019/ 34537	Chassis No	KNAFZ411MJ5740971	Engine No	G4FGHH678892	Make/Model	KIA/CERATO K3 1.6 A SX SR	Colour/Trim	B4U / WK
Cust No/Name	/Ms Tan Geok Kian														
Reg No/Reg Date	SGZ1193A / 04/10/2017														
Date In/Mileage	02/07/2019/ 34537														
Chassis No	KNAFZ411MJ5740971														
Engine No	G4FGHH678892														
Make/Model	KIA/CERATO K3 1.6 A SX SR														
Colour/Trim	B4U / WK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000008	Credit	12/07/2019/ 08:25	DS	218 / MarsLer	60785				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
S	MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							60.00
S	MIPNT88088	TO REPLACE REAR BODY KIT,ETC -REPAIR REAR BUMPER STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS							600.00
S	MIPNT88088	TO APPLY SEALANT KIT ON REAR BODY KIT							100.00
S	MIPNT98088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							840.00
M	SUK11010115-K3	K3 BODY KIT			1.00	1800.00	0.00	1800.00	
M	KS 0G032 50 037A	FASTENER- BUMPER			10.00	2.00	0.00	20.00	
Z	NOTES ACCIDENT ON 04/07/2018 ALONG LORONG 6 TOA PAYOH OWNER CLAIMING THIRD PARTY LOSS OF USE 02DAYS TP # FBL1602U TP INS : AXA								
Confirm & accepted by					Parts			1,820.00	
					Labour			0.00	
					Standard Menu			0.00	
					Specialist Job			1,600.00	
					Others(Lub,etc)			0.00	
					Sundry			0.00	
					Total(w/o GST)			3,420.00	

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.