



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD

EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
Ms TAN GEOK KIAN Blk 470 Tampines St 44 #11-200 Singapore 520470	Cust No/Name /Ms Tan Geok Kian Reg No/Reg Date SGZ1193A / 04/10/2017 Date In/Mileage 09/07/2018/ 0 Chassis No KNAFZ411MJ5740971 Engine No G4FGHH678892 Make/Model KIA/CERATO K3 1.6 A SX SR Colour/Trim B4U / WK
Contact No Mobile: 98342705	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00001	Cash	09/07/2018/ 18:31	DS	218 / MarsLer	60785
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
S MIPNT88088	TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS				80.00
S MIPNT88088	DIAGNOSTIC/SCANNING				250.00
S MIPNT88088	TO REPLACE REAR BUMPER,BODY KIT,ETC				1800.00
S MIPNT88088	STRAIGHTEN,REFORM,ALIGN ON REAR ACCIDENT AFFECTED AREAS				100.00
S MIPNT88088	TO APPLY SEALANT KIT ON REAR BODY KIT				1260.00
S MIPNT88088	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS				
M SUK11010115-K3	K3 BODY KIT	1.00	1177.00	0.00	1177.00
M KS 86611 A7 810	COVER-REAR BUMPER	1.00	688.00	0.00	688.00
M KS 86695 A7 810	COVER-REAR BUMPER,CE	1.00	347.00	0.00	347.00
M KS 92405 A7 500	LH REFLECTOR REFLEX	1.00	99.00	0.00	99.00
M KS 86613 A7 001	LH SIDE BRACKET - RE	1.00	29.00	0.00	29.00
M KS 86614 A7 001	RH SIDE BRACKET - RE	1.00	29.00	0.00	29.00
M KS 0G032 50 037A	FASTERNER- BUMPER	10.00	2.00	0.00	20.00
M KS 95720 A7 0009 P	ULTRASONIC SENSOR AS	1.00	177.00	0.00	177.00
Z NOTES	ACCIDENT ON 04/07/2018 ALONG LORONG 6 TOA PAYOH OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # FBL1602U TP INS : AXA				
Confirm & accepted by		Parts			2,566.00
		Labour			0.00
		Standard Menu			0.00
		Specialist Job			3,490.00
		Others(Lub,etc)			0.00
		Sundry			0.00
		Total(w/o GST)			6,056.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- No illegal modification

Signature: _____ Date: _____

Not Added
2/17/18

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.