

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

9-Jul-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8043 T

1 pc	Rear o/s floor side panel <i>X/m</i>	\$	65.00
1 pc	Rear o/s air vent <i>?</i>	\$	30.00
1 pc	Rear o/s tail lamp <i>X</i>	\$	421.00
1 pc	Rear o/s fender <i>/</i>	\$	1,205.00
1 pc	Rear o/s fender inner shield <i>?</i>	\$	120.00
1 pc	Rear windscreen moulding <i>/</i>	\$	87.00
1 pc	Rear bumper <i>/</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X/</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 <i>X</i>	\$	58.00
1 pc	Rear bumper reflector o/s <i>X</i>	\$	46.00
1 pc	Rear o/s lower arm <i>?</i>	\$	351.00
1 pc	Rear o/s shock absorber <i>?</i>	\$	313.00
1 pc	Rear o/s trailing arm <i>?</i>	\$	159.00
1 pc	Rear o/s assist arm <i>?</i>	\$	163.00
1 pc	Rear o/s bearing <i>?</i>	\$	349.00
1 pc	Rear o/s upper arm <i>?</i>	\$	84.00
1 pc	Hub & Bearing Assy- Rear <i>?</i>	\$	349.00
1 pc	Rear o/s knuckle arm <i>?</i>	\$	525.00
1 pc	Rear o/s fender inner trim <i>?</i>	\$	184.00
1 pc	Rear o/s rim <i>?</i>	\$	246.00
1 pc	Rear o/s wheel cover <i>/</i>	\$	116.00
		\$	5,773.00
Less 10%		\$	577.30
		\$	5,195.70

S/NETT

1 set	Rear bumper clips <i>/</i>	\$	48.00
1 set	Rear fender inner shield clips <i>X</i>	\$	38.00
1 pc	Rear o/s fender sticker <i>/</i>	\$	60.00
1 pc	Rear bumper top protector <i>X</i>	\$	80.00 50
1 pc	Sealant <i>/</i>	\$	50.00 40

9-Jul-17

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8043 T

Towing Fee	\$ 50.00	✓
Sundry	\$ 50.00	20
To check wheel alignment	\$ 80.00	60
To dismantle / replace exhaust pipe	\$ 80.00	X
To dismantle and refit rear windscreen	\$ 120.00	100
To dismantle and replace the rear o/s undercarriage	\$ 250.00	100
To dismantle / refit reverse sensor to new bumper and reset to the same	\$ 120.00	50
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00	50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender, rear o/s side panel. Including knock-out, straighten, repair, reshape and adjust of the rear o/s fender inner panel	\$ 1,200.00	600
To putty and spray painting on rear bumper, rear o/s fender, rear o/s side panel, rear o/s fender inner panel	\$ 900.00	720
To apply rustproofing on the repaired and replaced panels.	\$ 200.00	50
	<u>\$ 8,701.70</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**

Kalvin CICK
10/7/18 1320hrs
5 Days
P/P
Before Part photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: