



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE

Company Registration No. 201118055N

ESTIMATE

Karz-Ta Leasing
317 Outram Road #B1-03 Concorde Shopping
Centre Singapore 169075

Contact : 83223232

Code : C101811

Date in : 09/07/2018

Vehicle Num. : SLP4037S

Model : TOYOTA VIOS 1.5E CVT

Chassis/Eng# : MHFB29F3202011955/2NRX159118

Not Allowed
haha
no need
take the other
rep
4 days
10/7/18
H/S

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
Front Door Black Tape LH	1 <i>rec</i>	49.78	49.78
Front Door Cabin Weather Strip LH	1 <i>rec</i>	311.67	311.67
Front Door Checker LH	1	120.15	120.15 ?
Front Door Hinge LH	2	75.30	150.60 ?
Front Door Inner Trimboard LH	1	759.85	759.85 ?
Front Door LH	1 <i>BY D</i>	1001.79	1,001.79 ✓
Front Door Lock Striker LH	1 <i>u y</i>	27.80	27.80 X
Front Door Mechanism Lock LH	1	331.60	331.60 ?
Front Door Regulator LH	1	197.68	197.68 ?
Front Door Regulator Motor LH	1	520.30	520.30 ?
Front Door Sash Channel LH	1 <i>u y</i>	145.60	145.60 X
Front Door Weather Strip LH	1 <i>rec</i>	153.60	153.60 ✓
Front Fender Inner Shield LH	1 <i>u y</i>	147.80	147.80 X
Front Fender LH	1 <i>u</i>	544.09	544.09 X
Rear Door Black Tape LH	1 <i>rec</i>	48.70	48.70 ✓
Rear Door Cabin Weather Strip LH	1 <i>u y</i>	299.60	299.60 X
Rear Door Checker LH	1	118.60	118.60 ?

page 1

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

Rear Door Hinge LH	2	17	78.34	156.68	α
Rear Door Inner Trimboard LH	1	17	721.60	721.60	α
Rear Door LH	1	10/24	989.76	989.76	—
Rear Door Lock Striker LH	1	17	25.60	25.60	X
Rear Door Mechanism Lock LH	1	17	298.70	298.70	α
Rear Door Regulator LH	1		189.75	189.75	?
Rear Door Regulator Motor LH	1		498.74	498.74	?
Rear Door Sash Channel LH	1		133.77	133.77	?
Rear Door Weather Strip LH	1	24	148.67	148.67	—
Rear Fender Inner Shield LH	1	17	75.60	75.60	α
Rear Fender LH	1	2	898.67	898.67	α
Subtotal before discount				9,066.75	
Percentage discount 25%				2,266.69	
Sub-total 1				6,800.06	
Front Door Inner Trimboard Clips LH (Set)(SN)	1	24	30.00	30.00	—
Front Fender Inner Shield Clips LH (Set)(SN)	1	17	30.00	30.00	α
Rear Door Inner Trimboard Clips LH (Set)(SN)	1	24	30.00	30.00	—
Rear Fender Inner Shield Clips LH (Set)(SN)	1	17	30.00	30.00	α
Subtotal before discount				120.00	
Percentage discount 0%				0.00	
Sub-total 2				120.00	
Parts-total				6,920.06	



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE

Company Registration No. 201118055N

LABOUR

Description	Price
To diagnose, replace and/or repair to rectify front door electrical system for proper functioning	60 120.00
To diagnose, replace and/or repair to rectify rear door electrical system for proper functioning	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80 80.00
To transfer front door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	60 120.00
To transfer rear door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle	60 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1000 1,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600 900.00
To apply anti-rust chemical on repaired and replaced panel.	60 120.00
Labour Total	2,740.00
Parts & Labour Total	9,660.06