

SSS EC. BY:

REF: CS/CTL18012530/Number

Special Instruction:

SUNVAJOR: Bathya ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTL Date/Time: 10/7/2018 1:47pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 2347Y Insured: STJ 3558S

at Workshop m/s: Sin Yew Hup Tel: 6760089

of: Bk D4 Yew Tee Ind Est 393m

Policy No: DMPCSN 3086431701 Claim No: SNM18D 03386C02

Sum Insured: Excess:

Make of Veh: D.O.A. 08/7/2018 (Client's Record)

CA / REV / REP. / REV 24 HRS WP: H.O.D. Endorsement:


Date/Time: 10/7/2018 2:17pm Person Contacted: Yong Jian Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHF 2347Y - X
	STJ 3558S - NA / CTL 7015159 / H4 RA: 000317
23/7 11:00am	Bathya confirmed R & \$2250 and 6 days with Yong Jian. (Red 1186f, 24%)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Veh No: **SGF 2347 Y** Yr Regn: **Apr / 2006**
 Type: M.Car / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Toyota Vios** c.c: **1497**
 Colour: **silver** A/C: Insured / Std / NI / NA
 Sp. Reading: **140406** T/Radio: Insured / Std / NI / NA
 Eng/No: **INZX390396**
 C/No: **MR053HY4204178042**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size F: **195/50 R15**
 R: **195/50 R15**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Westlake (Rear), Michelin (Front)**

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 8/7/2018	D.O.I. 10/7/2018

 Survey held at **Sin Yew Hup**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Sathya, pls see my remarks.
	RECEIVED 29 OCT 2018
	<i>[Signature]</i>
	11/7

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to? _____
 2) _____
 Report Format : **TP**
 Lump Sum / I.B.I: (\$) **2250/-**

Days Of Repair: **6**
 Resurvey No. of Trip: **2**
 Survey Fee: **220**

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech Invs (\$)
 Weekend (\$)

Transportation: _____
 Photos: _____
 Other: _____
 TOTAL: **220**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2018 Sendback Est	09 Jul 2018 18:18 S\$3,436.00	10 Jul 2018 13:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			
Insured:	UNKNOWN, Co. Reg. No.: 0		
Main Claimant:	ZAWAWI BIN BUANG, ID: S1506352A		
Vehicle Reg. No.:	SGF2347Y	Date of Loss:	08/07/2018 21:00 - :59 [147 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03386C02	Policy/Cover Note No.:	DMPCSN3086431701
Vehicle Reg. No. (Insured):	SJJ3558S	Policy No. (Claimant):	A80448374QMX
		Excess:	S\$0.00
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/07/2018]		
Driver/Custodian (Insured):	LEE CHUAN HOE (/ Male), NRIC: S1587285C		
Adj Asg. Remarks:	EST \$3676.52, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807
 Tel: (65) 6827 7888 Fax: (65) 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G


Certificate of Insurance

ORIGINAL

ROAD TRANSPORT ACT 1987 (MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
 THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
 (REPUBLIC OF SINGAPORE)
 THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1 Individual Ownership	MOTOR MAX Comprehensive
Certificate No. A 80448374 QMX	Excess : SGD500 Windscreen Excess : SGD100
<p>1. Index Mark and Registration Number of Vehicle SGF2347Y</p> <p>2. Name of Policyholder ZAWAWI BUANG</p> <p>3. Effective Date of the Commencement of Insurance for the purposes of the Act 15/11/2017</p> <p>4. Date of Expiry of Insurance 14/11/2018</p> <p>5. Persons or Classes of Persons entitled to drive*</p> <p>ZAWAWI BUANG Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.</p> <p>* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>6. Limitations as to use*</p> <p>Use only for social domestic and pleasure purposes and for the Policyholder's business. The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</p> <p>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</p>	
<p>PLEASE NOTE ALL CLAIMS RELATED REPAIR MUST BE CARRIED OUT AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.</p> <p>This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).</p>	

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.



 Signature / Date

Counter-Signatory:
iMotor Insure

MSIG Insurance (Singapore) Pte. Ltd.
 Approved Insurers



Amy Ler
 Senior Vice President, Agencies

This certificate is not valid unless it is signed for & on behalf of the Company and Counter-Signed by a duly authorised representative of the Counter-Signatory.

XIMOTCLHH2017111414075694

DRIVER DETAIL Pg. 1

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1506352A



Name
ZAWAWI BIN BUANG
زواوي بن بوانغ
Race
MALAY
Date of Birth
15-06-1961
Sex
M
Country of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number
S1506352A
Name
ZAWAWI BIN BUANG
Birth Date: 15 Jun 1961
Issue Date: 08 Oct 2003



2034905



NRIC No S1506352A



Blood Group Date of issue
A+ 17-05-1994

APT BLK 610 SENJA ROAD #13-22
SINGAPORE 670610
NRIC No: S1506352A Date: 18-12-2000 No: 3730986

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 3500 kilograms	11 Jul 1981

NP 428A



Licence No: S1506352A

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6352A
Vehicle Details	
Vehicle No.:	SGF2347Y
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1NZX390396
Chassis No.:	MR053HY4204178042
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,040.00
Original Registration Date:	04 Apr 2006
First Registration Date:	04 Apr 2006
Transfer Count:	1
Actual ARF Paid:	\$14,344.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$23,039.00
COE Rebate Amount:	\$11,396.00
Total Rebate Amount:	\$11,396.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/07/2018 13:35
Date Of Accident	08/07/2018 21:35
Exact Location Of Accident	ALONG TPE-->SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGF2347Y
Insured/Policyholder	
Name Of Registered Owner	ZAWAWI BIN BUANG
NRIC No	S1506352A
Email Address	ZAWAWI61@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91261700
Alternative Phone No	OFFICE-91261700

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80448374QMX
Cover Note Number	

Driver

Name of Driver	ZAWAWI BIN BUANG
NRIC No	S1506352A
Date Of Birth	15/06/1961
Occupation	INDOOR
Date Of Driving Pass	11/07/1981
Driving Experience	36 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91261700
Fax Number	
Contact Number	OFFICE-91261700
E-Mail Address	ZAWAWI61@GMAIL.COM

Address	APT BLK 610 SENJA ROAD #13-22 SINGAPORE
Postcode	670610
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ZAINAB BTE AHMAD
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG
Police Station Address	ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ3558S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE CHUAN HOE
NRIC/Passport Number	S1587285C
Contact Number	81131410
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CONFIDENTIAL



NOTICE OF COMPLIANCE

1. This is to inform that Zawawi Bin Buang NRIC S1506352A, HP 91261700 residing at Blk 610 Senja Road #13-22 has report to the Police a non-injury traffic accident which occurred at Tampines Expressway on 08/07/2018 at 2135hrs involving the following vehicles:

- I SGF2347Y (Grey, Toyota Vios)
- II SJJ3558S (Black, Honda)


2. If the accident was reported to Police within 24 hours of its accident occurrence, He/she therefore has complied with Sec 84(2) of the Road Traffic Act, 276

Rank/Name of Issuing Officer: SGT Kai Ze Chua *k*

Date : 08/07/2018

S/D Ref : 222

Police Post/ Unit : Bukit Panjang NPC



Original - To issue to informant
Duplicate - To be retained at NPC or Police Post

CONFIDENTIAL



新友合汽车私人有限公司
SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
UNKNOWN

Singapore

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/07/2018
Vehicle Reg. No.:	SGF2347Y	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	LEE CHUAN HOE
Driver (TP):	ZAWAWI BIN BUANG		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	04/04/2006
Vehicle Colour:	METALLIC SILVER	Chassis No:	MR053HY4204178042
Engine No:	1NZX390396		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLEASE REFER TO THE ATTACHED SKETCH PLAN.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,086.00
Miscellaneous Items	0.00
Labour	2,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,436.00
+ GST 7.00% (S\$)	240.52
Nett Amount (S\$)	3,676.52

This claim is handled by: LIM JING YEE

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jul 2018)
Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT LID ✓DT - photo to show damaged	0.00	0.00	*225.00 F
2	1		*REAR BOOT LID LOCK ✓cut	0.00	0.00	*18.00 F
3	1		*VIOS EMBLEM ✓NEC	0.00	0.00	*12.00 F
4	1		*TOYOTA LOGO EMBLEM ✓NEC	0.00	0.00	*18.00 F
5	1		*VVTI EMBLEM ✓NEC	0.00	0.00	*15.00 F
6	1		*1.5 EMBLEM ✓NEC	0.00	0.00	*12.00 F
7	1		*E EMBLEM ✓NEC	0.00	0.00	*15.00 F
8	1		*REAR BOOT LID WEATHERSTRIP ✓BT	0.00	0.00	*30.00 F
9	2		*TAIL LAMP LH? RH ✓CRK	0.00	0.00	*150.00 F
10	1		*REAR BUMPER ✓CRK	0.00	0.00	*120.00 F
11	2		*REAR BUMPER SIDE RETAINER ?	0.00	0.00	*20.00 F
12	4		*REAR BUMPER CLIP ✓NEC	0.00	0.00	*6.00 F
13	1		*REAR END PANEL ✓DT	0.00	0.00	*210.00 F
14	1		*REAR END PANEL TOP GARNISH ✓deform	0.00	0.00	*35.00 F
15	1		*REAR BUMPER SENSOR ✓DMG	0	0.00	*200.00 FS
Total Parts (S\$)						1,086.00

F=Franchise part. S=SpcNett.

Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove and refit the rear boot mechanism	New	40.00 ✓NEC
2	To remove and refit fender inner trim x2, rear end panel top garnish ✓NEC	New	60.00 50
3	To antirust the affected portion ✓NEC	New	50.00
4	To putty and spray paint rear boot lid in and out, rear bumper, rear end panel, tail lamp panel x2, rear fender LH and RH, floor panel	New	1,200.00 850
5	To remove and refit rear boot, rear bumper, tail lamp x2, cut and weld rear end panel, panel beat tail lamp panel x2, floor panel	New	1,000.00 750
Gross Labour Cost (S\$)			2,350.00

Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sathya Sai
10/7/2018

5 - 6 days

- Lump Sum Repair
- Question mark item photo
- Photo after paint


11/7/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
 Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
 Co./GST Regn. No. 200921075G Specialise in Insurance Claims and General Motor Repair Work

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
UNKNOWN

Singapore

Claimant Insurer: MSIG Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/07/2018
Vehicle Reg. No.:	SGF2347Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ZAWAWI BIN BUANG	Driver (Insured):	LEE CHUAN HOE
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	04/04/2006
Vehicle Colour:	METALLIC SILVER		
Engine No:	1NZX390396	Chassis No:	MR053HY4204178042
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLEASE REFER TO THE ATTACHED SKETCH PLAN.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,086.00
Miscellaneous Items	0.00
Labour	2,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,436.00
+ GST 7.00% (S\$)	240.52
Nett Amount (S\$)	3,676.52

This claim is handled by: LIM JING YEE

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jul 2018)
Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT LID ✓DT	0.00	0.00	*225.00 F
2	1		*REAR BOOT LID LOCK ✓LUT	0.00	0.00	*18.00 F
3	1		*VIOS EMBLEM ✓NEC	0.00	0.00	*12.00 F
4	1		*TOYOTA LOGO EMBLEM ✓NEC	0.00	0.00	*18.00 F
5	1		*VVTI EMBLEM ✓NEC	0.00	0.00	*15.00 F
6	1		*1.5 EMBLEM ✓NEC	0.00	0.00	*12.00 F
7	1		*E EMBLEM ✓NEC	0.00	0.00	*15.00 F
8	1		*REAR BOOT LID WEATHERSTRIP ✓BT	0.00	0.00	*30.00 F
9	2		*TAIL LAMP LH? CRK ✓CRK	0.00	0.00	*150.00 F
10	1		*REAR BUMPER ✓CRK	0.00	0.00	*120.00 F
11	2		*REAR BUMPER SIDE RETAINER ? CRK ✓	0.00	0.00	*20.00 F
12	4		*REAR BUMPER CLIP ✓NEC	0.00	0.00	*6.00 F
13	1		*REAR END PANEL ✓DT	0.00	0.00	*210.00 F
14	1		*REAR END PANEL TOP GARNISH ✓deform	0.00	0.00	*35.00 F
15	1		*REAR BUMPER SENSOR ✓DMG	0	0.00	*200.00 FS
Total Parts (S\$)						1,086.00

F=Franchise part. S=SpcNett.

Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS


 Rasul
 16/07/18

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove and refit the rear boot mechanism	New	40.00 ✓NEC
2	To remove and refit fender inner trim x2, rear end panel top garnish ✓NEC	New	60.00 50
3	To antirust the affected portion ✓NEC	New	50.00
4	To putty and spray paint rear boot lid in and out, rear bumper, rear end panel, tail lamp panel x2, rear fender LH and RH, floor panel	New	1,200.00 850
5	To remove and refit rear boot, rear bumper, tail lamp x2, cut and weld rear end panel, panel beat tail lamp panel x2, floor panel	New	1,000.00 750
Gross Labour Cost (S\$)			2,350.00

Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Sathya San
10/7/2018

5 - 6 days

- Lump Sum Repair
- Question mark item photo
- Photo after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



新友合汽車私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677881
Tel: 6760 0819 Fax: 6769 0221 Email: cyhapl@singnet.com.sg

CO, GST Reg. No. 200921C710

Specialise in Insurance Claims and General Motor Repair Work.

TP INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**
UNKNOWN

Singapore

Claimant Insurer: **MSIG Insurance (Singapore) Pte. Ltd.**

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/07/2018
Vehicle Reg. No.:	SGF2347Y	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	LEE CHUAN HOE
Driver (TP):	ZAWAWI BIN BUANG		
Make/Model:	TOYOTA VIOS, 1.5 E (A)	Vehicle Reg. Date:	04/04/2006
Vehicle Colour:	METALLIC SILVER	Chassis No:	MR053HY4204178042
Engine No:	1NZX390396		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	PLEASE REFER TO THE ATTACHED SKETCH PLAN.		
Present Location:	SIN YEW HUP AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,086.00
Miscellaneous Items	0.00
Labour	2,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,436.00
+ GST 7.00% (S\$)	240.52
Nett Amount (S\$)	3,676.52

This claim is handled by: **LIM JING YEE**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jul 2018)
 Parts: 143 TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT LID ✓DT	0.00	0.00	*225.00 F
2	1		*REAR BOOT LID LOCK ✓LUT	0.00	0.00	*18.00 F
3	1		*VIOS EMBLEM ✓NEC	0.00	0.00	*12.00 F
4	1		*TOYOTA LOGO EMBLEM ✓NEC	0.00	0.00	*18.00 F
5	1		*VVTI EMBLEM ✓NGC	0.00	0.00	*15.00 F
6	1		*1.5 EMBLEM ✓NGC	0.00	0.00	*12.00 F
7	1		*E EMBLEM ✓NEC	0.00	0.00	*15.00 F
8	1		*REAR BOOT LID WEATHERSTRIP ✓BT	0.00	0.00	*30.00 F
9	2		*TAIL LAMP LH ² ✓R+VCRK	0.00	0.00	*150.00 F
10	1		*REAR BUMPER ✓CRK	0.00	0.00	*120.00 F
11	2		*REAR BUMPER SIDE RETAINER ? ✓CR ✓	0.00	0.00	*20.00 F
12	4		*REAR BUMPER CLIP ✓NEC	0.00	0.00	*6.00 F
13	1		*REAR END PANEL ✓DT	0.00	0.00	*210.00 F
14	1		*REAR END PANEL TOP GARNISH ✓deform	0.00	0.00	*35.00 F
15	1		*REAR BUMPER SENSOR ✓0.114	0	0.00	*200.00 FS

F=Franchise part, S=SpcNett.

Total Parts (S\$)

1,086.00

Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Total Part 1,086.00 ✓
 Labour 1,140.00 ✓

 2,226.00 ✓
 HS 20% 565.20

 2,260.80 ✓

Rasul
 16/07/18

L/S ~\$2,250.00 @ 6 days

confirmed.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove and refit the rear boot mechanism	New	40.00 ✓NEC
2	To remove and refit fender inner trim x2, rear end panel top garnish ✓NEC	New	60.00 50
3	To antirust the affected portion ✓NEC	New	50.00
4	To putty and spray paint rear boot lid in and out, rear bumper, rear end panel, tail lamp panel x2, rear fender LH and RH, floor panel	New	1,200.00 850
5	To remove and refit rear boot, rear bumper, tail lamp x2, cut and weld rear end panel, panel beat tail lamp panel x2, floor panel	New	1,000.00 750
Gross Labour Cost (S\$)			1,740 2,350.00

Sin Yew Hup Auto Pte Ltd/SGF2347Y/09/07/2018 18:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Suthya San
10/7/2017

5 - 6 days

- Lump Sum Repair
- Question mark item photo
- Photo after paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jul 2018 Sendback Est	09 Jul 2018 18:18 S\$3,436.00	10 Jul 2018 13:47 Edit Adj Rpt	S\$2,250.00 Edit Estimates	S\$2,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	UNKNOWN , Co. Reg. No.: 0								
Main Claimant:	ZAWAWI BIN BUANG , ID: S1506352A								
Vehicle Reg. No.:	SGF2347Y	Date of Loss:	08/07/2018 21:00 - :59 [147 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03386C02	Policy/Cover Note No.:	DMPCSN3086431701						
Vehicle Reg. No. (Insured):	SJJ3558S	Policy No. (Claimant):	A80448374QMX						
		Excess:	S\$0.00						
Repairer:	Sin Yew Hup Auto Pte Ltd (HQ) Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate, 677981 Woodlands - Tel: 67600819								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 19/07/2018]								
Driver/Custodian (Insured):	LEE CHUAN HOE (/ Male), NRIC: S1587285C								
Adj Asg. Remarks:	EST \$3676.52, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGF2347Y (SNM18D03386C02)
[SJJ3558S]
TP
ZAWAWI BIN BUANG
Jul 8 2018 9:00PM
[UNKNOWN]
Sin Yew Hup Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Assessment Reports			1 per page <input type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail Print
1	09/07/18 13:50	Accident Statement	Load HTM
2	09/07/18 18:18	Repairer Estimates	Load HTM
Photos/Images			3 per page <input type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail Print
1	09/07/18 13:45	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
2	09/07/18 13:45	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
3	09/07/18 13:45	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
4	09/07/18 13:45	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
5	09/07/18 13:45	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
6	09/07/18 13:45	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
7	09/07/18 13:45	Accident Photo [Linked Accident Report Documents]	Load JPG <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
2	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
3	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
4	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
5	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
6	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
7	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
8	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
9	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
10	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
11	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
12	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
13	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
14	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
15	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
16	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
17	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
18	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
19	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
20	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
21	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
22	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>
23	11/07/18 10:46	General View	Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
24	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/07/18 10:46	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
30	11/07/18 10:46	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
31	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/07/18 10:46	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/07/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	24/07/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	24/07/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	24/07/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	24/07/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	24/07/18 10:04	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	29/10/18 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	29/10/18 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	29/10/18 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	29/10/18 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	29/10/18 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	29/10/18 12:25	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sin Yew Hup Auto Pte Ltd (HQ)	Thumbnail	Print
1	09/07/18 13:47	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	09/07/18 13:47	Accident Sketch Plan [Linked Accident Report Documents]	 Load TIF	
3	09/07/18 13:47	POLICE NOTICE OF COMPLIANCE [Linked Accident Report Documents]	 Load TIF	
4	09/07/18 13:47	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	 Load TIF	
5	09/07/18 13:47	DRIVER DETAIL [Linked Accident Report Documents]	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012530/NRBE2

Date: 30/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN3086431701	
Claimant Vehicle No: SGF2347Y	Insured Vehicle No: SJJ3558S	
Date of Loss: 08/07/2018	Nature of Claim: TP	Claim No: SNM18D03386C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGF2347Y	Engine No: 1NZX390396
Make & Model: TOYOTA VIOS, 1.5 E (A)	Chassis No: MR053HY4204178042
Reg. Date: 04/04/2006 (Man. Year: 2006)	Odometer: 140406 km
Colour: Silver	
Engine Capacity: 1497 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 195/50 R15	Rear Tyre Size: 195/50 R15
Front Left Side: Michelin 6 mm	Rear Left Side: West Lake 6 mm
Front Right Side: Michelin 6 mm	Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,086.00	1,086.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,350.00	1,740.00	610.00	25.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,436.00	2,826.00	610.00	17.75
Approved Total (Overridden) (S\$)		2,250.00		
	(S\$)	3,436.00	2,250.00	1,186.00
	+ GST 7.00/7.00% (S\$)	240.52	157.50	83.02
	Nett Amount (S\$)	3,676.52	2,407.50	1,269.02

INSPECTION

Date of Assignment: 10/07/2018	Present Location: Sin Yew Hup Auto Pte Ltd (HQ)	
Date Inspected: 10/07/2018	Inspected At: Sin Yew Hup Auto Pte Ltd (HQ)	
	Blk D4 Woodlands Road 393M, Yew Tee Industrial Estate	
	Singapore 677981	

Estimated Period of Repair: 6.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGF2347Y)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	225.00 F	*225.00 F
2	1		*REAR BOOT LID LOCK	Cut	18.00 F	*18.00 F
3	1		*VIOS EMBLEM	Necessary	12.00 F	*12.00 F
4	1		*TOYOTA LOGO EMBLEM	Necessary	18.00 F	*18.00 F
5	1		*VVTI EMBLEM	Necessary	15.00 F	*15.00 F
6	1		*1.5 EMBLEM	Necessary	12.00 F	*12.00 F
7	1		*E EMBLEM	Necessary	15.00 F	*15.00 F
8	1		*REAR BOOT LID WEATHERSTRIP	Bent	30.00 F	*30.00 F
9	2		*TAIL LAMP	Cracked	150.00 F	*150.00 F
10	1		*REAR BUMPER	Cracked	120.00 F	*120.00 F
11	2		*REAR BUMPER SIDE RETAINER	Cracked	20.00 F	*20.00 F
12	4		*REAR BUMPER CLIP	Necessary	6.00 F	*6.00 F
13	1		*REAR END PANEL	Dented	210.00 F	*210.00 F
14	1		*REAR END PANEL TOP GARNISH	Deformed	35.00 F	*35.00 F
15	1		*REAR BUMPER SENSOR	Damaged	200.00 FS	*200.00 FS
Total Parts (S\$)					1,086.00	1,086.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To remove and refit the rear boot mechanism	New	40.00	40.00
2	To remove and refit fender inner trim x2, rear end panel top garnish	New	60.00	50.00
3	To antirust the affected portion	New	50.00	50.00
4	To putty and spray paint rear boot lid in and out, rear bumper, rear end panel, tail lamp panel x2, rear fender LH and RH, floor panel	New	1,200.00	850.00
5	To remove and refit rear boot, rear bumper, tail lamp x2, cut and weld rear end panel, panel beat tail lamp panel x2, floor panel	New	1,000.00	750.00
			Gross Labour Cost (S\$)	2,350.00
				1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >