

SS REC. BY:

REF: CS/CT48012532/Ksbnz

Special Instruction:

Survivor

Kenneth

ASSIGNMENT (Office)

Marmen

From (Person):

Chung Soon Sen

of CTL

Date/Time: 10072018 206pm

Estimated Cost:

Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGL 303E

Insured:

SJR 7364R

at Workshop m/s

Cheng Hoe

Tel:

6755 6142

of

Bik 1019 Yishun Ind Park A #01-374

Policy No:

DMPCSN 301521801

Claim No:

SNM18D03148C02.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25062018

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time:

10072018 213pm

Person Contacted:

Sharon

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGL 303E - CCG /ATG12014434/Kbl+2w2

DA: 140712

SJR 7364R - X

10/12

L1 Rm @ Good Carpenters Etc

ASS. REC. BY:

REF:

072 /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL 303E

Yr Regn:

08, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Odyssey

c.c

2354

Colour:

H. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

141082

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RB1 - 1300186

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

25/11/18

D.O.I.

10/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/7 File pass to Carhenge

18/12/18 Confirmed HS \$ 6,000/- @ 8 days with Kenneth
(\$ 2,487.00 Rd - 29%)

RECEIVED

Date/Time, File Pass to?

18/12/18



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

6,000/- HS

220

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018 Sendback Est	10 Jul 2018 12:44 S\$8,302.00	10 Jul 2018 14:06 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	MUNINDRA NATH CHAKRAVARTY, ID: S7467548D		
Main Claimant:	KOO CHIN TAT, ID: S77803761		
Vehicle Reg. No.:	SGL303E	Date of Loss:	25/06/2018 10:00 - :59 [142 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D03148C02	Policy/Cover Note No.:	DMPCSN3015621801
Vehicle Reg. No. (Insured):	SJR7364R	Policy No. (Claimant):	
		Excess:	\$50.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/07/2018]		
Driver/Custodian (Insured):	MUNINDRA NATH CHAKRAVARTY (/ Male), NRIC: S7467548D		
Adj Asg. Remarks:	EST \$8883.14 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> **Back to OneMotoring**


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0376I
Vehicle Details	
Vehicle No.:	SGL303E
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY ABSOLUTE 2.4 A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	K24A5800241
Chassis No.:	RB11300186
Maximum Power Output:	147.0 kW (197 bhp)
Open Market Value:	\$30,960.00
Original Registration Date:	25 Aug 2006
First Registration Date:	25 Aug 2006
Transfer Count:	4
Actual ARF Paid:	\$34,056.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jul 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$51,630.00
COE Rebate Amount:	\$41,803.00
Total Rebate Amount:	\$41,803.00

The information contained herein is correct as at 26 Jun 2018

OK



**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
 Tel : 67556142 Fax : 67557719
 Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
MUNINDRA NATH CHAKRAVARTY

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP CHINA
Policy No:		Date of Loss:	25/06/2018
Vehicle Reg. No.:	SGL303E	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHIN YOKE WEI	Driver (Insured):	MUNINDRA NATH CHAKRAVARTY
Make/Model:	HONDA ODYSSEY, 2.4 (A)	Vehicle Reg. Date:	25/08/2006
Vehicle Colour:	BLACK		
Engine No:	K24A5800241	Chassis No:	RB11300186
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0 8 days		
Description of Accident/Loss	REFER EFILE REPORT		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

*Not Authorized
 L1 Sup &?
 Rebody & the Paint*

COST OF CLAIMS	Amount
Parts	4,962.00
Miscellaneous Items	240.00
Labour	3,100.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,302.00
+ GST 7.00% (S\$)	581.14
Nett Amount (S\$)	8,883.14

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

SGL303E

TP / CHINA (25/6/18)

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Jul 2018)

Parts: M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SGL303E/10/07/2018 12:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 pc rear bumper	0.00	0.00	*380.00F	✓
2	1		*1 pc rear bumper reinforcement	0.00	0.00	*75.00F	✓
3	1		*6 pcs rear bumper clip (1.50/pc)	0.00	0.00	*9.00F	✓
4	1		*1 pc tailgate	0.00	0.00	*620.00F	✓
5	1		*1 pc tailgate logo	0.00	0.00	*18.00F	✓
6	1		*1 pc tailgate emblem - ABSOLUTE	0.00	0.00	*190.00F	✓
7	1		*1 pc tailgate inner lock	0.00	0.00	*95.00F	✓
8	1		*1 pc tailgate inner rubber	0.00	0.00	*90.00F	✓
9	1		*1 pc tailgate lower protector	0.00	0.00	*400.00F	✓
10	1		*1 pc rear windscreen moulding	0.00	0.00	*105.00F	✓
11	1		*1 pc frt bumper	0.00	0.00	*390.00F	✓
12	1		*1 pc frt bumper reinforcement	0.00	0.00	*185.00F	✓
13	1		*1 pc frt bumper centre lower grille	0.00	0.00	*60.00F	X
14	1		*1 pc frt bumper lh side retainer	0.00	0.00	*12.00F	✓
15	1		*6 pcs frt bumper clip (1.50/pc)	0.00	0.00	*9.00F	✓
16	1		*1 pc frt grille	0.00	0.00	*190.00F	✓
17	1		*1 pc frt grille moulding	0.00	0.00	*210.00F	✓
18	1		*1 pc frt grille logo	0.00	0.00	*18.00F	✓
19	1		*4 pcs frt bumper clip (1.50/pc)	0.00	0.00	*6.00F	✓
20	1		*2 pcs headlamp @ 950/pc	0.00	0.00	*1,900.00F	✓
Total Parts (S\$)						4,962.00	

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SGL303E/10/07/2018 12:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount	
<u>Miscellaneous Items</u>				
1	1	1 pc rear windscreen gum	40.00	✓
2	1	1 pc reverse sensor	200.00	✓
Sub Total (S\$)			240.00	

Estimates on Labour

No	Particulars	Lab.Type	Amount	
<u>Labour Items</u>				
1		New	700.00	650

Cheng Hoe Motor Pte Ltd/SGL303E/10/07/2018 12:44. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

No	Particulars	Lab.Type	Amount
	1) To remove and refix rr bumper assy, taillamps, spoiler, tailgate & attachment; knock and repair rear panel and re-align to same		
2	2) To remove and refix rear windscreen glass	New	100.00 ✓
3	3) To putty and respray on rear bumper, lower skirt, tailgate, lower protector, rear bumper, rear panel and rear affected areas	New	900.00 Pool
4	4) To remove and refix frt bumperassy, headlamp, radiator & motor, grille, knock and repair frt support panel, bonnet & re-align other to same	New	600.00 500/
5	5) To remove and refix aircon, vacuum and refill gas	New	100.00 X
6	6) To Putty and respray on bonnet, frt support panel, frt bumper, reinforcement and all affected areas	New	700.00 600/
Gross Labour Cost (\$\$)			3,100.00

Cheng Hoe Motor Pte Ltd/SGL303E/10/07/2018 12:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Suppl

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2018)**Parts:** M1-MPV HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Cheng Hoe Motor Pte Ltd/SGL303E/30/08/2018 15:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE INN.BOARD	0.00	0.00	*185.00F
Total Parts (S\$)						185.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SGL303E/30/08/2018 15:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Cheng Hoe Motor Pte Ltd/SGL303E/30/08/2018 15:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18012532/KSBN2

Date: 21/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3015621801
Claimant Vehicle No :	SGL303E	Insured Vehicle No :	SJR7364R
Date of Loss:	25/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03148C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL303E	Engine No:	K24A5800241
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	RB11300186
Reg. Date:	25/08/2006 (Man. Year: 2006)	Odometer:	141082 km
Colour:	Metallic Black		
Engine Capacity:	2354 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,147.00	4,617.00	530.00	10.30
Miscellaneous Items	240.00	240.00	0.00	0.00
Labour	3,100.00	2,650.00	450.00	14.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,487.00	7,507.00	980.00	11.55
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	8,487.00	6,000.00	2,487.00	29.30
+ GST 7.00/7.00% (S\$)	594.09	420.00	174.09	29.30
Nett Amount (S\$)	9,081.09	6,420.00	2,661.09	29.30

INSPECTION

Date of Assignment:	10/07/2018	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	10/07/2018	Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun)
			Blk 1019 #01-374/382, Yishun Industrial Park A
			Singapore 768761

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2018)
Parts: M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGL303E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc rear bumper	Buckled	380.00 F	*380.00 F
2	1		*1 pc rear bumper reinforcement	Repair	75.00 F	*- F
3	1		*6 pcs rear bumper clip	Necessary	9.00 F	*9.00 F
4	1		*1 pc tailgate	Bent	620.00 F	*620.00 F
5	1		*1 pc tailgate logo	Necessary	18.00 F	*18.00 F
6	1		*1 pc tailgate emblem - ABSOLUTE	Necessary	190.00 F	*190.00 F
7	1		*1 pc tailgate inner lock	Dented	95.00 F	*95.00 F
8	1		*1 pc tailgate inner rubber	Distorted/Cut	90.00 F	*90.00 F
9	1		*1 pc tailgate lower protector	Dented	400.00 F	*400.00 F
10	1		*1 pc rear windscreen moulding	Necessary	105.00 F	*105.00 F
11	1		*1 pc frt bumper	Buckled	390.00 F	*390.00 F
12	1		*1 pc frt bumper reinforcement	Repair	185.00 F	*- F
13	1		*1 pc frt bumper centre lower grille	Serviceable	60.00 F	*- F
14	1		*1 pc frt bumper lh side retainer	Distorted	12.00 F	*12.00 F
15	1		*6 pcs frt bumper clip	Necessary	9.00 F	*9.00 F
16	1		*1 pc frt grille	Cracked	190.00 F	*190.00 F
17	1		*1 pc frt grille moulding	Serviceable	210.00 F	*- F
18	1		*1 pc frt grille logo	Necessary	18.00 F	*18.00 F
19	1		*4 pcs frt bumper clip	Necessary	6.00 F	*6.00 F
20	1		*2 pcs headlamp	Mtg Cracked	1,900.00 F	*1,900.00 F
Supplementary #1						
21	1		*TAILGATE INN.BOARD	Buckled/Warped	185.00 F	*185.00 F
F=Franchise part.						
Total Parts (S\$)					5,147.00	4,617.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc rear windscreen gum (NECESSARY)	40.00	40.00
2	1	1 pc reverse sensor (DENTED)	200.00	200.00
Sub Total (S\$)			240.00	240.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	1) To remove and refix rr bumper assy, taillamps, spoiler, tailgate & attachment; knock and repair rear panel and re-align to same	New	700.00	650.00
2	2) To remove and refix rear windscreen glass	New	100.00	100.00
3	3) To putty and respray on rear bumper, lower skirt, tailgate, lower protector, rear bumper, rear panel and rear affected areas	New	900.00	800.00
4	4) To remove and refix frt bumperassy, headlamp, radiator & motor, grille, knock and repair frt support panel, bonnet & re-align other to same	New	600.00	500.00
5	5) To remove and refix aircon, vacuum and refill gas	New	100.00	-
6	6) To Putty and respray on bonnet, frt support panel, frt bumper, reinforcement and all affected areas	New	700.00	600.00
Gross Labour Cost (S\$)			3,100.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >