

INSURANCE

INS. CASE OWNER:

CC 4/EQ11801 11/23, Kyr...

LKK:

IDAC:

Surveyor:

Fenneth

DOE:

ASSIGNMENT

11/18

Date / Time:

11/18

Registered in Merimex:

Pre-assign / CCU / FTE



Insured Vehicle No.:

CB 5294P

Name of Insured:

ET ANZ PIC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

11/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ANG 60F MEDWA

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

OM181001675

Policy No.:

OM1818-100061

Make / Model:

LOWEN DRAGON

Place of Accident:

UPP TRAWSON RD TRPS

MERIMEX

OI GIA REPORT: YES / NO

YES

NO

TP GIA REPORT: YES / NO

YES

NO

Insured Liability:

%

Final? Yes / No

SLE 8141E



INSRS: WSP: Tel: Liability: RMKS:

CDHE WINDON



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date / Time	STAGE	DATE / PIC
11/18 7AM	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	11-2-18 JUY
	After call Itr to OI:	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input checked="" type="checkbox"/>
	After call Itr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	\$S	days Reduction:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28, Ass. Lia:	
Repair Cost:	\$S 4,046.06			
Loss of Rental (LOR):	\$S 665.12 (8 days)	8314		
Loss of Use (LOU):	\$S - (5 x days)			
Loss of Income (LOI):	\$S - (5 x days)			
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search:	\$S 7.49			
Medical:	\$S -			
Disbursement:	\$S -	(e.g. Tow/Independent)		
Legal Cost:	\$S -			
Total:	\$S 4,715.67	Global Sum \$S:	4,715.67	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	\$S 4,715.67	Name 1:	COMFORTDRIVE ENGINEERING PTE LTD	
Payee 2: (Strike if N.A.)	\$S x	Name 2:		
Payee 3: (Strike if N.A.)	\$S	Name 3:		

COPY SENT

OW 18
6/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18012533/Kjb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 10-07-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	CB 5294P	Veh. Inspected	SLE 8141E
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	10/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/07/2018	Inspection Date	09/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLE8141EMake & Model : HONDA VEZEL HYBRID 1.5X AYear of Manufacture : 2016Chassis No. : RU31208026Ins Company : AIG VS EQEngine No. : LEB5908036Excess : -Policy No. : -Date of Accident : 03.07.2018Time of Accident : 14:15

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : WILLIAM

Signature : _____

Parts (a) Cost / List Price Items \$ 4,793.30Plus/Less 20% \$ 958.66Total of Cost / List \$ 3,834.64(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 270.00Total Parts Cost (Appendix A) \$ 4,104.64Labour (Appendix B) \$ 2,350.00Total Repair Cost \$ 6,454.64

Contact No

Frnt Counter Operation

63837103 - Patrick Tia

63837730 - Brenda Ng

63837466 - Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

braddell_operation@sparkcarcare.com*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLE8141E Case Owner : WILLIAM

Make & Model : HONDA VEZEL HYBRID 1. Year Manufacture : 2016

Chassis No : RU31208026 Engine No : LEB5908036

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 762.60			✓
2	Rear bumper reflector LH	1		\$ 151.80			X
3	Rear bumper side retainer LH	1		\$ 18.90			X
4	Rear bumper side retainer RH	1		\$ 18.90			X
5	Rear bumper clips	10		\$ 30.00			✓
6	Tailgate	1		\$ 928.80			✓
7	Tailgate emblem - VEZEL	1		\$ 38.90			✓
8	Tailgate emblem - HYBRID	1		\$ 670.40	57.40		✓
9	Tailgate badge logo	1		\$ 28.70			X
10	Tailgate lock	1		\$ 127.60			X
11	Tailgate lamp LH	1		\$ 443.10			✓
12	Tailgate weatherstrip	1		\$ 96.80			X
13	Rear windscreen glass moulding upper	1		\$ 28.60			✓
14	Rear windscreen glass moulding lower	1		C/W 13			✓
15	Rear windscreen glass moulding LH	1		\$ 29.30			✓
16	Rear windscreen glass moulding RH	1		\$ 29.30			✓
17	Rear windscreen glass sealant	1				\$ 40.00	✓
18	Rear windscreen glass inner seal	1				\$ 30.00	✓
19	Tail lamp LH	1		\$ 442.40			X
20	Rear end panel	1		\$ 523.60			
21	Rear end panel top garnish	1		\$ 523.60			
22	Reverse sensor set	1				\$ 200.00	✓
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Labour

Vehicle No. : SLE8141E Case Owner : WILLIAM
 Make & Model : NDA VEZEL HYBRID 1.5X A Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	201
2	To remove/refit rear windscreen to facilitate repairs.	\$120.00	✓
3	To transfer tailgate parts and fittings to new tailgate.	\$180.00	201
4	Labour charges to repair and panel beat the LH taillamp panel, bootfloor/sparetyre panel, cutting/welding and replacing damaged parts. (per day \$240.00)	\$750.00	? to confirm 618.00
5	To replace reverse sensor set.	\$80.00	✓
6	To check wiring functions.	\$40.00	201
7	To putty, apply primer & spray-paint the rear bumper, tailgate, rear end panel, LH taillamp panel, RH taillamp panel, bootfloor/spare tyre panel and affected areas. (c 250)	\$1,000.00	7501
	To = Kenneth		1610 1610
	Parts = 5376-70		
	-20% 475-34		
	= 1901-36		
	+SN 270-00		
	+Labor 1610-00		
	= 3781-36		
	31/7/18		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref.

Type of Claim : IP E Vehicle No. : SLE8141E
 Make & Model : HONDA VEZEL HYBRID 1.5X A
 Year of Manufacture : 2016
 Chassis No. : RU31208026
 Ins Company : AIG VS NTUC INCOME Engine No. : LEB5908036
 Excess : - Policy No. : -
 Date of Accident : 03.07.2018 Time of Accident : 14:15
 Suggested Days of Repair : _____ In-house Vehicle Assessor

Repair Estimate

Parts (a) Cost / List Price Items \$ -
 Plus/Less 20% \$ -
 Total of Cost / List \$ -
 (b) Nett Price Items \$ -
 Less _____
 Total of Nett Item _____
 (c) Special Nett Items \$ -
Total Parts Cost (Appendix A) \$ -
Labour (Appendix B) \$ 2,350.00
Total Repair Cost \$ 2,350.00

Case Owner : WILLIAM
 Signature : _____

Contact No
Frt Counter Operation
 63837103 - Patrick Tia
 63837730 - Brenda Ng
 63837466 - Rohani
 braddell_cr@sparkcarcare.com

Workshop Operation
 63837656 - Ngo Toh Wee
 63837362 -
 63838115 - William Wang
 63838115 - Andrew Goh
 braddell_operation@sparkcarcare.com

Not Authorized

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
 Company : LKK
 Survey conducted on : 9/7/18 at _____
 Remarks By Surveyor
 (a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.
 (b) Recommended Days of Repair : 4-6 day(s)
 (c) Resurvey : Required / ~~Not Required~~
 (d) Excess : \$ _____
 (e) Signature of surveyor : Lc Date: 9/7/18

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLE8141E Case Owner : WILLIAM

Make & Model : HONDA VEZEL HYBRID 1. Year Manufacture : 2016

Chassis No : RU31208026 Engine No : LEB5908036

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper <i>Ry</i>	1					✓
2	Rear bumper reflector LH <i>Sm</i>	1					X
3	Rear bumper side retainer LH <i>Sm</i>	1					X
4	Rear bumper side retainer RH <i>Sh</i>	1					X
5	Rear bumper clips <i>Me</i>	10					✓
6	Tailgate <i>Ry</i>	1					✓
7	Tailgate emblem - VEZEL <i>Me</i>	1					✓
8	Tailgate emblem - HYBRID <i>Me</i>	1					✓
9	Tailgate badge logo <i>na</i>	1					X
10	Tailgate lock <i>R</i>	1					X
11	Tailgate lamp LH <i>CM</i>	1					✓
12	Tailgate weatherstrip <i>Sm</i>	1					✓
13	Rear windscreen glass moulding upper <i>Me</i>	1					✓
14	Rear windscreen glass moulding lower <i>Me</i>	1					✓
15	Rear windscreen glass moulding LH <i>Me</i>	1					✓
16	Rear windscreen glass moulding RH <i>Me</i>	1					✓
17	Rear windscreen glass sealant <i>Me</i>	1					✓
18	Rear windscreen glass inner seal <i>Me</i>	1					✓
19	Taillamp LH <i>Sm</i>	1					X
20	Rear end panel	1					?
21	Rear end panel top garnish	1					?
22	Reverse sensor set <i>JCR</i>	1					✓
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. : SLE8141E Case Owner : WILLIAM
 Make & Model : NDA VEZEL HYBRID 1.5X A Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove/refit boot compartment trims and garnish to facilitate repairs.	\$180.00	201
2	To remove/refit rear windscreen to facilitate repairs.	\$120.00	✓
3	To transfer tailgate parts and fittings to new tailgate.	\$180.00	201
4	Labour charges to repair and panel beat the LH taillamp panel, bootfloor/spare tyre panel, cutting/welding and replacing damaged parts. (per day \$240.00)	\$750.00	? to cabin
5	To replace reverse sensor set.	\$80.00	✓
6	To check wiring functions.	\$40.00	201
7	To putty, apply primer & spray-paint the rear bumper, tailgate, rear end panel, LH taillamp panel, RH taillamp panel, bootfloor/spare tyre panel and affected areas. (c 250)	\$1,000.00	7501
<div style="border: 1px solid black; padding: 5px; width: fit-content; margin: auto;"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 9 July 2018 10:32 AM
To: assignments
Subject: FW: SLE8141E CLAIMING AGAINST CB5294P DOA03072018 CHECK LIABILITY & ARRANGE SURVEY - (DM18HO01695)
Attachments: SLE8141E DOA03072018 ESTIMATE.PDF; SLE8141E DOA03072018 SAS.PDF; CB5294P.PDF

2.13pm @ 9/7/2018
vehicle In
person @ willian
SUR @ Kenneth

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Monday, 9 July 2018 10:14 AM
To: Admin A <admin-a@lkkauto.com>
Subject: RE: SLE8141E CLAIMING AGAINST CB5294P DOA03072018 CHECK LIABILITY & ARRANGE SURVEY - (DM18HO01695)

Dear LKK

Apologies I had overlooked keeping you in the loop.
Please assist on this DS.

Kindly obtain a copy of our insured's accident report before any settlement.

Best Regards,

Joel Goh

Executive | Claims

 **eqnsurance**
Your Got a Friend

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: Joel Goh
Sent: Monday, July 9, 2018 10:05 AM
To: 'CDGE Braddell Private Cars Crash Repair Operation'
Cc: braddell_cr@sparkcarcare.com; Denis Teo Chin Chye
Subject: RE: SLE8141E CLAIMING AGAINST CB5294P DOA03072018 CHECK LIABILITY & ARRANGE SURVEY - (DM18HO01695)

Without Prejudice

Dear William

Our apologies for the late response.
We will assign LKK to take over this direct settlement.

Dear LKK

Please assist on this DS.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: CDGE Braddell Private Cars Crash Repair Operation [mailto:braddell_operation@sparkcarcare.com]
Sent: Friday, July 6, 2018 6:16 PM
To: EQI PRS
Cc: braddell_cr@sparkcarcare.com; braddell_operation@sparkcarcare.com; Denis Teo Chin Chye
Subject: Fw: SLE8141E CLAIMING AGAINST CB5294P DOA03072018 CHECK LIABILITY & ARRANGE SURVEY - REMINDER

Dear Sir/Madam,

A Kind reminder, please reply to the email below.

Thanks.

Best Regards
William Wang
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 8115 | Fax: 6281 5767
www.SPARKcarcare.com

— Forwarded by CDGE Braddell Private Cars Crash Repair Operation/sparkcarcare/cdge/delgronotes on 07/06/2018 06:14 PM —

From: CDGE Braddell Private Cars Crash Repair Operation/sparkcarcare/cdge/delgronotes
To: egiprs@eqinsurance.com.sg

Cc: braddell_cr@sparkcarcare.com, braddell_operation@sparkcarcare.com
Date: 07/05/2018 01:09 PM
Subject: SLE8141E CLAIMING AGAINST CB5294P DOA03072018 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir/Madam,

Kindly assist to check liability for this case and arrange survey.
Your insured vehicle number is CB5294P
Please see attached and reply as soon as possible.

Thanks.

Best Regards
William Wang
External Business | ComfortDelGro Engineering Pte Ltd
Off: 6383 8115 | Fax: 6281 5767
www.SPARKcarcare.com

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S1317437G

LIM JOO HENG

Date of Birth: 14 Jul 1958

Issue Date: 14 Oct 2003

0009180112




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S1317437G

LIM JOO HENG

林楚興

Race: CHINESE

Date of Birth: 14-07-1958

Sex: M

Country of Birth: SINGAPORE





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIFICATION

ALL PERIODS

Class 2B	Motorcycles not exceeding 200 cc	31 Jan 1978
Class 2A	Motorcycles between 201 cc and 400 cc	31 Jan 1978
Class 3	Motorcycles exceeding 400 cc	31 Jan 1978
Class 3	Motor Cars and Motor Tractors the weight of which (including fuel) does not exceed 2500 kilograms	17 Oct 1977
Class 4	Heavy Motor Cars and Motor Tractors the weight of which (including fuel) exceeds 2500 kilograms	21 Jul 1983
Class 5	Motor Vehicles which are not constructed themselves to carry any load and the weight of which (including fuel) exceeds 7200 kilograms	22 Sep 1982

License No. S1317437G



NP 215A

0009180112

Identity Card No. S1317437G

ART BLK 324C BENSANG EAST WAY #11-807

SINGAPORE 543324

NRIC No. S1317437G Date: 27-02-2003 No. 4006780






HOTLINE TEL: (65) 6419-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1968

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.Z.400

COMPREHENSIVE COMMERCIAL MOTOR		(The below excess is subject to GST)	
CERTIFICATE NO.	SLEB141E	ALL CLAIMS EXCESS	S\$2000.00
		WINDSCREEN EXCESS	S\$100.00
		SUM INSURED	Market Value
		INSURING WITH COE/PARF	Yes
1) VEHICLE REGISTRATION NO.		SLEB141E	
2) NAME OF INSURED		LCRF Pte Ltd	
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT		25 February 2018	
4) DATE OF EXPIRY OF INSURANCE		24 February 2019	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*	Any person who is driving on the Insured's order or with their permission.		
	If You or Your Authorised Driver is below the age of 21 years old and/or has less than 1 year driving experience, the excess is S\$3,500(All Claims).		
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.			
6) LIMITATION AS TO USE*	<ul style="list-style-type: none"> 1) Use for social, domestic, pleasure purposes and business purposes of Insured 2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired. 3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired. <p>The Policy does not cover: 1) Use for lullion, driving test, racing, pace-making, reliability trial or speed-testing. 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle. 3) Use for any purpose in connection with the Motor Trade.</p>		
	LOSS OF USE	Not Included	
	HIRE PURCHASE COMPANY	Refer to Policy Terms and Conditions	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.			

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued in Singapore 13 Feb 2018

AIG Asia Pacific Insurance Pte. Ltd.

030050-000
Aon Singapore Pte Ltd
2 Shenton Way
#25-01 SGX Centre 1
SINGAPORE 068804

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPAHN



ComfortDelGro Engineering

Our Ref: PTE/SLE8141E/20180703/DS-CL

04/09/2018

EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block
MND Complex
Singapore 069110
Attn: Motor Claims Department

Without Prejudice

Dear Sirs

ACCIDENT ON 03/07/2018 INVOLVING SLE8141E & CB5294P ALONG UPPER THOMSON ROAD

We are the authorised repair workshop for the owner of vehicle, SLE8141E, which was involved in the captioned accident with your insured's vehicle. The vehicle owner has requested and authorized us to assist him/her in presenting his claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured, CB5294P, we are submitting these claims for your consideration on behalf of the owner/driver/claimant.

1. Cost of Repairs	4,046.06
2. 14.0 days Loss of Rental @ \$83.14	1,163.96
3. LTA Fee	7.49
4. Loss of Income	80.00

(E&OE) 5,297.51

We enclose the following documents to support the claims: -

- | | |
|---|---|
| <input checked="" type="checkbox"/> Repair/Excess Bill | <input checked="" type="checkbox"/> Insurance Certificate |
| <input type="checkbox"/> Surveyor Report | <input checked="" type="checkbox"/> Power of Attorney |
| <input type="checkbox"/> Coloured Photographs | <input type="checkbox"/> Car Rental Bill |
| <input checked="" type="checkbox"/> GIA/Police Report(s) | <input type="checkbox"/> Medical Bill |
| <input checked="" type="checkbox"/> GIA/TP Search | <input type="checkbox"/> Witness Statement |
| <input checked="" type="checkbox"/> Others: <u>Rental Agreement</u> | |

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/driver/claimant.

Yours faithfully

Cecilia Lee

CDGE Claims Department

DID: 6214 8354 FAX: 6214 1843 Email: cecilialee@sparkcarcare.com

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Bras Basah Road Singapore 179701
Mobile: +65 6283 5290
Facsimile: +65 6283 9750

Company Registration No: 170000048

Car Care Centres

Bras Basah
205 Bras Basah Road
Singapore 179701
Tel: 6283 8117

Loyang
391 Upper Cross
Singapore 508818
Tel: 6744 6200

Pandan
45 Pandan Road
Singapore 609246
Tel: 6338 6715

Sin Ming
263 Sin Ming Drive
Singapore 572117
Tel: 6283 6800

Sungei Kadut
7 Sungei Kadut Way
Singapore 728291
Tel: 6383 7388

Ubi
300 Ubi Road 3
Singapore 408846
Tel: 6740 0800

Yishion
381 Yishion Industrial Park A, 2
Singapore 160720
Tel: 6757 7880

www.SPARKcarcare.com

A member of
COMFORTDELGRO





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/EQI18012533/Kjb3

11 JULY 2018

EZ BUZZ PTE LTD

325 Ubi Ave 1
#01-707
Singapore 400305

Dear Sir/Madam,

ACCIDENT INVOLVING CB 5294P AND SLE 8141E ON 03/07/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.


Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully


Joy Irene
Case Handler
DID: 6841 2409
FAX: 6741 4108
Email: jovirene@lkkauto.com

c.c. EQ INSURANCE COMPANY LIMITED
(Motor Claims Dept)

ComfortDelGro Engineering Pte Ltd

Corporate Office
205 Braddell Road
Singapore 579701
Tel: +65 63832280
Fax: +65 62808793
www.cdge.com.sg

Car Care Centres
205 Braddell Road Singapore 579701
59 Laying Drive Singapore 608960
45 Pandan Road Singapore 608960
343 Sin Ming Drive Singapore 575117
7 Tuong Khat Way Singapore 726791
320 Ubi Road 3 Singapore 408649
301 Yuhon Industrial Park A Singapore 760732
www.SPARKCarCare.com

Tel: 6383 8110
Tel: 6214 5330
Tel: 6338 6779
Tel: 6553 0400
Tel: 6399 3166
Tel: 6968 5221
Tel: 6737 7896



ComfortDelGro Engineering
COMPANY REG. NO: 199506048W
GST REG. NO. M2-8921817

TAX INVOICE

8010325
EO INSURANCE COMPANY LIMITED
5 MAXWELL ROAD TOWER BLOCK #17-00
SINGAPORE SG 069110
CONTACT NO: 62239433

VEHICLE NO
SL88141R
MAKE
HONDA
MODEL,
VEZEL, HYBRID
DATE OF REG
02.08.2016
CHASSIS CODE
RU31208026
INVOICE NO./DATE
91392813 30.08.2018
JOB NO.
305183468
ODOMETER READING

Description : TP - AIG - BO

S/No	Part No. Description	Qty	Unit Price		Nat.
01	20-501 LABOUR CHARGES	1 EAC	1,610.00	SGD	1,610.00
02	29905 SEALANT	1 EAC	40.00	SGD	40.00
03	29904 INNER SEAL,	1 PC	30.00	SGD	30.00
04	1979 REAR BUMPER	1 PC	610.08	SGD	610.08
05	1979 REAR BUMPER CLIPS	10 PC	2.40	SGD	24.00
06	1979 TAILGATE	1 PC	743.04	SGD	743.04
07	1979 TAILGATE EMBLEM VEZEL	1 PC	31.12	SGD	31.12
08	1979 TAILGATE EMBLEM HYBRID	1 PC	45.92	SGD	45.92

Checks should be crossed and made payable to "ComfortDelGro Engineering Pte Ltd"

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Blk C Ext 1 Level 2
Singapore 579701

Attn: Finance Department

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ N
8010325	91392813	4,046.06	

ComfortDelGro Engineering Pte Ltd

Corporate Office
315 Braddell Road
Singapore 579701
Telephone : + 65 6481 8280
Fax Number : 65 6280 8235
www.cdge.com.sg

Car Care Centres
205 Braddell Road Singapore 579701
58 Luyang Drive Singapore 608100
43 Pandan Road Singapore 609200
381 Sin Ming Drive Singapore 575717
7 Sungei Kadut Way Singapore 726791
320 Ubi Road 3 Singapore 408649
301 Tekong Industrial Park 4 Singapore 768732
www.cdgc.com.sg

Tel: 6361 8110
Tel: 6214 8300
Tel: 6538 8779
Tel: 6533 0400
Tel: 6308 7369
Tel: 6648 5721
Tel: 6751 7888



ComfortDelGro Engineering
COMPANY REG. NO: 199506048W
GST REG. NO. M2-8921817

TAX INVOICE

8010325
EO INSURANCE COMPANY LIMITED
5 MAXWELL ROAD TOWER BLOCK #17-00
SINGAPORE SG 069110

VEHICLE NO
SF88141R
INVOICE NO. /DATE
91392813 30.08.2018
MAKE
HONDA
JOB NO.
305183468
MODEL
VEZEL HYBRID
ODOMETER READING
DATE OF REG
02.08.2016
CHASSIS CODE
RU31208026

S/No	Part No. Description	Qty	Unit Price		Net
09	1979 TAILGATE BADGE LOGO	1 PC	22.96	SGD	22.96
10	1979 TAILGATE LAMP LH	1 PC	354.48	SGD	354.48
11	1979 REAR WINDSCREEN MLDG UPPER	1 PC	22.88	SGD	22.88
12	1979 REAR WINDSCREEN MLDG LH	1 PC	23.44	SGD	23.44
13	1979 REAR WINDSCREEN MLDG RH	1 PC	23.44	SGD	23.44
14	1979 REVERSE SENSOR SET (2PC)	1 PC	200.00	SGD	200.00
			Items total		3,781.36
			Add GST @	7.000 %	264.70
			Invoice amount		4,046.06

Issued by : SIEWHWA 30.08.2018 16:25:54
Repair type : CESO/52/5T
Payment Type/Term: /

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office should be crossed and made payable to COMFORTDELGRO ENGINEERING PTE LTD
315 Braddell Road
Bk C Ext 1 Level 2
Singapore 579701

Attn: Finance Department
Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO N

SCHEDULE 1

1. Hirer's Details

LIM CHO HENG (Hirer's Name) S1317437G (*NRIC/Passport No.)

324C SENGKANG EAST WAY #11-607 SINGAPORE 543324 (Address)

(Mailing address, if different from above)

willie.com.sg@gmail.com (Email address)

(Telephone No.) 97543174 (Mobile No.) 14/07/58 (Date of Birth dd/mm/yy)

(Driver's Licence No.) (Expiration Date) (Class(es) of Driver's Licence)

*Please delete where applicable.

2. Vehicle Description

Table with 3 columns: Make & Model, Colour, Registration No. Row 1: HONDA VEZEL HYBRID, BLUE, SLE8141E

3. Commencement Date and Minimum Rental Period

The Minimum Rental Period is for 26 Weeks and commences on the 03/07/18 (being the date of collection of the Vehicle from LCR by the Hirer).

For the avoidance of doubt, the Minimum Rental Period is exclusive of any period where the Vehicle is being repaired due to an accident and the Hirer is not offered a Replacement Vehicle by LCR during such period. For example, if a Hirer has completed 2 weeks of the Minimum Rental Period, and the Vehicle is sent for repair for 2 weeks due to an accident, then only 2 weeks of the Minimum Rental Period has been fulfilled. As a result, the Hirer must still fulfill an additional 2 weeks to complete the Minimum Rental Period.

SCHEDULE 1A

1. Rental Plan

28 Weeks

2. Deposit

200

3. Rental Fee & Charges

- (a) The Rental Fee per week is S\$ 582.
- (b) Weekly Payment Fee: All weekly rental payments are due the following Wednesday at 17:00hrs and if the Wednesday falls on a Public Holiday, then the due date will be the next working day at 17:00hrs.
- (c) Late Payment Fee: All outstanding payments after the above mentioned day will be subject to a late payment fee of S\$60.
- (d) Cleaning Fee: S\$300. Not limited to Cigarette odour.
- (e) Vehicle Damage Fee: In cases where the Vehicle has been involved in an accident requiring repairs to the Vehicle, the Hirer will be responsible for the actual cost of repair to the Vehicle up to a maximum of S\$2,200 per accident.

4. Insurance Excess

In the event of an accident resulting in a claim made against or reported to LCR's insurers for damage to third party property (including other vehicles), the Hirer will be liable for any insurance excess* ("**Insurance Excess**") payable as a result.

The Insurance Excess is payable in addition to any other amounts that may be applicable under this Agreement.

* **S\$2,140** or such other amount as notified to the Hirer by LCR from time to time



Thank you

Teo Chin Chye has successfully logged out.

Your last login date and time was 05 Jul 2018, 10:57:57.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$)	Log Date/Time
1	Vehicle	CB5294P	-	18.32 Insurance Enquiry (GIRO Payment)	7.49	05 Jul 2018 / 10:59:49

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
CBS294P	03 Jul 2018 / 14:15:00	Successful	E04	EQ INSURANCE COMPANY LTD

Previous

OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 18/01/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	CB 5294P (Insd Veh)	Your Ref. No. : DM18HO01695
	SLE 8141E (TP Veh)	Our Ref. No. : CC4/EQI18012533/Kjb3q2
Date of Accident	3/7/2018	

Liability	100%	
Final Repair Cost	: \$ 4,046.06	
Loss of Use	: \$	days
Rental (If any)	: \$ 665.12	8 days
Others:	: \$ 7.49	
	: \$	
	4,718.67	
Final Settlement Sum	: \$ 4,715.00	GLOBAL SUM
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 4,715.00
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC4/EQ18012533/Kjb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 18-01-2019	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	CB 5294P	Veh. Inspected	SLE 8141E
Policy No.	DMCFHQ18-000081	Coverage (\$)	0.00
Claim No.	DM18HO01695	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	09/07/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31208026	Colour	METALLIC DARK BLUE
Odometer	115425	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	HIFLY	7 mm
L/H Front Tyre	215/60 R16	HIFLY	7 mm
R/H Rear Tyre	215/60 R16	ACHILLES	9 mm
L/H Rear Tyre	215/60 R16	ACHILLES	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/07/2018	Inspection Date	09/07/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD Blk C, 3rd Floor SINGAPORE 579701.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 8141E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	762.60	762.60
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	151.80	-
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	18.90	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	18.90	-
10	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	TAILGATE	BENT	928.80	928.80
1	TAILGATE EMBLEM -VEZEL	NECESSARY	38.90	38.90
1	TAILGATE EMBLEM-HYBRID	NECESSARY	570.40	57.40
1	TAILGATE BADGE LOGO	NECESSARY	28.70	28.70
1	TAILGATE LOCK	TO REPAIR SEE LABOUR	127.60	-
1	TAILGATE LAMP LH	CRACKED	443.10	443.10
1	TAILGATE WEATHERSTRIP	SERVICEABLE	96.80	-
1	REAR WINDSCREEN GLASS MOULDING UPPER }	NECESSARY	28.60	28.60
1	REAR WINDSCREEN GLASS MOULDING LOWER }	NECESSARY	-	-
1	REAR WINDSCREEN GLASS MOULDING LH	NECESSARY	29.30	29.30
1	REAR WINDSCREEN GLASS MOULDING RH	NECESSARY	29.30	29.30
1	TAILLAMP LH	SERVICEABLE	442.40	-
1	REAR END PANEL	SERVICEABLE	523.60	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	523.60	-
	LESS 20% DISCOUNT		-958.66	-475.34
			3,834.64	1,901.35
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR WINDSCREEN GLASS INNER SEAL (SN)	NECESSARY	30.00	30.00
1	SET REVERSE SENSOR (SN)	SCRATCHED	200.00	200.00
			270.00	270.00
LABOUR				
	TO REMOVE /REFIT BOOT COMPARTMENT TRIMS AND GARNISH TO FACILITATE REPAIRS.		180.00	80.00

Report Ref No. CC4/EQ118012533/Kjb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.		✓ 120.00	120.00
	TO TRANSFER TAILGATE PARTS AND FITTINGS TO NEW TAILGATE.		✓ 180.00	80.00
	LABOUR CHARGES TO REPAIR AND PANEL BEAT THE LH TAILLAMP PANEL, BOOTFLOOR/SPARETYRE PANEL, CUTTING/WELDING AND REPLACING DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE LOCK.		✓ 750.00	480.00
	TO REPLACE REVERSE SENSOR SET.		✓ 80.00	80.00
	TO CHECK WIRING FUNCTIONS.		✓ 40.00	20.00
	TO PUTTY, APPLY PRIMER & SPRAY -PAINT THE REAR BUMPER, TAILGATE, REAR END PANEL, LH TAILLAMP PANEL, RH TAILLAMP PANEL, BOOTFLOOR /SPARE TYRE PANEL AND AFFECTED AREAS.		1,000.00	750.00
			2,350.00	1,610.00
	GRAND TOTAL		6,454.64	3,781.36
	RECOMMENDED COST OF REPAIRS			3,781.36

Report Ref No. CC4/EQ118012533/Kjb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Friday, 18 January 2019 3:50 PM
To: 'eqiprs@eqinsurance.com.sg'
Subject: TP Direct Settlement - Accident Involving CB 5294P (OI) and SLE 8141E (TP) on 03/07/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933