



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TP

Vehicle No. : SLE8141E

Make & Model : HONDA VEZEL HYBRID 1.5X A

Year of Manufacture : 2016

Chassis No. : RU31208026

Ins Company : AIG VS NTUC INCOME

Engine No. : LEB5908036

Excess : -

Policy No. : -

Date of Accident : 03.07.2018

Time of Accident : 14:15

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor

**Repair Estimate**

Case Owner : WILLIAM

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ -

Plus/Less 20% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less \_\_\_\_\_

Total of Nett Item \_\_\_\_\_

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ -

Labour (Appendix B) \$ 2,350.00

Total Repair Cost \$ 2,350.00

Contact No  
**Frnt Counter Operation**  
 63837103 – Patrick Tia  
 63837730 - Brenda Ng  
 63837466 – Rohani  
[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)

**Workshop Operation**  
 63837656 - Ngo Toh Wee  
 63837362 -  
 63838115 - William Wang  
 63838115 - Andrew Goh  
[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
<b>Remarks By Surveyor</b>		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:	\$ _____
(e) Signature of surveyor	:	_____ Date: _____

# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

## Spare Parts

Vehicle No : SLE8141E Case Owner : WILLIAM

Make & Model : HONDA VEZEL HYBRID 1. Year Manufacture : 2016

Chassis No : RU31208026 Engine No : LEB5908036

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1					
2	Rear bumper reflector LH	1					
3	Rear bumper side retainer LH	1					
4	Rear bumper side retainer RH	1					
5	Rear bumper clips	10					
6	Tailgate	1					
7	Tailgate emblem - VEZEL	1					
8	Tailgate emblem - HYBRID	1					
9	Tailgate badge logo	1					
10	Tailgate lock	1					
11	Tailgate lamp LH	1					
12	Tailgate weatherstrip	1					
13	Rear windscreen glass moulding upper	1					
14	Rear windscreen glass moulding lower	1					
15	Rear windscreen glass moulding LH	1					
16	Rear windscreen glass moulding RH	1					
17	Rear windscreen glass sealant	1					
18	Rear windscreen glass inner seal	1					
19	Taillamp LH	1					
20	Rear end panel	1					
21	Rear end panel top garnish	1					
22	Reverse sensor set	1					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

