

AIGAsia Insured's Veh No : SLK6448C

Date of Accident : 09 July 2018



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Mohamed Padrun Bin Johari

Date : 11 July 2018

continued with
marcus

17.67.2018

Estimate To Repair SGK9795P - Toyota Vios 1.5E A

Chassis No : MR053HY4204201309

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper	\$ 231.20 ✓
02	8 pc	front bumper clips @ \$4.30	\$ 34.40 ✓
03	1 pc	n/s front bumper side retainer	\$ 20.00 ✓
04	1 pc	front bumper reinforcement	\$ 410.00 X
05	1 pc	n/s front bumper fog lamp garnish	\$ 35.00 X
06	1 pc	n/s front bumper fog lamp bracket	\$ 35.00 X
07	1 pc	front bumper lower spoiler moulding	\$ 125.00 ✓
08	1 pc	n/s fog lamp	\$ 250.00 X
09	1 pc	n/s headlamp	\$ 310.00 ✓
10	1 pc	n/s front fender	\$ 170.00 ✓
11	1 pc	n/s front fender inner cowling	\$ 35.00 ✓
12	4 pc	front fender inner cowling clips @ \$4.30	\$ 17.20 ✓
13	1 pc	n/s front shock absorber	\$ 250.00 X
14	1 pc	n/s front lower arm	\$ 300.00 X
15	1 pc	n/s front knuckle arm	\$ 175.00 X
Less 25 %			\$ 2,397.80
			\$ 599.45
			\$ 1,798.35
<u>SPECIAL NETT ITEMS</u>			
16	1 pc	n/s front wheel rim	\$ 380.00 300
17	1 pc	n/s front wheel tyre	\$ 300.00 X
			\$ 680.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 30.00 20
02		To check steering geometry and computer wheel alignment.	\$ 60.00 60
03		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 120.00 X
04		To rust-proofing of the affected areas.	\$ 80.00 30
05		Putty and spray painting of the affected portion.	\$ 600.00 400
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 600.00 580
			\$ 1,490.00
Total			\$ 3,968.35

942.80
707.10
2097.10
1677.68

2097.1
1677.68