

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

9-Jul-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8983 E

1 pc	Rear bumper <i>X hyper</i>	\$	696.00
1 pc	Rear bumper lower cover <i>X</i>	\$	206.00
		\$	902.00
	Less 10%	\$	90.20
		\$	811.80

### S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 set	Reverse sensor <i>X</i>	\$	280.00

Sundry	\$	<del>50.00</del> 20
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	<del>120.00</del> <i>X</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	<del>450.00</del> 200
To putty and spray painting on rear bumper	\$	<del>200.00</del> 180
	\$	2,139.80

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

*Ka Li Ulla*  
*9/7/18 1040hrs*  
*2 Rep.*  
*L/S*  
*After Repair*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: