

INS. CASE OWNER:

CC 4, CPC 180 V542, R E6302

LKK:

IDAC:

Surveyor:

Rasm

DOI:

ASSIGNMENT

10/7/18

Date / Time:

9/7/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJN 9552 Y

Name of Insured:

91 50024 HEE

Insured Tel No.:

HP:

95677621

Excess Sec II :SS

D.O.A.:

5/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

18/8/18 / VPOS 1020740

Policy No.:

312VP1507768

Make / Model:

Mitsubishi

Place of Accident:

ARABIAN RD TMS LTR

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLG 42370



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hitachi



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time		STAGE	DATE / PIC
11/7/18	SLG 42370 - X	Non-Reporting ltr (1st):	
11/7/18		Non-Reporting ltr (2nd):	
11/7/18		Non-Reporting ltr (Final):	
11/7/18		Notification ltr (if non-pickup):	
11/7/18		Call OI:	
11/7/18		After call ltr to OI:	
12-7-18	EMAIL WSP LIABILITY CLEAR.	Documentation Check List:	Handler Typist
13/7/19	FILE PAS TO TYPE MANDATE	Notification ltr (if non-pickup)	☐
30/8/19	FILE PAS TO LSP TO CLOSE	After call ltr to OI:	☐
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☐
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	\$4,813.50	(7 days) Reduction:	30 %
FINAL SETTLEMENT		Date/Time: 27/8/19	Confirm with: Sam, lah
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	21
Repair Cost: (w/ GST)	\$5149.38	OI REPAIR ENDED TP.	
Loss of Rental (LOR): (w/ GST)	\$599.20	(7 days) x \$80	
Loss of Use (LOU):	\$ -	(\$ x days)	
Loss of Income (LOI):	\$ -	(\$ x days)	
LOR only ☒	LOU only ☐	LOR + LOU ☐	LOR + LOI ☐ [Tick only one]
GIA/LTA Search	\$31.00		
Medical:	\$ -		
Disbursement:	\$ -	(e.g. Tow/ Independent)	
Legal Cost	\$ -		
Total:	\$5779.58	Global Sum SS:	
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	\$5779.58	Name 1:	Hitachi Capital Asia Pacific Pte Ltd
Payee 2: (Strike if N.A.)	\$ -	Name 2:	
Payee 3: (Strike if N.A.)	\$ -	Name 3:	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18012542/eb3		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 10-07-2018		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 9552Y	Veh. Inspected	SLG 4237D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	10/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/07/2018	Inspection Date		
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18012542/R1eb3

Date: 12.07.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLG4237D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10.07.2018 at the premises of M/s Hitachi Capital Asia Pacific Pte. Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	6,641.87
Revised Estimate Amount	: S\$	4,345.25
"Check" Items Amount	: S\$	416.25
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

LONPAC

QUOTE NO :
 ACCIDENT DATE : 05/07/2018@0735HRS
 VRN : SLG4237D
 MODEL : TOYOTA ALTIS
 TP VRN : SJN9552Y

ATTN: MOTOR CLAIMS DEPT

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Rear Bumper	1	\$ 485.00	\$ 485.00	DE -
2 Rear Bumper Clips	10	\$ 5.50	\$ 55.00	nn -
3 Rear Bumper Inner Bracket LH/RH	1/2	\$ LH - 120.00	\$ 240.00	nn - X RH nn
4 Rear Bumper Outer Bracket LH/RH	1/2	\$ RH - 80.00	\$ 160.00	nn - X RH nn
5 Rear Bumper Reflector LH	1	\$ 58.00	\$ 58.00	CR -
6 Rear Bumper Re-inforcement	1	\$ 395.00	\$ 395.00	? X sue
7 Taillamp LH/RH	2	\$ LH - 395.00	\$ 790.00	RH - X nn
8 Taillamp Panel LH/RH	2/1	\$ LH - 108.00	\$ 216.00	RH - X nn
9 Rear Fender LH	1	\$ 987.00	\$ 987.00	Rue -
10 Rear Fender Shield LH	1	\$ 55.00	\$ 55.00	? X nn
11 Rear Fender Shield clips LH	5	\$ 5.50	\$ 27.50	nn X nn
12 Air Vent LH	1	\$ 140.00	\$ 140.00	DE -
13 Bootlid Reflector LH	1	\$ 339.00	\$ 339.00	cut -
14 Bootlid	Repair	\$ -	\$ -	
15 Sealant	S/nett	\$ 45.00	\$ 45.00	X new -
16 Damp	1	\$ 35.00	\$ 35.00	nn -
Discount 25%			\$ (995.63)	
TOTAL			\$ 3,031.87	

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	1000	\$ 1,250.00
2 Putty, blend and paint affected area	800 850	\$ 1,250.00
3 Check Wiring, re-align taillamps and ensure proper function		\$ 30 80.00
4 Remove and reinstall 2 pieces bumper sensor		\$ 60 120.00
5 Cavity Treatment on new parts		\$ 40 160.00
6 Remove & reinstall Rear reverse camera	nn	\$ X 120.00
7 Remove & re-install fuel tank to facilitate cutting and repairing work		\$ 80 180.00
8 Remove & re-install Rear Windscreen		\$ 120 180.00
9 Remove & re-install rear trim compartment to facilitate cutting and repairing work		\$ 80 150.00

10 Conduct water seepage test

\$ 120.00

Sub Total

\$ 3,610.00

Grand Total : \$ 6,641.87

Add 7% GST : \$ 464.93

Nett Total : \$ 7,106.80

No. of repair days: 10

7097.87

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Rahul

Hp 90010068

7 days

P/P

10/07/18 @ 1500

Resurvey of panel

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE SUPPLEMENTARY ESTIMATE

LONPAC

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 05/07/2018@0735HRS
VRN : SLG4237D
MODEL : TOYOTA ALTIS
TP VRN : SJN9552Y

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 End Panel	1	\$ 590.00	\$ 590.00	PA ✓
2 Fuel Rivet	2	\$ 5.00	\$ 10.00	PA ✓
3 Taillamp Clip LH	1	\$ 8.00	\$ 8.00	PA ✓
Discount 25%			\$ (152.00)	
TOTAL			\$ 456.00	

2. Labor Charges

Sub Total : \$ -

Grand Total : \$ 456.00
Add 7% GST : \$ 31.92
Nett Total : \$ 487.92

No. of repair days: 10

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705

Tel : 64663022 Fax : 68966591

Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

LONPAC

QUOTE NO :

ACCIDENT DATE : 05/07/2018@0735HRS

VRN : SLG4237D

ATTN: MOTOR CLAIMS DEPT

MODEL : TOYOTA ALTIS

TP VRN : SJN9552Y

	Qty	S\$ Unit	S\$ Amt	S\$ Labor
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
✓1 Rear Bumper	1	\$ 485.00	\$ 485.00	DE -
✓2 Rear Bumper Clips	10	\$ 5.50	\$ 55.00	AM -
✓3 Rear Bumper Inner Bracket LH/RH	1/2	\$ LH - 120.00	\$ 240.00	AM - RH X RH
✓4 Rear Bumper Outer Bracket LH/RH	1/2	\$ LH - 80.00	\$ 160.00	AM - RH X RH
✓5 Rear Bumper Reflector LH	1	\$ 58.00	\$ 58.00	CH -
6 Rear Bumper Re-inforcement	1	\$ 395.00	\$ 395.00	?
✓7 Taillamp LH/RH	2	\$ LH - 395.00	\$ 790.00	CH - X
8 Taillamp Panel LH/RH	2/1	\$ LH - 108.00	\$ 216.00	CH - X
✓9 Rear Fender LH	1	\$ 987.00	\$ 987.00	AM -
10 Rear Fender Shield LH	1	\$ 55.00	\$ 55.00	2X
11 Rear Fender Shield clips LH	5	\$ 5.50	\$ 27.50	AM X
✓12 Air Vent LH	1	\$ 140.00	\$ 140.00	DE -
✓13 Bootlid Reflector LH	1	\$ 339.00	\$ 339.00	cut -
14 Bootlid	Repair	\$ -	\$ -	
✓15 Sealant	S/nett	\$ 45.00	\$ 45.00	AM -
✓16 Damp	1	\$ 35.00	\$ 35.00	AM -
Discount 25%			\$ (995.63)	
TOTAL			\$ 3,031.87	

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	1000	\$ 1,280.00
2 Putty, blend and paint affected area	800 850	\$ 1,250.00
3 Check Wiring, re-align taillamps and ensure proper function	30	\$ 80.00
4 Remove and reinstall 2 pieces bumper sensor	60	\$ 120.00
5 Cavity Treatment on new parts	40	\$ 160.00
6 Remove & reinstall Rear reverse camera	X	\$ 120.00
7 Remove & re-install fuel tank to facilitate cutting and repairing work	80	\$ 180.00
8 Remove & re-install Rear Windscreen	120	\$ 180.00
9 Remove & re-install rear trim compartment to facilitate cutting and repairing work	80	\$ 150.00

10 Conduct water seepage test

\$ 120.00

Sub Total

\$ 3,610.00

Grand Total : \$ 6,641.87

Add 7% GST : \$ 464.93

Nett Total : \$ 7,106.80

No. of repair days: 10

SL64237D

DOA: 5/7/2018

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

fs - \$2802.00
- 25% - 700.50

\$2101.50

S/mett + \$45.00

\$2146.50

Supp - \$608.00

- 25% - \$152.00

\$456.00

labour - \$2210.00

Total - \$4812.50

Rahul

Hp 900/10068

7 days

P/P

10/07/18 @ 1500

Resurvey by panel

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 12 July 2018 11:11 AM
To: 'jionghow.ng@hcspl.com.sg'
Subject: RE: SLG4237D Third party claim against SJN9552Y (LONPAC) Liability check confirmation and arrange survey Our Ref: 18/18/18/VP05/020740 ***LKK REF:CC4/LPC18012542/eb3

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Monday, 9 July 2018 2:42 PM

To: jionghow.ng@hcspl.com.sg; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com) <sur@lkkauto.com>; 'Nivitha (LKK Auto)' <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: FW: SLG4237D Third party claim against SJN9552Y (LONPAC) Liability check confirmation and arrange survey
Our Ref: 18/18/18/VP05/020740

Without Prejudice

Dear Jiong How

Please liaise with LKK Auto Consultants Pte Ltd for survey/liability.

Dear Catherine/Nivitha

FYA -New case

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: JiongHow, Ng [<mailto:jionghow.ng@hcspl.com.sg>]

Sent: Monday, 9 July, 2018 2:32 PM

To: GERALD POH WEE BIN

Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim; ChiaLiang, Cheong

Subject: SLG4237D Third party claim against SJN9552Y (LONPAC) Liability check confirmation and arrange survey

Dear all,

Please refer to above subject matter.

Attached GIA report and Estimate for your arrangement.

Kindly Assign Survey, Car In No.8 Fourth lok yang road S/629705

Regards

Ng Jiong How

Motor Claims Advisor

Auto Servicing

Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705

t: 6833 6282

e: jionghow.ng@hcspl.com.sg

w: www.hitachi-capital.com.sg

Hitachi Capital Asia Pacific

www.hitachi-capital.com.sg

Hitachi Capital is a leader in the provision of financial services needed for procuring business equipment as well as financing consumer goods

DISCLAIMER:

This email and/or any files and/or attachments transmitted are PRIVATE & CONFIDENTIAL and may be LEGALLY PRIVILEGED. This email is intended solely for the attention and use of the name addressee(s). If you are not a named addressee, you must not use, disseminate, forward, print or copy this email and all its contents/attachments. If you have received this email in error, please notify the sender immediately by email and delete it from your system.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 9 July 2018 2:42 PM
To: jionghow.ng@hcspl.com.sg; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com); 'Nivitha (LKK Auto)'
Cc: MT_Claim_SG
Subject: FW: SLG4237D Third party claim against SJN9552Y (LONPAC) Liability check confirmation and arrange survey Our Ref: 18/18/18/VP05/020740
Attachments: report & estimate.pdf

2.52pm @ 9/7/2018
person @ jiong how
vehicle In

Without Prejudice

Dear Jiong How

Please liaise with LKK Auto Consultants Pte Ltd for survey/liability.

Dear Catherine/Nivitha

FYA –New case

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: JiongHow, Ng [<mailto:jionghow.ng@hcspl.com.sg>]
Sent: Monday, 9 July, 2018 2:32 PM
To: GERALD POH WEE BIN
Cc: Vonn, LM Siow; Jamilah, Binte MohdKassim; ChiaLiang, Cheong
Subject: SLG4237D Third party claim against SJN9552Y (LONPAC) Liability check confirmation and arrange survey

Dear all,

Please refer to above subject matter.

Attached GIA report and Estimate for your arrangement.

Kindly Assign Survey, Car In No.8 Fourth lok yang road S/629705

Regards

Ng Jiong How
Motor Claims Advisor
Auto Servicing
Total Vehicle Solutions Department

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18012542/R1db3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 03-09-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 9552Y	Veh. Inspected	SLG 4237D	
Policy No.	Z18VP05017768	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020740	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	09/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104557237	Colour	GREY	
Odometer	132431	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	6 mm	
L/H Front Tyre	205/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2018	Inspection Date	10/07/2018	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 4237D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	485.00	485.00
10	REAR BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
2	REAR BUMPER INNER BRACKET LH/RH @\$120.00	N/S NECESSARY / O/S NOT NECESSARY	240.00	120.00
2	REAR BUMPER OUTER BRACKET LH/RH @\$80.00	N/S NECESSARY / O/S NOT NECESSARY	160.00	80.00
1	REAR BUMPER REFLECTOR LH	CRACKED	58.00	58.00
1	REAR BUMPER RE-INFORCEMENT	SERVICEABLE	395.00	-
2	TAILLAMP LH/RH @\$395.00	N/S CRACKED / O/S NOT NECESSARY	790.00	395.00
2	TAILLAMP PANEL LH/RH @\$108.00	N/S BENT / O/S NOT NECESSARY	216.00	108.00
1	REAR FENDER LH	BUCKLED	987.00	987.00
1	REAR FENDER SHIELD LH	NOT NECESSARY	55.00	-
5	REAR FENDER SHIELD CLIPS LH @\$5.50	NOT NECESSARY	27.50	-
1	AIR VENT LH	DEFORMED	140.00	140.00
1	BOOTLID REFLECTOR LH	CUT	339.00	339.00
1	BOOTLID (NPA)	TO REPAIR SEE LABOUR	-	-
1	DAMP	NECESSARY	35.00	35.00
1	END PANEL (ADDITIONAL)	BENT	590.00	590.00
2	FUEL RIVET @\$5.00 (ADDITIONAL)	NECESSARY	10.00	10.00
1	TAILLAMP CLIP LH (ADDITIONAL)	NECESSARY	8.00	8.00
	LESS 25% DISCOUNT		-1,147.63	-852.50
			3,442.87	2,557.50
SPECIAL NETT ITEMS				
1	SEALANT (SN)	NECESSARY	45.00	45.00
			45.00	45.00

Report Ref No. CC4/LPC18012542/R1db3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEAT,CUT,WELD,RE-ALIGN & REPLACE DAMAGED PARTS OF AFFECTED AREA.INCLUSIVE OF THE REPAIR OF BOOTLID.		1,250.00	1,000.00
	PUTTY,BLEND AND PAINT AFFECTED AREA.		1,250.00	800.00
	CHECK WIRING,RE-ALIGN TAILLAMPS AND ENSURE PROPER FUNCTION.		80.00	30.00
	REMOVE AND REINSTALL 2 PIECES BUMPER SENSOR.		120.00	60.00
	CAVITY TREATMENT ON NEW PARTS.		160.00	40.00
	REMOVE & RE-INSTALL REAR REVERSE CAMERA.	NOT NECESSARY	120.00	-
	REMOVE & RE-INSTALL FUEL TANK TO FACILITATE CUTTING AND REPAIRING WORK.		180.00	80.00
	REMOVE & RE-INSTALL REAR WINDSCREEN.		180.00	120.00
	REMOVE & RE-INSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK.		150.00	80.00
	CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	120.00	-
			3,610.00	2,210.00
	GRAND TOTAL		7,097.87	4,812.50
RECOMMENDED COST OF REPAIRS				4,812.50

Report Ref No. CC4/LPC18012542/R1db3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.