

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE

LONPAC

QUOTE NO :
 ACCIDENT DATE : 05/07/2018@0735HRS
 VRN : SLG4237D
 MODEL : TOYOTA ALTIS
 TP VRN : SJN9552Y

ATTN: MOTOR CLAIMS DEPT

PARTS REPLACEMENT

1. Body Repair

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
1 Rear Bumper	1	\$ 485.00	\$ 485.00	DE -
2 Rear Bumper Clips	10	\$ 5.50	\$ 55.00	an -
3 Rear Bumper Inner Bracket LH/RH	1 2	\$ LH - 120.00	\$ 240.00	an - an X RH
4 Rear Bumper Outer Bracket LH/RH	1 2	\$ RH - 80.00	\$ 160.00	an - an X RH
5 Rear Bumper Reflector LH	1	\$ 58.00	\$ 58.00	CH -
6 Rear Bumper Re-inforcement	1	\$ 395.00	\$ 395.00	?
7 Taillamp LH/RH	2	\$ LH - 395.00	\$ 790.00	CH - X
8 Taillamp Panel LH/RH	2 1	\$ LH - 108.00	\$ 216.00	an - X
9 Rear Fender LH	1	\$ 987.00	\$ 987.00	an -
10 Rear Fender Shield LH	1	\$ 55.00	\$ 55.00	X
11 Rear Fender Shield clips LH	5	\$ 5.50	\$ 27.50	an X
12 Air Vent LH	1	\$ 140.00	\$ 140.00	DE -
13 Bootlid Reflector LH	1	\$ 339.00	\$ 339.00	an -
14 Bootlid	Repair	\$ -	\$ -	
15 Sealant	S/nett	\$ 45.00	\$ 45.00	an -
16 Damp	1	\$ 35.00	\$ 35.00	an -
Discount 25%			\$ (995.63)	
TOTAL			\$ 3,031.87	

2. Labor Charges

1 Panel beat, cut, weld, re-align & replace damaged parts of affected area	\$ 1,250.00
2 Putty, blend and paint affected area	\$ 1,250.00
3 Check Wiring, re-align taillamps and ensure proper function	\$ 30.00
4 Remove and reinstall 2 pieces bumper sensor	\$ 60.00
5 Cavity Treatment on new parts	\$ 40.00
6 Remove & reinstall Rear reverse camera	\$ X 120.00
7 Remove & re-install fuel tank to facilitate cutting and repairing work	\$ 80.00
8 Remove & re-install Rear Windscreen	\$ 120.00
9 Remove & re-install rear trim compartment to facilitate cutting and repairing work	\$ 80.00

1000
 800 850

10 Conduct water seepage test

\$ 120.00

Sub Total : \$ 3,610.00

Grand Total : \$ 6,641.87

Add 7% GST : \$ 464.93

Nett Total : \$ 7,106.80

No. of repair days: 10

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

Rasul
Hp 90010068
7 days
P/P
10/07/18 @ 1500
Resurvey of panel

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: