

REPAIR ESTIMATE*

VEHICLE NO : SHA 4980U

DATE 9/7/2018 13:39

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender (RH) <i>X repair</i>			\$ 593.00	
	Front Fender Shield (RH) <i>X</i>			\$ 86.00	
	Front Fender Retainer <i>X</i>			\$ 9.20	
	<i>Front Bumper X repair</i>				
	SUB TOTAL			\$ 688.20	
	LESS 20%			\$ 137.64	
	DISCOUNTED TOTAL			\$ 550.56	
	Front Fender Advertisement Logo (RH) <i>/</i>			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge				
	Panel Beating			\$ 560.00 <i>200</i>	
	Spray Painting Charge-Fender/Bumper			\$ 500.00 <i>400</i>	
	Tuff Kote			\$ 50.00 <i>X</i>	
	TOTAL LABOUR			\$ 1,110.00	
	ESTIMATE TOTAL			\$ 1,760.56	
<i>Kalvin LKK</i> <i>10/7/18 1020hrs</i> <i>2 Days.</i> <i>P/P</i> <i>After Repair photo</i>					
<div> LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to inspection • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company </div> <div> Acknowledged by Repairer Signature: Date: </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					