

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Car In

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

10 JUL 2018

Estimate No. : b1 47628
Date Estimated : 10/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Er Ang Hooa
29A HILLVIEW AVENUE
#10-02
SINGAPORE
Singapore 669562

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX2261G	WC09030	21/03/2018	520i	0

DESCRIPTIONVALUE

To replace front bumper, front right side panel, right headlamp bracket. attachments cause by accident.
To repair on front right door assembly.

2125 4,250.00

Painting on front bumper, front right side panel & front right door

2527 2,808.00

To remove and install front suspension for inspection and replace damaged parts.

2177? photo 2,655.00

To check steering geometry and conduct wheel alignment according to BMW specification (2x)

902 1,062.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check electrical wiring systems at the front section for proper function.

150 177.00

To replace right headlight including program and conduct tests for proper function.

451 531.00

To carry out body cavity preservation.
(Per panel).

100 118.00

Sundries.

? 150.00

Total Labour 1: **11,845.00**DESCRIPTIONQTY PRICVALUE

RH TENSION STRUT W/RUBBER MOUNTING
RH WISHBONE BOTTOM W/RUBBER MOUNT
TOP CONTROL ARM CAMBER CORRECTION -
WHEEL HUB WITH BEARING
FRT RH CARRIER
FRT STABILIZER LINK

1 507.70
1 609.25
1 726.00
1 411.85
1 627.00
1 112.80

507.70
609.25
726.00
411.85
627.00
112.80



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 47628**
Date Estimated : **10/07/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLX2261G	WC09030	21/03/2018	520i	0

DESCRIPTION	QTY	PRIC	VALUE
FRT RH SPRING STRUT	1	618.85	618.85
ALLOY RIM 8JX18 DOUBLE SPK 634	1	1,110.85	1,110.85
HUB CAP WITH CHROME EDGE	1	35.75	35.75
FRT SIDE PANEL BRACKET 3	1	53.55	53.55
FRT RH SIDE PANEL BRACKET 1	1	53.55	53.55
FRT RH SIDE PANEL ALUMINIUM	1	906.50	906.50
FRT RH SIDE PANEL BRACKET 2	1	53.55	53.55
COVER GRILLE RH	1	78.10	78.10
GRILLE AIR INLET MIDDLE (LINES)	1	80.85	80.85
GRILLE AIR INLET OPEN RH (LINES)	1	87.35	87.35
RH PROTECTIVE STRIP LINES (SPORT)	1	49.70	49.70
IMPACT ABSORBER TOP	1	58.75	58.75
RH FOG LAMP SUPPORT	1	77.95	77.95
GUIDE TOP RH	1	34.55	34.55
RH BUMPER GUIDE	1	16.15	16.15
FRT BUMPER PANEL PRIMED (PMA/PDC)	1	1,290.35	1,290.35
SET MOUNTING PDC/PMA SENSOR FRT	1	62.95	62.95
TRIM GRILLE FRONT	1	26.65	26.65
FRAME BOTTOM	1	51.50	51.50
LETTERING (SPORT LINE)	1	45.20	45.20
RH HEADLIGHT MOUNTING	1	136.80	136.80
LID OF DISPLACED RADIATOR	1	22.20	22.20
FRT RH WHEEL ARCH FRT SECTION COVER	1	128.40	128.40
FRT RH WHEEL ARCH RR SECTION COVER	1	128.40	128.40
COVERING CROSS MEMBER (ECE)	1	33.50	33.50
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	4,703.95	4,703.95
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
PDC SENSOR SOPHISTOGRAU II WA90	1	380.65	380.65

Total Parts : **13,341.35**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time **11/7/18 @ 11:50** Excess S\$ _____Surveyor's Name **Tan Jun** Sign **[Signature]**Surveyor's Tel **97495865** Authorized Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail **tanjun@leant.com**No. of Working Days Recommend **6 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Labour 1 **11,845.00**
Parts **13,341.35**

• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed : **0.00**
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company **0.00**

Excess **0.00**Acknowledged by Repairer @ 7% : **1,763.04**

Signature: _____

Date: **Grand Total** : **26,949.39**

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **