

KL-25

CC 4, Asm 180

12547, Kwa32

LKK:
IDAC:

56369

Kenneth

DOI:

ASSIGNMENT

10/7/2018

Date / Time:

10/7/2018

Registered in Merimen:

Pre-assign / CCU / FTE

Ym 94055



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Paramasivam Rengharaj

82674966

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

SGM 00N8F

VCA / P19A4157

15220

UPPER SCHOOL RD

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHD 9808L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans. Cab.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

12/7/2018

SHD 9808L - X;

Ym 94055. N/A (V/L: YES / NO); DOA: 12/7/18

Reg for Letter of employment - LOA

15/5/19

seek mandati via SMART

16/5/19

mandati approve via SMART.

20/9/19

File -> Su to send DS form

* V/A search date is diff w DOA.

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call OI:
After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):
After call ltr to OI:
Authorisation To Act:
Release Voucher:
Final Repair Bill:
Car Rental Invoice:
Towing Invoice:
LTA / GIA:
Medical Bill:
PIR:
Mandate/Reject Instruction:
LOD:
Payment Breakdown Form:Post-Repair Photos:
Others:

PRELIMINARY ADVICE

Date/Time: 11/7/18

Sent By: Hwa (V/L: YES / NO)

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 20/9/19

Confirm with: Jasmine

Email

Call

Final Liability:

SS

1979.50

(Agreed / Assessed) BOLA S/N No.: 27

Repair Cost:

w/hsr

SS

397.28

(4 days) X \$99.32

Loss of Rental (LOR):

SS

-

(\$ x days)

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

SS

2.45

LOR + LOU

LOR + LOI

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

Total:

SS 2389.23

Global Sum SS: 2380.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

2380.00

Name 1:

Trans-cab Auto Services Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$250.00

COPY SENT
20/9/19

GIA

ASS. REC. BY:

REF:

A2A1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S140 9808L Yr Regn: 04, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c. 1995

Colour: M. white / R. A/C: Insured / Std / NI / NA

Sp. Reading 458761 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF1ABCL15AUC 277375

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Giti

Front _____ Rear _____

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 5/7/18 D.O.I. 10/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11/7 File sent to Customer
C12m 818501

(Redacted signature)

Date/Time, File Pass to?

☐: Prell. Report

Days Of Repair: _____

1)

☐: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐: Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

☐: Interview (\$ _____)

Fees: _____

☐: Tech Invs (\$ _____)

Others: _____

☐: Weekend (\$ _____)

TOTAL

Report Format:

Lump Sum / I.B.I. (\$ _____)

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 9808L**AAD1807-050***Not Authorized**L18mg \$18506*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 9808L

VF1ABL15AUC277375

RENAULT

LATITUDE

5.7.2018

AXA**PART****LIST**

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMEP R BRACKET SIDE RH REAR
- 5 1 BUMEP R RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMEP R BRACKET SIDE LH REAR
- 8 1 BUMEP R RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 BOOT REAR
- 14 1 BOOT FINISHER
- 15 1 BOOT WHEATERSTRIP
- 16 1 BOOT REFLECTOR LAMP LH
- 17 1 BOOT REFLECTOR LAMP RH
- 18 1 BOOT BADGE 'RENAULT'
- 19 1 BOOT BADGE
- 20 1 BOOT STRUT LH
- 21 1 BOOT STRUT RH
- 22 1 BOOT HINGE LH
- 23 1 BOOT HINGE RH
- 24 1 BOOT INNER TRIM
- 25 1 BOOT SWITCH
- 26 1 BOOT LOCK
- 27 1 BOOT LOCK CATCH
- 28 2 LICENCE PLATE LAMP
- 29 2 BOOT RUBBER PLUG

\$	<i>Buclm</i>	1,108.46	✓
\$	<i>nd</i>	768.84	✓
\$	<i>Sn</i>	113.47	}
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	43.61	
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	43.61	
\$	<i>n</i>	777.52	
\$	<i>n</i>	225.95	
\$	<i>n</i>	225.95	
\$	<i>n</i>	2,872.68	
\$	<i>Sn</i>	470.06	
\$	<i>Sn</i>	323.05	
\$	<i>Sn</i>	493.35	
\$	<i>Sn</i>	493.35	
\$	<i>nn</i>	225.36	
\$	<i>nn</i>	225.36	
\$	<i>Sn</i>	276.08	
\$	<i>Sn</i>	276.08	
\$	<i>n</i>	367.84	
\$	<i>n</i>	367.84	
\$	<i>Sn</i>	586.45	
\$	<i>n</i>	168.13	
\$	<i>n</i>	202.67	
\$	<i>n</i>	74.40	
\$	<i>Sn</i>	50.52	
\$	<i>Sn</i>	221.81	

Trans-cab Auto Services Pte Ltd

AAD1807-050

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9808L

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	}
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	
33	1 WHEELARCH REAR LH	\$	Sn	543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
35	1 FENDER PANEL REAR RH	\$	R	3,299.13	
36	1 WHEELARCH REAR RH	\$	Sn	543.47	
37	1 TAILLAMP RH	\$	Sn	552.55	
38	1 TAILLAMP PANEL RH	\$	R	986.70	
39	1 TAILLAMP LH	\$	Sn	552.55	
40	1 TAILLAMP PANEL LH	\$	R	986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
44	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	
45	1 EXHAUST REAR	\$	R	7,489.05	}
46	1 EXHAUST CAP REAR	\$	R	230.49	
47	1 FUEL FLAP L70Y	\$	Sn	343.57	
48	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	
49	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	
TOTAL		\$		47,505.69	
10%		\$		4,750.57	
		\$		42,755.12	

Special Nett

1	1SET PARKING AID	\$	Sn	700.00	X
2	1SET REAR BUMPER CLIP	\$	R	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	R	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	R	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	R	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	R	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	R	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	R	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	R	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET BOOT FINISHER CLIP	\$	R	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	R	30.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-050**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9808L

13	1 BOOT STICKER "6555-3333"	\$	<i>nn</i>	30.00	}	<i>X</i>
14	1 BOOT INNER TRIM CLIP	\$	<i>nn</i>	45.00		
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>nn</i>	35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00		
19	1 TAILLAMP CLIP RH	\$	<i>nn</i>	5.00		
20	1 TAILLAMP CLIP LH	\$	<i>nn</i>	5.00		
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i>	80.00		
22	1 WINDSCREEN MOULDING	\$	<i>nn</i>	100.00		
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00		
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sm</i>	385.00		
25	1 SPARE TYRE	\$	<i>sm</i>	330.00		

TOTAL \$ 2,225.02**TOTAL PARTS \$ 44,980.14****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	<i>2001</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00	<i>X</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9808L

AAD1807-050

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00 X

TOTAL \$ 12,540.00

Over All Total \$ 57,520.14

57900-12 *

(LUMP SUM)

Repair Days

20 DAYS

2 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHD9808L

Vehicle to be Exported: Yes

Intended De-registration Date: 06 Jul 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2013

Engine No.: M9R8839C001190

Chassis No.: VF1ABL15AUC277375

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 14 Apr 2014

First Registration Date: 14 Apr 2014

Transfer Count: 0

Actual ARF Paid: \$12,498.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Apr 2022

PARF Rebate Amount: \$9,373.00

Intended COE Rebate Details

COE Expiry Date: 13 Apr 2022

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$59,871.00

COE Rebate Amount: \$28,210.00

Total Rebate Amount: \$37,583.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Jul 2018

OK



Service Request Details

Claim

S8M00NJF

Reference

None 

Kenneth

Loss Date

July 5, 2018

Request Date

July 10, 2018

Due Date

July 17, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHD9808L

Make

TPVD RENAULT

Model

LATTUDE 2.0

Service Address

Primary Contact/Insured

CKR CONTRACT SERVICES PTE LTD

56 SUNGEI KADUT DRIVE, CKR BUILDING, 729573, Singapore

63089300

rani@ckrgroup.com.sg

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)



CKR CONTRACT SERVICES PTE LTD

Building & Civil Engineering Contractors

56 Sungei Kadut Drive, CKR Building
Singapore 729573
Tel: 6308 9300 Fax: 6308 9301
Email: ckr@ckrgroup.com.sg
Website: www.ckrgroup.com.sg
Co. Reg No.: 200416739G
Gst Reg No.: 200416739G

2nd January 2019

AJAX Adjusters & Surveyors Pte Ltd
120 Lower Delta Road
#08-08 Cendex Centre
Singapore 169208

Attn: Alex Chew

Dear Alex

AUTHORISATION LETTER

We write to confirm that (Paramasivam Rengaraj / G8375546L) is employed by our company as a (Coordinator cum Driver) since (19th August 2016) and he is authorised to drive (YM9405S).

Please contact me at (6308 9344) for further enquiries.

Yours faithfully


NAME & COMPANY STAMP



We Offer Competitive Value with Quality Service



Re:S8M00NJF- seek mandate

Type

🔗 Question

Message

PLS PROCEED

Reply

Hsiao Tong (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 7 August 2019 10:09 AM
To: Hsiao Tong (LKKAuto)
Subject: FW: New message for service request 56369, vehicle number SHD9808L

7/8/19 8:29 AM *** Re:S8M00NJF- seek mandate *** UPDATES? - CHAN Kian Chuan

-----Original Message-----

From: kianchuan.chan@axa.com.sg [mailto:kianchuan.chan@axa.com.sg]
Sent: Wednesday, 7 August, 2019 8:29 AM
To: admin-d@lkkauto.com
Subject: New message for service request 56369, vehicle number SHD9808L

AXA Insurance has sent you a message for claim number S8M00NJF.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/5/2018

Survey Details:

Date of loss	5-Jul-18
Date of appointment	10-Jul-18
Date of survey	10-Jul-18
Location of survey	Trans-cab Auto Services Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SHA 4398B
Make and Model	Renault Latitude 2.0L DCI - 1995cc
Date of registration	14-Apr-14
Excess	
Market Value	\$ -
Parf Rebate	\$ -
Nett Loss	\$ -

Repair details:

Initial Estimate	57,520.14
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 1,854.57
Check items (estimate)	\$ -
Labour	\$ 480.00
Total	\$ 2,334.57
Lump Sum(if applicable)	\$ 1,850.00

Number of days for repair	<u>2 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Head to rear BOLA 27

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 1,979.50	
Loss of use		no. of days
Loss of rental	\$ 595.92	no. of days 6days x \$ 99.32
Loss of income		no. of days
LTA search fees	\$ 7.49	
Others		
Proposed Total	\$ 2,582.91	

Hsiao Tong (LKKAUTO)

From: claims <claims@transcab.com.sg>
Sent: Saturday, 14 September 2019 1:43 PM
To: Hsiao Tong (LKKAUTO); 'Ng Wai Yin'
Cc: claims@transcab.com.sg
Subject: RE: Your ref: AAD1807-050 (SHD9808L) *Our ref: CC4/ASM18012547/Kpa3 [ACCIDENT INVOLVING YM 9405S(AXA) AND SHD 9808L ON 05/07/2018]

Without Prejudice

Dear Hsiao Tong

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Monday, 12 August 2019 1:49 PM
To: 'jasminetan@transcab.com.sg' <jasminetan@transcab.com.sg>; Ng Wai Yin <waiyin.ng@transcab.com.sg>; claims@transcab.com.sg
Subject: Your ref: AAD1807-050 (SHD9808L) *Our ref: CC4/ASM18012547/Kpa3 [ACCIDENT INVOLVING YM 9405S(AXA) AND SHD 9808L ON 05/07/2018]

Your ref: **AAD1807-050 (SHD9808L)**
Our ref: CC4/ASM18012547/Kpa3

Without Prejudice

Dear Sirs/Madam,

ACCIDENT INVOLVING YM 9405S(AXA) AND SHD 9808L ON 05/07/2018

We refer to the above matter.

We propose settlement at a global sum of \$2,380.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Lkk

Our Ref : AAD1807-050

Your Ref : YM9405S

Date : 12.October 2018

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

**ACCIDENT INVOLVING SHD9808L AND YM9405S ON 05/07/18 02:20 PM ALONG
UPPER SERANGOON ROAD**

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	1,979.50
2.	Loss of Rental for <u>6</u> days @ \$ <u>99.32</u> per day	\$	595.92
3.	Loss of Income for ____ days @ \$____ per day	\$	0.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	2,582.91

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver
Certificate of Insurance
Original final repair bill

Rental rate and mileage records
Authorization To Act
LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully
Trans-Cab Services Pte Ltd



Jasmine Tan
General Manager
Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012547/Kpa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN		Date : 01-10-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YM 9405S	Veh. Inspected	SHD 9808L
Policy No.	VCA/P1994157	Coverage (\$)	0.00
Claim No.	S8M00NJF	Excess (\$)	0.00
Assign From	KIAN CHUAN	Assign Date	10/07/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	VF1ABL15AUC277375	Colour	METALLIC WHITE / RED
Odometer	458761	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/07/2018	Inspection Date	10/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9808L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR (CONSISTENT)	BUCKLED / DENTED	1,108.46	1,108.46
1	BUMPER LOWER REAR (CONSISTENT)	DENTED	768.84	768.84
1	BUMPER BRACKET CTR REAR (CONSISTENT)	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR (CONSISTENT)	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR (CONSISTENT)	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH (CONSISTENT)	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR (CONSISTENT)	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET LH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR (CONSISTENT)	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR (CONSISTENT)	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER (CONSISTENT)	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH (CONSISTENT)	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT' (CONSISTENT)	NOT NECESSARY	225.36	-
1	BOOT BADGE (CONSISTENT)	NOT NECESSARY	225.36	-
1	BOOT STRUT LH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT STRUT RH (CONSISTENT)	SERVICEABLE	276.08	-
1	BOOT HINGE LH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH (CONSISTENT)	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM (CONSISTENT)	SERVICEABLE	586.45	-
1	BOOT SWITCH (CONSISTENT)	TO REPAIR SEE LABOUR	168.13	-

Report Ref No. CC4/ASM18012547/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH (CONSISTENT)	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP (CONSISTENT)	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG (CONSISTENT)	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	TAILLAMP RH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH (CONSISTENT)	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM (CONSISTENT)	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM (CONSISTENT)	SERVICEABLE	612.21	-
1	EXHAUST REAR (CONSISTENT)	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR (CONSISTENT)	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y (CONSISTENT)	SERVICEABLE	343.57	-
1	CHASSIS PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,766.43	-
1	WHEEL HOUSING PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	4,682.09	-

Report Ref No. CC4/ASM18012547/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-4,750.57	-187.73
			42,755.10	1,689.57
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN) (CONSISTENT)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN) (CONSISTENT)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN) (CONSISTENT)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN) (CONSISTENT)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN) (CONSISTENT)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN) (CONSISTENT)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN) (CONSISTENT)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
			2,225.02	165.00

Report Ref No. CC4/ASM18012547/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM REAR, BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT SWITCH, BOOT LOCK, BOOT LOCK CATCH, DOOR PANEL REAR LH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR, }		4,200.00	200.00
	EXHAUST CAP REAR, CHASSIS PANEL REAR RH AND WHEEL HOUSING PANEL REAR RH. }		-	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER BOOTLID FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	480.00

Report Ref No. CC4/ASM18012547/Kpa3s2



GRAND TOTAL		57,900.12	2,334.57
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,850.00

Report Ref No. CC4/ASM18012547/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.