

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

10-07-18

OUR REF NO. SCU 1817H

ONG HOCK CHWEE
BLK 909, HOUGANG
ST 91, #01-94
SINGAPORE 530909

SUPPLEMENTARY BILL FOR VEHICLE NO. SCU 1817H
MODEL : TOYOTA COROLLA

LIST ITEM

1) REAR FENDER (RH)	<i>11</i>	1,124.00	<i>X</i>
2) REAR WINDSCREEN MOULDING	<i>12</i>	214.00	<i>X</i>

		1,338.00	
	LESS DISCOUNT - 25%	334.50	
			1,003.50

SPECIAL NETT ITEM

1) REAR WINDSCREEN INNERSEAL	<i>11</i>	60.00	<i>X</i>
2) REAR WINDSCREEN GUM	<i>12</i>	60.00	<i>X</i>
			120.00

LABOUR CHARGE

1) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC - REAR FENDER (RH)	<i>11</i>	700.00	<i>X</i>
2) TO RESPRAY ON REAR FENDER RH	<i>11</i>	440.00	<i>X</i>
3) TO REPLACE REAR WINDSCREEN	<i>12</i>	220.00	<i>X</i>
			1,360.00
	GRAND TOTAL		<u>2,483.50</u>