

REPAIR ESTIMATE*

VEHICLE NO : SHA 3260X

DATE 9/7/2018 9:46

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>cr</i>			\$ 578.40	
	Rear Bumper Reinforcement <i>X su</i>			\$ 483.30	
	Rear Bumper Clip <i>— ne</i>			\$ 22.00	
	Rear Bumper Sponge <i>X su</i>			\$ 137.40	
	Rear Bumper Under Cover <i>X su</i>			\$ 185.80	
	Rear Bumper Protector (RH) <i>X su</i>			\$ 38.00	
	SUB TOTAL			\$ 1,444.90	
	LESS 20%			\$ 288.98	
	DISCOUNTED TOTAL			\$ 1,155.92	
	Rear Bumper Reverse Sensor <i>X su</i>			\$ 135.70	Nett
	Rear Bumper Advertisement Logo <i>— ne</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>— ne</i>		\$ 100.00	\$ 200.00	Nett
	<i>Rear Bumper Rubber Mat — ne</i>	<i>\$50</i>			
				\$ 385.70	
	Labour Charge				
	Panel Beating			\$ 350.00 <i>200</i>	
	Spray Painting Charge			\$ 250.00 <i>200</i>	
	Wiring Charge			\$ 50.00 <i>X 11</i>	
	Remove/Refix Reverse Sensor			\$ 120.00 <i>30</i>	
	TOTAL LABOUR			\$ 770.00	
	ESTIMATE TOTAL			\$ 2,311.62	
<p><i>Kehi LKK</i></p> <p><i>9/7/18 1125 hr.</i></p> <p><i>2 Br.</i></p> <p><i>L/S</i></p> <p><i>After Repair photo</i></p>					
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party surveys on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					