

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 13 Jul 2018

Preliminary Advice

Insured Vehicle No	: SJL1896T		
TP Vehicle No	: SGZ8505M	Accident Date	: 23/06/2018
Make	: TOYOTA COROLLA	Assignment Date	: 10/07/2018
Date of Inspection	: 11/07/2018	Est. Duration of Repair	: 3 days
Inspection At	: Motorway Car Care Centre Pte Ltd - Lower Delta (HQ) 1094 LOWER DELTA ROAD Singapore 169205		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,700.00
Revised Amount	:S\$	2,330.00
Check Items (Estimated)	:S\$	790.00
Total	:S\$	3,120.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.