

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

10-Jul-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6372 B

### S/NETT

1 set	n/s door sticker ✓	\$	100.00
1 pc	Rear n/s fender sticker ✓	\$	60.00
	Sundry	\$	<del>50.00</del> 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s door, rear n/s fender, etc.	\$	<del>650.00</del> 400
	To putty and spray painting on rear n/s door, rear n/s fender	\$	<del>400.00</del> 360
	To apply rustproofing on the repaired and replaced panels.	\$	<del>150.00</del> x
		\$	<u>1,590.00</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

Kalvin Ullay  
10/7/18 1305h  
3 Pm.  
4s  
Atta Rumpu

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: