

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 12 Jul 2018

Preliminary Advice

Insured Vehicle No : SKX7657C

TP Vehicle No : SJP4613C

Make : HONDA STREAM

Date of Inspection : 11/07/2018

Inspection At : Lim Motor Pte Ltd (HQ)
160 Sin Ming Drive, #05-20 Autocity
Singapore 575722

Accident Date : 07/07/2018

Assignment Date : 10/07/2018

Est. Duration of Repair : 7 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear body. U/C affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,552.80
Revised Amount	:S\$	3,529.88
Check Items (Estimated)	:S\$	1,810.00
Total	:S\$	5,339.88

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.