

ASS. REC. BY:

REF:

CS/msh18012556/Kob⁰²

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Maiman

From (Person):

Christina Wong

of

MSLH

Date/Time:

10/7/2018 4:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJP 4613C

Insured:

SKX 7657C

at Workshop m/s

Lim Motor

Tel:

9271 2214

of

160 Sin Ming Drive #05-20

Policy No:

A28832018ARW

Claim No:

563909

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP:

11/07/2018 @ morning

H.O.D. Endorsement:

Date/Time:

10/07/2018 4:40pm

Person Contacted:

Chris

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJP 4613C - CT / ALH 11/07/2018 / Kpb32
	SKX 7657C - X
12/07/18	@ 14:46 p.m. revised IA to Christina Wong via Maiman.
20/8	11 Lm @ 280d email & confirm

ASS. REC. BY:

REF:

MSG/

ASSIGNMENT

25/3/2009

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

3:19

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

12/7

File pass to Catherine

(\$ 8,752.80 Red - 76%)

RECEIVED 20 AUG 2018

Date/Time, File Pass to?

20/08/08

1)

Typist

Date/Time, File Return to?

2)

☐

: Prell. Report

☒

: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

: Factors

: Others

TOTAL

200
10
210

Veh No:

STP 4613C

Yr Regn:

03 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

MPV

Make:

Honda Stream

c.c

1799

Colour:

M-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

260762

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RNG

1072302

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Maxxis

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

7/7/18

D.O.I.

11/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/Side body & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Report Format:

Lump Sum / I.B.I: (\$ 2,800/- 1/5)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018		10 Jul 2018 16:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All	
CLAIM SUBFOLDER DETAILS					
Insured:		CHUA TIONG LOCK, ID: S72182661			
Main Claimant:		LIM JIT HIANG DAMIEN, ID: S76367011			
Vehicle Reg. No.:		SJP4613C	Date of Loss:	07/07/2018 14:00 - :59 [124 Months and 8 Days From LTA Reg Date (Man Yr)]	
Claim Type:		TP / 563909	Policy/Cover Note No.:	A28832018AVW (Comprehensive) Coverage: 28/12/2017 - 27/12/2018	
Vehicle Reg. No. (Insured):		SKX7657C	Policy No. (Claimant):		
		Excess:	S\$750.00		
Repairer:		Lim Motor Pte Ltd (HQ) 160 Sin Ming Drive, #05-20 Autocity, 575722 Sin Ming - Tel:			
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]			
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/07/2018]			
Adj Asg. Remarks:		Liability not clear. Contact Person: Chris Chan Pick Yuen / 9271 2214. TP agree to use LKK Auto Consultants as the SJE.			
ASSOCIATED MAIL RECEIVED					
			View All	Compose Case Mail	
There are no mail for this case.					
ALL ASSOCIATED TASKS					
		View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler
		Assigned By	Completed On	Created On	Done?
No results.					

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 12 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKX7657C	Accident Date	: 07/07/2018
TP Vehicle No	: SJP4613C	Assignment Date	: 10/07/2018
Make	: HONDA STREAM	Est. Duration of Repair	: 7 days
Date of Inspection	: 11/07/2018		
Inspection At	: Lim Motor Pte Ltd (HQ) 160 Sin Ming Drive, #05-20 Autocity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear body. U/C affected due to collision and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,552.80
Revised Amount	:S\$	3,529.88
Check Items (Estimated)	:S\$	1,810.00
Total	:S\$	5,339.88

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Lim Motor Pte Ltd

160 Sin Ming Drive #05-20

Sin Ming Auto City

Singapore 575722

Phone Number: 6552 7761

Fax Number: Mobile No. 9766 7543

Customer:	Date: 7/7/2018 3:37 PM
Company:	VIN
License NO:	Technician:
Odometer:	Order NO:

VEHICLE ALIGNMENT REPORT

HONDA, STREAM RN6, RN8 (2WD, 17" Wheel), 06-12 (Customized)


Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	3°20'	5°20'	----
		Right	----	3°20'	5°20'	----
	Camber	Left	0°06'	-0°45'	0°45'	0°06'
		Right	-0°12'	-0°45'	0°45'	-0°12'
	Toe	Left	0.6mm	-0.5mm	0.5mm	0.6mm
		Right	-1.6mm	-0.5mm	0.5mm	-1.6mm
Total		-0.9mm	-1.1mm	1.1mm	-0.9mm	
Rear	Camber	Left	-1°18'	-1°45'	-0°15'	-1°18'
		Right	-1°18'	-1°45'	-0°15'	-1°18'
	Toe	Left	1.2mm	0.3mm	1.1mm	1.2mm
		Right	0.6mm	0.3mm	1.1mm	0.6mm
		Total	1.9mm	0.6mm	2.2mm	1.9mm
	Max Thrust Angle		-0°03'	----		-0°03'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	----	11°05'	11°05'	----
		Right	----	11°05'	11°05'	----
Included Angle		Left	----	----	----	----
		Right	----	----	----	----
Toe Out On Turns		Left	----	----	----	----
		Right	----	----	----	----
Max Turn Inside		Left	----	----	----	----
		Right	----	----	----	----
Toe Curve Change		Left	----	----	----	----
		Right	----	----	----	----
Setback		Front	-3mm	----	----	-3mm
		Rear	-13mm	----	----	-13mm
Track Width Diff.			12mm			12mm
Wheel Base Diff.			10mm			10mm
Front Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Rear Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Frame Angle						----

Thank You For Your Business.



+65 9166 5806 @ Lim Motor Office

07/7/2018 lúc 16:02



> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	67011
Vehicle Details	
Vehicle No.:	SJP4613C
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A1779825
Chassis No.:	RN61072302
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$5,244.00
Original Registration Date:	29 Feb 2008
First Registration Date:	25 Mar 2009
Transfer Count:	3
Actual ARF Paid:	\$5,244.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Feb 2018
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$4,889.00
COE Rebate Amount:	\$341.00
Total Rebate Amount:	\$341.00

The information contained herein is correct as at 12 Jul 2018

OK

LIM MOTOR PTE LTD

BLOCK 160 Sin Ming Drive, Sin Ming Autocity # 05-20 Singapore 575722
Tel: (65) 65527761 HP: 92712214

LIM JI HANG DAMIEN
Blk 160 SIN MING DRIVE
05-20 SIN MING AUTOCITY
Singapore 575722

10th JULY 2018

Accident date: 07th JULY 2018

Estimated repair cost for vehicle no: SJP4613C HONDA STREAM 1.8X A '09

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear L/H door	Ry	\$960.30 ✓
2	1	Rear L/H Door Lower Lock	R	\$203.30 x
3	1	Rear L/H door inner trim board	Sn	\$502.30 x
4	1	Rear L/H door inner rubber	Sn	\$152.30 x
5	1	Rear door glass gear motor assy - LH	Sn	\$397.20 x
6	1	Rear sport rim - LH	Net	\$600.00 4 new
7	1	raer tyre - LH	755N Gt	\$350.00 309sn
8	1	Rear Trailing Arm		\$384.10 ?
9	1	Rear Knuckle Arm Bearing		\$339.00 ?
10	1	Rear Knuckle Arm		\$308.00 ?
11	1	Rear Shock Absorber		\$404.00 ?
12	1	Rear tail lamp-LH		\$352.40 ✓
13	1	Rear Bumper	Sn	\$1,377.00 x
14	1	Rear fender L/H	Ry	\$858.30 ✓
15	1	Rear fender inner trim board top	Sn	\$209.20 x
16	1	Rear fender L/H INNER PANEL	R	\$750.10 x
17	1	Rear fender L/H trim board	Sn	\$385.30 x

Subtotal :- \$8,532.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

labour charges

To remove & refit fender glass

\$200.00 501

Gum

nn \$50.00 30sn

To remove & refit petrol tank

\$180.00 601

To remove & refit L/H undercarriage

nn \$280.00 7X

To check wheel alignment computer

\$150.00 601

To check wiring

\$60.00 201

Towing charges

nn \$100.00 8

Panel beating

\$1,000.00 8001

Spray painting

\$1,000.00 5501

Subtotal :- \$3,020.00Total:- \$11,552.80

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18012556/KSBN2

Date: 20/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28832018AVW
Claimant Vehicle No :	SJP4613C	Insured Vehicle No :	SKX7657C
Date of Loss:	07/07/2018	Nature of Claim:	TP
		Claim No:	563909

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP4613C	Engine No:	R18A1779825
Make & Model:	HONDA STREAM, 1.8 X (A)	Chassis No:	RN61072302
Reg. Date:	25/03/2009 (Man. Year: 2008)	Odometer:	260762 km
Colour:	Metallic Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	Maxxis 3 mm	Rear Right Side:	Maxxis 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,582.80	1,959.88	6,622.92	77.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,970.00	1,540.00	1,430.00	48.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,552.80	3,499.88	8,052.92	69.71
Approved Total (Overridden) (\$\$)		2,800.00		
(\$\$)	11,552.80	2,800.00	8,752.80	75.76
+ GST 7.00/7.00% (\$\$)	808.70	196.00	612.70	75.76
Nett Amount (\$\$)	12,361.50	2,996.00	9,365.50	75.76

INSPECTION

Date of Assignment:	10/07/2018	
Date Inspected:	11/07/2018	Inspected At: Lim Motor Pte Ltd (HQ) 160 Sin Ming Drive, #05-20 Autocity Singapore 575722
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2018)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP4613C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR L/H DOOR	Bent	960.30 F	*960.30 FL
2	1		*REAR L/H DOOR LOWER LOCK	Repair	203.30 F	*- FL
3	1		*REAR L/H DOOR INNER TRIM BOARD	Serviceable	502.30 F	*- FL
4	1		*REAR L/H DOOR INNER RUBBER	Serviceable	152.30 F	*- FL
5	1		*REAR DOOR GLASS GEAR MOTOR ASSY-LH	Serviceable	397.20 F	*- FL
6	1		*REAR TRAILING ARM	Serviceable	384.10 F	*- FL
7	1		*REAR KNUCKLE ARM BEARING	Serviceable	339.00 F	*- FL
8	1		*REAR KNUCKLE ARM	Serviceable	308.00 F	*- FL
9	1		*REAR SHOCK ABSORBER	Serviceable	404.00 F	*- FL
10	1		*REAR TAIL LAMP-LH	Serviceable	352.40 F	*- FL
11	1		*REAR BUMPER	Serviceable	1,377.00 F	*- FL
12	1		*REAR FENDER L/H	Bent	858.30 F	*858.30 FL
13	1		*REAR FENDER INNER TRIM BOARD TOP	Serviceable	209.20 F	*- FL
14	1		*REAR FENDER L/H INNER PANEL	Repair	750.10 F	*- FL
15	1		*REAR FENDER L/H TRIM BOARD	Serviceable	385.30 F	*- FL
16	1		*REAR SPORT RIM-LH	Dented	600.00 FS	*400.00 FS
17	1		*REAR TYRE-LH (\$250.00)(30%)	Cut	350.00 FS	*75.00 FS
18	1		*GUM	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,582.80	2,323.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	363.72
Total Parts (\$\$)	8,582.80	1,959.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FENDER GLASS	New	200.00	50.00
2	TO REMOVE & REFIT PETROL TANK	New	180.00	60.00
3	TO REMOVE & REFIT L/H UNDERCARRIAGE	New	280.00	-
4	TO CHECK WHEEL ALIGNMENT COMPUTER	New	150.00	60.00
5	TO CHECK WIRING	New	60.00	20.00
6	TOWING CHARGES	New	100.00	-
7	PANEL BEATING	New	1,000.00	800.00
8	SPRAY PAINTING	New	1,000.00	550.00
Gross Labour Cost (S\$)			2,970.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >