

22/03/2002

ASS. REC. BY:

REF:

CS/FL18012563/Kvbnz

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): CWS Eileen Lee of FCL Date/Time: 10/7/2018 5:04pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 7709K Insured: SHD 3948E

at Workshop m/s Accord Auto Tel: 97400999

of Blk 10 Amk Ind Park 2A #03-11

Policy No: Claim No: 018005182MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 06/7/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

Date/Time: 10/7/2018 5:24pm Person Contacted: Jessy Vehicle: IN / OUT

Date/Time Action/Instruction (✓) Estimate

SLV 7709K - CS/TM18012440/Kvbnz DA: 06/7/2018

SHD 3948E - CS/FL18012563/Kvbnz DA: 07/5/2017

12/7/18 Email preli revised to FCL

14/8/18 @ 3796.56 email confirmed by email (Red 4855.44, 5610)

(08/11/13) wef

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 11/07/18

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MVTo Inspect Vehicle No: SLV 7709Kat Workshop m/s Accord Autoof BLK 10 Amk Ind. Park 2A # 03-11

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record) after 10am

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 880k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLV 7709K Yr Regn: 01, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Honda Shuttle c.c. 1498Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 12936 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: E-K 8 : 1200 405Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: M/S / Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 07/7/18

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 11/7/18Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/7 File post to Caravan

RECEIVED 14 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 14/8 - typistReport Format: CWSLump Sum / I.B.I.: (\$ 3796.56)Days Of Repair: 5Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

160

50

30 + 50

30

340



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005282MFSH

Our ref: CS/FCI18012563/Kvb

Date : 12/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 7709K


We thank for your instruction on 10/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 11/7/2018 at the premises of M/s ACCORD AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$8,352.80
Revised Estimate Amount	: S\$1,611.28
"Check" Items Amount	: S\$4,886.88
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front o/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 14 August 2018 11:32 AM
To: Accord Auto(Claims); Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: RE: SLV7709K - Bf Paint and Aft Paint Photos

Dear Jessy,

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Accord Auto(Claims) <claims@mycarworkshop.com.sg>
Sent: Tuesday, 14 August 2018 11:27 AM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Re: SLV7709K - Bf Paint and Aft Paint Photos

Dear Kenneth,

We confirmed acceptance COR at \$3796.56 (part by part) and 5 w/days.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

On 13 August 2018 at 09:04, Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com> wrote:

Attach finalised for SLV 7709K. Kenneth

From: Accord Auto(Claims) [mailto:claims@mycarworkshop.com.sg]
Sent: Monday, 23 July, 2018 11:58 AM

To: Kenneth Kong (LKKAUTO)
Subject: SLV7709K - Bf Paint and Aft Paint Photos

Dear Kenneth,

Please refer to attached photos.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

Veron Chen (LKKAUTO)

From: Accord Auto(Claims) <claims@mycarworkshop.com.sg>
Sent: Friday, 10 August 2018 5:03 PM
To: Veron Chen (LKKAUTO)
Subject: SLV7709K - Finalize
Attachments: Supp.pdf; Rewrite Estimate.pdf

Dear Veron,

Please refer to attached documents and finalize with us.

Thank you.

Kind regards,
Jessy Soe

Accord Auto Services Pte Ltd
10 Ang Mo Kio Ind Park 2A
#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999
Tel : (65) 6481 9517
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

MOTOR SURVEY ASSIGNMENT

Date	09-07-2018	Our Ref No. D18005282MFSH
Accident Date	06-07-2018	Claim Type. Third Party
Insured Vehicle	SHD3948E	Third Party Vehicle. SLV7709K
Survey Location	10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11	
Contact Person.	JESSY SOE	
Contact No.	64819517/ 97400999	Fax No. 64819516
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ACCORD AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 12 July 2018 11:21 AM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005282MFSH/1, SLV 7709K
Attachments: SLV 7709K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLV 7709K
Date of survey: 11/7/2018
Number of days: 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 10 July 2018 5:27 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005282MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 10 July, 2018 5:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005282MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> Back to OneMotoring

Enquire Transfer Fee

Vehicle No.:	SLV7709K
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT
Chassis No.:	GK81200405
Propellant:	Petrol
Engine No.:	L15B5460471
Engine Capacity:	1496 cc
Maximum Power Output:	97.0 kW (130 bhp)
Maximum Laden Weight:	1405 kg
Unladen Weight:	1130 kg
Year Of Manufacture:	2017
Original Registration Date:	15 Jan 2018
Lifespan Expiry Date:	-
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
Quota Premium:	\$38,200.00
COE Expiry Date:	14 Jan 2028
Road Tax Expiry Date:	14 Jul 2018
PARF Eligibility Expiry Date:	14 Jan 2028
Inspection Due Date:	14 Jan 2021
Intended Transfer Date:	07 Jul 2018
CO2 Emission:	120.00 (g/km)
CEV/VES Rebate Utilised Amount:	\$10,000.00
CO Emission:	0.117000 (g/km)
HC Emission:	0.014000 (g/km)
NOx Emission:	0.003000 (g/km)
PM Emission:	4.400000 (mg/km)

The current road tax expiry is 14 Jul 2018. You may renew the road tax from 15 Apr 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 14 Jul 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable. Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Additional Levy:			25.00
Sub Total:			341.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	366.00
Total Amount Payable:			366.00

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Additional Levy:			25.00
Sub Total:			682.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	707.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

MS First Capital Insurance Limited
36, Robinson Road
#16-01 City House
Singapore 068877
Attn: Motor Claims Department

Date : 07/07/2018
Vehicle No : SLV7709K
Veh Make/Model : Honda Shuttle 1.5G CVT
YOM : 2017
Chassis No : GK81200405
Date of Accident : 06/07/2018

Not withstanding
1.B.1
Repair by pain
4-5 days

No	Qty	Description	Amount \$
List Items:-			
1	1	Bonnet	\$ 920.80
2	1	RH headlamp	\$ 1088.70 2,230.80
3	1	Front RH fender	\$ 435.00
4	1	Front RH fender splash shield	\$ 110.00
5	10	Front RH fender splash shield clip	\$ 38.00
6	1	Front grille base	\$ 395.00
7	1	Front grille chrome	\$ 322.00
8	1	Front grille badge	\$ 24.00
9	1	Front bumper	\$ 1,050.00
10	1	Front bumper grille	\$ 140.00
11	1	Front RH bumper fog lamp cover (top)	\$ 33.20
12	1	Front RH bumper fog lamp cover (bottom)	\$ 45.00
13	1	Front bumper tow cover	\$ 25.00
14	1	Front bumper side retainer - RH	\$ 15.40
15	10	Front bumper clip	\$ 38.00
16	1	Front bumper reinforcement	\$ 420.90
17	1	Support panel	\$ 760.40
18	1	Washer tank	\$ 75.00
Total - List Item			\$ 7,078.50
Less 20%			\$ 1,415.70
Total			\$ 5,662.80
Labour Charges:-			
1		Spray painting on all affected area.	\$ 1,200.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,200.00
3		To apply anti rust treatment.	\$ 150.00
4		To check wiring system & light.	\$ 80.00
5		To check & adjust wheel alignment.	\$ 60.00
Total - L/C			\$ 2,690.00
Sub-Total			\$ 8,352.80
7% GST			\$ 584.70
Total			\$ 8,937.50

MSK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

MS First Capital Insurance Limited

36, Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Department

Date :

07/07/2018

Vehicle No :

SLV7709K

Veh Make/Model :

Honda Shuttle 1.5G CVT

YOM :

2017

Chassis No :

GK81200405

Date of Accident :

06/07/2018

Not Authored

1.B.1

Recovery B4 pain

3796.56 \$-5 day

No	Qty	Description	Amount \$
<u>List Items:-</u>			
1	1	Bonnet	\$ 920.80
2	1	RH headlamp (Not LED)	\$ 1088.70 -2,230.80
3	1	Front RH fender	\$ 435.00
4	1	Front RH fender splash shield	\$ 110.00
5	10	Front RH fender splash shield clip	\$ 38.00
6	1	Front grille base	\$ 395.00
7	1	Front grille chrome	\$ 322.00
8	1	Front grille badge	\$ 24.00
9	1	Front bumper	\$ 1,050.00
10	1	Front bumper grille	\$ 140.00
11	1	Front RH bumper fog lamp cover (top)	\$ 33.20
12	1	Front RH bumper fog lamp cover (bottom)	\$ 45.00
13	1	Front bumper tow cover	\$ 25.00
14	1	Front bumper side retainer - RH	\$ 15.40
15	10	Front bumper clip	\$ 38.00
16	1	Front bumper reinforcement	\$ 420.90
17	1	Support panel	\$ 760.40
18	1	Washer tank	\$ 75.00
Total - List Item			\$ 7,078.50
Less 20%			\$ 1,415.70
Total			\$ 5,662.80
<u>Labour Charges:-</u>			
1		Spray painting on all affected area.	\$ 1,200.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,200.00
3		To apply anti rust treatment.	\$ 150.00
4		To check wiring system & light.	\$ 80.00
5		To check & adjust wheel alignment.	\$ 60.00
Total - L/C			\$ 2,690.00
Sub-Total			\$ 8,352.80
7% GST			\$ 584.70
Total			\$ 8,937.50

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Date :	11/07/2018
Vehicle No :	SLV7709K
Veh Make/Model :	Honda Shuttle 1.5G CVT
YOM :	2017
Chassis No :	GK81200405
Date of Accident :	06/07/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012563/Kvbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3948E	Veh. Inspected	SLV 7709K
Policy No.		Coverage (\$)	0.00
Claim No.	D18005282MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	10/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GK81200405	Colour	METALLIC GREY
Odometer	12936	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60 R15	BRIDGESTONE	9 mm
L/H Front Tyre	185/60 R15	BRIDGESTONE	9 mm
R/H Rear Tyre	185/60 R15	BRIDGESTONE	9 mm
L/H Rear Tyre	185/60 R15	BRIDGESTONE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/07/2018	Inspection Date	11/07/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 7709K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	TO REPAIR SEE LABOUR	920.80	-
1	RH HEADLAMP	MTG CRACKED	2,230.80	1,088.70
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	435.00	-
1	FRONT RH FENDER SPLASH SHIELD	CRACKED	110.00	110.00
10	FRONT RH FENDER SPLASH SHIELD CLIP	NECESSARY	38.00	38.00
1	FRONT GRILLE BASE	SERVICEABLE	395.00	-
1	FRONT GRILLE CHROME	SERVICEABLE	322.00	-
1	FRONT GRILLE BADGE	SERVICEABLE	24.00	-
1	FRONT BUMPER	BENT	1,050.00	1,050.00
1	FRONT BUMPER GRILLE	DISTORTED	140.00	140.00
1	FRONT RH BUMPER FOG LAMP COVER (TOP)	DISTORTED	33.20	33.20
1	FRONT RH BUMPER FOG LAMP COVER (BOTTOM)	SERVICEABLE	45.00	-
1	FRONT BUMPER TOW COVER	DENTED	25.00	25.00
1	FRONT BUMPER SIDE RETAINER-RH	CRACKED	15.40	15.40
10	FRONT BUMPER CLIP	NECESSARY	38.00	38.00
1	FRONT BUMPER REINFORCEMENT	BENT	420.90	420.90
1	SUPPORT PANEL	TO REPAIR SEE LABOUR	760.40	-
1	WASHER TANK	MTG CRACKED	75.00	75.00
1	AIRBAG SENSOR (ADDITIONAL)	CRACKED	157.10	157.10
1	RH HEADLAMP BRACKET (ADDITIONAL)	CRACKED	63.60	63.60
1	WASHER TANK MOTOR (ADDITIONAL)	CRACKED	153.30	153.30
	LESS 20% DISCOUNT		-1,490.50	-681.64
			5,962.00	2,726.56
LABOUR				
	SPRAY PAINTING ON ALL AFFECTED AREA.		1,200.00	550.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF BONNET,FRONT RH FENDER AND SUPPORT PANEL.		1,200.00	500.00

Report Ref No. CS/FCI18012563/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI RUST TREATMENT.	NOT NECESSARY	150.00	-
	TO CHECK WIRING SYSTEM & LIGHT.		80.00	20.00
	TO CHECK & ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
			2,690.00	1,070.00
	GRAND TOTAL		8,652.00	3,796.56
	RECOMMENDED COST OF REPAIRS			3,796.56

Report Ref No. CS/FCI18012563/Kvbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.