

Date : 10/07/2018

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Joy Vivian

Our Customer : TAN MUN SHI MAISIE

Vehicle No : SLH8010J

Model : Toyota Sienta Hybrid 1.5G AT ABS

Manufacture Year : 2016

Date of Accident : 07-07-18

Total Estimate Repair Days : 8 Days

Total Pages : 2

Attn : Motor Claim Department
Email : motor.survey@axa.com.sg

AP1707064892

Re: Repair Estimate For Third Party Claim against SLW8713K

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper - LH <i>Reland</i>	1	\$435.00	\$435.00	✓
2	Rear bumper clip <i>in</i>	10	\$5.00	\$50.00	30
3	Rear bumper side retainer- LH <i>new</i>	1	\$90.00	\$90.00	✓
4	Rear bumper garnish - LH <i>new</i>	1	\$153.00	\$153.00	+
5	Rear LH fender <i>Dented.</i>	1	\$1,500.00	\$1,500.00	1075
6	Rear LH fender protector <i>Reland</i>	1	\$43.00	\$43.00	✓
7	Rear LH sliding door <i>Dented.</i>	1	\$1,245.00	\$1,245.00	✓
8	Rear LH sliding door rubber with sensor <i>new</i>	1	\$1,065.00	\$1,065.00	+
9	Rear LH sliding door lower roller <i>new</i>	1	\$315.00	\$315.00	+
10	Rear LH door protector <i>new</i>	1	\$125.00	\$125.00	+
11	Petrol cover <i>new</i>	1	\$104.00	\$104.00	+
12	Rocker panel - LH <i>new</i>	1	\$385.00	\$385.00	+
13	Rear fender lower pad - LH <i>Repaired</i>	1	\$55.00	\$55.00	+
14	Rocker panel Rubber - LH <i>cut</i>	1	\$100.00	\$100.00	✓
15	Rear door side trim chrome- LH <i>cut</i>	1	\$270.00	\$270.00	✓
16	Rear axle <i>new</i>	1	\$2,700.00	\$2,700.00	+
17	Wheel hub bearing - LH <i>new</i>	1	\$579.00	\$579.00	+
	Sub Total			\$9,214.00	
	Less 25%			\$2,303.50	
	Sub Total 1			\$6,910.50	
A.	Spare Parts (S/Nett)				
1	Rear Tyre - LH <i>new</i>	1	\$450.00	\$450.00	+
2	Rear Rim - LH <i>cut</i>	1	\$550.00	\$550.00	480
3	Sealant <i>new</i>	1	\$80.00	\$80.00	+
	Sub-Total 2			\$1,080.00	
	Total for Parts			\$7,990.50	

Date : 10/07/2018

TO: AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Our Customer : TAN MUN SHI MAISIE

Vehicle No : SLH8010J

Model : Toyota Sienta Hybrid 1.5G AT ABS

Manufacture Year : 2016

Date of Accident : 07-07-18

Total Estimate Repair Days : 8 Days

Total Pages : 2

Attn : Motor Claim Department
Email : motor.survey@axa.com.sg

Re: Repair Estimate For Third Party Claim against SLW8713K

B.	Labour		
1	To check wiring.	\$60.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.	\$1,000.00	80
3	Spray painting all affected parts & areas.	\$1,200.00	60
4	To remove and replace rear undercarriage - LH	\$300.00	80
5	To remove and refit rear fender quarter glass - LH	\$120.00	60
6	To spray anti-rust undercoat.	\$60.00	60
	Total Labour	\$2,740.00	
	Total Repair Cost	\$10,730.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 4626

h/s: 3-7K

Adrian King

h/s 11/07/18

Obhys

3-7K

Yours faithfully,



Candice Yee
f Premium Carz Services Pte Ltd



Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No