

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05811

Vehicle Insured : YP4668S

Accident Date : 06-Jul-2018

Date : 09-Jul-2018

Our Ref : 218116 (AXA) / CHAN

PAGE : 1

KO BAK PHENG

BLK 926 YISHUN CENTRAL 1

#03-177

Singapore 760926

*Not Notarized  
Resurvey B4 panel*

## ESTIMATED COST OF REPAIR FOR TOYOTA PRIUS 1.5 HYBRID SLD504A

1 pc	N/s taillamp	CM	472.60	✓
1 pc	N/s taillamp lower bracket		62.70	?
1 pc	Rear bumper fascia	Bu	469.70	✓
1 pc	Rear bumper reinforcement		372.90	?
1 pc	Rear n/s bumper bracket		72.80	?
2 pcs	Rear bumper side seal	@ S\$ 82.70	165.40	?
1 pc	Tail gate	R	866.70	X
1 pc	Tail gate "PRIUS C" emblem	na	59.40	—
1 pc	Tail gate "TOYOTA" emblem	na	41.40	—
1 pc	Tail gate logo	na	66.10	—
1 pc	Tail gate HYBRID plate	na	62.70	—
1 pc	Rear end panel		592.70	?
1 pc	End panel top garnish		288.70	?
			3,593.80	
Less 25% :			898.45	

- 1 pc Rear bumper reverse sensor  
1 pc Rear w/s glass sealant

2,695.35 2001a  
CM 300.00 sn  
na 30.00 sn ✓

To remove & refix rear windscreen  
glass and conduct water leak test.

na 150.00 X

To remove roof lining, front and  
rear seats, trim board and carpet

120.00 ?

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Con't Page 2 ...

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : YP4668S

Page : 2

To apply undersealing	60.00	?
To putty and spray replaced parts	900.00	Good
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	800.00	?
	-----	
Total :	S\$ 5,055.35	
	=====	

Singapore Dollars Five Thousand and Fifty Five  
and Cents Thirty Five Only