

ASS. REC. BY:

REF: CS/FC118012577/Kabn2

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): (WS) Serene Ker of FCI Date/Time: 10/7/2018 5:54pm

Estimated Cost: Bill to:

OD / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHF 752L Insured: SHA 4019X

at Workshop m/s Trans - Cab Tel: 6287 6666

of No. 2 Amk St 63

Policy No: Claim No: D18003291MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 06/7/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

11-07-2018

H.O.D. Endorsement:

Date/Time: 10/7/2018 Person Contacted: Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHF 752L - CS/III/8004931/Kpa3	DPA: 10/3/2018
	SHA 4019X - NS/INC/7007490/HWbn2	DEA: 14/04/17
12/7/18 @ 4.55pm	revised to Serene Ker by email.	

ASSIGNMENT

From: _____ Date: 11/7/2018

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SHF 752L

at Workshop m/s Trans. Carb

of No. 2 AMK St-63

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1.3% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHF 752L Yr Regn: 06, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Coptitude c.c. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 25338 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VF-1 ABC 15AUC-282739

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

Ling R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 6/7/18

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 11/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/17/18 File pass to Cathryn

8/14/18.00 (Red to 78955.77, 95%)

RECEIVED 13 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I. (\$) 1475

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos: 039

Others: 17/18

TOTAL

20x15=300

170+300

50

15

535

MOTOR SURVEY ASSIGNMENT

Date	10-07-2018	Our Ref No. D18005291MFSH
Accident Date	06-07-2018	Claim Type. Third Party
Insured Vehicle	SHA4019X	Third Party Vehicle. SHF752L
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: EST. COR - \$30,230.77	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 12 July 2018 4:55 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005291MFSH/1
Attachments: CSFCI18012577Kqb.pdf

Dear Serene,

Enclosed herewith preliminary advice of SHF 752L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 10 July 2018 6:47 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005291MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 10 July, 2018 5:54 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005291MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005291MFSH

Date: 12 July 2018

Our Ref: CS/FCI18012577/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHE 752L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/07/2018 at the premises of M/s TRANS-CAB and have the following to report:-

Workshop Estimate Amount	: S\$ 30,230.77 .
Revised Estimate Amount	: S\$ 1,475.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the o/s body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHF752L

Vehicle to be Exported: Yes

Intended De-registration Date: 06 Jul 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002728

Chassis No.: VF1ABL15AUC282739

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 30 Jun 2016

First Registration Date: 30 Jun 2016

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Jun 2024

PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 29 Jun 2024

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$37,164.00

COE Rebate Amount: \$27,782.00

Total Rebate Amount: \$42,780.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Jul 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 752L**AAD1807-056**

Not Authorised
Recovery B4 paint @ 1475.00

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 752L

VF1ABL15AUC282739

RENAULT

LATITUDE

6.7.2018

FIL

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>1</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>1</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>1</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>1</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>1</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>1</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>1</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>1</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>1</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>1</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>1</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>1</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>1</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>1</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>1</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>1</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>1</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>1</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>1</i> 6.91
1	DOOR CASING REAR RH	\$	<i>1</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>1</i> 30.39
1	DOOR CASING CLIP	\$	<i>1</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>1</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>1</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>1</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>1</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>1</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>1</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>1</i> 210.96
1	DOOR BLIND REAR RH	\$	<i>1</i> 741.80

Trans-cab Auto Services Pte Ltd**AAD1807-056**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 752L

1	DOOR WHEATHESTRIIP REAR RH	\$	410.66	} X
1	DOOR SEAL REAR RH	\$	162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	334.69	
1	DOOR WAIST SEAL INNER REAR RH	\$	115.64	
1	FENDER PANEL REAR RH	\$	3,299.13	
1	FENDER PANEL INNER TRIM REAR	\$	671.45	
1	WHEELARCH REAR RH	\$	543.47	
1	DOOR MIRROR ASSY RH	\$	1,483.40	
1	ROCKER PANEL INNER GARNISH RH	\$	466.51	
1	ROCKER PANEL INNER RH	\$	1,024.79	
1	ROCKER PANEL CENTER RH	\$	990.25	
1	BUMPER COVER REAR	\$	1,108.46	

\$	21,510.16
----	------------------

10% \$	2,151.02
--------	-----------------

\$	19,359.14
----	------------------

Specical Nett

1	REAR DOOR STICKER '6555 3333'	\$	80.00	} X
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR GUIDE SCREW	\$	10.85	
1	DOOR HINGE BOLT	\$	10.85	
1	DOOR HINGE NUT RH	\$	14.60	
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR CHECK NUT	\$	3.75	
1	DOOR LOCK SCREW L70Y	\$	6.12	
1	DOOR CATCH SCREW L70Y	\$	10.06	

TOTAL	\$	181.63
--------------	----	---------------

TOTAL PARTS	\$	19,540.77
--------------------	----	------------------

Trans-cab Auto Services Pte Ltd

AAD1807-056

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 752L

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 ³⁰⁰¹
Putty and spray painting of the affected portion.	\$	4,200.00 ¹¹⁰⁰¹
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 ¹⁵²
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
Towing Fees.	\$	<i>nn</i> 120.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 X

TOTAL \$ 10,690.00**Over All Total \$ 30,230.77**

75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)**15 DAYS****3 days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012577/Kqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 16-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4019X	Veh. Inspected	SHF 752L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005291MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	10/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC282739	Colour	METALLIC WHITE / RED	
Odometer	253381	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	LING LONG	5 mm	
L/H Rear Tyre	215/60 R16	LING LONG	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/07/2018	Inspection Date	11/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 752L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH/RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR RH	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH	SERVICEABLE	893.75	-
1	DOOR REGULATOR NUT REAR L70Y	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	NOT NECESSARY	6.91	-
1	DOOR CASING REAR RH	SERVICEABLE	1,509.06	-
1	DORO WATER SHIELD REAR RH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH	NOT NECESSARY	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-

Report Ref No. CS/FCI18012577/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR RH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH	NOT NECESSARY	410.66	-
1	DOOR SEAL REAR RH	NOT NECESSARY	162.02	-
1	DOOR GLASS RUBBER SEAL REAR RH	NOT NECESSARY	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	NOT NECESSARY	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	NOT NECESSARY	115.64	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	ROCKER PANEL INNER GARNISH RH	SERVICEABLE	466.51	-
1	ROCKER PANEL INNER RH	TO REPAIR SEE LABOUR	1,024.79	-
1	ROCKER PANEL CENTER RH	TO REPAIR SEE LABOUR	990.25	-
1	BUMPER COVER REAR	SERVICEABLE	1,108.46	-
	LESS 10% DISCOUNT		-2,151.02	-
			19,359.14	-
	SPECIAL NETT ITEMS			
1	REAR DOOR STICKER "6555-3333" (SN)	NECESSARY	80.00	60.00
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-

Report Ref No. CS/FCI18012577/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			181.61	60.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL REAR RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR LOCK REAR RH,DOOR REGULATOR REAR RH,DOOR FINISHER BRACKET INNER REAR RH,FENDER PANEL REAR RH,ROCKER PANEL INNER RH AND ROCKER PANEL CENTER RH.		4,500.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,200.00	1,100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
			10,690.00	1,415.00
	GRAND TOTAL		30,230.75	1,475.00
RECOMMENDED COST OF REPAIRS				1,475.00

Report Ref No. CS/FCI18012577/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.