



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLL9416U
Chassis No : JHMGK5850HX201290
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : TAN JIN LI,ANDY
Ins Policy No. :
Date of Accident : 5/7/2018

Document No. : SQT18002804
Date : 9. Jul 2018
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B31190938
Date | Time : 9. Jul 2018 8:40:27 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAN JIN LI, ANDY OWNER INSURER: DIRECT ASIA ACC DATE: 05/07/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA TP VEH: SLG4829X						
68100-TAS-Z50ZZ	TAILGATE COMP	1	716.30		716.30	50.14	766.44
74800-T5S-K61	LOCK ASSY,TAILGATE	1	77.10		77.10	5.40	82.50
74813-T5A-003	STRIKER ASSYTAILGATE	1	24.70		24.70	1.73	26.43
74440-T5A-003	WEATHERSTRIPTAILGATE	1	92.30		92.30	6.46	98.76
75722-T5L-T01	EMBLEMRR.	1	10.50		10.50	0.74	11.24
34150-T5A-J01	LIGHT ASSYR.LID	1	79.30		79.30	5.55	84.85
34155-T5A-J01	LIGHT ASSYL.LID	1	79.30		79.30	5.55	84.85
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	52.10		52.10	3.65	55.75
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	5.00		5.00	0.35	5.35
04715-T5B-000ZZ	FACERR.BUMPER	1	492.60		492.60	34.48	527.08
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50		11.50	0.81	12.31
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50		11.50	0.81	12.31
91505-TM8-003	CLIPBUMPER	5	2.00		10.00	0.70	10.70
66100-TAR-T10ZZ	PANEL COMPRR.	1	314.00		314.00	21.98	335.98
33550-T5A-J02	TAILLIGHT ASSYL.	1	217.40		217.40	15.22	232.62
33500-T5A-J02	TAILLIGHT ASSY,R.	1	235.10		235.10	16.46	251.56
73225-TF0-000	RUBBER A WSHIELD DAM	1	36.30		36.30	2.54	38.84
73226-TF0-000	RUBBER B WSHIELD	1	31.50		31.50	2.21	33.71
73228-TF0-000	RUBBER D WSHIELD DAM	2	4.80		9.60	0.67	10.27
75717-SNB-E01	STICKER I-VTEC	1	12.40		12.40	0.87	13.27
91501-S70-003	FASTENER BW/SHIELD	4	3.20		12.80	0.90	13.70

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLL9416U
Chassis No : JHMGK5850HX201290
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : TAN JIN LI, ANDY
Ins Policy No. :
Date of Accident : 5/7/2018

Document No. : SQT18002804
Date : 9. Jul 2018
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B31190938
Date | Time : 9. Jul 2018 8:40:27 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91502-S70-003	FASTENER B	2	4.90		9.80	0.69	10.49
91536-SS0-J01	FASTENER AW/SHIELD	2	3.50		7.00	0.49	7.49
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
Sum Item					2608.10	182.60	2,790.70
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00		160.00	11.20	171.20
BOMISC1	RESET & CALLIBRATE REAR VIEW CAMERA (N)	1	380.00		380.00	26.60	406.60
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	180.00		180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	360.00		360.00	25.20	385.20
BG02R	REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT END PANEL	1	100.00		100.00	7.00	107.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	2500.00		2500.00	175.00	2675.00
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2500.00		2500.00	175.00	2675.00
Sum Labor					8340.00	583.80	8,923.80

Survey By Rahim - Hp 90010068Date & Time 10/07/18 @ 1100

Excess

Status

Signature

Total Amount 10,948.10 766.40 11,714.50

Total (Inclusive of GST) 11,714.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 9/7/2018 4:30:49 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

6 days
Resy 64 paint