

ASS. REC. BY:

REF: CS/FCI18012584/

Gad3ⁿ²

Special Instruction:

Surveyor:

CWS

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time: 11/7/18 @ 9:38am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 5606L

Insured:

SHD 3568T

at Workshop m/s

Trans Eurofers

Tel:

6395 7874

of

5 ubi close

Policy No:

Claim No:

D18005314MFSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/07/2018

CA / REV / REP. / REV 24 HRS

lup

13/07/18 @ 4:30pm ow

H.O.D. Endorsement:

Date/Time:

9:54am @ 11/7/18

Person Contacted:

Jess

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 5606L - x
	SHD 3568T - x.
18/7/18 @ 4:58pm	revised to Eileen Lee by email.
24/7/18 @ 2:30pm	confirmed with Catherine final fig B 9615.05, 8 days.
	(Red B 5452.48, 36%)

xhl.

REF: FA

73576

ASSIGNMENT

From: Date: 13072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 5606L
at Workshop m/s: Trans Eunokars
of: 5 Ubi Close

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Jess

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLV5606L Yr Regn: 04 Jan 2018

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 2 C.C. 1496

Colour: white A/C Insured / Std / NI / NA

Sp. Reading: 4606 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MM6RL2SAAJW345858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R15

R: 11

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. D.O.I. 13-07-18

Survey held at: w/s 4:30pm

Des. of Damages: Frt / Rear / O/S N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 SEP 2018

Date/Time: File Pass to?

1) 24/9/2018

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.L. (\$) 9615.05

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 8

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee:

Transportation:

) S + RS (\$) :

) Photos:

) Others:

TOTAL

5x15 = 75

170 + 75

50

30

325



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012589/Gqd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 11-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3568T	Veh. Inspected	SLV 5606L
Policy No.		Coverage (\$)	0.00
Claim No.	D18005314MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	11/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/07/2018	Inspection Date
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005314MFSH
Our Ref: CS/FCI18012589/Gqd3

Date: 18 July 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 5606L.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 13/07/2018 at the premises of M/s TRANS EUROKARS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>12,740.94</u> .
Revised Estimate Amount	: S\$ <u>7,288.46</u> .
"Check" Items Amount	: S\$ <u>946.35</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the o/s portion.



Yours faithfully

Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	10-07-2018	Our Ref No. D18005314MFSH
Accident Date	02-07-2018	Claim Type. Third Party
Insured Vehicle	SHD3568T	Third Party Vehicle. SLV5606L
Survey Location	5 UBI CLOSE	
Contact Person.	JESS FRANCIS CARLOS	
Contact No.	63957874/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUOKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242225)



PRI Documents



Close



PRI Header Details

Claim No	D18005314MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS EL
Workshop Name	TRANS EUROKARS PTE LTD (Contact Person : JESS FRANCIS CARLOS)	Survey Location & Contact Details	5 UBI CLOSE Mobile: 0 , Phone: 63957874 , Fax: 0 EmailId: JESS.FRANCIS@EUROKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3568T	TP Vehicle No	SLV5606L
PRI Recieved Date	10-07-2018 06:45:32 PM	Surveyor Appointed Date	11-07-2018 09:37:14 AM	Surveyor Accept Date	11-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-07-2018	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 24 September 2018 2:30 PM
To: 'catherinechua@eurokars.com.sg'
Cc: 'jess.francis@eurokars.com.sg'; CS A Team; Admin A; SUR
Subject: RE: SLV5606L - FINALISATION OF COR

Dear Catherine,

WITHOUT PREJUDICE

Confirm final fig \$9,615.05 before GST and 8 repair days.

Kindly send the relevant documents to First Capital Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Thursday, 20 September 2018 9:48 AM
To: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: FW: SLV5606L - FINALISATION OF COR

[CS/FC118012589/Gqd3](#)

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>
Sent: Thursday, 20 September, 2018 9:47 AM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: jess.francis@eurokars.com.sg; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: SLV5606L - FINALISATION OF COR

Dear Guo Qiang

Our COR computation and B4 paint photos are attached for your agreement.

COR: \$9615.05 before GST

9 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 18 July 2018 4:58 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005314MFSH/1
Attachments: CSFC18012589Gqd3.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SLV 5606L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 11 July 2018 9:56 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005314MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 11 July 2018 9:38 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005314MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7357B
Vehicle Details	
Vehicle No.:	SLV5606L
Vehicle to be Exported:	No
Intended De-registration Date:	18 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SEDAN 1.5 AT STANDARD PLUS EU6
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	P520438610
Chassis No.:	MM6DL2SAAJW345858
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$14,247.00
Original Registration Date:	04 Jan 2018
First Registration Date:	04 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jan 2028
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	03 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$40,051.00
Total Rebate Amount:	\$43,801.00

The information contained herein is correct as at 18 Jul 2018

OK

ORIGINAL

Co. Reg. No. 201009404M
Hotline: (65) 6419-3000 Fax: (65) 6415-3723

Cover Note: 3100026379

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.



Auto Protector

The following risk described in the Schedule below is hereby covered subject to the applicable terms and conditions of AIG's policy issued to the Policyholder. The Policy to which this Cover Note relates to is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Schedule (please circle where applicable)

Policyholder/Insured Daniel Tan Zhi wei	
Age Condition	1 All Age
	2 30 Years Old and Above
	3 35 Years Old and Above
	4 40 Years Old and Above
	5 Named Driver Basis
Policy Type	Comprehensive
	Third Party Fire and Theft
	Third Party only



Policy Period	04/01/2018 to 03/01/2020 23:59
Registration Number	
Make/Model	Mazda 2.1S Skyactiv
CC/Tonnage	1496
Engine Number	P520438610
Chassis Number	MM6DL22AA JW345858
Year of Registration	2018
Hire Purchase Company	Hoy Leong Finance Ltd
Excess	S\$ 600 (Section 1/II Both) S\$ 100 (Windscreen excess)

Please note that acceptance of the risk is subject to our final acceptance and the terms and conditions applicable to the policy. For important notes and applicable laws and regulations, please refer to the reverse page.

Issued in Singapore

21/2018
Date of Issuance

Authorised Representative

Agent Code

50329-190

Manik Bucha, Personal Insurance

Manik Bucha

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9025253D



Name
AUDREY TAN RUIPING
陳蕊萍

Race
CHINESE

Date of birth
13-07-1990

Sex
F

Country of birth
SINGAPORE





REPUBLIC OF SINGAPORE DRIVING LICENCE

ID No. S9025253D



AUDREY TAN RUIPING

Date of birth: 13 Jul 1990

Exp. Date: 23 Dec 2009




0018161263

3741423




NRIC No. S9025253D

91168710

Date of issue
14-07-2005

Address
220 LOYANG AVENUE
#03-01
SINGAPORE 509067

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

PASS DATE 23 Dec 2009

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg



Licence No. S9025253D

NP 428A

SUNNY

JULY 13, 2018 4:30 PM

MOA 02-04-18

SHD 25687



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Daniel Tan Zhiwei ADDRESS: 220 Loyang Avenue #03-01 Singapore 509067 TEL: 97359322		WIP: 20031 EXCESS: DATE: 3-Jul-18	
VEH NO:	SLV5606L	DATE IN:		CONTACT PERSON:	JESS 6395 7874
CHASSIS NO:	MM6DL2SAAJW345858	MILEAGE:	14600	TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA2	DATE REG.:	4-Jan-18	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER / ee 1		\$ 909.00
2	RETAINER(RHS), REAR BUMPER X NN 1		\$ 21.70
3	REFLECTOR RHS X NN 1		\$ 50.40
4	RHS REAR MUDGUARD / ee 1		\$ 50.00
5	FASTENER, REAR BUMPER 7		\$ 19.60
6	CLIP, REAR BUMPER / ee 1		\$ 3.20
7	GROMMET, REAR BUMPER / ee 1		\$ 2.80
8	GROMMET, REAR BUMPER / ee 4		\$ 10.00
9	PANEL, REAR END X NN 1		\$ 624.70
10	RHS REAR LOWER FENDER repair X 1		\$ 274.00
11	PLATE(RHS), CORNER / ee 1		\$ 37.00
12	GASKET(LHS), TAILLAMP / ee 1		\$ 31.90
13	GASKET(RHS), TAILLAMP / ee 1		\$ 31.90
14	RHS TAILLAMP X NN 1		\$ 376.40
15	GUARD(RHS), STONE / ee 1		\$ 14.00
TOTAL PARTS			\$ 2,456.60
LESS 10%			\$ 245.66
TOTAL PARTS COST			\$ 2,210.94

Labour Description

1	TO REPLACE REAR BUMPER, REAR END PANEL AND RHS REAR LOWER FENDER. TO REPAIR RHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	660	2640	\$ 3,960.00
2	TO RESPRAY REAR BUMPER, REAR END PANEL, RHS REAR LOWER FENDER AND RHS REAR FENDER.	630	2520	\$ 3,150.00
3	MZ-BR-SEALER TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	NN	X	\$ 350.00

4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$	250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	nn X	\$	660.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	330	\$	660.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$	250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$	350.00
9		TO SUPPLY BRILA PREMIUM COATING.	300	NETT	\$ 800.00
10	MZ-BR-SUNDRI	SUNDRIES.	net 20	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 10,530.00
TOTAL PARTS	\$ -	\$ 2,210.94
TOTAL	\$ -	\$ 12,740.94
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

8 Days .

before paint photos.

Gmo Qiap - 82880282

13/7/18

[Signature]
18/7/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
SUPPLEMENTARY ESTIMATE COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Daniel Tan Zhiwei ADDRESS: 220 Loyang Avenue #03-01 Singapore 509067 TEL: 97359322		WIP: 20031 EXCESS: DATE: 3-Jul-18	
VEH NO:	SLV5606L	DATE IN:		CONTACT PERSON:	JESS 6395 7874
CHASSIS NO:	MM6DL2SAAJW345858	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA2	DATE REG.:	4-Jan-18	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO		QTY		REVISED	PRICES
1	FRONT DOOR RHS / Bnc	1	MDAY0-58-02XF		\$ 1,109.30
2	FASTENER, FRONT DOOR /	25	MBBM6-58-762		\$ 75.00
3	GROMMET, FRONT DOOR /	8	MBF67-51-261		\$ 17.60
4	PLUG DRAIN, FRONT DOOR /	2	MB45A-56-052		\$ 5.00
5	CLIP, FRONT DOOR /	2	MG51D-58-315A		\$ 4.40
6	FASTENER, FRONT DOOR /	10	MGJ6A-68-AB1		\$ 68.00
7	GROMMET, FRONT DOOR /	2	MG51D-68-402		\$ 5.20
8	REAR DOOR RHS / Bnc	1	MDAY0-72-02XE		\$ 925.10
9	FASTENER, REAR DOOR /	28	MBBM6-58-762		\$ 84.00
10	FASTENER, REAR DOOR /	2	MGHP9-58-762A		\$ 6.00
11	FASTENER, REAR DOOR /	8	MG51M-58-762		\$ 97.60
12	FASTENER, REAR DOOR /	1	MD09L-72-762		\$ 12.60
13	SEAL RHS, REAR DOOR HANDLE /	1	MDB2M-58-414		\$ 4.40
14	GROMMET, REAR DOOR /	4	MBF67-51-261		\$ 8.80
15	GROMMET, REAR DOOR /	14	MGJ6A-58-975		\$ 39.20
16	CLIP, REAR DOOR /	2	MG51D-58-315A		\$ 4.40
17	GROMMET, REAR DOOR /	2	MG51D-68-402		\$ 5.20
18	FASTENER, REAR DOOR /	10	MGJ6A-68-AB1		\$ 68.00
19	STRIPE RHS, FRONT DOOR /	1	MDB2M-50-8V1		\$ 23.70
20	STRIPE RHS, REAR DOOR /	1	MDB2M-50-8V2		\$ 21.60
TOTAL PARTS					\$ 2,585.10
LESS 10%					\$ 258.51
TOTAL PARTS COST					\$ 2,326.59
Labour Description					
1					

2				
			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ 2,326.59
			TOTAL	\$ - \$ 2,326.59
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD		NAME : Mr Daniel Tan Zhiwei		WIP : 20031	
36 ROBINSON ROAD		ADDRESS : 220 Loyang Avenue		EXCESS :	
#16-01 CITY HOUSE		#03-01		DATE: 3-Jul-18	
SINGAPORE 068877		Singapore 509067			
ATTN. : MOTOR CLAIMS		TEL : 97359322			
FAX :					
VEH NO :	SLV5606L	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	MM6DL2SAJW345858	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	4-Jan-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MDB7A-50-221BBB	\$ 909.00	\$ 909.00
2	RETAINER(RHS), REAR BUMPER	1	MDB7A-50-2H1		\$ 21.70
3	REFLECTOR RHS	1	MD350-51-5M0E		\$ 50.40
4	RHS REAR MUDGUARD	1	MDB7A-50-340	\$ 50.00	\$ 50.00
5	FASTENER, REAR BUMPER	7	MB45A-56-146A	\$ 19.60	\$ 19.60
6	CLIP, REAR BUMPER	1	MGJ21-50-049	\$ 3.20	\$ 3.20
7	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80
8	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.00	\$ 10.00
9	PANEL,REAR END	1	MDBYA-70-75Z		\$ 624.70
10	RHS REAR LOWER FENDER	1	MDBYB-70-40XA		\$ 274.00
11	PLATE(RHS), CORNER	1	MDBYA-70-490	\$ 37.00	\$ 37.00
12	GASKET(LHS), TAILLAMP	1	MDB7A-51-163	\$ 31.90	\$ 31.90
13	GASKET(RHS), TAILLAMP	1	MDB7A-51-153	\$ 31.90	\$ 31.90
14	RHS TAILLAMP	1	MDB7A-51-150A		\$ 376.40
15	GUARD(RHS), STONE	1	MDB1L-50-4P2	\$ 14.00	\$ 14.00
SUPPLEMENTARY ITEMS					
1	FRONT DOOR RHS	1	MDAY0-58-02XF	\$ 1,109.30	\$ 1,109.30
2	FASTENER, FRONT DOOR	25	MBBM6-58-762	\$ 75.00	\$ 75.00
3	GROMMET, FRONT DOOR	8	MBF67-51-261	\$ 17.60	\$ 17.60
4	PLUG DRAIN,FRONT DOOR	2	MB45A-56-052	\$ 5.00	\$ 5.00
5	CLIP,FRONT DOOR	2	MGS1D-58-315A	\$ 4.40	\$ 4.40
6	FASTENER,FRONT DOOR	10	MGJ6A-68-AB1	\$ 68.00	\$ 68.00
7	GROMMET,FRONT DOOR	2	MGS1D-68-402	\$ 5.20	\$ 5.20
8	REAR DOOR RHS	1	MDAY0-572-02XE	\$ 925.10	\$ 925.10
9	FASTENER,REAR DOOR	28	MBBM6-58-762	\$ 84.00	\$ 84.00
10	FASTENER,REAR DOOR	2	MGHP9-58-762A	\$ 6.00	\$ 6.00
11	FASTENER,REAR DOOR	8	MGS1M-58-762	\$ 97.60	\$ 97.60
12	FASTENER,REAR DOOR	1	MD09L-72-762	\$ 12.60	\$ 12.60
13	SEAL RHS,REAR DOOR HANDLE	1	MDB2M-58-414	\$ 4.40	\$ 4.40
14	GROMMET,REAR DOOR	4	MBF67-51-261	\$ 8.80	\$ 8.80
15	GROMMET,REAR DOOR	14	MGJ6A-58-975	\$ 39.20	\$ 39.20

16	CLIP, REAR DOOR	2	MGS1D-58-315A	\$ 4.40	\$ 4.40
17	GROMMET, REAR DOOR	2	MGS1D-68-402	\$ 5.20	\$ 5.20
18	FASTENER, REAR DOOR	10	MGJ6A-68-AB1	\$ 68.00	\$ 68.00
19	STRIPE RHS, FRONT DOOR	1	MD82M-50-8V1	\$ 23.70	\$ 23.70
20	STRIPE RHS, REAR DOOR	1	MD82M-50-8V2	\$ 21.60	\$ 21.60
TOTAL PARTS				\$ 3,694.50	\$ 5,041.70
LESS 10%				\$ 369.45	\$ 504.17
TOTAL PARTS COST				\$ 3,325.05	\$ 4,537.53

Labour Description					
1		TO REPLACE REAR BUMPER, REAR END PANEL AND RHS REAR LOWER FENDER. TO REPAIR RHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 2,640.00	\$ 3,960.00	
2		TO RESPRAY REAR BUMPER, REAR END PANEL, RHS REAR LOWER FENDER AND RHS REAR FENDER.	\$ 2,520.00	\$ 3,150.00	
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		\$ 350.00	
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00	
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 660.00	
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	\$ 330.00	\$ 660.00	
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00	
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00	
9		TO SUPPLY BRILA PREMIUM COATING.	\$ 300.00	\$ 800.00	
10	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00	
TOTAL LABOUR			\$ 6,290.00	\$ 10,530.00	
TOTAL PARTS			\$ 3,325.05	\$ 4,537.53	
TOTAL			\$ 9,615.05	\$ 15,067.53	
LESS EXCESS			\$ -	\$ -	
TOTAL AFTER EXCESS			\$ 9,615.05		
GST 7%			\$ 673.05	\$ -	
GRAND TOTAL			\$ 10,288.10	\$ -	

REMARKS:

9 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012589/Gqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3568T	Veh. Inspected	SLV 5606L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005314MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	11/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 2	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MM6DL2SAAJW345858	Colour	WHITE	
Odometer	14606	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	8 mm	
L/H Front Tyre	185/65 R15	DUNLOP	8 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	8 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2018	Inspection Date	13/07/2018	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 5606L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	909.00	909.00
1	RETAINER (RHS), REAR BUMPER	NOT NECESSARY	21.70	-
1	REFLECTOR RHS	NOT NECESSARY	50.40	-
1	RHS REAR MUDGUARD	DEFORMED	50.00	50.00
7	FASTENER, REAR BUMPER	NECESSARY	19.60	19.60
1	CLIP, REAR BUMPER	NECESSARY	3.20	3.20
1	GROMMET, REAR BUMPER	NECESSARY	2.80	2.80
4	GROMMET, REAR BUMPER	NECESSARY	10.00	10.00
1	PANEL, REAR END	NOT NECESSARY	624.70	-
1	RHS REAR LOWER FENDER	TO REPAIR SEE LABOUR	274.00	-
1	PLATE (RHS), CORNER	NECESSARY	37.00	37.00
1	GASKET (LHS), TAILLAMP	NECESSARY	31.90	31.90
1	GASKET (RHS), TAILLAMP	NECESSARY	31.90	31.90
1	RHS TAILLAMP	NOT NECESSARY	376.40	-
1	GUARD (RHS), STONE	NECESSARY	14.00	14.00
1	FRONT DOOR RHS (ADDITIONAL)	BUCKLED	1,109.30	1,109.30
25	FASTENER, FRONT DOOR (ADDITIONAL)	NECESSARY	75.00	75.00
8	GROMMET, FRONT DOOR (ADDITIONAL)	NECESSARY	17.60	17.60
2	PLUG DRAIN, FRONT DOOR (ADDITIONAL)	NECESSARY	5.00	5.00
2	CLIP, FRONT DOOR (ADDITIONAL)	NECESSARY	4.40	4.40
10	FASTENER, FRONT DOOR (ADDITIONAL)	NECESSARY	68.00	68.00
2	GROMMET, FRONT DOOR (ADDITIONAL)	NECESSARY	5.20	5.20
1	REAR DOOR RHS (ADDITIONAL)	BUCKLED	925.10	925.10
28	FASTENER, REAR DOOR (ADDITIONAL)	NECESSARY	84.00	84.00
2	FASTENER, REAR DOOR (ADDITIONAL)	NECESSARY	6.00	6.00
8	FASTENER, REAR DOOR (ADDITIONAL)	NECESSARY	97.60	97.60
1	FASTENER, REAR DOOR (ADDITIONAL)	NECESSARY	12.60	12.60
1	SEAL RHS, REAR DOOR HANDLE (ADDITIONAL)	NECESSARY	4.40	4.40
4	GROMMET, REAR DOOR (ADDITIONAL)	NECESSARY	8.80	8.80
14	GROMMET, REAR DOOR (ADDITIONAL)	NECESSARY	39.20	39.20

Report Ref No. CS/FCI18012589/Gqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	CLIP, REAR DOOR (ADDITIONAL)	NECESSARY	4.40	4.40
2	GROMMET, REAR DOOR (ADDITIONAL)	NECESSARY	5.20	5.20
10	FASTENER, REAR DOOR (ADDITIONAL)	NECESSARY	68.00	68.00
1	STRIPE RHS, FRONT DOOR (ADDITIONAL)	NECESSARY	23.70	23.70
1	STRIPE RHS, REAR DOOR (ADDITIONAL)	NECESSARY	21.60	21.60
	LESS 10% DISCOUNT		-504.17	-369.45
			4,537.53	3,325.05
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER, REAR END PANEL AND RHS REAR LOWER FENDER. TO REPAIR RHS REAR FENDER AND ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF RHS REAR LOWER FENDER.		3,960.00	2,640.00
	TO RESPRAY REAR BUMPER, REAR END PANEL, RHS REAR LOWER FENDER AND RHS REAR FENDER.		3,150.00	2,520.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	350.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	NOT NECESSARY	660.00	-
	TO TRANSFER REVERSE SENSORS.		660.00	330.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
	TO SUPPLY BRILA PREMIUM COATING.		800.00	300.00
	-		-	-
	-		-	-
	-		-	-
			10,430.00	6,270.00
	GRAND TOTAL		15,067.53	9,615.05

Report Ref No. CS/FCI18012589/Gqd3n2



RECOMMENDED COST OF REPAIRS			9,615.05
-----------------------------	--	--	----------

Report Ref No. CS/FCI18012589/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.