



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
SUPPLEMENTARY ESTIMATE COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Daniel Tan Zhiwei ADDRESS : 220 Loyang Avenue #03-01 Singapore 509067 TEL : 97359322		WIP : 20031 EXCESS : DATE: 3-Jul-18	
VEH NO :	SLV5606L	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	MM6DL2SAAJW345858	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	4-Jan-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT DOOR RHS / <i>Buc</i>	1	MDAY0-58-02XF		\$ 1,109.30
2	FASTENER, FRONT DOOR /	25	MBBM6-58-762		\$ 75.00
3	GROMMET, FRONT DOOR /	8	MBF67-51-261		\$ 17.60
4	PLUG DRAIN, FRONT DOOR /	2	MB45A-56-052		\$ 5.00
5	CLIP, FRONT DOOR /	2	MGS1D-58-315A		\$ 4.40
6	FASTENER, FRONT DOOR /	10	MGJ6A-68-AB1		\$ 68.00
7	GROMMET, FRONT DOOR /	2	MGS1D-68-402		\$ 5.20
8	REAR DOOR RHS / <i>Buc</i>	1	MDAY0-72-02XE		\$ 925.10
9	FASTENER, REAR DOOR /	28	MBBM6-58-762		\$ 84.00
10	FASTENER, REAR DOOR /	2	MGHP9-58-762A		\$ 6.00
11	FASTENER, REAR DOOR /	8	MGS1M-58-762		\$ 97.60
12	FASTENER, REAR DOOR /	1	MD09L-72-762		\$ 12.60
13	SEAL RHS, REAR DOOR HANDLE /	1	MDB2M-58-414		\$ 4.40
14	GROMMET, REAR DOOR /	4	MBF67-51-261		\$ 8.80
15	GROMMET, REAR DOOR /	14	MGJ6A-58-975		\$ 39.20
16	CLIP, REAR DOOR /	2	MGS1D-58-315A		\$ 4.40
17	GROMMET, REAR DOOR /	2	MGS1D-68-402		\$ 5.20
18	FASTENER, REAR DOOR /	10	MGJ6A-68-AB1		\$ 68.00
19	STRIPE RHS, FRONT DOOR /	1	MDB2M-50-8V1		\$ 23.70
20	STRIPE RHS, REAR DOOR /	1	MDB2M-50-8V2		\$ 21.60
TOTAL PARTS					\$ 2,585.10
LESS 10%					\$ 258.51
TOTAL PARTS COST					\$ 2,326.59
Labour Description					
1					