SIN HO AUTO

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel: (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email:chris_chanbebe@hotmail.com

SEK WAI BLOCK 3020A UBI ROAD 1 # 01-33 Singapore 408714 10th JULY 2018

Accident date: 10th JULY 2018

Estimated repair cost for vehicle no: SKK9494K Toyota Wish 1.8 A '06

S/n	Qty	Items	U/pi	rice	Amount
1	1	Rear Boot Lid	Phaeciden 2 co.co.componitrocompina 9 (2016) Arigonal (13.200-ymraetosus 19.900g, a, cela lur versonas, conse	\$950.00
2	2	Rear Boot Lid Hinges	\$187	7.70	\$375.40
3	1	Rear boot lid emble logo			\$74.10
4	1	Rear Boot Lid Inner Lock	-		\$549.10
5	1	Rear boot lid inner rubber			\$276.10
6	1	Rear Boot Lid center moulding			\$613.80
7	2	Rear Boot Lid center moulding side clips	\$8.	50	\$17.00
8	1	Rear Boot Lid Number Plate			\$50.00
9	2	Rear Boot Lid Number Plate Lamp	\$13	5.10	\$270.20
10	1	Rear Boot Lid Inner Trim board			\$680.00
11	1	Rear Boot Lid Inner lock side cover			\$68.00
12	1	Rear boot lid windscreen seal			\$310.10
13	2	Rear tail lamp	\$640).10	\$1,280.20
14	4	Rear tail lamp clips	\$8.	50	\$34.00
15	2	Rear tail lamp panel	\$320	00.0	\$640.00
16	1	Rear End Panel outer			\$740.00
17	1	Rear End Panel inner			\$580.00
18	1	Rear End Panel Top Garnish			\$403.40
19	1	Rear spare tire lock			\$536.10

Sheet1

00	4	Rear floor panel top cover			\$535.77
20	1	Rear floor panel sealant			\$120.00
21		Rear floor panel side cover	\$225.	50	\$451.00
22	2	Rear floor panel inner garnish			\$682.70
23		Rear floor panel inner trim			\$503.10
24	1	Rear Bumper			\$1,077.00
25	2	Rear Bumper side reflector	\$83.	10	\$166.20
26 27	2	Rear Bumper Side Bracket	\$55.		\$111.20
	1	Rear Bumper reverse sensor			\$350.00
28	2	Rear Bumper Bracket	\$68.	40	\$136.80
29		Rear bumper clips	\$6.3		\$52.00
30	8	rear exhaust			\$971.10
31	1	rear exhaust aluminium cover			\$212.15
32	1	rear exnaust aiuminium cover			
			0	4-1.	\$12.916.52
			Subto	tal:-	\$13,816.52
lahoi	ur cha	rnac			
labot	II CIIA	inges	i.a		*020.00
To C	heck \	Wiring System			\$80.00
Tuff	Kote				\$150.00
1 (411	1000				
To R	emov	e & refix cushion			\$150.00
To R	emov	e & refix rear exhaust			\$220.00
To R	lemov	e & refix rear windscreen			\$120.00
Gum	1				\$50.00
ToR	Remov	re & refix reverse Sensor			\$100.00
Tow	ing ch	narges			\$100.00
Pane	el bea	ting			\$1,000.00
Spra	ay pai	nting			\$1,000.00
			Subt	otal :-	\$2,970.00
			Tot	tal:-	\$16,786.52
			PA.		

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	and the second section of the section of the second	and the second s	
Owner ID Type:	Singapore NRIC		
Owner ID:	8505G		
Vehicle Details			
Vehicle No.:	SKK9494K		
Vehicle to be Exported:	Yes		
Intended Deregistration Date:	12 Oct 2018		
Vehicle Make:	TOYOTA		
Vehicle Model:	WISH 1.8 A		
Primary Colour:	Grey		
Manufacturing Year:	2006		
Engine No.:	1ZZ2522518		
Chassis No.:	ZNE100297401		
Maximum Power Output:	97.0 kW (130 bhp) .		
Open Market Value:	\$19,764.00		
Original Registration Date:	05 May 2006	The second section of the second seco	
First Registration Date:	05 May 2006		
Transfer Count:	1		
Actual ARF Paid:	\$21,741.00		
Intended PARF Rebate Details			
PARF Eligibility:	Forfeited		
PARF Eligibility Expiry Date:	-		
PARF Rebate Amount:	\$0.00		
Intended COE Rebate Details			
COE Expiry Date:	04 May 2026		
COE Category:	E - Open Category		
COE Period(Years):	10		
PQP Paid:	\$46,048.00		
COE Rebate Amount:	\$34,815.00		
Total Rebate Amount:	\$34,815.00		

The information contained herein is correct as at 12 Oct 2018

OK