

ASSIGN BY

REF CS/CTI18012596 / T1cd3er

Perimen

Taykhk
Chang Boon Sen

ASSIGNMENT (Office)

CTI

Date/Time 10/07/2018 @ 5:24pm

Estimated Cost:

Bill to:

① OD/TP/WS/TP RES/OD RPS/EVA/INV/MV7CS

To Inspect Vehicle No:

WC 4764P

Insured:

at Workshop no:

Fook Heng Motor

Tel:

6244 3203

of

No. 29 Sungai Kerdut st. 4

Policy No:

DMCVSN 1768971700

Claim No:

SNM18DO3065C0114

Sum Insured:

Excess:

~~\$9,500.00~~ \$1,500.00

Make of Vch:

D.O.A 19/06/2018

(Client's Record)

CA

REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9:21am 11/7/2018

Person Contacted:

Annie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	WC 4764P-x
13/7/2018	Revert the perimen; Pending mandate
26/7/18	According Boon Sen, we can authorize first; Pending amend Excess.
26/7/18.	Inform Annie authorize repair thru phone & email. Excess TBA
31/7/18	Boon Sen inform excess \$9500 (refer email.)
20/11/18	Alfred inform Swee Seng Group had take over the vehicle
	Excess collect from receiver should be \$1500.00

ASSIGNMENT

From: _____ Date: 12/07/2018

Estimated Cost: _____

☒ P WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: WC 4764P

at Workshop m/s Fook Heng Motor

of No. 29 Sungai Kadut St-4

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: \$1,500-00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 880k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: WC 4764P Yr Regn: 2011 / Dec.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Mixer truck

Make: 1334 CH528 c.c. 15681

Colour: White/Blue A/C: Insured / Std / NI / NA

Sp. Reading: 224304 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JALCH528B-7000209

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: ☒ S/Rim / STD A/Rim or

Tyre Size: F: 295/80R22.5

R: 9 - (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Anyone

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. _____

Rear

R/Bal. 8/8 mm

L/Bal. 8/8 mm

D.O.I. 12/7/18 @ 1530

Survey held at Fook Heng Motor

Des. of Damages: ☒ Fnt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/7 4/5 \$15,600, 21 days
Amie confirmed LS \$11,700 and 21 days (Clid. 8802.75, 42%)

Date/Time, File Pass to?

☐ : Prell. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: 21

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: 270

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

270

Report Format: OD

Imp Sum / I.B.I: (\$11,700)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18012596/T1rd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 11-07-2018



Code : CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	WC 4764P
Policy No.	DMCVSN1768971700	Coverage (\$)	0.00
Claim No.	SNM18D03065C01/4	Excess (\$)	1,500.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	11/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/06/2018	Inspection Date	12/07/2018
Survey held at	FOOK HENG MOTOR SERVICE 29 SUNGAI KADUT STREET 4 SINGAPORE 729054		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		10 Jul 2018 17:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAT HING TRANSPORT PTE LTD, Co. Reg. No.: 201414922Z		
Vehicle Reg. No.:	WC4764P	Date of Loss:	19/06/2018 04:00 - :59
Claim Type:	OD / SNM18D03065C01/4	Policy/Cover Note No.:	DMCVSN1768971700 (Comprehensive) Coverage: 09/12/2017 - 08/12/2018
		Excess:	S\$1,500.00
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/07/2018]		
Adj Asp, Remarks:	Please survey on W/O prejudice & let us have findings		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 13 Jul 2018

Preliminary Advice

Vehicle No	: WC4764P	Accident Date	: 19/06/2018
Make	: ISUZU CYH52S	Policy No.	: DMCVSN1768971700
Assignment Date	: 10/07/2018	Excess	: S\$1,500.00
Date of Inspection	: 12/07/2018	Est. Duration of Repair	: 21.00
Inspection At	: FOOK HENG MOTOR SERVICE (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922 SINGAPORE 460100		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, o/s body, n/s body and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	20,502.75
Revised Amount	:S\$	18,160.75
Check Items (Estimated)	:S\$	1,362.00
Total	:S\$	19,522.75

Lump Sum Repair	:S\$	15,600.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	80,000.00
COE / PARF Rebate	:S\$	13,881.00
Salvage Value	:S\$	
Margin for Repair	:S\$	66,119.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on lumpsum basis.

Print Received Message

This mail is associated with :

***WC4764P (SNM18D03065C01/4)**

OD

Jun 19 2018 4:00AM

[TAT HING TRANSPORT PTE LTD]

Fook Heng Motor Service

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 25/07/2018 13:55 PM,
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11713.65) - WC4764P - Claim Handler: Chong Boon Sen

Approved:11713.65;please inform workshop that we intend to deduct Section Excess Amount in addition to the Section 1 Excess

Sec 2 → \$8000.

Sec 1 → \$1500.

\$9500

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, July 26, 2018 9:55 AM
To: 'slmoter@yahoo.com.sg'
Cc: SUR
Subject: WC 4764P OD DOA : 19.06.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **WC 4764P (excess \$TBA/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lee (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, July 31, 2018 2:31 PM
To: Janice Lee (LKKAUTO)
Subject: RE: SNM18D03065C01 - WC4764P

Dear Janice,

The mentioned outstanding Section 2 Excess for below mentioned vehicles is for 3 different policies under the same Insured.

We had earlier sent out Section 2 excess recovery letters to Insured (respectively on 8.12.17, 10.7.18, and 10.7.18) but did not receive any response. You may ask Insured to refer to his letters received should he not understand.

Hope information clarifies for explanation to Insured.

Thank you.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Chong Boon Sen
Sent: Tuesday, 31 July, 2018 2:06 PM
To: 'Janice Lee (LKKAUTO)' <JaniceLee@lkkauto.com>
Subject: RE: SNM18D03065C01 - WC4764P

Dear Janice

We refer to our authorization on repairs to WC4674P at \$11,713.65 before Section 1 Excess of \$1,500/- under the terms and conditions of this motor policy.

In addition, please assist to notify M/s Fook Heng Motor Service that we shall proceed to deduct \$8,000 being the outstanding Section 2 Excess for vehicle no. WC6519T, WC4861S, WC4715G due to us from the insured and the amount payable to the workshop is as follows:=-

Item	Amount S\$	Remarks
Authorised repair amount	11,713.65	
Less: Policy Excess	1,500.00	
Net Amount	10,213.65	
Less:-		
3 outstanding Section 2 Excess	8,000.00	WC6519T (\$1,000) / WC4861S(\$4,000) WC4715G (\$3,000)
Amount payable to Fook Heng Motor Service	2,213.65	

Regards,
Chong Boon Sen
 Claims Executive
 Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
 Singapore 079909
 Co. Reg. No. 200208384E
 DID: 63896171
 Fax: 62247175
 Email: boonsen.chong@sg.cntaiping.com
 Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4922Z
Vehicle Details	
Vehicle No.:	WC4764P
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jul 2018
Vehicle Make:	ISUZU
Vehicle Model:	CYH52S
Primary Colour:	Blue
Manufacturing Year:	2011
Engine No.:	6WG1415585
Chassis No.:	JALCYH525B7000209
Maximum Power Output:	-
Open Market Value:	\$145,119.00
Original Registration Date:	09 Dec 2011
First Registration Date:	09 Dec 2011
Transfer Count:	1
Actual ARF Paid:	\$7,256.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	08 Dec 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,803.00
COE Rebate Amount:	\$13,881.00
Total Rebate Amount:	\$13,881.00

The information contained herein is correct as at 13 Jul 2018

OK

Claim Audit

- AUDIT TRAIL

No.	On	Audit	Remarks	By
1	10 Jul 2018 17:20	Cim Dtl Modified	Insured Name: -> TAT HING TRANSPORT PTE LTD.	[I] Alfred Toh
2	10 Jul 2018 17:20	Cim Dtl Modified	Claimant's Name: -> TAT HING TRANSPORT PTE LTD. Claimant's ID: -> 201414922Z.	[I] Alfred Toh
3	10 Jul 2018 17:20	Cim Veh Model Changed	(201615) ISUZU CYH52S 15.7 D (M).	[I] Alfred Toh
4	10 Jul 2018 17:20	Cim Created	Reg No: WC4764P. Policy No: DMCVSN1768971700. Acct Date: 2018/06/19. Claim Type: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Fook Heng Motor Service (HQ). Ins.Status => Incoming Claim	[I] Alfred Toh
5	10 Jul 2018 17:22	Cim 1st Attended By		[I] Alfred Toh
6	10 Jul 2018 17:22	Cim No. Updated	Claim No.: -> SNM18D03065C01/4.	[I] Alfred Toh
7	10 Jul 2018 17:22	Ins Claim Registration (Manual)	Registered & Approved: (CimNo:SNM18D03065C01/4)	[I] Alfred Toh
8	10 Jul 2018 17:23	Ins Claim Reg Modified		[I] Alfred Toh
9	10 Jul 2018 17:24	Cim Dtl Modified	Recovery: [Subrogation:N].	[I] Alfred Toh
10	10 Jul 2018 17:24	Personnel Assignment Changed	PIC: [None] -> Chong Boon Sen. Manager: [None] -> Alfred Toh.	[I] Alfred Toh
11	10 Jul 2018 17:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please survey on W/O prejudice & let us have findings	[I] Alfred Toh
12	10 Jul 2018 17:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/19	[I] Alfred Toh
13	10 Jul 2018 17:24	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Alfred Toh
14	10 Jul 2018 17:24	Ins Claim Assignment	(Survey:External Adj)	[I] Alfred Toh
15	10 Jul 2018 17:25	Document Access	36072724:+A	[I] Alfred Toh
16	11 Jul 2018 07:40	Assignment 1st Accessed		[A] Nivitha Govindasamy
17	12 Jul 2018 09:46	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/19. Mandate Remarks: PLEASE LET US HAVE YOUR FINDINGS ON THE SURVEY	[I] Alfred Toh
18	12 Jul 2018 09:46	Adj Mandate Set	Approved:0.00:PLEASE LET US HAVE YOUR FINDINGS ON THE SURVEY	[I] Alfred Toh
19	13 Jul 2018 11:24	Cim Details Notified		[A] Janice Lee Si Hua
20	13 Jul 2018 12:30	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/07/19	[A] Janice Lee Si Hua
	13 Jul	Adj Mandate	Cur.Req:15600.00:DAMAGES CONSISTENT. REPAIR COST E	[A] Janice

21	2018 12:33	Request	CONOMICAL. REPAIR ON LUMP SUM BASIS	Lee Si Hua
22	2018 25 Jul 13:55	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/07/19. Mandate Rem arks: please inform workshop that we intend to deduct Secti on Excess Amount in addition to the Section 1 Excess	[1] Susan Teo
23	2018 25 Jul 13:55	Adj Mandate Set	Approved:11713.65:please inform workshop that we intend to deduct Section Excess Amount in addition to the Section 1 Excess	[1] Susan Teo
24	2018 31 Jul 14:08	Cim Registration Modified	Excess: 1500.00 -> 9500.00.	[1] Chong Boon Sen
25	2018 20 Nov 16:58	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/07/19. Mandate Rem arks: Please proceed to finalize report & forward bill for servi ces rendered.	[1] Alfred Toh
26	2018 20 Nov 16:58	Adj Mandate Set	Approved:11713.65:Please proceed to finalize report & forw ard bill for services rendered.	[1] Alfred Toh

Date From    Date To    Audit Type  Go

OFFER APPEAL HISTORY

There are no offer appeal histories.

ACTIVITY

No record

ADJUSTER ACTIVITY LOG

[13/07/2018 11:19] Janice Lee Si Hua:
The vehicle survey on 12/07/2018 , 3.30pm

Janice Lee (LKKAUTO)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Wednesday, November 21, 2018 10:31 AM
To: Janice Lee (LKKAUTO); Taufikh (LKKAUTO); Celine Fong (LKKAUTO); slmoter@yahoo.com.sg; assignments
Cc: Chong Boon Sen; Alfred Toh; Chee So Chow; Susan Teo; ryan.pohlk@ssgroup.sg; ivy.limls@ssgroup.sg; KKLau; Andrew Lee
Subject: RE: WC4764P - TAT HING TRANSPORT PTE LTD - OD CLAIM - Claim Ref: SNM18D03065C01/4
Attachments: 21112018102221.pdf

Dear Janice/Catherine

We thank you for your email pertaining to the above matter.

Insured vehicle number should read as **WC4764P**.

Please note that **the Section I Excess applicable for this claim shall be \$1,500.00 payable by M/s Swee Seng Group/Swee Seng Credit Pte Ltd instead of Insured, M/s Tat Hing Transport Pte Ltd.**

Best Regards

Alfred Toh
Senior Executive
Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: +65 6389 6183
FAX: +65 6224 7478/6224 7175
Email: claimsdept@sg.cntaiping.com
alfred.toh@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Wednesday, November 21, 2018 10:14 AM

To: Alfred Toh <alfred.toh@sg.cntaiping.com>
Cc: Celine Fong (LKKAuto) <celinefong@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Subject: RE: WC4764P - TAT HING TRANSPORT PTE LTD - OD CLAIM - Claim Ref: SNM18D03065C01/4

Dear Alfred,

Just to clarify,

- Excess that should collect from insured is \$1,500.00 instead of \$9,500.00 ?
- The vehicle mention below XC 4764P is a typo or another vehicle number for repairer, Annie reference ?

If possible, kindly drop me a call before 23/11/2018 or Celine after 23/11/2018 [6256 3561]

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept of CTI [<mailto:claimsdept@sg.cntaiping.com>]

Sent: Tuesday, November 20, 2018 5:22 PM

To: slmoter@yahoo.com.sg; assignments <assignments@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>

Cc: Chee So Chow <sochow.chee@sg.cntaiping.com>; Susan Teo <susan.teo@sg.cntaiping.com>; Andrew Lee <andrew.lee@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; ryan.pohlk@ssgroup.sg; ivy.lims@ssgroup.sg; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: WC4764P - TAT HING TRANSPORT PTE LTD - OD CLAIM - Claim Ref: SNM18D03065C01/4

M/s Fook Heng Motor Service

Attn: Ms Annie Yeong

Dear Annie

We refer to the above matter and understand that M/s Swee Seng Group has taken over conduct of the vehicle, XC4764P.

Please proceed to repair the vehicle no more than \$11,713.65 before Section I Excess of \$1,500.00.

You may liaise with M/s Swee Seng Credit Pte Ltd on the collection of vehicle when repair is completed and forward your Final Repair Bill to us for our next course of action.

Aside to M/s LKK Auto Consultants Pte Ltd, please finalize report and forward your bill via Merimen at your earliest convenience.

Best Regards

Alfred Toh

Senior Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: +65 6389 6183

FAX: +65 6224 7478/6224 7175

Email: claimsdept@sg.cntaiping.com

alfred.toh@sg.cntaiping.com

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/06/2018 10:03
Date Of Accident	19/06/2018 04:00
Exact Location Of Accident	GAMBAS AVENUE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	WC4764P
Insured/Policyholder	
Name Of Registered Owner	TAT HING TRANSPORT PTE LTD
Co Reg No	201414922Z
Email Address	SHARONPHANGSP@YAHOO.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-97260876
Vehicle Particulars	
Manufacturer	ISUZU
Model	CYH52S
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1768971700
Cover Note Number	
Driver	
Name of Driver	GANESAN VELMURUGAN
Passport No/FIN	G7351275T
Date Of Birth	08/10/1980
Occupation	OUTDOOR
Date Of Driving Pass	17/11/2014
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91437009
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	17 SUNGEI KADUT STREET 3 SUNGEI KADUT INDUSTRIAL ESTATE
Postcode	729148
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - CO-COMPANY WORKER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG GAM BAS AVENUE. I WAS ON THE THIRD LANE. AFTER THE CYCLIST WAS ON THE WAY GOING FORWARD, I MOVE ON TO THE RIGHT A LITTLE BIT AND THEN LOST CONTROL AND SKIDDED TO THE RIGHT SIDE. MY FRONT BUMPER HIT THE KERB AND THEN FINALLY AGAINST THE TREE. PASSERBY CALLED FOR AMBULANCE AND I WAS ADMITTED TO KTPH FOR MEDICAL TREATMENT AND WAS GIVEN 3 DAYS OF MC. INSURED VEHICLE CANNOT BE DRIVEN. PHOTOS ARE PROVIDED BY POLICYHOLDER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	ROAD KERB AND TREE
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 10/6/18
0900h


Driver's Signature
(If driver is not the policyholder)
Date & Time: 19/6/18


Reporting Centre Personnel's Signature
Name: Cassandra
NRIC/IN No.:

Accident Sketch Plan

SKETCH PLAN

Refer to the accident scene photo.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the attached Police Report No: T/20180619/2181.

Insured vehicle cannot be driven. Photos are provided by policyholder.

DECLARATION

I/We declare that the above particulars are true in every respect.

Policyholder's
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name: *Cassandra*
NRIC/TIN No.:



Police Report



**SINGAPORE
POLICE FORCE**



T/20180619/2181

1 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No: T/20180619/2181

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/06/2018 20:21		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: ganesan velmurugan			Address:		
ID Type / ID No.:			Contact No.:		Mobile: 91437009
FIN NO / G7351275T			Home/Office:		
Nationality: INDIAN			Email:		
Sex: Male	Age: 37	Date of Birth: 08/10/1980	Type of Informant: Driver		
Race: Indian		Language:		Institution / School Name:	
Occupation: DRIVER		Driving Licence Information: Class: 2B,3,4		Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 18/06/2018 17:30	Type of Location: Straight Road
Location: Along Road 1 GAMBAS AVENUE				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: AGAINST A TREE				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
WC4764P	TRUCK	ISUZU	CYH52S	Blue	Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police Report



**SINGAPORE
POLICE FORCE**



T/20180619/2181

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180619/2181

CONTINUATION OF REPORT

Driver			
Name	ganesan velmurugan	ID No.	G7351275T
Related Vehicle	WC4764P (TRUCK)	Contact No.	91437009
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	18/06/2018	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

ON THE ABOVE MENTION DATE TIME AND LOCATION

WAS TRAVELLING ALONG GAMBAS AVENUE, I WAS ON THE THIRD LANE. AFTER THE CYCLIST WAS ON THE WAY GOING FORWARD, I MOVE ON TO THE RIGHT A LITTLE BIT AND THEN LOST CONTROL AND SKIDDED TO THE RIGHT SIDE. MY FRONT BUMPER HIT THE KERB AND THEN FINALLY AGAINST THE TREE. PASSERBY CALLED FOR AMBULANCE AND I WAS ADMITTED TO KTPH FOR MEDICAL TREATMENT AND WAS GIVEN 3 DAYS OF MC.

Police Report



SINGAPORE
POLICE FORCE



T/20180619/2181

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180619/2181

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
NG JIN SHENG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
19/06/2018 20:21

Officer In Charge Of Case:
TP / GIA /
Staff Sgt TANG SIEW PING
Contact No. 65476430

Classification Of Case:

Authentication Stamp
NP168

Authorisation Letter

TAT HING TRANSPORT PTE LTD

17 Sungei Kadut Street 3, Sungei Kadut Industrial Estate (S) 729148.

Tel : 9726 0876 / 9660 1618 Fax : 6366 1618 / 6269 1306

REG. NO. 2014140222

Date : 19th June 2018

THL/2018/089

To : Jin Auto Services Pte Ltd
Add : Blk 14 #01-412 Defu Lane10
Singapore 539195
Tel : 6289 8126 Fax : 6287 0590
Email : jin@jinauto.com.sg (Jin)

Attn : Whom It May Concern

Dear Sir/Madam,

RE: LETTER OF AUTHORIZATION 864 - WC4764P.

We would like to certify that Mr Ganesan Velmurugan (Fin: G7351275T) is working as Driver in Tat Hing Transport Pte Ltd. Truck no : 864 - WC4764P
He has joined our company in April 2018.

Please feel free to contact us should you require further clarifications.
Thank you

Yours sincerely,
Tat Hing Transport Pte Ltd

104 

Mr. Toh Teng Yam
Director

Identification Card



Driving License

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

CLASS	VEHICLE CLASS	EXPIRATION DATE
Class 1	WHICH VEHICLE CATEGORIES ARE IN THE	01 Jan 2018
Class 2	VEHICLE CLASS WHICH ARE IN THE	01 Jan 2018
Class 3	VEHICLE CLASS WHICH ARE IN THE	01 Jan 2018
Class 4	VEHICLE CLASS WHICH ARE IN THE	01 Jan 2018

5 / No. 9000245499

HP 4284

Expiry No. 023612757

VISIT PASS

Immigration Regulations

NAME: GAREAN FELMUGAN

Photo

Class of Pass: 01

Period of Validity: 03-06-2017 to 03-06-2018

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.

Barcode

Scene Photo



Scene Photo



Scene Photo



Scene Photo



Accident Photo



CHASSIS NO : JALCYH52 SB7000209
U/W : 13480 KG
M/L/W : 34000KG
PASS CAP : 02
TYRE SIZE : F 295-80R22-5(S)2
 : R 295-80R22-5(D)x2

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451
E-mail: slmoter@yahoo.com.sg
Business Reg. No.: 52938821M

Date: 09th July, 2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road #16-00 Springleaf Tower Singapore 079909
The Motor Claims Department

cc: Bryan

VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC4764P (FLEET NO: 864)

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE
1)	rooftop windscreen panel	1 pc	1)	\$ 220.00 <i>bt</i>
2)	top center panel garnish (black color)	1 pc	2)	\$ 110.00 <i>cut</i>
3)	top LH panel garnish (black color)	1 pc	3)	\$ 48.00 <i>de</i>
4)	aluminium mirror stay bracket LH	1 pc	4)	\$ 120.00 <i>bt</i>
5)	mirror stay LH	1 pc	5)	\$ 155.00 <i>bt</i>
6)	round mirror LH	1 pc	6)	\$ 45.00 <i>crn</i>
7)	square mirror LH	1 pc	7)	\$ 45.00 <i>crn</i>
8)	front windscreen glass	1 pc	8)	\$ 1,286.00 <i>crn</i>
9)	front windscreen glass weatherstrip	1 pc	9)	\$ 285.00 <i>nae</i>
10)	wiper panel	1 pc	10)	\$ 210.00 <i>bt</i>
11)	front big panel	1 pc	11)	\$ 1,390.00 <i>crn</i>
12)	front center radiator grille	1 pc	12)	\$ 145.00 <i>crn</i>
13)	front LH side radiator grille	1 pc	13)	\$ 60.00 <i>aa</i>
14)	front bumper	1 pc	14)	\$ 1,280.00 <i>bt</i>
15)	front headlamp RH	1 pc	15)	\$ 425.00 <i>aa</i>
16)	front headlamp bracket RH	1 pc	16)	\$ 280.00 <i>bt</i>
17)	fog lamp RH	1 pc	17)	\$ 160.00 <i>crn</i>
18)	signal lamp RH	1 pc	18)	\$ 42.00 <i>mis</i>
19)	step panel bracket RH	1 pc	19)	\$ 295.00 <i>bt</i>
20)	aluminium step panel RH	1 pc	20)	\$ 40.00 <i>mis</i>
21)	stand step panel RH	1 pc	21)	\$ 225.00 <i>dis</i>
22)	front headlamp LH	1 pc	22)	\$ 425.00 <i>crn</i>
23)	front headlamp bracket LH	1 pc	23)	\$ 280.00 <i>bt</i>
24)	fog lamp LH	1 pc	24)	\$ 160.00 <i>crn</i>
25)	signal lamp LH	1 pc	25)	\$ 42.00 <i>mis</i>
26)	step panel bracket LH	1 pc	26)	\$ 295.00 <i>bt</i>
27)	aluminium step panel LH	1 pc	27)	\$ 40.00 <i>mis</i>
28)	stand step panel LH	1 pc	28)	\$ 225.00 <i>dis</i>
29)	corner panel LH	1 pc	29)	\$ 415.00 <i>crn</i>
30)	Door LH	1 pc	30)	\$ 1,850.00 <i>buc</i>
		Total (Parts)		\$ 10,598.00

Cont'd in Page 2***

福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451
E-mail: slmoter@yahoo.com.sg
Business Reg. No.: 52938821M

Cont'd sheet***2

Vehicle No. WC4764P (FLEET NO: 864)

Total (Parts) b/f \$ 10,598.00

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE
31)	fender blister LH	1 pc	31)	\$ 380.00 <i>de✓</i>
32)	fender fibre	1 pc	32)	\$ 320.00 <i>an✓</i>
33)	door quarter LH	1 pc	33)	\$ 670.00 <i>buc✓</i>
34)	lower chassis support beam	1 pc	34)	\$ 450.00 <i>bt✓</i>
35)	front exhaust pipe no. 1 RH	1 pc	35)	\$ 1,250.00 <i>bt✓</i>
36)	front exhaust pipe no. 2 RH	1 pc	36)	\$ 850.00 <i>bl✓</i>
37)	fuse box cover	1 pc	37)	\$ 232.00 <i>an✓</i>
38)	inner stand panel <i>behind big panel</i>	1 pc	38)	\$ 560.00 <i>bt✓</i>
39)	floorboard panel	1 pc	39)	\$ 385.00 <i>buc✓</i>
				\$ 15,695.00
Less 15%				\$ 2,354.25
Total (Parts)				\$ 13,340.75

NUMBER	NETT ITEMS	QUANTITY	NUMBER	UNIT PRICE
40)	center sideguard complete	1 pc	40)	\$ 120.00 <i>bl✓</i>
41)	air-con heater	1 pc	41)	\$ 682.00 <i>?</i>
42)	air-con blower	1 pc	42)	\$ 295.00 <i>?</i>
43)	air-con condenser	1 pc	43)	\$ 550.00 <i>bt✓</i>
44)	air-con fan	1 pc	44)	\$ 385.00 <i>?</i>
Total (Nett Items)				\$ 2,032.00

Cont'd in Page 3****

福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451
E-mail: slmoter@yahoo.com.sg
Business Reg. No.: 52938821M

Cont'd sheet ****/3

Vehicle No. WC4764P (FLEET NO: 864)

Total (Parts) & (Nett Items) b/f \$ 15,372.75

LABOUR CHARGES & MISC

45)	To remove/renew front windscreen glass.	\$ 180.00 ¹⁵⁰
46)	To remove/renew air-con heater, blower, condenser, fan and refill gas.	\$ 350.00 ²⁰⁰
47)	To dismantle and installation to above damaged parts and job completed.	\$ 2,800.00 ²⁴⁰⁰
48)	To spray paint on the accident affected area.	\$ 1,400.00 ¹⁴⁰⁰
Total (Labour)		\$ 5,130.00

ALL TOTAL \$ 20,502.75

62563561
Tanjiluh 97495749
Revert, Not Authorise
12/7/18 @ 1530
EX \$1500
lumpsum
Resurvey after repair
sur @ lkk auto.wm
21 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451

E-mail: slmoter@yahoo.com.sg
Business Reg. No.: 52938821M

Date: 09th July, 2018

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 Anson Road #16-00 Springleaf Tower Singapore 079909
The Motor Claims Department

cc: Bryan

VEHICLE INSPECTION REPORT FOR ISUZU CYH52S WC4764P (FLEET NO: 864)

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE
1)	rooftop windscreen panel	1 pc	1)	\$ 220.00 <i>bt</i>
2)	top center panel garnish (black color)	1 pc	2)	\$ 110.00 <i>bt</i>
3)	top LH panel garnish (black color)	1 pc	3)	\$ 48.00 <i>de</i>
4)	aluminium mirror stay bracket LH	1 pc	4)	\$ 120.00 <i>bt</i>
5)	mirror stay LH	1 pc	5)	\$ 155.00 <i>bt</i>
6)	round mirror LH	1 pc	6)	\$ 45.00 <i>cr</i>
7)	square mirror LH	1 pc	7)	\$ 45.00 <i>cr</i>
8)	front windscreen glass	1 pc	8)	\$ 1,286.00 <i>cr</i>
9)	front windscreen glass weatherstrip	1 pc	9)	\$ 285.00 <i>nc</i>
10)	wiper panel	1 pc	10)	\$ 210.00 <i>bt</i>
11)	front big panel	1 pc	11)	\$ 1,390.00 <i>cr</i>
12)	front center radiator grille	1 pc	12)	\$ 145.00 <i>cr</i>
13)	front LH side radiator grille	1 pc	13)	\$ 60.00 <i>cr</i>
14)	front bumper	1 pc	14)	\$ 1,280.00 <i>bt</i>
15)	front headlamp RH	1 pc	15)	\$ 425.00 <i>cr</i>
16)	front headlamp bracket RH	1 pc	16)	\$ 280.00 <i>bt</i>
17)	fog lamp RH	1 pc	17)	\$ 160.00 <i>cr</i>
18)	signal lamp RH	1 pc	18)	\$ 42.00 <i>mis</i>
19)	step panel bracket RH	1 pc	19)	\$ 295.00 <i>bt</i>
20)	aluminium step panel RH	1 pc	20)	\$ 40.00 <i>mis</i>
21)	stand step panel RH	1 pc	21)	\$ 225.00 <i>dis</i>
22)	front headlamp LH	1 pc	22)	\$ 425.00 <i>cr</i>
23)	front headlamp bracket LH	1 pc	23)	\$ 280.00 <i>bt</i>
24)	fog lamp LH	1 pc	24)	\$ 160.00 <i>cr</i>
25)	signal lamp LH	1 pc	25)	\$ 42.00 <i>mis</i>
26)	step panel bracket LH	1 pc	26)	\$ 295.00 <i>bt</i>
27)	aluminium step panel LH	1 pc	27)	\$ 40.00 <i>mis</i>
28)	stand step panel LH	1 pc	28)	\$ 225.00 <i>dis</i>
29)	corner panel LH	1 pc	29)	\$ 415.00 <i>cr</i>
30)	Door LH	1 pc	30)	\$ 1,850.00 <i>but</i>
		Total (Parts)		\$ 10,598.00

Cont'd in Page 2***

10598

福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451
E-mail: slmotor@yahoo.com.sg
Business Reg. No. 52938821M

Cont'd sheet***/2

Vehicle No. WC4764P (FLEET NO: 864)

Total (Parts) b/f \$ 10,598.00

NUMBER	LIST ITEMS	QUANTITY	NUMBER	UNIT PRICE
31)	fender blister LH	1 pc	31)	\$ 380.00 <i>de</i>
32)	fender fibre	1 pc	32)	\$ 320.00 <i>an</i>
33)	door quarter LH	1 pc	33)	\$ 670.00 <i>bu</i>
34)	lower chassis support beam	1 pc	34)	\$ 450.00 <i>bt</i>
35)	front exhaust pipe no. 1 RH	1 pc	35)	\$ 1,250.00 <i>bt</i>
36)	front exhaust pipe no. 2 RH	1 pc	36)	\$ 850.00 <i>bt</i>
37)	fuse box cover	1 pc	37)	\$ 232.00 <i>an</i>
38)	inner stand panel <i>behind by panel</i>	1 pc	38)	\$ 560.00 <i>bt</i>
39)	floorboard panel	1 pc	39)	\$ 385.00 <i>bu</i>
				\$ 15,695.00 ✓
				Less 15%
				\$ 2,354.25
				Total (Parts) \$ 13,340.75 ✓

NUMBER	NETT ITEMS	QUANTITY	NUMBER	UNIT PRICE
40)	center sideguard complete	1 pc	40)	\$ 120.00 <i>bt</i>
41)	air-con heater	1 pc	41)	\$ 682.00 <i>? Cha</i>
42)	air-con blower	1 pc	42)	\$ 295.00 <i>? Cha</i>
43)	air-con condenser	1 pc	43)	\$ 550.00 <i>bt</i>
44)	air-con fan	1 pc	44)	\$ 385.00 <i>? Bro</i>
				Total (Nett Items) \$ 2,032.00 ✓

Cont'd in Page 3****

福興修理囉喱汽車 FOOK HENG MOTOR SERVICE

No. 29, Sungei Kadut Street 4, Sungei Kadut Industrial Estate,
Singapore 729054 Tel: 6244 3203 Fax: 6441 5451

E-mail: slmoter@yahoo.com.sg

Business Reg. No.: 52938821M

Cont'd sheet ****/3

Vehicle No. WC4764P (FLEET NO: 864)

Total (Parts) & (Nett Items) b/f \$ 15,372.75

LABOUR CHARGES & MISC

45)	To remove/renew front windscreen glass.	\$ 180.00	150
46)	To remove/renew air-con heater, blower, condenser, fan and refill gas.	\$ 350.00	200
47)	To dismantle and installation to above damaged parts and job completed.	\$ 2,800.00	2400
48)	To spray paint on the accident affected area.	\$ 1,800.00	1400
Total (Labour)		\$ 5,130.00	4150

ALL TOTAL \$ 20,502.75

62563561
Taufik 97495749
wpr
Revert, Not Authorise
12/7/18 @ 1530
EX \$1500
lumpsum
Reserving after repair
sur @ tuk auto.wm
21 days

Parts - 13840.75
Nett - 2032
labour - 4150

19522.75
4/5/15,600

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jul 2018		10 Jul 2018 17:24 Edit Adj Rpt	S\$11,700.00 Edit Estimates	S\$11,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAT HING TRANSPORT PTE LTD, Co. Reg. No.: 201414922Z								
Vehicle Reg. No.:	WC4764P	Date of Loss:	19/06/2018 04:00 - :59 [78 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM18D03065C01/4	Policy/Cover Note No.:	DMCVSN1768971700 (Comprehensive) Coverage: 09/12/2017 - 08/12/2018						
		Excess:	S\$1,500.00						
Repairer:	Fook Heng Motor Service (HQ) 100 BEDOK NORTH AVENUE 4 PEARL GARDENS, #13-1922, 460100 Sungei Kadut - Tel: 62443203								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/07/2018]								
Driver/Custodian:	GANESAN VELMURUGAN (/ Male) Email:								
Adj Asg. Remarks:	Please survey on W/O prejudice & let us have findings								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (20/11/2018): Alert - Adj Mandate Approved (S\$11713.65) - WC4764P - Claim Handler: Chong Boon ... - CHINA_TAIPING (25/07/2018): Alert - Adj Mandate Approved (S\$11713.65) - WC4764P - Claim Handler: Chong Boon ... - CHINA_TAIPING (12/07/2018): Alert - Adj Mandate Approved (S\$0.00) - WC4764P - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*WC4764P (SNM18D03065C01/4)

OD

Jun 19 2018 4:00AM

[TAT HING TRANSPORT PTE LTD]

Fook Heng Motor Service

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	13/07/18 12:30	Adjuster Immediate Advice					1	Load HTM		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	13/07/18 11:33	General View					1	Load JPG	☒	
2	13/07/18 11:33	General View					1	Load JPG	☒	
3	13/07/18 11:33	General View					1	Load JPG	☒	
4	13/07/18 11:33	General View					1	Load JPG	☒	
5	13/07/18 11:33	General View					1	Load JPG	☒	
6	13/07/18 11:33	General View					1	Load JPG	☒	
7	13/07/18 11:33	General View					1	Load JPG	☒	
8	13/07/18 11:33	General View					1	Load JPG	☒	
9	13/07/18 11:33	General View					1	Load JPG	☒	
10	13/07/18 11:33	General View					1	Load JPG	☒	
11	13/07/18 11:33	General View					1	Load JPG	☒	
12	13/07/18 11:33	General View					1	Load JPG	☒	
13	13/07/18 11:33	General View					1	Load JPG	☒	
14	13/07/18 11:33	General View					1	Load JPG	☒	
15	13/07/18 11:33	General View					1	Load JPG	☒	
16	13/07/18 11:33	General View					1	Load JPG	☒	
17	13/07/18 11:33	General View					1	Load JPG	☒	
18	13/07/18 11:33	General View					1	Load JPG	☒	
19	13/07/18 11:33	General View					1	Load JPG	☒	
20	13/07/18 11:33	General View					1	Load JPG	☒	
21	13/07/18 11:33	General View					1	Load JPG	☒	
22	13/07/18 11:33	General View					1	Load JPG	☒	
23	13/07/18 11:33	General View					1	Load JPG	☒	
24	13/07/18 11:33	General View					1	Load JPG	☒	
25	13/07/18 11:33	General View					1	Load JPG	☒	
26	13/07/18 11:33	General View					1	Load JPG	☒	
27	13/07/18 11:33	General View					1	Load JPG	☒	
28	13/07/18 11:33	General View					1	Load JPG	☒	
29	13/07/18 11:33	General View					1	Load JPG	☒	
30	13/07/18 11:33	General View					1	Load JPG	☒	
31	13/07/18 11:33	General View					1	Load JPG	☒	
32	13/07/18 11:33	General View					1	Load JPG	☒	
33	13/07/18 11:33	General View					1	Load JPG	☒	
34	13/07/18 11:33	General View					1	Load JPG	☒	
35	13/07/18 11:33	General View					1	Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	13/07/18 11:33	General View	 Load JPG	☒
37	13/07/18 11:33	General View	 Load JPG	☒
38	13/07/18 11:33	General View	 Load JPG	☒
39	13/07/18 11:33	General View	 Load JPG	☒
40	13/07/18 11:33	General View	 Load JPG	☒
41	13/07/18 11:33	General View	 Load JPG	☒
42	13/07/18 11:33	General View	 Load JPG	☒
43	13/07/18 11:33	General View	 Load JPG	☒
44	13/07/18 11:33	General View	 Load JPG	☒
45	13/07/18 11:33	General View	 Load JPG	☒
46	13/07/18 11:33	General View	 Load JPG	☒
47	13/07/18 11:33	General View	 Load JPG	☒
48	13/07/18 11:33	General View	 Load JPG	☒
49	13/07/18 11:33	General View	 Load JPG	☒
50	13/07/18 11:33	General View	 Load JPG	☒
51	13/07/18 11:33	General View	 Load JPG	☒
52	13/07/18 11:33	General View	 Load JPG	☒
53	13/07/18 11:33	General View	 Load JPG	☒
54	13/07/18 11:33	General View	 Load JPG	☒
55	13/07/18 11:33	General View	 Load JPG	☒
56	13/07/18 11:33	General View	 Load JPG	☒
57	13/07/18 11:33	General View	 Load JPG	☒
58	13/07/18 11:33	General View	 Load JPG	☒
59	13/07/18 11:33	General View	 Load JPG	☒
60	13/07/18 11:33	General View	 Load JPG	☒
61	13/07/18 11:33	General View	 Load JPG	☒
62	13/07/18 11:33	General View	 Load JPG	☒
63	13/07/18 11:33	General View	 Load JPG	☒
64	13/07/18 11:33	General View	 Load JPG	☒
65	13/07/18 11:33	General View	 Load JPG	☒
66	13/07/18 11:33	General View	 Load JPG	☒
67	13/07/18 11:33	General View	 Load JPG	☒
68	13/07/18 11:33	General View	 Load JPG	☒
69	13/07/18 11:33	General View	 Load JPG	☒
70	13/07/18 11:33	General View	 Load JPG	☒
71	13/07/18 11:33	General View	 Load JPG	☒
72	13/07/18 11:33	General View	 Load JPG	☒
73	13/07/18 11:33	General View	 Load JPG	☒
74	13/07/18 11:33	General View	 Load JPG	☒
75	13/07/18 11:33	General View	 Load JPG	☒
76	13/07/18 11:33	General View	 Load JPG	☒
77	13/07/18 11:33	General View	 Load JPG	☒
78	13/07/18 11:33	General View	 Load JPG	☒
79	13/07/18 11:33	General View	 Load JPG	☒
80	13/07/18 11:33	General View	 Load JPG	☒
81	13/07/18 11:33	General View	 Load JPG	☒
82	13/07/18 11:33	General View	 Load JPG	☒
83	13/07/18 11:33	General View	 Load JPG	☒
84	13/07/18 11:33	General View	 Load JPG	☒
85	13/07/18 11:33	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	13/07/18 11:33	General View	 Load JPG	☒
87	13/07/18 11:33	General View	 Load JPG	☒
88	13/07/18 11:33	General View	 Load JPG	☒
89	13/07/18 11:33	General View	 Load JPG	☒
90	13/07/18 11:33	General View	 Load JPG	☒
91	13/07/18 11:33	General View	 Load JPG	☒
92	13/07/18 11:33	General View	 Load JPG	☒
93	13/07/18 11:33	General View	 Load JPG	☒
94	13/07/18 11:33	General View	 Load JPG	☒
95	13/07/18 11:33	General View	 Load JPG	☒
96	13/07/18 11:33	General View	 Load JPG	☒
97	13/07/18 11:33	General View	 Load JPG	☒
98	13/07/18 11:33	General View	 Load JPG	☒
99	13/07/18 11:33	General View	 Load JPG	☒
100	13/07/18 11:33	General View	 Load JPG	☒
101	13/07/18 11:33	General View	 Load JPG	☒
102	13/07/18 11:33	General View	 Load JPG	☒
103	13/07/18 11:33	General View	 Load JPG	☒
104	13/07/18 11:33	General View	 Load JPG	☒
105	13/07/18 11:33	General View	 Load JPG	☒
106	13/07/18 11:33	General View	 Load JPG	☒
107	13/07/18 11:33	General View	 Load JPG	☒
108	13/07/18 11:34	General View	 Load JPG	☒
109	13/07/18 11:34	General View	 Load JPG	☒
110	13/07/18 11:34	General View	 Load JPG	☒
111	13/07/18 11:34	General View	 Load JPG	☒
112	13/07/18 11:34	General View	 Load JPG	☒
113	13/07/18 11:34	General View	 Load JPG	☒
114	13/07/18 11:34	General View	 Load JPG	☒
115	13/07/18 11:34	General View	 Load JPG	☒
116	13/07/18 11:34	General View	 Load JPG	☒
117	13/07/18 11:34	General View	 Load JPG	☒
118	13/07/18 11:34	General View	 Load JPG	☒
119	13/07/18 11:34	General View	 Load JPG	☒
120	13/07/18 11:34	General View	 Load JPG	☒
121	13/07/18 11:34	General View	 Load JPG	☒
122	13/07/18 11:34	General View	 Load JPG	☒
123	13/07/18 11:34	General View	 Load JPG	☒
124	13/07/18 11:34	General View	 Load JPG	☒
125	13/07/18 11:34	General View	 Load JPG	☒
126	13/07/18 11:34	General View	 Load JPG	☒
127	13/07/18 11:34	General View	 Load JPG	☒
128	13/07/18 11:34	General View	 Load JPG	☒
129	13/07/18 11:34	General View	 Load JPG	☒
130	13/07/18 11:34	General View	 Load JPG	☒
131	13/07/18 11:34	General View	 Load JPG	☒
132	13/07/18 11:34	General View	 Load JPG	☒
133	13/07/18 11:34	General View	 Load JPG	☒
134	13/07/18 11:34	General View	 Load JPG	☒
135	13/07/18 11:34	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
136	13/07/18 11:34	General View	 Load JPG	☒
137	13/07/18 11:34	General View	 Load JPG	☒
138	13/07/18 11:34	General View	 Load JPG	☒
139	13/07/18 11:34	General View	 Load JPG	☒
140	13/07/18 11:34	General View	 Load JPG	☒
141	13/07/18 11:34	General View	 Load JPG	☒
142	13/07/18 11:34	General View	 Load JPG	☒
143	13/07/18 11:34	General View	 Load JPG	☒
144	13/07/18 11:34	General View	 Load JPG	☒
145	13/07/18 11:34	General View	 Load JPG	☒
146	13/07/18 11:34	General View	 Load JPG	☒
147	13/07/18 11:34	General View	 Load JPG	☒
148	13/07/18 11:34	General View	 Load JPG	☒
149	13/07/18 11:34	General View	 Load JPG	☒
150	13/07/18 11:34	General View	 Load JPG	☒
151	13/07/18 11:34	General View	 Load JPG	☒
152	13/07/18 11:34	General View	 Load JPG	☒
153	13/07/18 11:34	General View	 Load JPG	☒
154	13/07/18 11:34	General View	 Load JPG	☒
155	13/07/18 11:34	General View	 Load JPG	☒
156	13/07/18 11:34	General View	 Load JPG	☒
157	13/07/18 11:34	General View	 Load JPG	☒
158	13/07/18 11:34	General View	 Load JPG	☒
159	13/07/18 11:34	General View	 Load JPG	☒
160	13/07/18 11:34	General View	 Load JPG	☒
161	13/07/18 11:34	General View	 Load JPG	☒
162	13/07/18 11:34	General View	 Load JPG	☒
163	13/07/18 11:34	General View	 Load JPG	☒
164	13/07/18 11:34	General View	 Load JPG	☒
165	13/07/18 11:34	General View	 Load JPG	☒
166	13/07/18 11:34	General View	 Load JPG	☒
167	13/07/18 11:34	General View	 Load JPG	☒
168	13/07/18 11:34	General View	 Load JPG	☒
169	13/07/18 11:34	General View	 Load JPG	☒
170	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
171	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
172	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
173	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
174	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
175	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
176	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
177	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
178	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
179	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
180	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
181	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
182	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
183	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
184	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
185	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
186	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
187	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
188	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
189	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
190	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
191	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
192	06/03/19 18:56	Photographs of Damaged Parts	 Load JPG	☒
193	06/03/19 18:57	Photo After Spray	 Load JPG	☒
194	06/03/19 18:57	Photo After Spray	 Load JPG	☒
195	06/03/19 18:57	Photo After Spray	 Load JPG	☒
196	06/03/19 18:57	Photo After Spray	 Load JPG	☒
197	06/03/19 18:57	Photo After Spray	 Load JPG	☒
198	06/03/19 18:57	Photo After Spray	 Load JPG	☒
199	06/03/19 18:57	Photo After Spray	 Load JPG	☒
200	06/03/19 18:57	Photo After Spray	 Load JPG	☒
201	06/03/19 18:57	Photo After Spray	 Load JPG	☒
202	06/03/19 18:57	Photo After Spray	 Load JPG	☒
203	06/03/19 18:57	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 17:21	ESTIMATES	 Load PDF	
2	10/07/18 17:21	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 11:32	WC 4764P ESTIMATE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI18012596/T1CD3E2

Date: 07/03/2019

REFERENCE

Insured/Claimant: TAT HING TRANSPORT PTE LTD Policy No: DMCVSN1768971700

Date of Loss: 19/06/2018

Nature of Claim: OD

Claim No: SNM18D03065C01/4

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: WC4764P

Make & Model: ISUZU CYH52S, 15.7 D (M)

Reg. Date: 09/12/2011 (Man. Year: 2011)

Colour: White/Blue

Engine Capacity: 15681 cc

Market Value/New Car Price: S\$80,000.00

Sum Insured (S\$): Market Value/New Car Price

Engine No: 6WG1415585

Chassis No: JALCYH52SB7000209

Odometer: 224304 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Austone 8 mm

Rear Left Side: Austone 8/8 mm

Front Right Side: Austone 8 mm

Rear Right Side: Austone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,372.75	15,372.75	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,130.00	4,150.00	980.00	19.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,502.75	19,522.75	980.00	4.78
Approved Total (Overridden) (S\$)		11,700.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (S\$)	19,002.75	10,200.00	8,802.75	46.32

INSPECTION

Date of Assignment: 10/07/2018

Date Inspected: 12/07/2018 Inspected At:

Fook Heng Motor Service (HQ)
29 SUNGAI KADUT STREET 4
SINGAPORE 729054

Estimated Period of Repair: 21.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Mar 2019)	
Parts:	N/A	ISUZU CYH52S 15.7 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WC4764P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ROOFTOP WINDSCREEN PANEL	Bent	220.00 FL	*220.00 FL
2	1		*TOP CENTER PANEL GARNISH (BLACK COLOR)	Cut	110.00 FL	*110.00 FL
3	1		*TOP LH PANEL GARNISH (BLACK COLOR)	Deformed	48.00 FL	*48.00 FL
4	1		*MIRROR STAY LH	Bent	155.00 FL	*155.00 FL
5	1		*ROUND MIRROR LH	Cracked	45.00 FL	*45.00 FL
6	1		*SQUARE MIRROR LH	Cracked	45.00 FL	*45.00 FL
7	1		*FRONT WINDSCREEN GLASS	Cracked	1,286.00 FL	*1,286.00 FL
8	1		*FRONT WINDSCREEN GLASS WEATHERSTRIP	Necessary	285.00 FL	*285.00 FL
9	1		*WIPER PANEL	Bent	210.00 FL	*210.00 FL
10	1		*FRONT BIG PANEL	Cracked	1,390.00 FL	*1,390.00 FL
11	1		*FRONT CENTER RADIATOR GRILLE	Cracked	145.00 FL	*145.00 FL
12	1		*FRONT LH SIDE RADIATOR GRILLE	Cracked	60.00 FL	*60.00 FL
13	1		*FRONT BUMPER	Bent	1,280.00 FL	*1,280.00 FL
14	1		*FRONT HEADLAMP RH	Cracked	425.00 FL	*425.00 FL
15	1		*FRONT HEADLAMP BRACKET RH	Bent	280.00 FL	*280.00 FL
16	1		*FOG LAMP RH	Cracked	160.00 FL	*160.00 FL
17	1		*SIGNAL LAMP RH	Missing	42.00 FL	*42.00 FL
18	1		*STEP PANEL BRACKET RH	Bent	295.00 FL	*295.00 FL
19	1		*ALUMINIUM STEP PANEL RH	Missing	40.00 FL	*40.00 FL
20	1		*STAND STEP PANEL RH	Distorted	225.00 FL	*225.00 FL
21	1		*FRONT HEADLAMP LH	Cracked	425.00 FL	*425.00 FL
22	1		*FRONT HEADLAMP BRACKET LH	Bent	280.00 FL	*280.00 FL
23	1		*FOG LAMP LH	Cracked	160.00 FL	*160.00 FL
24	1		*SIGNAL LAMP LH	Missing	42.00 FL	*42.00 FL
25	1		*STEP PANEL BRACKET LH	Bent	295.00 FL	*295.00 FL
26	1		*ALUMINIUM STEP PANEL LH	Missing	40.00 FL	*40.00 FL
27	1		*STAND STEP PANEL LH	Distorted	225.00 FL	*225.00 FL
28	1		*CORNER PANEL LH	Cracked	415.00 FL	*415.00 FL
29	1		*DOOR LH	Buckled	1,850.00 FL	*1,850.00 FL
30	1		*FENDER BLISTER LH	Deformed	380.00 FL	*380.00 FL
31	1		*FENDER FIBRE	Cracked	320.00 FL	*320.00 FL
32	1		*DOOR QUARTER LH	Buckled	670.00 FL	*670.00 FL
33	1		*LOWER CHASSIS SUPPORT BEAM	Bent	450.00 FL	*450.00 FL
34	1		*FRONT EXHAUST PIPE NO. 1 RH	Bent	1,250.00 FL	*1,250.00 FL
35	1		*FRONT EXHAUST PIPE NO. 2 RH	Bent	850.00 FL	*850.00 FL
36	1		*FUSE BOX COVER	Cracked	232.00 FL	*232.00 FL
37	1		*INNER STAND PANEL	Bent	560.00 FL	*560.00 FL
38	1		*FLOORBOARD PANEL	Buckled	385.00 FL	*385.00 FL
39	1		*CENTER SIDEGUARD COMPLETE	Bent	120.00 FS	*120.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*AIR-CON HEATER	Cracked	682.00 FS	*682.00 FS
41	1		*AIR-CON BLOWER	Cracked	295.00 FS	*295.00 FS
42	1		*AIR-CON CONDENSER	Bent	550.00 FS	*550.00 FS
43	1		*AIR-CON FAN	Broken	385.00 FS	*385.00 FS
44	1		*ALUMINIUM MIRROR STAY BRACKET LH	Bent	120.00 FL	*120.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,727.00	17,727.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	2,354.25	2,354.25
Total Parts (\$\$)	15,372.75	15,372.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE / RENEW FRONT WINDSCREEN GLASS	New	180.00	150.00
2	TO REMOVE / RENEW AIR-CON HEATER, BLOWER, CONDENSER, FAN AND REFILL GAS	New	350.00	200.00
3	TO DISMANTLE AND INSTALLATION TO ABOVE DAMAGED PARTS AND JOB COMPLETED	New	2,800.00	2,400.00
4	TO SPRAY PAINT ON THE ACCIDENT AFFECTED AREA	New	1,800.00	1,400.00
Gross Labour Cost (S\$)			5,130.00	4,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >