

ASS: REC BY

REP: CS/CT#18012602/Atd3n2

Special Instruction

Surveyor

Meinmen

Adrian

ASSIGNMENT (Office)

From (Person)

Huang Sheng Yi

of

CTI

Date/Time: 11/07/2018 @ 9:24am

Estimated Cost

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 5370H

Insured:

GT 3462S

at Workshop in/s

Vision Autowork

Tel:

6341 6789

of

8 kaki Bukit Ave 4 #08-09 Premier

Policy No:

DMCVSN1333001704

Claim No:

SNM18DO 3394C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

10/07/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:01am @ 11/7/18

Person Contacted:

Michelle

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKB 5370H-X

GT 3462S - NA / HSBBSB10003306/r

D.O.A: 18/02/2010

US \$4800, 6 days. Cred \$5841.84, 55%.

ASS. REC. BY: Adrian King

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKB 537014

Yr Regn:

2011, JueType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c.

1598

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

144932

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Jm6BL021A0158964Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

11/07/18

Survey held at

VisionDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ClaimMV: 37KPV: 24.6KNett: 12.4K

RECEIVED 16 NOV 2018

Date/Time, File Pass to?



: Preli. Report

1) 16/11/18 Trans

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

(TOTAL)

110

Report Format:

MER-TP

Lump Sum / L.P. (\$)

4800

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2018		11 Jul 2018 09:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	HIAP HUN PENG
Vehicle Reg. No.:	SKB5370H
Date of Loss:	10/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03394C02
Policy/Cover Note No.:	DMCVSN1333001704
Vehicle Reg. No. (Insured):	GT3462S
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/07/2018]
Adj Asg. Remarks:	NO EST, CASE WITH SJE.

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Inchcape
Pre-Owned

WIDE RANGE OF PRE-OWNED TOYOTA AND OTHER MAKES AVAILABLE

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRESCENT INCHCAPE CENTRE



LEARN MORE

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

Mitsubishi Lancer 1.6A At Cheapest Price!

Well Maintained Interior And Exterior By Owner! Cheapest In The Market.
Direct Owner StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category [Save Search](#) [Print](#) Sort by Date Posted 20 results/page

3 vehicles		Search		mazda 3		Advanced Search		Search		View All							
Make		Model		Price		Depreciation		Reg Date		Eng Cap		Mileage		Veh Type		Status	
Search Selection		mazda 3		Any		Any		2011		Any		Any		Any		Available	



☐ **Mazda 3 1.6A Luxury** \$37,800 \$9,980 /yr 28-Apr-2011 1,598 cc 100,838 km Sedan Available

1 Owner, Mileage Done Only 13000km Per Year, Road Tax Until April 2019, Accident Free. Superb Condition. Neat And Clean Interior. Bank Or In House Loan Available. Test Drive To Believe Condition.

Posted: 10-Jul-2018 Tags: 2011 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



☐ **Mazda 3 1.6A Luxury** \$39,800 \$10,030 /yr 24-Jun-2011 1,598 cc 119,000 km Sedan Available

Superb Well Maintained By Only 1 Owner, High ARF After Scrap, Genuine Mileage Done At 119k Km, Low Down Payment, No Gimmicks, No Monkey Business, High Loan Or Bank Loan Available, \$3k Down Payment, Ca...

Posted: 06-Jul-2018 Tags: 2011 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



☐ **Mazda 3 1.6A Luxury** \$42,000 \$10,390 /yr 08-Aug-2011 1,598 cc 79,000 km Sedan Available

Pearl White, Most Affordable Sporty Sedan, Lowest Depreciation In The Market, Well Maintain, With Service Records, No Repairs Needed, New 6 Months Road Tax, View To Believe, Call Our Friendly Sales To ...

Posted: 15-Jun-2018 Tags: 2011 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

[Save Search](#)

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used mazda 3; mazda 3 Singapore, used mazda 3 Singapore, used mazda 3, used vehicles Singapore or even buy used mazda 3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6378J
Vehicle Details	
Vehicle No.:	SKB5370H
Vehicle to be Exported:	Yes
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 1.6L SDN
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	Z6871830
Chassis No.:	JM6BL10Z1A0158964
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$20,340.00
Original Registration Date:	07 Jun 2011
First Registration Date:	07 Jun 2011
Transfer Count:	1
Actual ARF Paid:	\$20,340.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2021
PARF Rebate Amount:	\$12,204.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$42,600.00
COE Rebate Amount:	\$12,370.00
Total Rebate Amount:	\$24,574.00

The information contained herein is correct as at 11 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/07/2018 21:08
Date Of Accident	10/07/2018 06:25
Exact Location Of Accident	SLIP ROAD OF PUNGGOL ROAD TOWARDS TPE(SIE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB5370H
Insured/Policyholder	
Name Of Registered Owner	HIAP HUN PENG
NRIC No	S1816378J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96189200
Alternative Phone No	OFFICE-96189200

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	Z18VP05018888
Cover Note Number	

Driver

Name of Driver	HIAP HUN PENG
NRIC No	S1816378J
Date Of Birth	10/06/1967
Occupation	INDOOR
Date Of Driving Pass	24/08/1992
Driving Experience	25 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96189200
Fax Number	
Contact Number	OFFICE-96189200
Email Address	NOEMAIL

Address	BLOCK 188A RIVERVALE DRIVE #05-1084 (S)541188
Postcode	541188
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 10/07/2018 AT ABOUT 06:25 HOURS ALONG SLIP ROAD OF PUNGGOL ROAD TOWARDS TPE(SLE), I WAS STATIONARY ON THE LANE 2, WAITING FOR THE ONCOMING TRAFFIC TO CLEAR. SUDDENLT I HEARD ALOUD BANG FROM BEHIND . WHEN I ALIGHTED I REALISED IT WAS VEHICLE (B) HAD HIT ONTO REAR PORTION OF MY VEHICLE (A).
VEHICLE (A) : SKB5370H VEHICLE (B) : GT3462S

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GT3462S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE


- .. Please report **correctly** the details of the accident to speed up the claims process.
1. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
2. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
3. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
4. **Any false reporting may be referred to the Police for investigation.**
5. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
6. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
7. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Sketch Plan #2 Pg. 1

SKETCH PLAN



A = SKB 5370 H

B = GI 3462 S

Slip Road of
Punggol Road
towards TPE (SLE)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

On 10.07.18 at about 06:25 hours along Slip Road of Punggol Road towards TPE (SLE). I was stationary on the lane 2, waiting for the oncoming traffic to clear.

Suddenly I heard a loud bang from behind. When I alighted I realised it was vehicle (B) had hit onto rear portion of my vehicle (A).

Vehicle (A): SKB 5370H

Vehicle (B): GT 3462S



Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 10.07.18

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SKB5370H
MODEL : MAZDA 3
DATE OF ACCIDENT : 10.07.18
TIME OF ACCIDENT : 06:25HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 1,078.10	\$ 1,078.10
2	BOOT LID SHOCK ABSORBER <i>New</i>	2	\$ 71.70	\$ 143.40
3	BOOT LID LAMP <i>New</i>	2	\$ 298.00	\$ 596.00
4	BOOT LID LOGO <i>2</i>	1	\$ 65.80	\$ 65.80
5	BOOT LID EMBLEM 'MAZDA' <i>New</i>	1	\$ 34.40	\$ 34.40
6	BOOT LID EMBLEM '3'	1	\$ 22.50	\$ 22.50
7	BOOT LID TOP LOCK <i>Damaged</i>	1	\$ 164.50	\$ 164.50
8	BOOT LID HINGE <i>new New</i>	2	\$ 101.10	\$ 202.20
9	BOOT LID WEATHERSTRIP <i>at</i>	1	\$ 130.60	\$ 130.60
10	BOOT LID DETECTOR <i>Outd</i>	1	\$ 397.80	\$ 397.80
11	BOOT LID DETECTOR BRACKET <i>New</i>	1	\$ 69.40	\$ 69.40
12	REAR NUMBER PLATE LAMP <i>Outd</i>	2	\$ 144.40	\$ 288.80
13	REAR BUMPER <i>Dented</i>	1	\$ 1,276.80	\$ 1,276.80
14	REAR BUMPER REFLECTOR <i>New New</i>	2	\$ 54.90	\$ 109.80
15	REAR BUMPER SIDE RETAINER <i>New New</i>	2	\$ 34.30	\$ 68.60
16	REAR BUMPER BRACKET <i>New</i>	2	\$ 42.80	\$ 85.60
17	REAR BUMPER REINFORCEMENT <i>Best</i>	1	\$ 491.70	\$ 491.70
18	TAIL LAMP <i>Outd</i>	2	\$ 467.40	\$ 934.80
19	REAR FENDER INNER TRIM <i>New New</i>	2	\$ 180.00	\$ 360.00
20	REAR FENDER INNER COWLING <i>New</i>	2	\$ 142.20	\$ 284.40
21	REAR END PANEL <i>Dented</i>	1	\$ 380.00	\$ 380.00
22	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 179.60	\$ 179.60

4843.60
3874.88

TOTAL PRICE \$ 7,364.80
LESS 20% \$ 1,472.96
SUB TOTAL PRICE \$ 5,891.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Outd</i>	1	\$ 50.00	\$ 50.00

2	REAR BUMPER CLIP (SET) <i>Mer</i>	1	\$ 80.00	\$ 80.00	30
3	TAIL LAMP CLIP (SET) <i>Mer</i>	1	\$ 30.00	\$ 30.00	✓
4	BOOT LID INSULATOR CLIP (SET) <i>Mer</i>	1	\$ 50.00	\$ 50.00	x
5	BOOT LID STOPPER (UPPER) <i>Mer</i>	2	\$ 10.00	\$ 20.00	+
6	REAR FENDER COWLING CLIPS (SET) <i>Mer</i>	1	\$ 50.00	\$ 50.00	+
7	REAR FENDER INNER TRIM CLIPS (SET) <i>Mer</i>	1	\$ 50.00	\$ 50.00	+
8	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Mer</i>	1	\$ 30.00	\$ 30.00	10
9	REAR END PANEL INSULATION SEAL <i>Mer</i>	1	\$ 150.00	\$ 150.00	60
10	REVERSE SENSOR (SET) <i>Prongd</i>	1	\$ 220.00	\$ 220.00	200

380

TOTAL \$ 730.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,400.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	800
3	TUFF COAT	\$ 250.00	40
4	WIRING CHECK	\$ 80.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 150.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
7	REAR CHASSIS ALIGNMENT	\$ 250.00	x
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	x
9	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	x

1770

TOTAL

\$4,020.00

LKK Auto Consultants hence notify the Repairer of the following:

ESTIMATE REPORT

• To resupply parts and labour
 • To display parts and labour
 • Parts prices are subject to change
 • Third party liability
 • No illegal modifications is allowed
 • Supplier is subject to change

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS. EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

Acknowledged by Repairer
 Signature: _____
 Date: _____

PARTS PRICES ARE SUBJECT TO CHANGES.

Adrian L
 2/5 11/07/18
 062488
 4/5: 48k

VISION AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No. : 201500371E

Date: 11/02/18

By Fax & Email

To: China Taiping

Attn : Motor Claims Department

Re: Accident involving motor vehicle Nos. SKB5370H and GT3462S
along Slip Road of Punggol Road towards TPE (SLE) on 10/07/2018


We refer to the above matter.

We are instructed by Hiap Hun Heng to notify you of a road traffic accident
on 10/07/2018 at about 06:25 at Slip Road of Punggol Road towards TPE (SLE)
involving our client's/customer's vehicle registration number SKB5370H and vehicle
registration number GT3462S driven by you at the material time.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our
client/we proceed to repair the damaged vehicle, please let us know within 2 working days of
your receipt of this notice whether you or your insurer would like to conduct a pre-repair
survey of the vehicle. If we do not receive any reply from you within the stipulated timeline,
our client/we shall proceed to repair the vehicle without further reference to you.

Thank You

Yours faithfully


Abby

Hp : 9856 4815

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012602/ATD3N2

Date: 20/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1333001704
Claimant Vehicle No :	SKB5370H	Insured Vehicle No :	GT3462S
Date of Loss:	10/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03394C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB5370H	Engine No:	Z6871830
Make & Model:	MAZDA 3, 1.6 (A)	Chassis No:	JM6BL10Z1A0158964
Reg. Date:	07/06/2011 (Man. Year: 2010)	Odometer:	144932 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,621.84	4,254.88	2,366.96	35.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,770.00	2,250.00	55.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,641.84	6,024.88	4,616.96	43.38
Approved Total (Overridden) (\$\$)		4,800.00		
(\$\$)	10,641.84	4,800.00	5,841.84	54.90
+ GST 7.00/7.00% (\$\$)	744.93	336.00	408.93	54.90
Nett Amount (\$\$)	11,386.77	5,136.00	6,250.77	54.90

INSPECTION

Date of Assignment:	11/07/2018
Date Inspected:	11/07/2018 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2018)
Parts: 144	MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKB5370H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,078.10 FL	*1,078.10 FL
2	2		*BOOT LID SHOCK ABSORBER	Not Necessary	143.40 FL	*- FL
3	2		*BOOT LID LAMP	Not Necessary	596.00 FL	*- FL
4	1		*BOOT LID LOGO	Necessary	65.80 FL	*65.80 FL
5	1		*BOOT LID EMBLEM MAZDA	Necessary	34.40 FL	*34.40 FL
6	1		*BOOT LID EMBLEM 3	Necessary	22.50 FL	*22.50 FL
7	1		*BOOT LID TOP LOCK	Damaged	164.50 FL	*164.50 FL
8	2		*BOOT LID HINGE	Not Necessary	202.20 FL	*- FL
9	1		*BOOT LID WEATHERSTRIP	Cut	130.60 FL	*130.60 FL
10	1		*BOOT LID DETECTOR	Cracked	397.80 FL	*125.50 FL
11	1		*BOOT LID DETECTOR BRACKET	Not Necessary	69.40 FL	*- FL
12	2		*REAR NUMBER PLATE LAMP	Cracked	288.80 FL	*288.80 FL
13	1		*REAR BUMPER	Deformed	1,276.80 FL	*947.30 FL
14	2		*REAR BUMPER REFLECTOR	Not Necessary	109.80 FL	*- FL
15	2		*REAR BUMPER SIDE RETAINER	Not Necessary	68.60 FL	*- FL
16	2		*REAR BUMPER BRACKET	Not Necessary	85.60 FL	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Bent	491.70 FL	*491.70 FL
18	2		*TAIL LAMP	Cracked	934.80 FL	*934.80 FL
19	2		*REAR FENDER INNER TRIM	Not Necessary	360.00 FL	*- FL
20	2		*REAR FENDER INNER COWLING	Not Necessary	284.40 FL	*- FL
21	1		*REAR END PANEL	Dented	380.00 FL	*380.00 FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	179.60 FL	*179.60 FL
23	1		*REAR NUMBER PLATE	Cracked	50.00 FS	*50.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
25	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*30.00 FS
26	1		*SET BOOT LID INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
27	2		*BOOT LID STOPPER (UPPER)	Not Necessary	20.00 FS	*- FS
28	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
31	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
32	1		*SET REVERSES ENSOR	Damaged	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,094.80	5,223.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,472.96	968.72
Total Parts (\$\$)	6,621.84	4,254.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	150.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	40.00
7	REAR CHASSIS ALIGNMENT	New	250.00	-
8	TRANSFER BOOTLID MECHANISM	New	80.00	-
9	CONDUCT WATER LEAKAGE TEST	New	80.00	-
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	250.00	-
Gross Labour Cost (\$\$)			4,020.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >