

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5169D**AAD1807-055***Not Authenticated*
L1 Lm B

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5169D

VF1ABL15AUC276729

RENAULT

LATITUDE

6.7.2018

AIG

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>cm</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>cm</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>sl</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>cm</i> 135.97 —
5	1 BUMEP R RETAINER RH REAR	\$	<i>cm</i> 44.99 ✓
6	1 BUMPER REFLECTOR RH	\$	<i>Bn</i> 43.61 —
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>sl</i> 135.97 X
8	1 BUMEP R RETAINER LH REAR	\$	<i>sl</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>sl</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>Bn</i> 777.52 —
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Bn</i> 225.95 —
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Bn</i> 225.95 —
13	1 BOOT REAR	\$	<i>Bn</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>sl</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>sl</i> 323.05 X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>sl</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>sl</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	<i>sl</i> 225.36 —
19	1 BOOT BADGE	\$	<i>sl</i> 225.36 —
20	1 BOOT STRUT LH	\$	<i>sl</i> 276.08
21	1 BOOT STRUT RH	\$	<i>sl</i> 276.08
22	1 BOOT HINGE LH	\$	<i>sl</i> 367.84
23	1 BOOT HINGE RH	\$	<i>sl</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>sl</i> 586.45
25	1 BOOT SWITCH	\$	<i>sl</i> 168.13
26	1 BOOT LOCK	\$	<i>sl</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>sl</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>sl</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>sl</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1807-055**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5169D

30	1 DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66 <i>X</i>
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45 <i>X</i>
32	1 FENDER PANEL REAR LH	\$	<i>NA</i> 3,299.13 <i>X</i>
33	1 WHEELARCH REAR LH	\$	<i>Sn</i> 543.47 <i>X</i>
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45 <i>X</i>
35	1 FENDER PANEL REAR RH	\$	<i>Bu</i> 3,299.13 <i>✓</i>
36	1 WHEELARCH REAR RH	\$	<i>Sn</i> 543.47 <i>✓</i>
37	1 TAILLAMP RH	\$	<i>CM</i> 552.55 <i>✓</i>
38	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70 <i>X</i>
39	1 TAILLAMP LH	\$	<i>Sn</i> 552.55 <i>X</i>
40	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70 <i>X</i>
41	1 OUTER PANEL REAR (End Panel)	\$	<i>B</i> 1,471.77 <i>✓</i>
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56 <i>X</i>
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88 <i>X</i>
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21 <i>X</i>
45	1 EXHAUST REAR	\$	<i>B</i> 7,489.05 <i>✓</i>
46	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49 <i>X</i>
47	1 FUEL FLAP L70Y	\$	<i>Sn</i> 343.57 <i>X</i>
48	1 CHASSIS PANEL REAR RH	\$	<i>R</i> 3,766.43 <i>X</i>
49	1 WHEEL HOUSING PANEL REAR RH	\$	<i>R</i> 4,682.09 <i>X</i>
TOTAL		\$	47,505.69
10%		\$	4,750.57
		\$	42,755.12

Special Nett

1	1SET PARKING AID	\$	<i>Short</i> 700.00 <i>down</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00 <i>✓</i>
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00 <i>✓</i>
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00 <i>X</i>
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00 <i>X</i>
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00 <i>X</i>
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00 <i>X</i>
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00 <i>X</i>
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00 <i>✓</i>
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82 <i>X</i>
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20 <i>X</i>
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00 <i>✓</i>

Trans-cab Auto Services Pte Ltd**AAD1807-055**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5169D

13	1 BOOT STICKER "6555-3333"	\$	na 30.00 ✓
14	1 BOOT INNER TRIM CLIP	\$	na 45.00 X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na 35.00 X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na 35.00 X
17	1 FENDER INNER TRIM CLIP LH	\$	na 28.00 X
18	1 FENDER INNER TRIM CLIP LH	\$	na 28.00 X
19	1 TAILLAMP CLIP RH	\$	na 5.00 ✓
20	1 TAILLAMP CLIP LH	\$	na 5.00 X
21	2 REAR WINDSCREEN SELANT	\$	na 80.00 80.00
22	1 WINDSCREEN MOULDING	\$	na 100.00 ✓
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na 100.00 30.00
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na 385.00 X
25	1 SPARE TYRE	\$	na 330.00 X

TOTAL \$ 2,225.02**TOTAL PARTS \$ 44,980.14****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 12001
To Rust-Proofing Of The Affected Areas.	\$	170.00 901
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 601
To repair and realign rear exhaust pipe.	\$	170.00
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } 801

Trans-cab Auto Services Pte Ltd

AAD1807-055

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5169D

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	1001
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TOTAL \$ 12,540.00**Over All Total \$ 57,520.14****(LUMP SUM)****Repair Days****20 DAYS***8 days*

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date: